

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7247Z

DATE 1/27/2018 10:18

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket Top (LH) ?			\$ 222.40
	Front Bumper Retainer (LH) ?			\$ 9.20
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) ✕			\$ 169.80
	Front Fender Retainer (LH) ?			\$ 9.20
	Front Wheel Hub Cap (LH) ✓			\$ 150.70
	SUB TOTAL			\$ 3,420.50
	LESS 20%			\$ 684.10
	DISCOUNTED TOTAL			\$ 2,736.40
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,120.00
	ESTIMATE TOTAL			\$ 3,956.40

Kalin (Ucker)

29/1/18 1020h

3 Days

PIP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a without prejudice basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval by Insurance Company

Acknowledged by Repairer

Signature
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.