

CITY CAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 804L

DATE 29/1/2018 10:18

MAKE :

Doc: 27-01-18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>x repair</i>			\$ 1,681.40
	Boot Lid Rubber <i>x</i>			\$ 115.80
	Boot Lid Lock Upper <i>x</i>			\$ 137.90
	Boot Lid Lock Lower <i>x</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>-</i>			\$ 27.20
	Boot Lid CRDI Plate <i>-</i>			\$ 41.00
	Bootlid Moulding <i>x</i>			\$ 85.00
	Bootlid i40 Emblem <i>-</i>			\$ 41.00
	Bootlid Lower Garnish <i>x repair</i>			\$ 398.00
	Rear Bumper <i>-</i>			\$ 603.60
	Rear Bumper Reinforcement <i>-</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>-</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>?</i>		\$ 49.00	\$ 98.00
	Rear Bumper Clips <i>-</i>			\$ 22.00
	Rear Bumper Sponge <i>-</i>			\$ 143.40
	Rear Bumper Under Cover <i>-</i>			\$ 225.00
	Rear Bumper Reflector Lamp (RH) <i>x</i>			\$ 32.00
	Rear Panel <i>x repair</i>			\$ 592.30
	Rear Panel Garnish <i>?</i>			\$ 57.70
	Rear Panel Lower Panel <i>x repair</i>			\$ 495.50
	SUB TOTAL			\$ 5,692.85
	LESS 20%			\$ 1,138.57
	DISCOUNTED TOTAL			\$ 4,554.28
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Rear Bumper Reverse Sensor <i>-</i>			\$ 135.70 Nett
	Rear Bumper Advertisement Logo <i>-</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00 Nett
				\$ 415.70
	Labour Charge			600
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00 <i>5%</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Tuff Kote			\$ 50.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 6,639.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: *Kelvin*
 Date: *29/1/18*

Before paint photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.