



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
Comfortdelgo Transportation Pte Ltd

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

LKL
marcus 31/01/18 @ 0946

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP030012018
Policy No:		Date of Loss:	26/01/2018 ✓
Vehicle Reg. No.:	SJL9735Y	Driveable?	YES
Pa At Fault:	UNKNOWN	Driver (Insured):	ONG SER HUAT
Driver (TP):	CHAI WAI WAI, CARNATION		
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	17/12/2008
Vehicle Colour:	PURPLE	Gen Condition:	GOOD
Engine No:	K24A65005077	Chassis No:	JHMRB18508C205074
Odometer:	216432 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair 7 (day)			

31/01 - confirmed with marcus
LS \$2350

not Accident taken place after
1/5 \$2350
31/1/18

Description of Accident/Loss

ON 26/01/2018 AT ABOUT 2043HRS, I WAS DRIVING MY VEHICLE (A: SJL9735Y) ALONG HARPER ROAD HEADING TOWARDS CITIMAC INDUSTRIAL. I SAW THE VEHICLE (B: SHC3821S) WHICH WAS STATIONARY AT LEONG HUAT BUILDING ENTRANCE/EXIT, I PROCEED STRAIGHT. SUDDENLY I FELT AN IMPACT FROM MY VEHICLE'S RIGHT PORTION AND REALISED THAT VEHICLE B MOVED OUT WITHOUT CHECKING AND HIT ONTO MY VEHICLE'S RIGHT PORTION. NOBODY WAS INJURED IN THIS ACCIDENT.

VEHICLE A (SJL9735Y) - 1 CHILDREN PASSENGER ON BOARD.

VEHICLE B (SHC3821S) - NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEEU)

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

LKL Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Amount
3,151.60
10.00
1,200.00
1,100.00
0.00

Acknowledged by Repairer

Signature:

Date:

Gross Total (S\$)	5,461.60
+ GST 7.00% (S\$)	382.31
Nett Amount (S\$)	5,843.91

This claim is handled by: LAM WEI SHONG

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jan 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SJL9735Y/29/01/2018 20:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*o/s rear door <i>DD/3 emp</i>	20.00	0.00	*950.60 FL
2	1		*o/s rear door protector garnish <i>cut</i>	20.00	0.00	*129.70 FL
3	1		*o/s rear door window glass channel weatherstrip <i>11</i>	20.00	0.00	*150.20 FL
4	1		*o/s rear door outer weatherstrip moulding <i>11</i>	20.00	0.00	*176.10 FL
5	1		*o/s rear fender protector garnish <i>11</i>	20.00	0.00	*89.80 FL
6	1		*rear bumper <i>Deep cut 687.20</i>	20.00	0.00	*901.90 FL
7	1		*rear bumper lower <i>NK</i>	20.00	0.00	*452.70 FL
8	1		*rear bumper side retainers <i>11</i>	20.00	0.00	*21.20 FL
9	1		*o/s rear wheel rim <i>cut 5.25H</i>	0	0.00	*350.00 FS
10	1		*o/s rear shock absorber <i>11</i>	20.00	0.00	*310.40 FL
11	1		*o/s rear wheel bearing with hub <i>11</i>	20.00	0.00	*319.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,852.00
- List Item Discount on L Items (\$\$)	700.40
Total Parts (\$\$)	3,151.60

Tan Lim Motor Pte Ltd/SJL9735Y/29/01/2018 20:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1767.5
1414

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	ML ✓ 10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 800	1,100.00
Labour Items			
2	To check steering geometry and computer wheel alignment.	New 60	120.00
3	To rust-proofing of the affected areas.	New 30	100.00
4	To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	New 11X	380.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 300	600.00
Gross Labour Cost (S\$)			2,300.00

Tan Lim Motor Pte Ltd/SJL9735Y/29/01/2018 20:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2964

51 Defu Lane 10 Singapore 539216
 Tel : 6858 5151 (24 hours) Fax : 6858 0877
 email@timotor.com.sg www.timotor.com.sg
 Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2