

12/03/2012

ASS. REC. BY:

REF: CS/MSG18001837 / Srd3 12

Special Instructions:

Surveyor
Menimen

Sebastian

ASSIGNMENT (Office)

From (Person): Pearlyn Kong of MSIG Date/Time: 30/01/2018 @ 3:15pm

Estimated Cost: Bill to:

OE / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 6387B Insured:

at Workshop m/s Sin Yew Hup Tel: 67600819

of BIK D4 Woodlands Rd, 393M Yew Tee Ind. Est.

Policy No: 80434085 QMX Claim No: 548010

Sum Insured: Excess: \$1,000.00

Make of Veh: D.O.A. 16/12/2017

(Client's Record)

01/02/2017 @ 11am owner waiting

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4:00pm @ 30/1/18 Person Contacted: Jin Yee Vehicle-IN (OUT)

Date/Time Action/Instruction (✓) Estimate

SKL 6387B - X

8/201 Sent peti thru menimen, seek mandate
 Authorize repair & inform Repower to proceed repair & excess by
 all and email

MSIG

ASSIGNMENT

6/12/2013

From: _____ Date: **7/12/18**

Estimated Cost: _____

☒ P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SKL 6387**

at Workshop this: **Sin Yew Hup**

of: **BLK 4, 393M Woodlands Rd Yew Tee Ind. Est**

Insured: _____


Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: **\$1,000.00**

Client's Record: **10:30am - 11am**

Make of Van: **owner waiting**



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: **113**

DAO Accident Report: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Fee: Yes or No

Lum Sum: _____ % 3 year: Yes or No

CA ☒ REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Van No: **SKL 6387B**

Type: ☒ M / ☐ M Cycle / ☐ Bus / Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover

Truck / Trailer or: _____

Make: **Toyota** **Vellfire** **2362**

Colour: **Black** **40** Insured: **Std / NI / NA**

So Reading: **28878** **7** Radio: **Insured / Std / NI / NA**

Eng No: _____

C No: **ANH 208301235**

Gen Cond: **Good** / **28** / **Poor** / **Burnt**

Steering: **In order** / **28** / **Jammed** / **Leaked** / **Burnt** or

Brake: **In order** / **28** / **Jammed** / **Leaked** / **Burnt** or

Mod: **Nil** / **SRM** / **STD A/Rim** or

Tyre Size: **F: 245/40 ZR19**

R: 4

BS / DUN / EXNOVA / GY / PS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or **Drumtop**

Front: _____ Rear: _____

R.Bal: **6** mm R.Bal: **6** mm

L.Bal: **6** mm L.Bal: **6** mm

D.O.A: **16/12/2011** D.O.A: **7/12/2018**

Survey held at: **Sin Yew Hup**

Des of Damages: **FR / Rear / O/S / N/S / UIC / Roofed** or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision:

Date: _____ Time: _____ Action / Instruction: _____

Confirm **\$ 2568 @ 5 days**

Red: **\$ 482.00, 15%**

2 9/6/18

RECEIVED 27 APR 2018

Date/Time File Passed?



Date/Time File Returned?

Days Of Repair: **5**Resurvey No. of Trip: **1**

Surveys Fee

Transportation

Report Format: **TP**Lum Sum: **2568**

Add Fee:

Steiner: **\$**

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001837/Srd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 30-01-2018	
			Code : MSG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKL 6387B
Policy No. 80434085QMX		Coverage (\$)		0.00
Claim No. 548010		Excess (\$)		1,000.00
Assign From MERIMEN (PEARLLYN KANG)		Assign Date		30/01/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date 16/12/2017		Inspection Date		
Survey held at		SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018 Sendback Est	30 Jan 2018 12:38 S\$3,050.00	30 Jan 2018 15:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GOH AH TEE, ID: S1567575F, Tel: +6593854999, Email: KENNY_XIANG1991@HOTMAIL.COM		
Vehicle Reg. No.:	SKL6387B	Date of Loss:	16/12/2017 23:00 - :59
Claim Type:	OD / 548010	Policy/Cover Note No.:	80434085QMX (Comprehensive) Coverage: 29/06/2017 - 28/06/2018
		Excess:	S\$1,000.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]		
Driver/Custodian:	GOH AH TEE (55 / Male), NRIC: S1567575F, Tel: +6593854999		
Adj Asg. Remarks:	Car in tmr 31/01/2018 @ 10am. Please survey and revert. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 26 Apr 2018

Preliminary Advice

Vehicle No	: SKL6387B	Accident Date	: 16/12/2017
Make	: TOYOTA VELLFIRE	Policy No.	: 80434085QMX
Assignment Date	: 30/01/2018	Excess	: S\$1,000.00
Date of Inspection	: 07/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,050.00
Revised Amount	:S\$	2,568.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,568.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	88,166.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,834.00

Remarks

(X) The vehicle is economical/not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 08 Feb 2018

Preliminary Advice

Vehicle No	: SKL6387B	Accident Date	: 16/12/2017
Make	: TOYOTA VELLFIRE	Policy No.	: 80434085QMX
Assignment Date	: 30/01/2018	Excess	: S\$1,000.00
Date of Inspection	: 07/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,050.00
Revised Amount	:S\$	2,143.40
Check Items (Estimated)	:S\$	127.60
Total	:S\$	2,271.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	113,000.00
COE / PARF Rebate	:S\$	88,166.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,834.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

SKL6387B (548010)

OD

Dec 16 2017 11:00PM

[GOH AH TEE]

Sin Yew Hup Auto Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 08/02/2018 16:10 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2143.40) - SKL6387B - Claim Handler: Pearllyn Kang Yen
Lin

Approved:2143.40:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, February 08, 2018 5:25 PM
To: 'syhapl@singnet.com.sg'
Cc: SUR
Subject: SKL 6387B MSIG OD DOA: 16/12/2017

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKL 6387B (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7575F
Vehicle Details	
Vehicle No.:	SKL6387B
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.4Z PLATINUM SELECTION A
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	2AZG263852
Chassis No.:	ANH208301235
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,816.00
Original Registration Date:	06 Dec 2013
First Registration Date:	06 Dec 2013
Transfer Count:	2
Actual ARF Paid:	\$44,943.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2023
PARF Rebate Amount:	\$33,707.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$93,889.00
COE Rebate Amount:	\$54,459.00
Total Rebate Amount:	\$88,166.00

The information contained herein is correct as at 08 Feb 2018

OK




MY CAR FORUM MARKETPLACE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Honda CRV 2012 2.0 At \$85k.



Very Low Mileage (25900km),
Registered In 2013. Very Good
Condition.
Direct Owner - StarAd



Post an Ad

Advertiser Login

Ways of Selling

Sort by Date Posted

20 results/page

Browse by Category

4 vehicles

Toyota Vellfire

Advanced Search

Search Selection

Toyota Vellfire



Toyota Vellfire 2.4A Z Golden Eyes

\$117,800

\$16,550 /yr

30-Oct-2013

2,362 cc

70,180 km

MPV

Available

4 Set Of New Bridgestone Tyres! New 2 Pc Rear Absorber! Class Of Its Own Elegant People Carrier (MPV). Luxurious, Spacious, Comfortable And Quiet.
One Careful Owner. Well Maintained And Cared! Hurry Do...

Posted: 03-Feb-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota

PREMIUM AD



Toyota Vellfire 2.4A Z

\$106,800

\$16,980 /yr

18-Feb-2013

2,362 cc

129,000 km

MPV

Available

Viewings And Test Drives Are Strictly By Appointment Only. Up To 90% Loan And Trade In Available. (Free Polishing By Monster Shine Before Handing Over The Car!)

Monster Motors Pte Ltd

Posted: 03-Feb-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota

PREMIUM AD



Toyota Vellfire 2.4A G's

\$118,800

\$15,940 /yr

02-Dec-2013

2,362 cc

76,250 km

MPV

Available

Please Call Or Whatsapp For A Non-obligatory Discussion. Viewing Strictly Via Appointment Only.

Posted: 03-Jan-2018 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota

PREMIUM AD



Toyota Vellfire 2.4A Z

\$106,800

\$16,790 /yr

06-Feb-2013

2,362 cc

99,812 km

MPV

Available

Seller Consignment Unit, Call For Appointment Before Coming Down Thank You. High Current Paper Value. Cheapest In Market. Most Popular MPV In Town, Spacious Cabin, Foldable Rear Seats, Tip Top Condi...

Auto Inn

Posted: 29-Dec-2017 Tags: 2013 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

20 results/page

For old advertisements, view **Expired ads**

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Vellfire, Toyota Vellfire Singapore, used Toyota Vellfire Singapore, used Toyota Vellfire, used vehicles Singapore or even buy used Toyota Vellfire Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2018)**Parts:** M1-MPV TOYOTA VELLFIRE 2.4 Z Platinum Selection II (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP RH ✓ cut	0.00	0.00	✓ *580.00 F
2	1		*FRONT BUMPER R / cut	0.00	0.00	✓ *250.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH ? nec	0.00	0.00	✓ *42.00 F
4	6		*FRONT BUMPER CLIP ✓ nec	0.00	0.00	✓ *9.00 F
5	1		*FRONT FENDER RH ✓ D7	0.00	0.00	✓ *350.00 F
6	1		*FRONT FENDER INNER SHIELD Rd / mul Guard de	0.00	0.00	140 ✓ *65.00 F
7	6		*FRONT FENDER INNER SHIELD CLIP ? / nec	0.00	0.00	✓ *9.00 F
8	1		*FRONT FENDER GARNISH ✓ cut x nn	0.00	0.00	✓ *55.00 F
9	1		*FRONT DOOR PROTECTOR RH X nn	0.00	0.00	✓ *140.00 F

F=Franchise part.

Sub Total (S\$)	1,500.00
+ Margin on L,N Items 10.00% (S\$)	150.00
Total Parts (S\$)	1,650.00

Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE AND REFIT FRONT BUMPER, FRONT BUMPER SIDE RETAINER, HEADLAMP X2 , FRONT FENDER AND FRONT FENDER INNER SHIELD.	New	400 880.00
2	SPRAY PAINT FRONT BUMPER, SIDE DOOR, FRONT FENDER AND FRONT DOOR PROTECTOR RH.	New	650 880.00
Gross Labour Cost (\$\$)			1,400.00

Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sebastian:
7/2/18.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

90036121

sebastianyang@lkkauto.com

Excess: \$1000

Revert:

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


13/2/18



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapi@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./201 Reg. No. 200510750

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80434085QMX	Date of Loss:	16/12/2017
Vehicle Reg. No.:	SKL6387B	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH AH TEE	Contact No:	+6593854999
Driver:	GOH AH TEE		
Make/Model:	TOYOTA VELLFIRE, 2.4 Z PLATINUM SELECTION II (A)	Vehicle Reg. Date:	06/12/2013
Vehicle Colour:	BLACK	Chassis No:	ANH208301235
Engine No:	2AZG263852		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	PLS REFER TO THE DOCUMENTS ATTACHED		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	1,650.00
Miscellaneous Items	0.00
Labour	1,400.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	3,050.00
- Excess (S\$)	1,000.00
(S\$)	2,050.00
+ GST 7.00% (S\$)	143.50
Nett Amount (S\$)	2,193.50

This claim is handled by: **LIM JING YEE**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2018)

Parts: M1-MPV TOYOTA VELLFIRE 2.4 Z Platinum Selection II (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP RH <i>cut</i>	0.00	0.00	*580.00 F ✓
2	1		*FRONT BUMPER <i>cut</i>	0.00	0.00	*250.00 F ✓
3	1		*FRONT BUMPER SIDE RETAINER RH <i>✓</i> <i>NEC</i>	0.00	0.00	*42.00 F ✓
4	6		*FRONT BUMPER CLIP <i>✓</i> <i>NEC</i>	0.00	0.00	*9.00 F ✓
5	1		*FRONT FENDER RH <i>✓</i> <i>D7</i>	0.00	0.00	*350.00 F ✓
6	1		*FRONT FENDER INNER SHIELD <i>✓</i> <i>Mud Guard</i>	0.00	0.00	*65.00 F /40 ✓
7	6		*FRONT FENDER INNER SHIELD CLIP <i>✓</i> <i>NEC</i>	0.00	0.00	*9.00 F ✓
8	1		*FRONT FENDER GARNISH <i>✓</i> <i>cut</i> <i>NN</i>	0.00	0.00	*66.00 F ✓
9	1		*FRONT DOOR PROTECTOR RH <i>X</i> <i>NN</i>	0.00	0.00	*140.00 F ✓
Sub Total (S\$)						1,500.00
+ Margin on L/N Items 10.00% (S\$)						150.00
Total Parts (S\$)						1,650.00

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Parts: \$1380
+10%
\$1518
Labour: \$1050
\$2568 @ 5 days

1/30/2018

Estimate Report

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE AND REFIT FRONT BUMPER, FRONT BUMPER SIDE RETAINER, HEADLAMP X2, FRONT FENDER AND FRONT FENDER INNER SHIELD.	New	400 800.00
2	SPRAY PAINT FRONT BUMPER, SIDE DOOR, FRONT FENDER AND FRONT DOOR PROTECTOR RH.	New	600 800.00
Gross Labour Cost (\$)			1,400.00

Sin Yew Hup Auto Pte Ltd/SKL6387B/30/01/2018 12:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Sebastian
7/2/18
- Part by part repair.
 - Question Mark Iron Photo
 - Photo Before Paint.

90036121

sebastianyong@lkkauto.com

Excess: \$1000

Revert.

- 5 days
- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0619 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	80434085QMX	Date of Loss:	16/12/2017
Vehicle Reg. No.:	SKL6387B	Driveable?	
Driver Age/Info:	55 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH AH TEE	Contact No:	+6593854999
Driver:	GOH AH TEE		

Make/Model:	TOYOTA VELLFIRE, 2.4 Z PLATINUM	Vehicle Reg. Date:	06/12/2013
	SELECTION II (A)		
Vehicle Colour:	BLACK		
Engine No:	2AZG263852	Chassis No:	ANH208301235
Odometer:	0 KM		

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 5

Description of Accident/Loss PLS REFER TO THE DOCUMENTS ATTACHED
Present Location: SIN YEW HUP AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	154.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	154.00
+ GST 7.00% (\$)	10.78
Nett Amount (\$)	164.78
+ Previous Estimates (\$)	2,193.50
Claim Total (\$)	2,358.28

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 28 Feb 2018)**Parts:** M1-MPV TOYOTA VELLFIRE 2.4 Z Platinum Selection II (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sin Yew Hup Auto Pte Ltd/SKL6387B/28/02/2018 15:30**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FENDER MUDGUARD RH	0.00	0.00	*140.00 F de
F=Franchise part.						
Sub Total (S\$)						140.00
+ Margin on L,N Items 10.00% (S\$)						14.00
Total Parts (S\$)						154.00

Sin Yew Hup Auto Pte Ltd/SKL6387B/28/02/2018 15:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sin Yew Hup Auto Pte Ltd/SKL6387B/28/02/2018 15:30. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2627 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SIN YEW HUP AUTO PTE LTD

393M WOODLANDS ROAD
YEW TEE INDUSTRIAL ESTATE
SINGAPORE 677981

NO: DL19200126

PAGE: 1

DATE: 27/02/2018

A/C CODE: LDSY453

TERMS: CR

VEH NO: SKL6387B




Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
Our D/O No: DDO9021280					
1	T52119-58935	BUMPER FR DB2G	1	250.00	250.00
2	T52115-58050	BUMPER RETAINER FR RH DU1AD32-2	✓	42.00	42.00
3	T53801-58040	FENDER FR RH DB1B39	1	350.00	350.00
4	T53805-58060	FENDER LINER FR RH DBEE11	1	65.00	65.00
5	T52161-16010	CLIP DU1AD11-3	6	1.50	9.00
6	T53827-58030	PROTECTOR RH DU1AB33-6	✓	55.00	55.00
7	T90467-07216	CLIP DD1A169	6	1.50	9.00
8	T81145-58271	HEAD LAMP HID DDS	✓	580.00	580.00
TOTAL QUANTITY:			18	TOTAL	SIN 1,360.00
ADD GST @ 7%					95.20
GRAND TOTAL					SIN 1,455.20

Print / LIM / 27/02/2018 4:06:49 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717
Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

M/S: SIN YEW HUP AUTO PTE LTD


393M WOODLANDS ROAD
YEW TEE INDUSTRIAL ESTATE
SINGAPORE 677981

TAX INVOICE

NO: DLI9200174
PAGE: 1
DATE: 28/02/2018
A/C CODE: LDSY453
TERMS: CR

VEH NO: SKL6387B

Part No	Description	Location	Qty	Unit Price	Amount
T76901-58031-A0	FENDER MUDGUARD RH	DUIAB24-4	1	SIN 140.00	SIN 140.00
TOTAL QUANTITY:			1	TOTAL	SIN 140.00
				ADD GST @ 7%	9.80
				GRAND TOTAL	<u>SIN 149.80</u>



POSTED

Print / LIM / 28/02/2018 12:04:47 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001837/SRD3N2

Date: 30/04/2018

REFERENCE

Insured/Claimant:	GOH AH TEE	Policy No:	80434085QMX	Claim No:	548010
Date of Loss:	16/12/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL6387B	Engine No:	2AZG263852
Make & Model:	TOYOTA VELLFIRE, 2.4 Z Platinum Selection II (A)	Chassis No:	ANH208301235
Reg. Date:	06/12/2013 (Man. Year: 2013)	Odometer:	28898 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40ZR19	Rear Tyre Size:	245/40ZR19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,804.00	1,518.00	286.00	15.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,050.00	350.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,204.00	2,568.00	636.00	19.85
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	2,204.00	1,568.00	636.00	28.86
+ GST 7.00/7.00% (S\$)	154.28	109.76	44.52	28.86
Nett Amount (S\$)	2,358.28	1,677.76	680.52	28.86

INSPECTION

Date of Assignment: 30/01/2018 Present Location:
Date Inspected: 07/02/2018 Inspected At:

Sin Yew Hup Auto Pte Ltd (HQ)
Sin Yew Hup Auto Pte Ltd (HQ)
Blk D4 Woodlands Road 393M, Yew
Tee Industrial Estate
Singapore 677981

Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2018)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z Platinum Selection II (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL6387B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH (WCP)	Cut	580.00 F	*580.00 F
2	1		*FRONT BUMPER (WCP)	Cut	250.00 F	*250.00 F
3	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Necessary	42.00 F	*42.00 F
4	6		*FRONT BUMPER CLIP (WCP)	Necessary	9.00 F	*9.00 F
5	1		*FRONT FENDER RH (WCP)	Dented	350.00 F	*350.00 F
6	1		*FRONT FENDER INNER SHIELD (WCP)	Repeated	65.00 F	*- F
7	6		*FRONT FENDER INNER SHIELD CLIP (WCP)	Necessary	9.00 F	*9.00 F
8	1		*FRONT FENDER GARNISH (WCP)	Not Necessary	55.00 F	*- F
9	1		*FRONT DOOR PROTECTOR RH (WCP)	Not Necessary	140.00 F	*- F
Supplementary #1						
10	1		*FENDER MUDGUARD RH (WCP)	Deformed	140.00 F	*140.00 F

F=Franchise part.

Sub Total (\$\$)	1,640.00	1,380.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	164.00	138.00
Total Parts (\$\$)	1,804.00	1,518.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIT FRONT BUMPER, FRONT BUMPER SIDE RETAINER, HEADLAMP X2 , FRONT FENDER AND FRONT FENDER INNER SHIELD.	New	600.00	400.00
2	SPRAY PAINT FRONT BUMPER, SIDE DOOR, FRONT FENDER AND FRONT DOOR PROTECTOR RH.	New	800.00	650.00
Gross Labour Cost (\$\$)			1,400.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >