

ASS. REC. BY

REF: CS/MSG18001839/ Kvd322

Surveyor

Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSIG

Date/Time

30/1/18 @ 3:15pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 9829C

Insured:

YL 8194L

at Workshop m/s

T & B Motor Repairs

Tel:

6458 0296

of

Blk 160, Sin Ming Drive #08-03

Policy No:

B29032016TMV

Claim No:

547923

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/01/2018

CA / REV / REP. / REV 24 HRS

lwp

31/01/2018

H.O.D. Endorsement:

Date/Time:

4:20pm @ 30/1/18

Person Contacted:

Judy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SJW 9829C ✓

YL 8194L ✓

1/2/18

Informed Jasmine pending workshop est by merimen

9/2

C/Lyn B 2600d Confirm by email (Ref 348077, 5790)

20

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/800/839/Kvob
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merlmen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merlmen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

12/5/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2018




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001839/Kvd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 30-01-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 8194L	Veh. Inspected	SJW 9829C	
Policy No.	B29032016TMV	Coverage (\$)	0.00	
Claim No.	547923	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/01/2018	Inspection Date		
Survey held at	T & B MOTOR REPAIRS SERVICES PTE LTD BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 15:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SUNRAY WOODCRAFT CONSTRUCTION PTE LTD, Co. Reg. No.: NA		
Main Claimant:	LOH KEP ING, ID: S7913056G		
Vehicle Reg. No.:	SJW9829C	Date of Loss:	28/01/2018 18:00 - :59
Claim Type:	TP / 547923	Policy/Cover Note No.:	B29032016TMV (Third Party Only) Coverage: 14/10/2017 - 13/10/2018
Vehicle Reg. No. (Insured):	YL8194L	Policy No. (Claimant):	
		Excess:	
Repairer:	T & B Motor Repairs Services Pte Ltd () Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]		
Driver/Custodian (Insured):	TEO BOON HO (), NRIC: S0236066G, Tel: +6596629969		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Jasmine Lok Kheng Kwei	Date:	12 Feb 2018

Preliminary Advice

Insured Vehicle No	: YL8194L	Accident Date	: 28/01/2018
TP Vehicle No	: SJW9829C	Assignment Date	: 30/01/2018
Make	: HONDA CIVIC	Est. Duration of Repair	: 5.00
Date of Inspection	: 31/01/2018		
Inspection At	: T & B MOTOR REPAIRS SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-03, SIN MING AUTO CITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,080.77
Revised Amount	:S\$	2,600.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SJW9829C (547923)**
[YL8194L]

TP

LOH KEP ING

Jan 28 2018 6:00PM

[SUNRAY WOODCRAFT CONSTRUCTION PTE LTD]
T & B Motor Repairs Services Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **01/02/2018 15:54 PM.**
To MSIG_JLKK
Subject TP SURVEY SJW 9829C

Dear Jasmine,

Please be informed that we have inspected the vehicle SJW 9829C on 31/1/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 14:59
Date Of Accident	28/01/2018 17:50
Exact Location Of Accident	OUTSIDE SEE THIAN FOH COMBINED TEMPLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW9829C
Insured/Policyholder	
Name Of Registered Owner	LOH KEP ING
NRIC No	S7913056G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97998355
Alternative Phone No	OTHERS-97998355

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080113716-01
Cover Note Number	

Driver

Name of Driver	LOH KEP ING
NRIC No	S7913056G
Date Of Birth	05/05/1979
Occupation	INDOOR
Date Of Driving Pass	07/08/1998
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97998355
Fax Number	
Contact Number	OTHERS-97998355

Address BLK 473 CHOA CHU KANG AVENUE 3
#13-181
Postcode 680473
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : NA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL8194L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 29/01/18

1118hrs

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28th January 2018 at around 1750hrs, I was at along Bukit Batok St 23. ~~that~~ My car was stationary in front of gate of See thian Foh Combined Temple, my car plate number SJW 9829C. Lorry number YL8194L reversed and hit my car. The lorry driver and his spouse were in the lorry. My girlfriend and ~~are~~ were in car. No one is injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 28/01/18
1118hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NBIC/FIN No.:

KV

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

LOH KEPING

BLK 473 CHOA KANG AVENUE 3 #13-181

SINGAPORE 680473

Attention : Motor Claim Department

Estimate : ES003291

Date : 29/01/2018

Vehicle Num. : SJW9829C

Make/Model : HONDA CIVIC

Chassis/Eng# :

Accident Date : 28/01/2018

Claim No. :

Reference :

Policy No. : 5080113716-01

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :
1.	1	REAR WINDSCREEN GLASS MOULDING
2.	1 SET	REAR WINDSCREEN SEALANT
3.	1	REAR FENDER
4.	1	REAR LAMP LH
5.	1	REAR BUMPER
6.	1	REAR BUMPER SIDE RETAINER LH
7.	1	REAR BUMPER SIDE RETAINER RH
8.	12	REAR BUMPER CLIPS
9.	1	REAR FENDER INNER SHIELD LH
10.	8	REAR FENDER INNER SHIELD CLIPS
11.	1	REAR BOOT WEATHERSTRIP
12.	1	REAR LAMP PANEL LH

List Total S\$:

20.00% Discount S\$:

Mr	42.02	—
Mr	33.55	—
Mr	853.93	—
CM	275.33	—
Bull CM	787.27	—
017	18.59	—
5.50	18.59	X
5.50	66.00	X
5.50	185.00	X
5.50	44.00	X
5.50	109.23	X
5.50	279.95	X
		2,713.46
		542.69
		2,170.77

LABOUR :

1	1	1. REMOVE & REFIX REAR WINDSCREEN GLASS	250.00	250.00	1201
1	1	2. REMOVE & REFIX REAR FUEL TANK	380.00	380.00	601
1	1	3. REMOVE & REFIX REAR BUMPER REVERSE SENSOR	150.00	150.00	501
1	1	4. REMOVE & REFIX REAR WHEEL HOUSE GARNISH SPEAKER			
1	1	BOARD COVER, REAR PASSENGER SEAT & CARPET	450.00	450.00	1001
1	1	5. CHECK & REPAIR WIRING			
1	1	6. SPRAY PAINT ANTI-RUST COATING	180.00	180.00	301
1	1	7. SPRAY PAINTING ON AFFECTED PORTIONS	1,050.00	1,050.00	6001
1	1	8. REMOVE & REFIT REAR BUMPER SPOILER	250.00	250.00	801
1	1	9. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING,			

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T. & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

LOH KEPING

BLK 473 CHOA KANG AVENUE 3 #13-181

SINGAPORE 680473

Attention : Motor Claim Department

Estimate : ES003291

Date : 29/01/2018

Vehicle Num. : SJW9829C

Make/Model : HONDA CIVIC

Chassis/Eng# :

Accident Date : 28/01/2018

Claim No. :

Reference :

Policy No. : 5080113716-01

S/N	Quantity	Particular	Unit Price	Amount S\$
	1	WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE	1,200.00	1,200.00
		Labour Total S\$:		3,910.00

6001

SingDollars : Six Thousand Eighty & Cents Seventy-Seven Only

E. & O.E.

Total S\$:

6,080.77

=====



for T & B MOTOR REPAIRS SERVICES PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2018		30 Jan 2018 15:16 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SUNRAY WOODCRAFT CONSTRUCTION PTE LTD , Co. Reg. No.: NA		
Main Claimant:	LOH KEP ING , ID: S7913056G		
Vehicle Reg. No.:	SJW9829C	Date of Loss:	28/01/2018 18:00 - :59
Claim Type:	TP / 547923	Policy/Cover Note No.:	B29032016TMV (Third Party Only) Coverage: 14/10/2017 - 13/10/2018
Vehicle Reg. No. (Insured):	YL8194L	Policy No. (Claimant):	
		Excess:	
Repairer:	T & B Motor Repairs Services Pte Ltd () Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/03/2018]		
Driver/Custodian (Insured):	TEO BOON HO () , NRIC: S0236066G, Tel: +6596629969		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJW9829C (547923)**
[YL8194L]
TP
LOH KEP ING
Jan 28 2018 6:00PM
[SUNRAY WOODCRAFT CONSTRUCTION PTE LTD]
T & B Motor Repairs Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/01/18 10:47	Accident Statement From: SC - Reg. No: YL8194L, Claimant: SUNRAY WOODCRAFT CONSTRUCTION PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 13:57	Adjuster Immediate Advice	1	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	01/02/18 10:32	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	12/02/18 14:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
15	12/02/18 14:08	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/01/18 10:43	TP PRI & ACCDT REPORT	1	Load PDF	
2	30/01/18 10:47	E-FILE REPORT (SJW9829C) From: SC - Reg. No: YL8194L, Claimant: SUNRAY WOODCRAFT CONSTRUCTION PTE LTD	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001839/KVD3E2

Date: 14/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29032016TMV
Claimant Vehicle No :	SJW9829C	Insured Vehicle No :	YL8194L
Date of Loss:	28/01/2018	Nature of Claim:	TP
		Claim No:	547923

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW9829C	Engine No:	R16A14002887
Make & Model:	HONDA CIVIC, 1.6 L (A)	Chassis No:	JHMFD46209S200719
Reg. Date:	05/05/2010 (Man. Year: 2008)	Odometer:	120863 km
Colour:	Metallic Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,170.77	1,661.35	509.42	23.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	1,640.00	2,270.00	58.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,080.77	3,301.35	2,779.42	45.71
Approved Total (Overridden) (\$\$)		2,600.00		
Nett Amount (\$\$)	6,080.77	2,600.00	3,480.77	57.24

INSPECTION

Date of Assignment:	30/01/2018	
Date Inspected:	31/01/2018	Inspected At: T & B Motor Repairs Services Pte Ltd Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 14 Feb 2018)

Parts: 143 **HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SJW9829C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	42.02 FL	*42.02 FL
2	1		*SET REAR WINDSCREEN SEALANT	Necessary	33.55 FL	*33.55 FL
3	1		*REAR FENDER	Bent	853.93 FL	*853.93 FL
4	1		*REAR LAMP L/H	Cracked	275.33 FL	*275.33 FL
5	1		*REAR BUMPER	Buckled / Cracked	787.27 FL	*787.27 FL
6	1		*REAR BUMPER SIDE RETAINER LH	Distorted	18.59 FL	*18.59 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	18.59 FL	*- FL
8	12		*REAR BUMPER CLIPS	Necessary	66.00 FL	*66.00 FL
9	1		*REAR FENDER INNER SHIELD LH	Serviceable	185.00 FL	*- FL
10	8		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	44.00 FL	*- FL
11	1		*REAR BOOT WEATHERSTRIP	Serviceable	109.23 FL	*- FL
12	1		*REAR LAMP PANEL LH	Repair	279.95 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	2,713.46	2,076.69
- List Item Discount on L Items 20.00/20.00% (\$\$)	542.69	415.34
Total Parts (\$\$)	2,170.77	1,661.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	250.00	120.00
2	REMOVE & REFIX REAR FUEL TANK	New	380.00	60.00
3	REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	150.00	50.00
4	REMOVE & REFIX REAR WHEEL HOUSE GARNISH SPEAKER BOARD COVER, REAR PASSENGER SEAT & CARPET	New	450.00	100.00
5	CHECK & REPAIR WIRING (NPA)	New	0.00	0.00
6	SPRAY PAINT ANTI-RUST COATING	New	180.00	30.00
7	SPRAY PAINTING ON AFFECTED PORTIONS	New	1,050.00	600.00
8	REMOVE & REFIT REAR BUMPER SPOILER	New	250.00	80.00
9	LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,910.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >