

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

Pass Marcus by hand

not allowed
nkl
d/s \$3500
6dy.

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Estimate No: EST0000601

Date: 12 Mar 2018

Policy No: 5096968941

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline)

FAX: 6880 4740/6880 4838

Veh Reg No: FX396K

ATTN: Motor Claim Department

Make/Model: HONDA WAVW125S

Your Ref No: FX396K

Chassis No: NF125MD0063542

Claim Type: Third Party

Engine No: NF125MDE0063542

Accident Date: 09-01-2018

Reg. Date: 07-08-2003

TP Veh Reg No: PC2264L

Estimate Repair Cost to Vehicle No :FX396K

Description	U/Price	Quantity	List Price S\$	Amount S\$
HONDA WAVE125S				
List Price				
1 Front Handle Bar <i>ent</i>	60.0000	1 PC <i>ent</i>	60.00	✓
2 Front Handle Bar	120.0000	1 PC <i>ent</i>	120.00	✓
3 Front Core Bearing	80.0000	2 SET <i>NS</i>	160.00	α
4 Front Head Lamp <i>148</i>	298.0000	1 PC <i>ent</i>	298.00	✓
5 Front Signal Lamp	40.0000	2 PC <i>ent</i>	80.00	1PC
6 Front Headlamp Cover <i>245</i>	1,801.000	1 PC <i>ent</i>	1,801.00	✓
7 Front Meter	320.0000	1 PC <i>ent</i>	320.00	α
8 Front Meter Cover	150.0000	1 PC <i>ent</i>	150.00	✓
9 Front Fork <i>620</i>	350.0000	2 PC <i>ent/ent</i>	700.00	✓
10 Front Fork Bracket	100.0000	1 PC <i>ent</i>	100.00	✓
11 Front Fork Oil Seal	10.0000	1 SET <i>ent</i>	10.00	✓
12 Front Mudguard <i>60</i>	120.0000	1 PC <i>ent</i>	120.00	✓
13 Front Sport Rim	320.0000	1 PC <i>ent</i>	320.00	✓
14 Front Step Panel Garnish	200.0000	2 PC <i>ent</i>	400.00	✓
15 Front Wheel Axle	450.0000	1 PC <i>ent</i>	450.00	x
16 Rear Side <i>garnish</i>	150.0000	2 PC <i>ent</i>	300.00	✓
17 Rear Tail Lamp	90.0000	1 PC <i>ent</i>	90.00	✓
18 Swing Arm <i>28</i>	320.0000	1 PC <i>ent</i>	320.00	✓
19 Rear Shock Absorber	190.0000	1 SET <i>ent</i>	190.00	1PC
20 Foot Rest	25.0000	1 PC <i>ent</i>	25.00	✓
21 Gear Pedal	40.0000	1 PC <i>ent</i>	40.00	✓
22 Gear Shifter	50.0000	1 PC <i>ent</i>	50.00	x
23 Rear Pillion Foot Rest	40.0000	1 PC <i>ent</i>	40.00	✓
24 Rear Rest Bracket	30.0000	1 PC <i>ent</i>	30.00	✓
25 Brake Lever	45.0000	1 PC <i>ent</i>	45.00	x
26 Mirror <i>60</i>	180.0000	1 PC <i>ent</i>	180.00	✓
27 Side Stand	190.0000	1 PC <i>ent</i>	190.00	α
28 Rear Box Rack	180.0000	1 PC <i>ent</i>	180.00	✓
29 Rear Box	290.0000	1 PC <i>ent</i>	290.00	1605.2
30 Rear Mudguard	120.0000	1 PC <i>ent</i>	120.00	✓
31 Rear Boot Rest Rubber	45.0000	1 PC <i>ent</i>	45.00	α
32 Exhaust Pipe	320.0000	1 PC <i>ent</i>	320.00	✓
			7,544.00	
			Less 20%	1,508.80
				6,035.20
Special Net				
33 FRONT I.U UNIT	20.0000	1 PC <i>ent</i>	20.00	✓

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline)

FAX: 6880 4740/6880 4838

ATTN: Motor Claim Department

Your Ref No: FX396K

Claim Type: Third Party

Accident Date: 09-01-2018

TP Veh Reg No: PC2264L

Estimate No: EST0000601

Date: 12 Mar 2018

Policy No: 5096968941

Veh Reg No: FX396K

Make/Model: HONDA WAVW125S

Chassis No: NF125MD0063542

Engine No: NF125MDE0063542

Reg. Date: 07-08-2003

Estimate Repair Cost to Vehicle No :FX396K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
34 Number Plate (Front)	15.0000	1 SET	15.00	10
35 Rear Number Plate	15.0000	1 PC	15.00	10
			50.00	50.00
Labour				
36 Towing	40.0000	2 PC	80.00	35
37 Re-alignment Body Frame	380.0000	1 PC	380.00	350
38 To Remove & Replace Part, Align	450.0000	1 PC	450.00	330
39 To Remove & Replace Fork Tube, Bracket Rim, Swing Arm & Shock Absorber	200.0000	1 PC	200.00	X
40 Top up Engine Oil	20.0000	1 PC	20.00	X
			1,130.00	1,130.00
			Total	S\$ 7,215.20

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND TWO HUNDRED FIFTEEN AND CENTS TWENTY ONLY

For PROGRESSIVE AUTO PTE LTD

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

Tel: 68444620 Fax: 68444625

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: