

ASS. REC. BY

REF: CS/MSG18001859/T1rd301

Surveyor

Mevimen

Tau Hieh

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSG

Date/Time: 30/1/18 @ 3:01 pm

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SLS 6847S

Insured:

SKB 5167D

at Workshop no:

Performance

Tel:

63190174

of

303 Alexandra Rd

Policy No:

D28651481AMY

Claim No:

547883

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 3:59pm @ 30/1/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLS 6847S - NA/MSG18001667/13

D.O.A.: 29/01/2018

SKB 5167D - NA/MSG18001667/13

D.O.A.: 29/01/2018

Sent preli thru Mevimen

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 15:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM KWEE NYUK KELVIN, ID: S8206070G, Tel: +6597766293, Email: kgent@hotmail.com		
Main Claimant:	DAVID HO KAH KEONG, ID: S6963612H		
Vehicle Reg. No.:	SLS6847S	Date of Loss:	29/01/2018 08:00 - :59
Claim Type:	TP / 547883	Policy/Cover Note No.:	D28651481QMY (Comprehensive) Coverage: 07/12/2017 - 06/12/2018
Vehicle Reg. No. (Insured):	SKB5167D	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]		
Driver/Custodian (Insured):	LIM KWEE NYUK KELVIN (35 / Male), NRIC: S8206070G, Tel: +6597766293		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001859/T1rd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 31-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 5167D	Veh. Inspected	SLS 6847S	
Policy No.	D28651481QMY	Coverage (\$)	0.00	
Claim No.	547883	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 06 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKB5167D	Accident Date	: 29/01/2018
TP Vehicle No	: SLS6847S	Assignment Date	: 30/01/2018
Make	: BMW 530I	Est. Duration of Repair	: 3.00
Date of Inspection	: 05/02/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,966.90
Revised Amount	:S\$	3,307.55
Check Items (Estimated)	:S\$	2,793.50
Total	:S\$	6,101.05

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 15:29
Date Of Accident	29/01/2018 08:50
Exact Location Of Accident	BOON LAY WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS6847S
Insured/Policyholder	
Name Of Registered Owner	DAVID HO KAH KEONG
NRIC No	S6963612H
Email Address	DAVIDK2HO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81261070
Alternative Phone No	OFFICE-81261070

81261020

Vehicle Particulars

Manufacturer	BMW
Model	530IA
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2002259
Cover Note Number	

Driver

Name of Driver	DAVID HO KAH KEONG
NRIC No	S6963612H
Date Of Birth	27/12/1969
Occupation	INDOOR
Date Of Driving Pass	24/11/2006
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81261070
Fax Number	
Contact Number	OFFICE-81261070
Email Address	DAVIDK2HO@GMAIL.COM

Address	5 PINE GROVE #07-02
Postcode	597591
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB5167D
Vehicle Make/Model/Colour	HYUNDAI SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM KWEE NYUK KELVIN
NRIC/Passport Number	S8206070G
Contact Number	97766293
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	2

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

Jun 29, 2018

1 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) Was in middle lane of Boon Lay Way.
- 2) Had to stop as car on left cut into my way as there was a closure of left most lane due to ~~that~~ road works
- 3) Car behind braked but could not stop in ~~times~~ time
- 4) Collision ~~was~~ from front to my rear.
- 5) Damage to bumper, a bit to front of ~~the~~ his car.

DÉCLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Jan 29, 2018
1 pm.

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

29/1/2018
@ 1332hrs

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**29 JAN 2018**Estimate No. : **b1 45685**
Date Estimated : **29/01/2018**
Prepared By : **Chua Kee Sin**

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -**David Ho kah keong**
5 Pine Grove
#07-02**Singapore 597591****- ACCOUNT - 40000****Cash Sales - Service**
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS6847S	WA34761	29/09/2017	530iA	0

DESCRIPTIONVALUE

Replace rear bumper and remove attachment etc include knock on accident dent

- 850 1,275.00

Spray painting on rear bumper

- 934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

- 150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

2307 271.00

Sundries.

- ? 80.00

Total Labour 1: **2,841.00**DESCRIPTIONQTY PRICVALUE

Carrier, bum

1 567.95

der 50 25 567.95

REAR BUMPER BOTTOM REINFORCEMENT

1 78.30

der 50 25 78.30

REAR BUMPER CENTRE GUIDE

1 58.55

na 58.55

REAR BUMPER LH SIDE GUIDE

1 55.65

na 55.65

REAR BUMPER RH SIDE GUIDE

1 55.65

na 55.65

REAR BUMPER TRIM STRIP

1 103.40

- 103.40

REAR BUMPER TOWING EYE FLAP PRIMED

1 39.05

Rv 39.05

REAR BUMPER PANEL PRIMED (PDC/PMA)

1 1,445.75

1451 1,445.75

SET MOUNTS PDC SENSOR REAR

1 62.50

na 62.50

PLUG

4 1.05

- 4.20

UNDERBODY PANELLING REAR

1 41.30

/ 41.30 der

REAR LH REAR REFLECTOR

1 35.40

na 35.40

REAR RH REAR REFLECTOR

1 35.40

na 35.40

DECOUPING RING PDC TORQUE CONVERTER

4 5.05

/ 20.20

PDC SENSOR SOPHISTOGRAU II WA90

4 380.65

na 1,522.60

Total Parts : **4,125.90**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45685
Date Estimated : 29/01/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS6847S	WA34761	29/09/2017	530ia	0

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Page No. _____	Claim No. _____
Date&Time <u>3/2/18 01:05</u>	Excess \$6
Surveyor's Name <u>Tan Jiah</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>92405219</u>	Authorised Yes / No
Authorised Date <u>3/2/18</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No	
Surveyor's E-mail <u>tanjiah@kha.com</u>	
No. of Working Days Recommend <u>3 day</u>	

[Signature]
12/2/18

7009.00

Labour 1	:	696.90	2,841.00
Parts	:		4,125.90
Labour 2	:		0.00
Excess	:		0.00
Total GST @ 7%	:		487.68
Grand Total	:		7,454.58

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45685
Date Estimated : 29/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
David Ho kah keong
5 Pine Grove
#07-02

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 597591

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLS6847S	WA34761	29/09/2017	530iA	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, rear underbody panelling include knocking out dents caused by the accident		850.00		850.00
To spray paint rear bumper		934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER BOTTOM REINFORCEMENT	80.25	1.00		80.25
REAR BUMPER TRIM STRIP	103.40	1.00		103.40
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,481.90	1.00		1,481.90
PLUG	1.05	4.00		4.20
UNDERBODY PANELLING REAR	41.30	1.00		41.30
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00		20.20

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,731.25
Total Labour & Parts :	3,745.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,745.25
GST @7%:	262.17
Grand Total :	4,007.42

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 15:01 Edit Adj Rpt	S\$3,745.25 Edit Estimates	S\$3,745.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

































CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	LIM KWEE NYUK KELVIN, ID: S8206070G, Tel: +6597766293, Email: kgent@hotmail.com					
Main Claimant:	DAVID HO KAH KEONG, ID: S6963612H					
Vehicle Reg. No.:	SLS6847S	Date of Loss:	29/01/2018 08:00 - :59			
Claim Type:	TP / 547883	Policy/Cover Note No.:	D28651481QMY (Comprehensive) Coverage: 07/12/2017 - 06/12/2018			
Vehicle Reg. No. (Insured):	SKB5167D	Policy No. (Claimant):				
		Excess:				
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174					
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/03/2018]					
Driver/Custodian (Insured):	LIM KWEE NYUK KELVIN (35 / Male), NRIC: S8206070G, Tel: +6597766293					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLS6847S (547883)**
[SKB5167D]
TP
DAVID HO KAH KEONG
Jan 29 2018 8:00AM
[LIM KWEE NYUK KELVIN]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/18 14:35	Accident Statement From: SC - Reg. No: SKB5167D, Claimant: LIM KWEE NYUK KELVIN	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 17:14	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/02/18 17:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/03/18 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	14/03/18 10:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	14/03/18 10:01	Reinspection Photo	 Load JPG	

					<input checked="" type="checkbox"/>
31	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
32	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	14/03/18 10:01	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/01/18 14:35	TP GIA Rep - SLS6847S From:SC - Reg. No: SKB5167D, Claimant: LIM KWEE NYUK KELVIN	1	Load PDF	
2	30/01/18 14:36	Email frm TP - PRI	1	Load PDF	
3	30/01/18 14:39	Estimate	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001859/T1RD3E2

Date: 20/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: D28651481QMY

Claimant Vehicle No : SLS6847S

Insured Vehicle No : SKB5167D

Date of Loss: 29/01/2018

Nature of Claim: TP

Claim No: 547883

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS6847S

Make & Model: BMW 530i, 2.0 LED NAV (A)

Engine No: 10569982B48B20B

Reg. Date: 29/09/2017 (Man. Year: 2017)

Chassis No: WBAJA52060WA34761

Colour: Black

Odometer: 3933 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,244.00	1,811.25	2,432.75	57.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,761.00	1,934.00	827.00	29.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,005.00	3,745.25	3,259.75	46.53
+ GST 7.00/7.00% (S\$)	490.35	262.17	228.18	46.53
Nett Amount (S\$)	7,495.35	4,007.42	3,487.93	46.53

INSPECTION

Date of Assignment: 30/01/2018

Date Inspected: 05/02/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 16 Mar 2018)

Parts: 143 **BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SLS6847S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*CARRIER, BUM	Not Necessary	567.95 FS	*- FS
3	1		*REAR BUMPER BOTTOM REINFORCEMENT	Deformed	80.25 FS	*80.25 FS
4	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	58.55 FS	*- FS
5	1		*REAR BUMPER LH SIDE GUIDE	Not Necessary	55.65 FS	*- FS
6	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	55.65 FS	*- FS
7	1		*REAR BUMPER TRIM STRIP	Cut	103.40 FS	*103.40 FS
8	1		*REAR BUMPER TOWING EYE FLAP PRIMED	Repair	39.05 FS	*- FS
9	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,481.90 FS	*1,481.90 FS
10	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.50 FS	*- FS
11	4		*PLUG	Necessary	4.20 FS	*4.20 FS
12	1		*UNDERBODY PANELLING REAR	Deformed	41.30 FS	*41.30 FS
13	1		*REAR LH REAR REFLECTOR	Not Necessary	35.40 FS	*- FS
14	1		*REAR RH REAR REFLECTOR	Not Necessary	35.40 FS	*- FS
15	4		*DECOUPLING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
16	4		*PDC SENSOR SOPHISTOGRAU II WA90	Not Necessary	1,522.60 FS	*- FS
Total Parts (S\$)					4,244.00	1,811.25

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,275.00	850.00
2	SPRAY PAINTING ON REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
Gross Labour Cost (\$\$)			2,761.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >