

22/03/2002

ASS. REC. BY:

REF: CS/III18001860/Avd3n2 Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

Menmen

From (Person):

Gabriel Wee

of

III

Date/Time: 30/1/18 @ 5.26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBU 5675 K

Insured:

SHC 2012S

at Workshop m/s

CK Vehicle Rental

Tel:

67478900

of BIK 1003, Eunus Ave 8 # 01-57

Policy No:

MCO m0015

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/01/2018

CA / REV / REP. / REV 24 HRS

lwp

31/01/2018

H.O.D. Endorsement:

Date/Time:

5.50pm @ 30/1/18

Person Contacted:

Raymond

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SBU 5675K - cc4/A16 13019424/M1pb3w2

D.O.A. = 12/10/13

SHC 2012S - X

16/3/18

Adnan Confirmed LS \$ 5700 (Rev 6581.36, 5370)

REF:

Sireyur

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SB4567SK Yr Regn: 1992, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla cc 1587Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 389834

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: AE1013012300Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 155/50R15R: 195/50R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 31/01/18Survey held at C.K.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP111

COE Expiry: 30/04/19.

MV: 7K

PV: 500

Nett: 6.5K

RECEIVED 10 MAR 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

19/3 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

5700/-)

Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

) Photos

) Others

TOTAL

350  
10

360

# Survey Department Check List (Case Handler)

Reference No.: CS/III/1800/860/Ave3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

): Case handler to make sure all information created by the assignment team are ACCURATE.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

Case Handler

19/3/18

Date

\*C: Critical \*N: Non-Critical

21/05/2018



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18001860/Avd3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 31-01-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2012S	Veh. Inspected	SBU 5675K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	31/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	25/01/2018	Inspection Date	31/01/2018
Survey held at	CK VEHICLE RENTAL PTE LTD BLK 1003 EUNOS AVE 8 #01-57 (OFF EUNOS ROAD 2) SINGAPORE 409498		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 30 January 2018 5:26 PM  
**To:** ct-admin@visionlawllc.com; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Sherini Pillai  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SBU5675K (Accident involving SBU5675K and SHC2012S on 25.01.2018)  
**Attachments:** 1487\_001.pdf; 1293\_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SBU5675K and let us have your report urgently.

This claim will be handled by Ms Sherini.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Motor Claim - III

**Sent:** 30 January, 2018 4:23 PM

**To:** 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>

**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. SBU5675K (Accident involving SBU5675K and SHC2012S on 25.01.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

**From:** ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]  
**Sent:** 30 January, 2018 2:27 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
SHARON PARWANI  
ONG BOCK KEE  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
TAN YING XIAN SELWYN

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com

## BRANCH

TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.C81.SBU 5675 K.18  
Your Ref: SHC 2012 S

30 January 2018

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
64 Cecil Street  
#04/#05 IOB Building  
Singapore 049711  
Attention: Motor Claims Department

BY FAX ((6225-7743)

motorclaim@iil.com.sg

Dear Sirs,

**ACCIDENT INVOLVING SBU 5675 K & SHC 2012 S ON 25 JANUARY 2018 ALONG HOUGANG AVENUE 3 AT ABOUT 1950 HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**Venue:** CK Vehicle Rental Pte Ltd  
Blk 1003 Eunos Avenue 8  
#01-57  
Singapore 409498  
Contact Person: Raymond Goh 6747-8900

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M  
(HEAD OFFICE)

cc: SBU 5675 K – By fax: 6763-6151 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7342I
Vehicle Details	
Vehicle No.:	SBU5675K
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6A
Primary Colour:	Green
Manufacturing Year:	1992
Engine No.:	4A3003738
Chassis No.:	AE1013012300
Maximum Power Output:	-
Open Market Value:	\$16,887.00
Original Registration Date:	12 Jun 1992
First Registration Date:	12 Jun 1992
Transfer Count:	4
Actual ARF Paid:	\$25,331.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$3,864.00
COE Rebate Amount:	\$483.00
<b>Total Rebate Amount:</b>	<b>\$483.00</b>

The information contained herein is correct as at 31 Jan 2018



MPA218612938 / Progressive Automotive Pte Ltd - HQ  
 ENTRY DATE & TIME: 26/01/2018 14:06  
 SUBMITTED BY: Lee Jia Min

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/01/2018 14:06
Date Of Accident	25/01/2018 19:50
Exact Location Of Accident	HOUGANG AVENUE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBU5675K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEE TIONG LIAN
NRIC No	S1387342I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96738846
Alternative Phone No	OTHERS-96738846

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	SI17V08902/VPE
Cover Note Number	

### Driver

Name of Driver	SEE TIONG LIAN
NRIC No	S1387342I
Date Of Birth	10/11/1959
Occupation	INDOOR
Date Of Driving Pass	19/07/1980
Driving Experience	37 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96738846
Fax Number	
Contact Number	OTHERS-96738846
Email Address	NOEMAIL

Address BLK 740 PASIR RIS STREET 71 # 14-53  
SINGAPORE

Postcode 510740

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions AFTER RAIN

Road Surface WET

**Other information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: MRS SEE  
GENDER: FEMALE

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHC2012S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan #2

## SKETCH PLAN

		<b>Vehicle No</b> A - SHC 2012 S B - SHC 2012 S
		<b>Legend</b> 

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car stop and Taxi SHC 2012 S hit the back of my car causing damage.

The impact causes my car to move onto the kerb at the left side.

## DECLARATION

We declare the foregoing particulars are true in every respect.  
 Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature  
 Date & Time:

26/1/18 2:06pm

Driver's signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Person's Signature  
 Name:  
 NRIC/ID No.:

City

## Sketch Plan

SKETCH PLANIMPORTANT NOTICE:

1. Please report correctly the details of the incident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false report may only be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes, mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes listed; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature

Date &amp; Time:

26/1/18 2:06pm

  
 Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

  
 Responding Centre Personnel's Signature

Name:

NIC/PIN no.:

Lily

# CK VEHICLE RENTAL PTE LTD

Blk 1003 Eunos Ave 8 #01-57 Singapore 409498 (Off Eunos Rd 2)

Tel: 6767 8900

Fax: 6747 8944

Email: ckvr88@singnet.com.sg

Vehicle No.: SBU5675K

Vehicle Made & Model: TOYOTA COROLLA

TR III Veron

AE1013012300

Qty	List Items	Amount \$
1	Rear boot lid Buckled	681.60 ✓
1	Rear boot logo new	38.60 ✓
1	Rear boot emblem "TOYOTA" } new	32.80 ✓
1	Rear boot emblem "GLi" }	32.80 ✓
1	Rear boot emblem "1.6" }	28.85 ✓
1	Rear boot reflector Lt	<del>512.60</del> 471.10
1	Rear boot inner lock new	115.20 ✓
1	Rear boot lock striker new	76.65 x
1	Rear boot lock cable new	89.90 x
2	Rear boot hinges - L/R @ 110.75 new	221.50 x
1	Rear boot w/strip Lt	121.60 ✓
1	Rear bumper Distorted.	<del>661.20</del> 497
1	Rear bumper top beam Best	189.60 ✓
2	Rear bumper side retainers @ 48.60 new	97.20 ✓
10	Rear bumper clips @ 4.50 new	45.00 30
2	Rear bumper licence lamps @ 42.20 new	84.40 x
1	Rear end panel Distorted.	<del>766.50</del> 585.40
1	Rear end panel inner trim Behind	160.90 ✓
1	Rear end panel garnish new	141.20 x
1	Rear exhaust silencer } new	760.20 ✓
2	Rear exhaust mountings @ 28.60 }	57.20 x
1	Rear floor board new	281.90 x
1	Rear floor panel Reps	741.60 x
1	Rear fender - LH Distorted.	891.60 ✓
2	Rear fender inner trims - L/R @ 280.60 LH torn	561.20 280.60
10	Rear fender inner trim clips @ 4.50 new	45.00 20
1	Rear fender inner shield - LH Behind	64.45 ✓
1	Rear fender air vent - LH Behind	104.10 ✓
1	Rear fender inner panel - LH Reps	441.50 x
2	Rear taillamps - L/R @ 441.55 LH cracked, RH cut	<del>883.10</del> 586.40
2	Rear taillamp lower panels - L/R @ 182.60 LH Distorted	<del>365.20</del> 182.60
4	Rear taillamp side clips @ 12.60 new	25.20 12.60
1	Rear spare wheel retainer lock new	48.60 x
1	Rear windscreen moulding new	126.20 ✓
Sub-total		9,495.15
Less 25%		2,373.79
Total List		7,121.36

5321.2

3990.90

Vehicle No.: SBU5675K

Vehicle Made & Model: TOYOTA COROLLA

**Special Nett Items:**

1 set Rear reverse sensor *Rgd*  
1 Rear no. plate *but*  
1 set Rear windscreen sealant *in*  
1 Rear boot top spoiler *in*

*285*

280.00	<i>200</i>
40.00	<i>25</i>
80.00	<i>60</i>
650.00	<i>X</i>
<b>Total Special Nett</b>	<b>1,050.00</b>

**Labour Charges:**

To remove, refix rear interior trims to assist repair  
To remove, refix reverse sensor  
To remove, refix rear windscreen  
To respray undercoating  
To remove, refix rear exhaust systems  
To check rear electrical wiring  
To respray painting & etc  
Panel beating, cut, weld, remove & replacing above parts

*2840*

120.00	<i>80</i>
80.00	<i>50</i>
180.00	<i>120</i>
150.00	<i>60</i>
100.00	<i>X</i>
80.00	<i>30</i>
1,400.00	<i>1200</i>
2,000.00	<i>1300</i>
<b>Total Labour</b>	<b>4,110.00</b>

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,281.36**

*total: 7115.90*

*L/S: 5.7K*

*08 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18001860/AVD3N2

Date: 20/03/2018

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SBU5675K	Insured Vehicle No :	SHC2012S
Date of Loss:	25/01/2018	Nature of Claim:	TP
		Claim No:	N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SBU5675K	Engine No:	4A3003738
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Chassis No:	AE1013012300
Reg. Date:	12/06/1992 (Man. Year: 1992)	Odometer:	389834 km
Colour:	White		
Engine Capacity:	1587 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,171.36	4,275.90	3,895.46	47.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,840.00	1,270.00	30.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,281.36</b>	<b>7,115.90</b>	<b>5,165.46</b>	<b>42.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,281.36</b>	<b>5,700.00</b>	<b>6,581.36</b>	<b>53.59</b>

## INSPECTION

Date of Assignment:	30/01/2018		
Date Inspected:	31/01/2018	Inspected At:	Ck Vehicle Rental Pte Ltd (HQ) BLK 1003 EUNOS AVE 8 #01-57 Singapore 409498

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
<b>Parts:</b>	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBU5675K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	681.60 FL	*681.60 FL
2	1		*REAR BOOT LOGO	Necessary	38.60 FL	*38.60 FL
3	1		*REAR BOOT EMBLEM TOYOTA	Necessary	32.80 FL	*32.80 FL
4	1		*REAR BOOT EMBLEM GLI	Necessary	32.80 FL	*32.80 FL
5	1		*REAR BOOT EMBLEM 1.6	Necessary	28.85 FL	*28.85 FL
6	1		*REAR BOOT REFLECTOR	Cut	512.60 FL	*471.10 FL
7	1		*REAR BOOT INNER LOCK	Damaged	115.20 FL	*115.20 FL
8	1		*REAR BOOT LOCK STRIKER	Not Necessary	76.65 FL	*- FL
9	1		*REAR BOOT LOCK CABLE	Not Necessary	89.90 FL	*- FL
10	2		*REAR BOOT HINGES-L/R	Not Necessary	221.50 FL	*- FL
11	1		*REAR BOOT W/STRIP	Cut	121.60 FL	*121.60 FL
12	1		*REAR BUMPER	Distorted	661.20 FL	*497.00 FL
13	1		*REAR BUMPER TOP BEAM	Bent	189.60 FL	*189.60 FL
14	2		*REAR BUMPER SIDE RETAINERS	Necessary	97.20 FL	*97.20 FL
15	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*30.00 FL
16	2		*REAR BUMPER LICENCE LAMPS	Not Necessary	84.40 FL	*- FL
17	1		*REAR END PANEL	Distorted	766.50 FL	*585.40 FL
18	1		*REAR END PANEL INNER TRIM	Deformed	160.90 FL	*160.90 FL
19	1		*REAR END PANEL GARNISH	Not Necessary	141.20 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Not Necessary	760.20 FL	*- FL
21	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.20 FL	*- FL
22	1		*REAR FLOOR BOARD	Not Necessary	281.90 FL	*- FL
23	1		*REAR FLOOR PANEL	Repair	741.60 FL	*- FL
24	1		*REAR FENDER-LH	Distorted	891.60 FL	*891.60 FL
25	1		*REAR FENDER INNER TRIMS-L/R	N/s Torn	561.20 FL	*280.60 FL
26	10		*REAR FENDER INNER TRIM CLIPS	Necessary	45.00 FL	*20.00 FL
27	1		*REAR FENDER INNER SHIELD -LH	Deformed	64.45 FL	*64.45 FL
28	1		*REAR FENDER AIR VENT-LH	Deformed	104.10 FL	*104.10 FL
29	1		*REAR FENDER INNER PANEL-LH	Repair	441.50 FL	*- FL
30	2		*REAR TAILLAMPS-L/R	N/s Cracked/O/s Cut	883.10 FL	*556.40 FL
31	1		*REAR TAILLAMP LOWER PANELS-L/R	N/s Distorted	365.20 FL	*182.60 FL
32	4		*REAR TAILLAMP SIDE CLIPS	Necessary	25.20 FL	*12.60 FL
33	1		*REAR SPARE WHEEL RETAINER LOCK	Not Necessary	48.60 FL	*- FL
34	1		*REAR WINDSCREEN MOULDING	Necessary	126.20 FL	*126.20 FL
35	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1		*REAR NO PLATE	Bent	40.00 FS	*25.00 FS
37	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
38	1		*REAR BOOT TOP SPOILER	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,545.15</b>	<b>5,606.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,373.79</b>	<b>1,330.30</b>
<b>Total Parts (\$\$)</b>	<b>8,171.36</b>	<b>4,275.90</b>

Report was unsubmitted during this print-out.

80

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	80.00
2	TO REMOVE,REFIX REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE,REFIX REAR WINDSCREEN	New	180.00	120.00
4	TO RESPRAY UNDERCOATING	New	150.00	60.00
5	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	100.00	-
6	TO CHECK REAR ELECTRICAL WIRING	New	80.00	30.00
7	TO RESPRAY PAINTING & ETC	New	1,400.00	1,200.00
8	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	2,000.00	1,300.00
Gross Labour Cost (S\$)			<b>4,110.00</b>	<b>2,840.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >