

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0099/2018/PH  
**Date** : 24-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Verma Navin Kumar  
**Address** : BLK 248 Westwood Avenue  
#07 - 62  
Singapore 648353  
**Telephone** : HP +65 85058527  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100498727-00000  
**Vehicle No** : **SLK 6558 T**  
**Model Code** : Audi A3 Sedan 1.0 TFSI (A)  
**Model / Year** : Jan-17  
**Engine No** : CHZ 184936  
**Chassis No** : WAUZZZ8VXH1046584  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Allan Wu  
**Accident Date** : 20-Jan-18  
**Place of Accident** : Jurong Central Carpark Macdonald

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLK 6558 T.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid . Check function .	S/N \$ 280.00 ✕	
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal .	S/N \$ 600.00 ✕	
3	To dislodge and reinstall rear wire harness for lights , battery manager , fuse and relay trays , electrical and audio equipment .	S/N \$ 1,400.00 ✕	
4	To remove and reinstall rear seat,back rest , hat tray , abcd pillar trims , luggage compartment trims , seat belts . Dislodge roof liner and disengage curtain airbag etc .	S/N \$ 1,400.00 ✕	
5	To dismantle rear bumper and rear lid . Cut out and weld lhs rear fender . Repair lhs rear outer wheel house . Reinstall all parts removed .	\$ <del>4,800.00</del> 1250	
6	To respray lhs rear fender , lhs sill panel , door entrance , drain panel ,roof channel and end panelling . To carry out stone chip treatment and joint sealer works .	\$ <del>3,200.00</del> 1400	
7	To carry out wheel alignment	S/N \$ 240.00 ✕	
8	To carry out diagnostic checks.	S/N \$ 192.00 ✕.	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 12,112.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLK 6558 T

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR FENDER SECTIONAL PART - LEFT <i>Pyis</i>	\$ 2,006.00	X
2	REAR WHEEL HOUSING LINER - LEFT <i>Ken</i>	\$ 215.00	X
3	1 SET ATTACHMENT PARTS FOR WHEEL HOUSING I <i>Ken</i>	\$ 77.00	X
4	1/4 GLASS WINDOW - LH	\$ 502.00	X
5	REAR WINDSCREEN	\$ 704.00	X
6	PRIMER	2 \$ 37.00	X
7	GROMMET	6 \$ 47.00	X
8	SOUND ABSORBER	2 \$ 216.00	X
9	1/4 GLASS SEALANT	S/N \$ 100.00	X
10	REAR WINDSCREEN SEALANT	S/N \$ 200.00	X
11	AYCLIC SEALER	S/N \$ 180.00	X
12	CAVITY WAX	S/N \$ 140.00	X
13	STONE CHIP	S/N \$ 180.00	X
14	METAL FILLER POWDER	S/N \$ 280.00	X
TOTAL SPARE PARTS CHARGES		: \$ 4,884.00	
TOTAL LABOUR CHARGES		\$ 12,112.00	
GRAND TOTAL		<u>\$ 16,996.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Adrian

Surveyed Date

: 30/01/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 04 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant