

REF: CC3/ATh18001867/Aqbez

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100498975

Claims No. 920191000959

Sum Insured: _____ Excess: 600 01/2/18

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 140K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09/8/18 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJZ12127. Yr Regn: 2017 Sen.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan c.c 1395

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 30288 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF4XHA/06423

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17.

R: 225/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/4/18

Survey held at Premium.

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08 AUG.

SJZ12127 - CC3/ATh17003805/Aq3m2

DOA: 210217

31/1/18 @ 3.30pm revert to Victor via Arunmen.

31/1/18 @ 6.14pm Lois Chang informed C/A via Messenger.

01/2/18 @ 11.04am Informed Jeffrey C/A & ex: 600 by email.

10/4/18 @ 5.04pm Informed Hq & 20609.72, confirmed with Mr BOO by email.

(Had 57676.28, 27%)

RECEIVED 3 APR 2018

Date/Time. File Pass to?

☐

: Preli. Report

1) 16/4 typist

☐

: Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format :

USER-DD

Lump Sum / I.B.I. (\$) 20609.72

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001867/Aqb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 31-01-2018		
Code : AIG				
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SJZ 1212T	
Policy No. 2100498975	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 28/01/2018	Inspection Date		30/01/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 April 2018 5:01 PM
To: 'Boo seng yak'; SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION - SJZ1212T - OD AIG - SURVEYED 30 JAN 18

Dear Mr Boo,

Confirm final fig \$20,609.72 before excess \$600.00 & GST and 9 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 19 March 2018 7:49 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION - SJZ1212T - OD AIG - SURVEYED 30 JAN 18

Hi Adrian and all,

Revised estimate attached.

Please confirm repair cost of \$20,609.72 @ 9 days exclude 2 Sundays with lock carrier etc etc replacement.

Mr. Rasul resurveyed on 6 Feb 18.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	29 Jan 2018 13:24	Clim Veh Model Changed	Reg No: SJZ1212T. Policy No: 2100498975-01. Acct Date: 2018/01/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118013861	[I] Merimen Administrator	[I] Merimen Administrator
2	29 Jan 2018 13:24	Clim Created			
3	31 Jan 2018 11:31	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[I] CATHERINE CHONG KAI LING
4	31 Jan 2018 11:31	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[I] CATHERINE CHONG KAI LING
5	31 Jan 2018 11:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	31 Jan 2018 11:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/09		[A] CATHERINE CHONG KAI LING
7	31 Jan 2018 11:31	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	31 Jan 2018 11:31	Clim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
9	31 Jan 2018 11:31	Clim Veh Model Changed	(204567) AUDI A4 1.4 T (A).		[A] CATHERINE CHONG KAI LING
10	31 Jan 2018 11:31	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] CATHERINE CHONG KAI LING
11	31 Jan 2018 14:49	Adj Rpt Initiated			[A] SHIAU CHAN
12	31 Jan 2018 14:49	Clim Details Notified			[A] SHIAU CHAN
13	31 Jan 2018 15:29	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/09		[A] SHIAU CHAN
14	31 Jan 2018 15:30	Adj Mandate Request	Cur.Req:23285.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
15	31 Jan 2018 16:39	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.		[I] Loo, Tong Shing
16	31 Jan 2018 16:39	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
17	31 Jan 2018 18:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/09. Mandate Remarks: RE-inspection damage photo require on hidden parts and supplementary parts		[I] Chang, Lois-KL
18	31 Jan 2018 18:14	Adj Mandate Set	Approved:19896.00:RE-inspection damage photo require on hidden parts and supplementary partsReinsp:Yes.		[I] Chang, Lois-KL
19	03 Apr 2018 17:44	Adj Mandate Request	Cur.Req:20609.72:KINDLY APPROVE REPAIR COST OF \$20,609.72.		[A] SHIAU CHAN
20	09 Apr 2018 13:40	Adj Mandate Set	Approved:20609.72.Reinsp:Adj decides.		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1710867	31/01/2018 14:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJZ1212T		10.70

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 1 February 2018 11:04 AM
To: Claims Department; SUR
Subject: RE: SJZ 1212 T Own Damage Claims (Vehicle IN)

Dear Jeffrey,

As instructed by our client AIG , please proceed to repair the insured vehicle **SJZ 1212T(Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 31 January 2018 10:20 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: SJZ 1212 T Own Damage Claims (Vehicle IN)

Dear all,

Kindly update us on approval.

Thank you

Best Regards,
Claims Advisor

Kee Siang

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 m. +65 8777 0600

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Jan 2018 13:24	Clim Veh Model Changed		[] Merimen Administrator
2	29 Jan 2018 13:24	Clim Created	Reg No: SJZ1212T. Policy No: 2100498975-01. Acct Date: 2018/01/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118013861	[I] Merimen Administrator
3	31 Jan 2018 11:31	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	31 Jan 2018 11:31	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	31 Jan 2018 11:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	31 Jan 2018 11:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/09	[A] CATHERINE CHONG KAI LING
7	31 Jan 2018 11:31	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	31 Jan 2018 11:31	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	31 Jan 2018 11:31	Clim Veh Model Changed	(204567) AUDI A4 1.4 T (A).	[A] CATHERINE CHONG KAI LING
10	31 Jan 2018 11:31	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	31 Jan 2018 14:49	Adj Rpt Initiated		[A] SHIAU CHAN
12	31 Jan 2018 14:49	Clim Details Notified		[A] SHIAU CHAN
13	31 Jan 2018 15:29	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/09	[A] SHIAU CHAN
14	31 Jan 2018 15:30	Adj Mandate Request	Cur.Req:23285.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
15	31 Jan 2018 16:39	Clim Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
16	31 Jan 2018 16:39	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	31 Jan 2018 18:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/09. Mandate Remarks: RE-inspection damage photo require on hidden parts and supplementary parts	[I] Chang, Lois-KL
18	31 Jan 2018 18:14	Adj Mandate Set	Approved:19896.00:RE-inspection damage photo require on hidden parts and supplementary partsReinsp:Yes.	[I] Chang, Lois-KL

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1710867	31/01/2018 14:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJZ1212T		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 31 Jan 2018

Preliminary Advice

Vehicle No	: SJZ1212T	Accident Date	: 28/01/2018
Make	: AUDI A4	Policy No.	: 2100498975-01
Assignment Date	: 31/01/2018	Excess	: S\$0.00
Date of Inspection	: 30/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,286.00
Revised Amount	:S\$	19,896.00
Check Items (Estimated)	:S\$	3,389.00
Total	:S\$	23,285.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	67,754.00
Salvage Value	:S\$	
Margin for Repair	:S\$	72,246.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9268C

Vehicle Details

Vehicle No.: SJZ1212T

Vehicle to be Exported: No

Intended De-registration Date: 31 Jan 2018

Vehicle Make: AUDI

Vehicle Model: A4 1.4 TFSI S TRONIC

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: CVN029719

Chassis No.: WAUZZZF4XHA106423

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$32,244.00

Original Registration Date: 23 Jan 2017

First Registration Date: 23 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$27,142.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Jan 2027

PARF Rebate Amount: \$20,356.00

Intended COE Rebate Details

COE Expiry Date: 22 Jan 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$52,807.00

COE Rebate Amount: \$47,398.00

Total Rebate Amount: \$67,754.00

The information contained herein is correct as at 31 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 12:40
Date Of Accident	28/01/2018 10:45
Exact Location Of Accident	PIE TOWARDS TUAS - BEF EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ1212T
Insured/Policyholder	
Name Of Registered Owner	LEONG CHI MENG
NRIC No	S1679268C
Email Address	CHIMENG64@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96841569
Alternative Phone No	OTHERS-67869018

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100498975-01
Cover Note Number	

Driver

Name of Driver	LEONG CHI MENG
NRIC No	S1679268C
Date Of Birth	11/05/1964
Occupation	INDOOR
Date Of Driving Pass	16/10/1985
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96841569
Fax Number	
Contact Number	OTHERS-67869018
EEmail Address	CHIMENG64@GMAIL.COM

DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number	SHD6501R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	HONDA JAZZ / RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Travelling in Lane 2 on PIE towards Tuas at 1045am
 Noticed road works on Lane 1. Traffic was generally slower due to road works on Lane 1 and vehicles filtering from Lane 1 to Lane 2.
 Car (1) stopped suddenly causing the taxi to hit its rear, followed by the VW Golf. My car (Audi) could not stop in time and hit the VW Golf.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Chia Meng
 Policyholder's Signature

Date & Time: 27/1/2018
 11:50am

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature

Name: Lim Keng Seng
 NRIC/FIN No. 9695235G

Accident Photo



Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEONG CHI MENG
Period of Insurance : 23 Jan 2018 To 22 Jan 2019
Engine No. : CVN029719
Chassis No. : WAUZZZF4XHA106423

Vehicle No. : SJZ1212T
Policy No. : 2100498975-01
Endorsement No. :
Issued Date : 05 Jan 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEONG CHI MENG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125256

PREMIUM LEASING -LSYA
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNFY

REPUBLIC OF SINGAPORE DRIVING LICENCE



LEONG CHI MENG

Exp Date: 11 May 1999
Issue Date: 08 Sep 1994

000810537E

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1679268C



Name
LEONG CHI MENG

梁志明

Race
CHINESE

Date of Birth
11-05-1964

Country of Birth
SINGAPORE

Sex
男

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B	Motorcycles not exceeding 200 cc	31 Jul 1985
Class 2A	Motorcycles between 201 cc and 400 cc	31 Jul 1985
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Oct 1996

NP 428A

Licence No: S1679268C

1611255



NRIC No: S1679268C



Blood Group
AB+

Date of issue
22-01-1994

18 SENEI RISE #06-48
SINGAPORE 528808
NRIC No: S1679268C

Date: 11-09-2004 No: 4873757

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No :
Reference : PA/OD/0127/2018/GW
Date : 29-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Chi Meng
Address : 18 Simei Rise
#06-48
Singapore 5228808
Telephone : HP +65 96841569
Type of Claim : Own Damage Claims
Policy No. : 2100498975-01
Vehicle No : **SJZ 1212 T**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Jan-17
Engine No : CVN029719
Chassis No : WAUZZZF4XHA106423
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jan-18
Place of Accident : Pie Towards Tuas - BEF Eunox Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJZ 1212 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00	✓
3	To remove front fittings, dismantle front bumper, rhs front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper rhs front fender and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 3,600.00 7000 1750	(Excluding lock carrier)
4	To respray front bumper, lhs front fender and bonnet.	\$ 2,300.00 1650	
4	To carry out diagnostic check.	S/N \$ 196.00	✓
TOTAL LABOUR CHARGES		: \$ <u>7,656.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,849.00	✓ 1474.70
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 245.00	+
3	FRONT BUMPER GRILLE <i>distorted</i>	\$ 171.00	✓ 136.80
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 180.00	+
5	FRONT BUMPER AIR GUIDE GRILLE -RH <i>Dist.</i>	\$ 118.00	? 94 ✓
6	RADIATOR GRILLE <i>crushed</i>	\$ 972.00	✓ 777.20
7	FRONT BUMPER BUMPER CARRIER <i>Bent</i>	\$ 702.00	✓ 561.60
8	FOAM FILLER PIECE <i>crushed</i>	\$ 107.00	✓ 82.20
9	FRONT BUMPER LOCK CARRIER BRACKET <i>crushed</i>	\$ 118.00	✓ 94
10	FRONT BUMPER SUPPORT-LH/RH <i>Dist.</i>	2 \$ 48.00	? 35.24 ✓
11	FRONT BUMPER BRACKET-LH/RH <i>Dist.</i>	2 \$ 390.00	? 312 ✓
12	FRONT BUMPER COVER <i>distorted</i>	\$ 109.00	✓ 87.20
13	FRONT BUMPER GUIDE SECTION-LH/RH <i>new Dist.</i>	2 \$ 63.00	+ 75.36 ✓
14	FOAM FILLER PIECE LH/RH <i>RH Damaged new</i>	2 \$ 30.00 15.00	
15	HEADLIGHT WASHER LIFT CYLINDER -RH <i>crushed</i>	\$ 184.00	? 147.20 ✓
16	LOW NOTE HORN -RH <i>new</i>	\$ 254.00	? 1
17	SPRING SHACKLE-RH <i>new</i>	\$ 25.00	? 1
18	TUBING <i>new Dist.</i>	\$ 79.00	+ 62.86 ✓
19	BONNET <i>Distorted</i>	\$ 2,163.00	✓ 1730.40
20	BONNET LID HINGE -LH/RH <i>new</i>	\$ 532.00	X
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,339.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET HOOD BUMPER STOP BUFFER-LH/RH <i>new</i>	4 \$	27.00 ✓ 20.14
22	IMPACT PROTECTION <i>new</i>	3 \$	72.00 ✓ 56.64
23	BONNET STRIKER-LH/RH <i>RH best</i>	2 \$	88.00 44. ✓ 34.30
24	BONNET LID LOCK <i>RH & New New</i>	2 \$	376.00 ? 1
25	BONNET BOWDEN CABLE <i>new</i>	\$	50.00 +.
26	FRONT FENDER COVER -RH <i>new</i>	\$	53.00 ✓ 42.32
27	FRONT FENDER TOP COVER -RH <i>new</i>	\$	20.00 ✓ 15.36
28	LED HEADLIGHT-RH <i>new</i>	\$	6,973.00 ✓ 5,178.40
29	FRONT FENDER-RH <i>Bruckled</i>	\$	665.00 ✓ 532
30	FRONT FENDER CLOSING ELEMENT -RH <i>new</i>	\$	44.00 *
31	FRONT FENDER BRACKET-RH <i>new</i>	\$	31.00 *
32	FRONT FENDER BRACKET DEFORMATION ELEMENT-RH <i>new</i>	\$	43.00 *
33	FRONT FENDER RETAINER BRACKET -RH <i>new</i>	\$	27.00 *
34	FRONT FENDER UPPER BRACKET-RH <i>2 new</i>		TBC *
35	FRONT WHEEL HOUSING LINER -RH	\$	209.00 *
36	FRONT WHEEL SPOILER-RH <i>new</i>	3 \$	138.00 *
37	A/C CONDENSER WITH FLUID RESERVOIR <i>Derbed</i>	\$	540.00 ✓ 432
38	A/C SEAL RING <i>New New</i>	4 \$	15.00 ? 1
39	HIGH PRESSURE SWITCH <i>new</i>	\$	46.00 *
40	PRESSURE SENSOR <i>new</i>	\$	170.00 *
SUB-TOTAL SPARE PARTS CHARGES		:	\$ <u>9,587.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	COOLER FOR COLANT <i>Replaced</i>	\$ 585.00	X. 463 ✓
42	COOLANT CONCENTRATE <i>Replaced</i>	\$ 100.00	? 79.68 ✓
43	ADDITIONAL COOLER FOR COOLANT <i>Dented</i>	\$ 455.00	? 364 ✓
44	COOLANT RADIATOR LOCK CARRIER <i>Replaced</i>	\$ 891.00	? 712.80 ✓
45	COOLANT REGULATOR SUPPORT <i>Dented</i>	\$ 33.00	? 26.24 ✓
46	INTAKE AIR DUCT <i>Replaced</i>	2 \$ 49.00	- 38.80
47	RADIATOR AIR GUIDE <i>Replaced</i>	4 \$ 66.00	52.16
48	FRONT NO.PLATE <i>Dented</i>	S/N \$ 25.00	✓
48	SUNDRIES <i>Replaced</i>	\$ 500.00	? 93.72
TOTAL SPARE PARTS CHARGES		:	\$ 20,630.00
TOTAL LABOUR CHARGES			\$ 7,656.00
GRAND TOTAL			\$ 28,286.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian

Surveyed Date

:

30/01/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

revised proposal.

Supplementary Estimate

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0127/2018/GW 5-Feb-18 CHANG 1 of 1 SJZ 1212 T Audi A4 SEDAN 1.4 TFSI
--	---	---

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	OUTER TEMPERATURE SEN. BRACKET	\$ 16.00	<i>RM -</i>
2	RADIATOR RUBBER BUSH SET	\$ 46.00	<i>RM -</i>
TOTAL PARTS :		\$ 62.00	
GRAND TOTAL :		\$ 62.00	

[Signature]
06/02/18 P1230

For Premium Automobiles Pte Ltd

[Signature]
Authorised Signature



Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,849.00	—
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 245.00	+
3	FRONT BUMPER GRILLE <i>del</i>	\$ 171.00	—
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 180.00	+
5	FRONT BUMPER AIR GUIDE GRILLE -RH ?	\$ 118.00	? (R) —
6	RADIATOR GRILLE <i>could</i>	\$ 972.00	—
7	FRONT BUMPER BUMPER CARRIER <i>Best</i>	\$ 702.00	—
8	FOAM FILLER PIECE <i>could</i>	\$ 107.00	—
9	FRONT BUMPER LOCK CARRIER BRACKET <i>could</i>	\$ 118.00	—
10	FRONT BUMPER SUPPORT-LH/RH ?	2 \$ 48.00	? new /
11	FRONT BUMPER BRACKET-LH/RH ?	2 \$ 390.00	? R /
12	FRONT BUMPER COVER <i>del</i>	\$ 109.00	—
13	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 63.00	+ CR / 1 pc
14	FOAM FILLER PIECE LH/RH <i>RH changed</i>	2 \$ 30.00 15.	
15	HEADLIGHT WASHER LIFT CYLINDER -RH ?	\$ 184.00	? CR /
16	LOW NOTE HORN -RH ?	\$ 254.00	?
17	SPRING SHACKLE-RH ?	\$ 25.00	?
18	TUBING <i>new</i>	\$ 79.00	+ new /
19	BONNET <i>Dis</i>	\$ 2,163.00	—
20	BONNET LID HINGE -LH/RH <i>new</i>	\$ 532.00	X
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,339.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET HOOD BUMPER STOP BUFFER-LH/RH <i>new</i>	4 \$ 27.00	✓
22	IMPACT PROTECTION <i>new</i>	3 \$ 72.00	✓
23	BONNET STRIKER-LH/RH <i>RH bent</i>	2 \$ 88.00 44.	
24	BONNET LID LOCK <i>RH & ?</i>	2 \$ 376.00	?
25	BONNET BOWDEN CABLE <i>new</i>	\$ 50.00	+ B ✓
26	FRONT FENDER COVER -RH <i>new</i>	\$ 53.00	✓
27	FRONT FENDER TOP COVER -RH <i>new</i>	\$ 20.00	✓
28	LED HEADLIGHT-RH <i>new</i>	\$ 6,973.00	✓
29	FRONT FENDER-RH <i>Buckled</i>	\$ 665.00	✓
30	FRONT FENDER CLOSING ELEMENT -RH <i>new</i>	\$ 44.00	✗
31	FRONT FENDER BRACKET-RH <i>new</i>	\$ 31.00	✗
32	FRONT FENDER BRACKET DEFORMATION ELEMENT-RH <i>new</i>	\$ 43.00	✗
33	FRONT FENDER RETAINER BRACKET -RH <i>new</i>	\$ 27.00	✗
34	FRONT FENDER UPPER BRACKET-RH <i>new</i>	TBC	✗
35	FRONT WHEEL HOUSING LINER -RH	\$ 209.00	✗
36	FRONT WHEEL SPOILER-RH <i>new</i>	3 \$ 138.00	✗
37	A/C CONDENSER WITH FLUID RESERVOIR <i>new</i>	\$ 540.00	✓
38	A/C SEAL RING	4 \$ 15.00	?
39	HIGH PRESSURE SWITCH <i>new</i>	\$ 46.00	✗
40	PRESSURE SENSOR <i>new</i>	\$ 170.00	✗
SUB-TOTAL SPARE PARTS CHARGES		\$ 9,587.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	COOLER FOR COLANT <i>New</i>	\$ 585.00	X. <i>PA</i> ✓
42	COOLANT CONCENTRATE ?	\$ 100.00	?
43	ADDITIONAL COOLER FOR COOLANT ?	\$ 455.00	? <i>PA</i> ✓
44	COOLANT RADIATOR LOCK CARRIER ?	\$ 891.00	? <i>CR</i> ✓
45	COOLANT REGULATOR SUPPORT ?	\$ 33.00	?
46	INTAKE AIR DUCT <i>Rehd</i>	2 \$ 49.00	✓
47	RADIATOR AIR GUIDE <i>Rehd</i>	4 \$ 66.00	
48	FRONT NO.PLATE <i>Rehd</i>	S/N \$ 25.00	✓
48	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 20,630.00	
TOTAL LABOUR CHARGES		\$ 7,656.00	
GRAND TOTAL		\$ 28,286.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No :
Reference : PA/OD/0127/2018/GW
Date : 29-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Leong Chi Meng
Address : 18 Simei Rise
#06-48
Singapore 5228808
Telephone : HP +65 96841569
Type of Claim : Own Damage Claims
Policy No. : 2100498975-01
Vehicle No : **SJZ 1212 T**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Jan-17
Engine No : CVN029719
Chassis No : WAUZZZF4XHA106423
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Jan-18
Place of Accident : Pie Towards Tuas - BEF Eunox Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJZ 1212 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00	\$ 1,200.00
3	To remove front fittings, dismantle front bumper, rhs front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper rhs front fender and bonnet. Re-organise front crash management components. Reinstall all parts removed .	\$ 3,600.00	\$ 3,000.00
	(Lock carrier replaced)		
4	To respray front bumper, lhs front fender and bonnet.	\$ 2,300.00	\$ 1,650.00
4	To carry out diagnostic check.	S/N \$ 196.00	\$ 196.00
TOTAL LABOUR CHARGES		: \$ 7,656.00	\$ 6,406.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONNT BUMPER GRILLE	\$ 171.00	\$ 136.80
4	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	
5	FRONT BUMPER AIR GUIDE GRILLE -RH	\$ 118.00	\$ 94.00
6	RADIATOR GRILLE	\$ 972.00	\$ 777.20
7	FRONT BUMPER BUMPER CARRIER	\$ 702.00	\$ 561.60
8	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
9	FRONT BUMPER LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
10	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	\$ 38.24
11	FRONT BUMPER BRACKET-LH/RH	2 \$ 390.00	\$ 312.00
12	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
13	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$ 63.00	\$ 25.36
14	FOAM FILLER PIECE LH/RH	2 \$ 30.00	
15	HEADLIGHT WASHER LIFT CYLINDER -RH	\$ 184.00	\$ 147.20
16	LOW NOTE HORN -RH	\$ 254.00	
17	SPRING SHACKLE-RH	\$ 25.00	
18	TUBING	\$ 79.00	\$ 62.56
19	BONENT	\$ 2,163.00	\$ 1,730.40
20	BONNET LID HINGE -LH/RH	\$ 532.00	
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,339.00	\$ 5,630.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 5,630.96
21	BONNET HOOD BUMPER STOP BUFFER-LH/RH	4 \$	27.00	\$ 20.64
22	IMPACT PROTECTION	3 \$	72.00	\$ 56.64
23	BONNET STRIKER-LH/RH	2 \$	88.00	\$ 34.80
24	BONNET LID LOCK	2 \$	376.00	
25	BONNET BOWDEN CABLE	\$	50.00	
26	FRONT FENDER COVER -RH	\$	53.00	\$ 42.32
27	FRONT FENDER TOP COVER -RH	\$	20.00	\$ 15.36
28	LED HEADLIGHT-RH	\$	6,973.00	\$ 5,578.40
29	FRONT FENDER-RH	\$	665.00	\$ 532.00
30	FRONT FENDER CLOSING ELEMENT -RH	\$	44.00	
31	FRONT FENDER BRACKET-RH	\$	31.00	
32	FRONT FENDER BRACKET DEFORMATION ELEMENT-RH	\$	43.00	
33	FRONT FENDER RETAINER BRACKET -RH	\$	27.00	
34	FRONT FENDER UPPER BRACKET-RH		TBC	
35	FRONT WHEEL HOUSING LINER -RH	\$	209.00	
36	FRONT WHEEL SPOILER-RH	3 \$	138.00	
37	A/C CONDENSER WITH FLUID RESERVOIR	\$	540.00	\$ 432.00
38	A/C SEAL RING	4 \$	15.00	
39	HIGH PRESSURE SWITCH	\$	46.00	
40	PRESSURE SENSOR	\$	170.00	
SUB-TOTAL SPARE PARTS CHARGES			\$ 9,587.00	\$ 12,343.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJZ 1212 T.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		c/f		\$ 12,343.12
41	COOLER FOR COLANT		\$ 585.00	\$ 468.00
42	COOLANT CONCENTRATE		\$ 100.00	\$ 79.68
43	ADDITIONAL COOLER FOR COOLANT		\$ 455.00	\$ 364.00
44	COOLANT RADIATOR LOCK CARRIER		\$ 891.00	\$ 712.80
45	COOLANT REGULATOR SUPPORT		\$ 33.00	\$ 26.24
46	INTAKE AIR DUCT	2	\$ 49.00	\$ 38.80
47	RADIATOR AIR GUIDE	4	\$ 66.00	\$ 52.16
48	FRONT NO.PLATE	S/N	\$ 25.00	\$ 25.00
48	SUNDRIES		\$ 500.00	\$ 93.92
TOTAL SPARE PARTS CHARGES		:	\$ 20,630.00	\$ 14,203.72
TOTAL LABOUR CHARGES			\$ 7,656.00	\$ 6,406.00
GRAND TOTAL			\$ 28,286.00	\$ 20,609.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0127/2018/GW 5-Feb-18 CHANG 1 of 1 SJZ 1212 T Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	OUTER TEMPERATURE SEN. BRACKET	\$ 16.00	
2	RADIATOR RUBBER BUSH SET	\$ 46.00	
	TOTAL PARTS :	\$ 62.00	
	GRAND TOTAL :	\$ 62.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJZ 1212 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0127/2018/MAS

14 April 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SJZ 1212 T, Audi A4 Sedan 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SJZ 1212 T**, claimant, **Mr. Leong Chi Meng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012348 – S\$21,410.40
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJZ 1212 T



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 1 13:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408619
Telephone 6388 1183
Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012348 Date : 13/04/2018 Order : SJZ1212T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJZ1212T (V 32735) Regn Date: 23/01/2017 Mileage: 32034 WIP No.: 53973
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA106423 Engine: CVN 029719 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UN TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOL SYSTEM.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE FRONT FITTINGS, DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARR AND ALIGN TO POSITION. RENEW FRONT BUMPER, RHS FRO FENDER AND BONNET. RE-ORGANISE FRONT CRASH MANAGEM	3000.00	1.00	3,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733
Page 2 13:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408649
Telephone 6388 2223
Telefax 6841 1183

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012348 Date : 13/04/2018 Order : SJZ1212T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJZ1212T (V 32735) Regn Date: 23/01/2017 Mileage: 32034 WIP No.: 53973
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA106423 Engine: CVN 029719 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	COMPONENTS. REINSTALL ALL PARTS REMOVED. M:	1650.00	1.00	1,650.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONN M:	196.00	1.00	196.00
		TO CARRY OUT DIAGNOSTIC CHECK.			
X	AG A13A8JM1	COOLANT ADDITIVE	3.00	33.20	79.60
X	A8W0853651 3FZ	GRILLE	1.00	971.50	777.20
X	A8W0941774A	HEADLIGHT	1.00	6973.00	5,578.40
X	A8W0821106A	FENDER	1.00	665.00	532.00
X	A8W0807081	COVER	1.00	109.00	87.20
X	A8W0121251K	RADIATOR	1.00	585.00	460.00
X	A8W0145804A	RADIATOR	1.00	455.00	364.00
X	A8W0816421H	CONDENSER	1.00	540.00	432.00
X	A8W0805594	CARRIER	1.00	891.00	712.80
X	A8W0807550A	FOAM INSER	1.00	106.50	85.20
X	A8W0807113	BRACKET	1.00	702.00	561.60
X	A8W0823029A	HOOD	1.00	2163.00	1,730.40
X	A8W0807065C GRU	COVER	1.00	1849.00	1,479.20
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2323
Main Telefax 6471 3733
Page 3 13:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408649
Telephone 6388 2223
Telefax 6441 1183

Customer Service
Service Appointment
24-hour Breakdown Service
6366 2323
9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012348 Date : 13/04/2018 Order : SJZ1212T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJZ1212T (V 32735) Regn Date: 23/01/2017 Mileage: 32034 WIP No.: 53973
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA106423 Engine: CVN 029719 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details		Qty	Unit Price	Amount
X	A8W0823746	COVER	Less 020%	1.00	19.20	15.36
X	A4M0121275A	MOUNTING	Less 020%	2.00	7.80	12.48
X	A4M0121268A	MOUNTING	Less 020%	2.00	10.90	17.44
X	A8W0129617A	AIR DUCT	Less 020%	1.00	17.70	14.16
X	A8W0807334	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0807333	SUPPORT	Less 020%	1.00	23.90	19.12
X	A8W0805201	MOUNTING	Less 020%	1.00	32.80	26.24
X	A8W0807284	GUIDE	Less 020%	1.00	31.70	25.36
X	A8W0823106D	CATCH (V)	Less 020%	1.00	43.50	34.80
X	A8W0807134	BRACKET	Less 020%	1.00	195.00	156.00
X	A8W0807133	BRACKET	Less 020%	1.00	195.00	156.00
X	A8W0129618	AIR DUCT	Less 020%	1.00	30.80	24.64
X	A4M0121095	BOLT(V)	Less 020%	2.00	2.20	3.52
X	A8W0121673A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0121674A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	A8W0820536	BRACKET	Less 020%	1.00	15.60	12.48
X	A8W0823125	PROTECTION	Less 020%	1.00	23.60	18.88
X	A8W0823126	PROTECTION	Less 020%	1.00	23.60	18.88

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 4 13:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408693
Telephone 6388 2223
Telefax 6841 1183

Customer Service
Service Appointment
24-hour Breakdown Service
6366 2323
9828 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012348 Date : 13/04/2018 Order : SJZ1212T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJZ1212T (V 32735) Regn Date: 23/01/2017 Mileage: 32034 WIP No.: 53973
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA106423 Engine: CVN 029719 Dept: U
USB No.:
You have been assisted by :- UB-Carrine (33)

		Details		Qty	Unit Price	Amount
X	A4E0260749A	WASHER	Less 020%	2.00	3.20	5.12
X	A3D0260749C	WASHER	Less 020%	2.00	3.00	6.00
X	A8T0823433B	BUMPER (V)	Less 020%	2.00	8.30	13.28
X	A8P0823433B	BUMPER (V)	Less 020%	2.00	4.60	7.36
X	A8K0805399B	BOLT	Less 020%	2.00	1.50	2.40
X	A8W0807682B 989	GRILLE	Less 020%	1.00	117.50	94.00
X	A8W0821170C	COVER	Less 020%	1.00	52.90	42.32
X	A8W0807683 989	GRILLE	Less 020%	1.00	171.00	136.80
X	A8W0955970A	TUBING	Less 020%	1.00	78.20	62.56
X	A8W0955775	BRACKET	Less 020%	1.00	5.10	4.08
X	A8W0955102A	CYLINDER	Less 020%	1.00	184.00	147.20
X	A8W0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	A8K0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	A8W0121283AR	AIR DUCT	Less 020%	1.00	23.00	18.40
X	A8W0121284AL	AIR DUCT	Less 020%	1.00	23.00	18.40
X	A8W0807771	BRACKET	Less 020%	1.00	117.50	94.00
X	AN 0161857	POP-RIVET	Less 020%	6.00	2.90	13.92
X	AN 91093901	RIVET	Less 020%	4.00	0.70	2.24

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 5 13:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408649
Telephone 6388 2223
Telefax 6841 1183
INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012348 Date : 13/04/2018 Order : SJZ1212T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJZ1212T (V 32735) Regn Date: 23/01/2017 Mileage: 32034 WIP No.: 53973
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA106423 Engine: CVN 029719 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	A0W0023124	PROTECTION Less 020%	1.00	23.60	18.88

Parts 14,178.72
Labour 0.00
Sublet 6,431.00
Menus 0.00
Lubricant 0.00

Sub-Total 20,009.72
7% GST 1,400.68
Grand Total 21,410.40



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJZ 1212 T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0127/2018/GW
13 February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF4XHA106423
Vehicle Regn No. : **SJZ 1212 T**
Vehicle Mileage : 80267 KM
Vehicle Owner : Mr. Leong Chi Meng
Certificate No : 2100498975-01
Policy Excess : **S\$642.00** (inclusive 7% GST)
Accident Date : 28 January 2018
Place : Pie Towards Tuas - BEF Eunus Exit
Repair Cost : \$ 21,410.40
WIP No. : **53973**
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

13/02/2018

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Identification Number: **S1679268C**

LEONG CHI MENG

Birth Date: **11 May 1964**
Issue Date: **08 Sep 2004**

000810537E

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1679268C**

Name: **LEONG CHI MENG**

梁志明

Race: **CHINESE**
Date of Birth: **11-05-1964** Sex: **M**
Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	31 Jul 1985
Class 2A	Motorcycles between 201 cc and 400 cc	31 Jul 1985
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Oct 1985

NP 428A



18 SIMEI RISE #06-48
SINGAPORE 528808
NRIC No: S1679268C



NRIC No: **S1679268C**

Blood Group: **AB+** Date of Issue: **22-01-1994**

Date: **11-09-2004** No: **4972757**

1611255



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LEONG CHI MENG
Period of Insurance : 23 Jan 2018 To 22 Jan 2019
Engine No. : CVN029719
Chassis No. : WAUZZZF4XHA106423

Vehicle No. : SJZ1212T
Policy No. : 2100498975-01
Endorsement No. :
Issued Date : 05 Jan 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEONG CHI MENG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125256

PREMIUM LEASING -LSYA

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNFY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	31 Jan 2018 14:49		31 Jan 2018 11:31 Edit Adj Rpt	S\$20,609.72 Edit Estimates	S\$20,609.72 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:

LEONG CHI MENG, ID: S1679268C, Tel: +6596841569, Email: CHIMENG64@GMAIL.COM

Vehicle Reg. No.:

SJZ1212T

Claim Type:

OD / 9201910009SG

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/02/2018]

Driver/Custodian:

LEONG CHI MENG (53 / Male), NRIC: S1679268C, Tel: +6596841569

[Created by insurer]

Date of Loss:

28/01/2018 10:00 - :59
[12 Months and 5 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

2100498975 (Comprehensive)

Excess:

S\$600.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (09/04/2018): Alert - Adj Mandate Approved (S\$20609.72) - SJZ1212T - Claim Handler: Loo, Tong ...
- AIG_SG (31/01/2018): Alert - Adj Mandate Approved (S\$19896.00) - SJZ1212T - Claim Handler: Loo, Tong ...
- AIG_SG (31/01/2018): SJZ1212T / OD / 28/01/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ1212T (9201910009SG)

OD

Jan 28 2018 10:00AM

[LEONG CHI MENG]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail
1	31/01/18 15:29	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail
1	31/01/18 14:47	General View		Load JPG ☒
2	31/01/18 14:47	Chassis Number		Load JPG ☒
3	31/01/18 14:47	General View		Load JPG ☒
4	31/01/18 14:47	General View		Load JPG ☒
5	31/01/18 14:47	General View		Load JPG ☒
6	31/01/18 14:47	General View		Load JPG ☒
7	31/01/18 14:47	General View		Load JPG ☒
8	31/01/18 14:47	General View		Load JPG ☒
9	31/01/18 14:47	General View		Load JPG ☒
10	31/01/18 14:47	General View		Load JPG ☒
11	31/01/18 14:47	General View		Load JPG ☒
12	31/01/18 14:47	General View		Load JPG ☒
13	31/01/18 14:47	General View		Load JPG ☒
14	31/01/18 14:47	General View		Load JPG ☒
15	31/01/18 14:47	General View		Load JPG ☒
16	31/01/18 14:47	General View		Load JPG ☒
17	31/01/18 14:47	General View		Load JPG ☒
18	31/01/18 14:47	General View		Load JPG ☒
19	31/01/18 14:47	General View		Load JPG ☒
20	31/01/18 14:47	General View		Load JPG ☒
21	31/01/18 14:47	General View		Load JPG ☒
22	31/01/18 14:47	General View		Load JPG ☒
23	31/01/18 14:47	General View		Load JPG ☒
24	31/01/18 14:47	General View		Load JPG ☒
25	31/01/18 14:47	General View		Load JPG ☒
26	31/01/18 14:47	General View		Load JPG ☒
27	31/01/18 14:47	General View		Load JPG ☒
28	31/01/18 14:47	General View		Load JPG ☒
29	31/01/18 14:47	General View		Load JPG ☒
30	31/01/18 14:47	General View		Load JPG ☒
31	31/01/18 14:47	General View		Load JPG ☒
32	31/01/18 14:47	General View		Load JPG ☒
33	31/01/18 14:47	General View		Load JPG ☒
34	31/01/18 14:47	General View		Load JPG ☒
35	31/01/18 14:47	General View		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	31/01/18 14:47	General View		Load JPG ☒
37	31/01/18 14:47	General View		Load JPG ☒
38	31/01/18 14:47	General View		Load JPG ☒
39	31/01/18 14:47	General View		Load JPG ☒
40	20/03/18 18:49	Reinspection Photo		Load JPG ☒
41	20/03/18 18:49	Reinspection Photo		Load JPG ☒
42	20/03/18 18:49	Reinspection Photo		Load JPG ☒
43	20/03/18 18:49	Reinspection Photo		Load JPG ☒
44	20/03/18 18:49	Reinspection Photo		Load JPG ☒
45	20/03/18 18:49	Reinspection Photo		Load JPG ☒
46	20/03/18 18:49	Reinspection Photo		Load JPG ☒
47	20/03/18 18:49	Reinspection Photo		Load JPG ☒
48	20/03/18 18:49	Reinspection Photo		Load JPG ☒
49	20/03/18 18:49	Reinspection Photo		Load JPG ☒
50	20/03/18 18:49	Reinspection Photo		Load JPG ☒
51	20/03/18 18:49	Reinspection Photo		Load JPG ☒
52	20/03/18 18:49	Reinspection Photo		Load JPG ☒
53	20/03/18 18:49	Reinspection Photo		Load JPG ☒
54	20/03/18 18:49	Reinspection Photo		Load JPG ☒
55	20/03/18 18:49	Reinspection Photo		Load JPG ☒
56	20/03/18 18:49	Reinspection Photo		Load JPG ☒
57	20/03/18 18:49	Reinspection Photo		Load JPG ☒
58	20/03/18 18:49	Reinspection Photo		Load JPG ☒
59	20/03/18 18:49	Reinspection Photo		Load JPG ☒
60	20/03/18 18:49	Reinspection Photo		Load JPG ☒
61	20/03/18 18:49	Reinspection Photo		Load JPG ☒
62	20/03/18 18:49	Reinspection Photo		Load JPG ☒
63	20/03/18 18:49	Reinspection Photo		Load JPG ☒
64	20/03/18 18:49	Reinspection Photo		Load JPG ☒
65	20/03/18 18:49	Reinspection Photo		Load JPG ☒
66	20/03/18 18:49	Reinspection Photo		Load JPG ☒
67	20/03/18 18:49	Reinspection Photo		Load JPG ☒
68	20/03/18 18:49	Reinspection Photo		Load JPG ☒
69	20/03/18 18:49	Reinspection Photo		Load JPG ☒
70	20/03/18 18:49	Reinspection Photo		Load JPG ☒
71	20/03/18 18:49	Reinspection Photo		Load JPG ☒
72	20/03/18 18:49	Reinspection Photo		Load JPG ☒
73	20/03/18 18:49	Reinspection Photo		Load JPG ☒
74	20/03/18 18:49	Reinspection Photo		Load JPG ☒
75	20/03/18 18:49	Reinspection Photo		Load JPG ☒
76	20/03/18 18:49	Reinspection Photo		Load JPG ☒
77	20/03/18 18:49	Reinspection Photo		Load JPG ☒
78	20/03/18 18:49	Reinspection Photo		Load JPG ☒
79	20/03/18 18:49	Reinspection Photo		Load JPG ☒
80	20/03/18 18:49	Reinspection Photo		Load JPG ☒
81	20/03/18 18:49	Reinspection Photo		Load JPG ☒
82	20/03/18 18:49	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 14:47	Singapore Accident Statement	Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	31/01/18 14:47	Certificate of Insurance	Load PDF	
3	31/01/18 14:47	Driver's Driving License	Load PDF	
4	31/01/18 14:47	WORKSHOP ESTIMATE	Load PDF	
5	03/04/18 17:43	REVISED ESTIMATE	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/01/18 13:24	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/01/18 13:11	Accident Photo	Load JPG	☒
2	29/01/18 13:11	Accident Photo	Load JPG	☒
3	29/01/18 13:11	Accident Photo	Load JPG	☒
4	29/01/18 13:11	Accident Photo	Load JPG	☒
5	29/01/18 13:11	Accident Photo	Load JPG	☒
6	29/01/18 13:11	Accident Photo	Load JPG	☒
7	29/01/18 13:11	Accident Photo	Load JPG	☒
8	29/01/18 13:11	Accident Photo	Load JPG	☒
9	29/01/18 13:11	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/01/18 12:56	Sketch Plan	Load JPG	☒
2	29/01/18 12:56	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001867/AQBE2

Date: 17/04/2018

REFERENCE

Insured/Claimant: LEONG CHI MENG Policy No: 2100498975
Date of Loss: 28/01/2018 Nature of Claim: OD Claim No: 9201910009SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ1212T**
Make & Model: AUDI A4, 1.4 T (A) Engine No: CVN029719
Reg. Date: 23/01/2017 (Man. Year: 2016) Chassis No: WAUZZZF4XHA106423
Colour: Blue Odometer: 30288 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,630.00	14,203.72	6,426.28	31.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,656.00	6,406.00	1,250.00	16.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,286.00	20,609.72	7,676.28	27.14
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	27,686.00	20,009.72	7,676.28	27.73
+ GST 7.00/7.00% (S\$)	1,938.02	1,400.68	537.34	27.73
Nett Amount (S\$)	29,624.02	21,410.40	8,213.62	27.73

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 30/01/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Deformed	171.00 FS	*136.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Damaged	118.00 FS	*94.00 FS
6	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
7	1		*FRONT BUMPER CARRIER	Bent	702.00 FS	*561.60 FS
8	1		*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
9	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
10	2		*FRONT BUMPER SUPPORT - LH/RH	Damaged	48.00 FS	*38.24 FS
11	2		*FRONT BUMPER BRACKET - LH/RH	Damaged	390.00 FS	*312.00 FS
12	1		*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
13	1		*FRONT BUMPER GUIDE SECTION - LH/RH	O/S Damaged	63.00 FS	*25.36 FS
14	2		*FOAM FILLER PIECE LH/RH	Not Necessary	30.00 FS	*- FS
15	1		*HEADLIGHT WASHER LIFT CYLINDER - RH	Cracked	184.00 FS	*147.20 FS
16	1		*LOW NOTE HORN - RH	Not Necessary	254.00 FS	*- FS
17	1		*SPRING SHACKLE - RH	Not Necessary	25.00 FS	*- FS
18	1		*TUBING	Damaged	79.00 FS	*62.56 FS
19	1		*BONNET	Distorted	2,163.00 FS	*1,730.40 FS
20	1		*BONNET LID HINGE - LH/RH	Not Necessary	532.00 FS	*- FS
21	4		*BONNET HOOD BUMPER STOP BUFFER - LH/RH	Necessary	27.00 FS	*20.64 FS
22	3		*IMPACT PROTECTION	Necessary	72.00 FS	*56.64 FS
23	1		*BONNET STRIKER - LH/RH	O/S Bent	88.00 FS	*34.80 FS
24	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
25	1		*BONNET BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
26	1		*FRONT FENDER COVER - RH	Necessary	53.00 FS	*42.32 FS
27	1		*FRONT FENDER TOP COVER - RH	Necessary	20.00 FS	*15.36 FS
28	1		*LED HEADLIGHT - RH	Cracked	6,973.00 FS	*5,578.40 FS
29	1		*FRONT FENDER - RH	Buckled	665.00 FS	*532.00 FS
30	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	44.00 FS	*- FS
31	1		*FRONT FENDER BRACKET - RH	Not Necessary	31.00 FS	*- FS
32	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - RH	Not Necessary	43.00 FS	*- FS
33	1		*FRONT FENDER RETAINER BRACKET - RH	Not Necessary	27.00 FS	*- FS
34	1		*FRONT FENDER UPPER BRACKET - RH (NPA)	Not Necessary	0.00 FS	*- FS
35	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	209.00 FS	*- FS
36	3		*FRONT WHEEL SPOILER - RH		138.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
37	1		*A/C CONDENSER WITH FLUID RESERVOIR	Dented	540.00 FS	*432.00 FS
38	4		*A/C SEAL RING	Not Necessary	15.00 FS	*- FS
39	1		*HIGH PRESSURE SWITCH	Not Necessary	46.00 FS	*- FS
40	1		*PRESSURE SENSOR	Not Necessary	170.00 FS	*- FS
41	1		*COOLER FOR COOLANT	Dented	585.00 FS	*468.00 FS
42	1		*COOLANT CONCENTRATE	Necessary	100.00 FS	*79.68 FS
43	1		*ADDITIONAL COOLER FOR COOLANT	Dented	455.00 FS	*364.00 FS
44	1		*COOLANT RADIATOR LOCK CARRIER	Deformed	891.00 FS	*712.80 FS
45	1		*COOLANT REGULATOR SUPPORT	Damaged	33.00 FS	*26.24 FS
46	2		*INTAKE AIR DUCT	Deformed	49.00 FS	*38.80 FS
47	4		*RADIATOR AIR GUIDE	Deformed	66.00 FS	*52.16 FS
48	1		*FRONT NO. PLATE	Dented	25.00 FS	*25.00 FS
49	1		*SUNDRIES	Necessary	500.00 FS	*93.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	20,630.00	14,203.72
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO REMOVE FRONT FITTINGS, DISMANTLE FRONT BUMPER, RHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER RHS FRONT FENDER AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	3,000.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,300.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	196.00	196.00
Gross Labour Cost (\$\$)			7,656.00	6,406.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >