

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0126/2018/GW
Date	:	29-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Low Swee Hee (Liu Ruixi)
Address	:	APT BLK 488 Admiralty Link #17-127 Singapore 750488
Telephone	:	HP +65 98789885
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	<b>SKW 7775 A</b>
Model Code	:	Audi A3 Sedan 1.0 TFSI S
Model / Year	:	Jan-18
Engine No	:	CHZ2593829
Chassis No	:	WAUZZZ8V0J1028066
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Jan-18
Place of Accident	:	Admiralty Link

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKW 7775 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs rr door's multi-lock system and power window devices.	S/N \$ 280.00 ✓	
2	To remove and renew rhs rear door, transfer old fittings to new door and position. Reshape rhs rear fender. Reinstall all parts removed.	\$ <del>1,200.00</del> 500	
3	To rep-spray rhs rear door and rear fender.	\$ <del>2,000.00</del> 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 3,672.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKW 7775 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR DOOR-RH <i>dent</i>	\$ 2,190.00	✓
2	REAR OUTER DOOR SEAL-RH <i>h</i>	\$ 139.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	REAR DOOR SEAL-RH <i>h h</i>	\$ 165.00	✓
6	SUNDRIES <i>?</i>	\$ 120.00	?
TOTAL SPARE PARTS CHARGES		\$ 2,721.00	
TOTAL LABOUR CHARGES		\$ 3,672.00	
GRAND TOTAL		\$ 6,393.00	

All charges are not inclusive of GST.


Legend :      Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian   
Surveyed Date : 30/01/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Authorised Repairs, OK Pays.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant