

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0116/2018/GW
Date : 27-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Gan Fong Yin
Address : 97 Hazel Park Terrace
Singapore 678930
Telephone : (HP)97459128
Type of Claim : Own Damage Claims
Policy No. : 1700056950
Vehicle No : **SDN 7518 G**
Model Code : Q5 Sport 2.0 TFSI qu
Model / Year : Sep-17
Engine No : DAX 012329
Chassis No : WAUZZZFYPXH2045653
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jan-18
Place of Accident : Junc Of Choa Chu Kang Rd & Woodlands Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDN 7518 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy. Front parking aid assy.	S/N \$ 480.00	✓
2	To remove front fittings, remove and reinstall front bumper. Renew radiator grille, re-organise frontal crash management components. Reinstall all parts removed. Renew both wheel arc trim.	\$ 1,200.00	SOD ✓
3	To respray front bumper, lower spoiler, lhs front fender, both arc trim.	\$ 2,250.00	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,122.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>reformed</i>	\$ 2,248.00	✓ 1798
2	FRONT BUMPER SPOILER <i>reformed</i>	\$ 652.00	✓ 521.60
3	FRONT BUMPER UNDERRUN BAR <i>reformed</i>	\$ 407.00	✓ 325.20
4	FRONT BUMPER CLOSING ELEMENT <i>reformed</i>	\$ 147.00	✓ 117.60
5	RADIATOR GRILLE <i>reformed</i>	\$ 3,101.00	✓ 2480.80
6	INSCRIPTION " QUATTRO " <i>re</i>	\$ 83.00	✓ 66.16
7	FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>LN 2nd</i>	2 \$ 996.00	498.398.40
8	FRONT BUMPER OUTER GRILLE CLIP <i>Not Nec</i>	4 \$ 14.00	? X
9	FRONT BUMPER COVER CAP- LH/RH <i>Not Nec</i>	\$ 74.00	? X
10	FRONT BUMPER SENSOR <i>re</i>	2 \$ 422.00	X
11	FRONT BUMPER SENSOR SEAL RING <i>re</i>	4 \$ 15.00	X
12	HEADLIGHT WASHER LIFT CYLINDER - LH <i>re</i>	\$ 123.00	X
13	HEADLIGHT WASHER LIFT CYLINDER - RH <i>re</i>	\$ 123.00	X
14	HEADLIGHT WASHER PIPE HOSE <i>re</i>	\$ 106.00	X
15	LED HEADLIGHT-LH <i>Not Nec</i>	\$ 7,112.00	? X
16	FOAM FILLER PIECE <i>reformed</i>	\$ 244.00	✓ 15.00
17	FRONT BUMPER CARRIER <i>Best</i>	\$ 786.00	? 628.80
18	FRONT BUMPER TOP COVER <i>re</i>	\$ 109.00	X
SUB - TOTAL SPARE PARTS		\$ 16,762.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
19	LED HEADLIGHT MOUNTING <i>cracked.</i>	\$ 103.00	? 82.40
20	LED HEADLIGHT BRACKET <i>Not New</i>	\$ 218.00	? X
21	FRONT WHEEL COVER - LH/RH <i>new</i>	2 \$ 1,090.00	✓ 872
22	FRONT NO. PLATE <i>Bent.</i>	S/N \$ 25.00	✓ 25
23	SUNDRIES <i>New.</i>	\$ 300.00	? 37.44
TOTAL SPARE PARTS		:	\$ 18,498.00
TOTAL LABOUR CHARGES		:	\$ 4,122.00
GRANDTOTAL		:	\$ 22,620.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

29.265

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lij

Surveyed Date

: 30/01/18.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 03 Pays.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant