

REF:

CC3 / ALG 18001869 / A/bn2

ASSIGNMENT

SDN 7518 G.

SDN 7518 G.

Yr Regn: 2017 / Sept

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1700056950

Claims No.

Sum Insured:

Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

190K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8/5/7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5

C.C. 1984

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

9518

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZFYXH2045653.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19.

R:

235/55R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

x6/1/18

D.O.I.

80/01/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG.

SDN 7518 G - CC3 / ALG 18001720 / A/b3

DIA: 26012018

31/1/18

Revert by merimen

31/1/18

Rec approved \$9923 from Chang Lois- KL

1/2/18

Informed Jeffery CIA ex \$500 by email

9/5/18

Final fig \$14,708.92 (Rec 14,556.08, 50%) confirmed by email

RECEIVED 20 APR 2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

25/5 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

14,708.92

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inv (\$



: Weekend (\$

) \$ - RS: \$

) Photos

) Others

TOTAL

200

10

210

Survey Department Check List (Case Handler)

Reference No. : CC3 / A14 / 800 / 869 / Avb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 9/5/14
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001869/Avb		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 31-01-2018		
		Code : AIG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SDN 7518G	
Policy No. 1700056950	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 26/01/2018	Inspection Date		30/01/2018	
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 31 Jan 2018

Preliminary Advice

Vehicle No	: SDN7518G	Accident Date	: 26/01/2018
Make	: AUDI Q5	Policy No.	: 1700056950
Assignment Date	: 31/01/2018	Excess	: S\$0.00
Date of Inspection	: 30/01/2018	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,620.00
Revised Amount	:S\$	9,923.00
Check Items (Estimated)	:S\$	8,799.00
Total	:S\$	18,722.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	88,434.00
Salvage Value	:S\$	
Margin for Repair	:S\$	101,566.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

4/3/2018

Adjuster Immediate Advice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 03 Apr 2018

Preliminary Advice

Vehicle No : SDN7518G

Make : AUDI Q5

Assignment Date : 31/01/2018

Date of Inspection : 30/01/2018

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)
55 UBI ROAD 1
SINGAPORE 408699

Accident Date : 26/01/2018

Policy No. : 1700056950

Excess : S\$500.00

Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,265.00	(incl.supplementary \$6645.00)
Revised Amount	:S\$	15,318.00	(incl.supplementary \$6645.00)
Check Items (Estimated)	:S\$	8,799.00	
Total	:S\$	24,117.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	88,434.00
Salvage Value	:S\$	
Margin for Repair	:S\$	101,566.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

***SDN7518G (3496887688SG)**

OD

Jan 26 2018 2:20PM

[GAN FONG YIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/05/2018 11:39 AM.
To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14708.92) - SDN7518G - Claim Handler: Dally Amri, Mimi Zarina

Approved:14708.92.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 2:36 PM
To: 'Boo seng yak'; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION SDN7518G - OD AIG - SURVEYED 30 JAN 18

Dear Mr Boo,

Confirm repair cost of \$14,708.92 before excess \$500 and GST @ 7 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Wednesday, 4 April 2018 3:38 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION SDN7518G - OD AIG - SURVEYED 30 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$14,708.92 @ 7 days exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 1 February 2018 9:07 AM
To: 'Claims Dept'; SUR
Subject: RE: SDN 7518 G Own Damage Claim

Dear Jeffery,

As instructed by our client AIG , please proceed to repair the insured vehicle **SDN 7518G (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 31 January 2018 3:33 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SDN 7518 G Own Damage Claim

Dear Jeffery,

We are pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 30 January 2018 11:08 AM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SDN 7518 G Own Damage Claim

Dear all,

Kindly assist in the Own Damage Claim for the above mentioned vehicle.

Car was surveyed by Adrian this morning.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Sent Message

This mail is associated with :

***SDN7518G (3496887688SG)**

OD

Jan 26 2018 2:20PM

[GAN FONG YIN]

Premium Automobiles Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/02/2018 09:12 AM.

To AIG_SG

Subject Re: Alert - Adj Mandate Approved (S\$9923.00) - SDN7518G - Claim Handler: Dally Amri, Mimi Zarina

Dear Sir,

According to surveyor, when front bumper has to been replaced, the front wheel covers (fender wheel arc garnish) have to removed. As the wheel covers are stucked with adhesive tapes, they will have to be replaced.

Hope that the above clarifies matters.

Best Regards,
Veron Chen

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 31/01/2018 06:35 PM

Subject: Alert - Adj Mandate Approved (S\$9923.00) - SDN7518G - Claim Handler: Dally Amri, Mimi Zarina

Approved:9923.00:Re-inspection require on hidden parts and supplementary parts. NOTE: KINDLY PROVIDE DAMAGE PHOTO NO 21"FRONT WHEEL COVER"

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

*SDN7518G (3496887688SG)

OD

Jan 26 2018 2:20PM

[GAN FONG YIN]

Premium Automobiles Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on **31/01/2018 18:35 PM**.

To LKK_HQ

Subject **Alert - Adj Mandate Approved (\$9923.00) - SDN7518G - Claim Handler: Dally Amri, Mimi Zarina**

Approved:9923.00:Re-inspection require on hidden parts and supplementary parts. NOTE: KINDLY PROVIDE DAMAGE PHOTO NO 21"FRONT WHEEL COVER"

DOCUMENTS SUMMARY

There are no documents.

When front bumper has to been replaced, the front wheel covers ~~fasten~~
(fender wheel are garnish) have to be removed.
As the wheel covers are ~~attached~~ ^{sticked} with adhesive tapes, they will have to
be replaced.
Hope that the above clarifies matters.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7101G
Vehicle Details	
Vehicle No.:	SDN7518G
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 SPORT 2.0 TFSI QU S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	DAX012329
Chassis No.:	WAUZZZFVXH2045653
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$44,891.00
Original Registration Date:	26 Sep 2017
First Registration Date:	26 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$54,848.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2027
PARF Rebate Amount:	\$41,136.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)

1/31/2018

PARF/COE Rebate Enquiry

COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$47,298.00
Total Rebate Amount:	\$88,434.00

The information contained herein is correct as at 31 Jan 2018

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GAN FONG YIN
Period of Insurance : 26 Sep 2017 To 25 Sep 2018
Engine No. : DAX012329
Chassis No. : WAUZZZFVXH2045653

Vehicle No. : sdn7518g
Policy No. : 1700056950
Endorsement No. :
Issued Date : 29 Sep 2017

ABOUT THE COVER

Make/Model : AUDI Q5 Sport 2.0 TFSI qu
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

GAN FONG YIN - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408899 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125264

PREMIUM LEASING -QKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE
Cheng Gan Yee

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S6977101G**

Name: **GAN FONG YIN**

Birth Date: **14 Feb 1969**

Issue Date: **27 May 2004**

001227062H



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S6977101G**

Name: **GAN FONG YIN**

姓名: **顏鋒穎**

Race: **CHINESE**

Date of Birth: **14-02-1969**

Sex: **M**

Country of Birth: **MALAYSIA**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES:

Class 2 Motor Cars of unladen weight not exceeding 2000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE: **11 Jul 1990**

NP 428A

Licence No: **S6977101G**

2043521

S6977101G

NRIC No: **S6977101G**

Blood Group: **O+**

Date of Issue: **20-05-1994**

97 HAZEL PARK TERRACE
SINGAPORE 678930

NRIC No: **S6977101G**

Date: **07/02/2011**

No: **6662553**



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0116/2018/GW
Date	:	27-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Gan Fong Yin
Address	:	97 Hazel Park Terrace Singapore 678930
Telephone	:	(HP)97459128
Type of Claim	:	Own Damage Claims
Policy No.	:	1700056950
Vehicle No	:	SDN 7518 G
Model Code	:	Q5 Sport 2.0 TFSI qu
Model / Year	:	Sep-17
Engine No	:	DAX 012329
Chassis No	:	WAUZZZFVXH2045653
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Jan-18
Place of Accident	:	Junc Of Choa Chu Kang Rd & Woodlands Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDN 7518 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy. Front parking aid assy.	S/N \$ 480.00 ✓	✓
2	To remove front fittings, remove and reinstall front bumper. Renew radiator grille, re-organise frontal crash management components. Reinstall all parts removed. Renew both wheel arc trim.	\$ 1,200.00 ✓	500 ✓
3	To respray front bumper, lower spoiler, lhs front fender, both arc trim. ✓	\$ 2,250.00 ✓	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 4,122.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>rebound</i>	\$ 2,248.00	✓ 1798
2	FRONT BUMPER SPOILER <i>Reps Deformed</i>	\$ 652.00	✓ 531.60
3	FRONT BUMPER UNDERRUN BAR <i>Reb'd</i>	\$ 407.00	✓ 325.20
4	FRONT BUMPER CLOSING ELEMENT <i>Reb'd</i>	\$ 147.00	✓ 117.60
5	RADIATOR GRILLE <i>crash'd.</i>	\$ 3,101.00	✓ 2480.80
6	INSCRIPTION "QUATTRO" <i>new</i>	\$ 83.00	✓ 66.16
7	FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>LH 2nd</i>	2 \$ 996.00 498.39	40
8	FRONT BUMPER OUTER GRILLE CLIP <i>Not Nec</i>	4 \$ 14.00	? X
9	FRONT BUMPER COVER CAP- LH/RH <i>Not Nec</i>	2 \$ 74.00	? X
10	FRONT BUMPER SENSOR <i>new</i>	2 \$ 422.00	X
11	FRONT BUMPER SENSOR SEAL RING <i>new</i>	4 \$ 15.00	X
12	HEADLIGHT WASHER LIFT CYLINDER - LH <i>new</i>	\$ 123.00	X
13	HEADLIGHT WASHER LIFT CYLINDER - RH <i>new</i>	\$ 123.00	X
14	HEADLIGHT WASHER PIPE HOSE <i>new</i>	\$ 106.00	X
15	LED HEADLIGHT-LH <i>Not Nec</i>	\$ 7,112.00	? X
16	FOAM FILLER PIECE <i>Reb'd</i>	\$ 244.00	✓ 195.00
17	FRONT BUMPER CARRIER <i>Best</i>	\$ 786.00	? 628.80
18	FRONT BUMPER TOP COVER <i>new</i>	\$ 109.00	X
SUB - TOTAL SPARE PARTS		\$ 16,762.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
19	LED HEADLIGHT MOUNTING <i>Cracked.</i>	\$ 103.00	? <i>82.40</i>
20	LED HEADLIGHT BRACKET <i>Not New</i>	\$ 218.00	? <i>X</i>
21	FRONT WHEEL COVER - LH/RH <i>New</i>	2 \$ 1,090.00	✓ <i>872</i>
22	FRONT NO. PLATE <i>Best.</i>	S/N \$ 25.00	✓ <i>25</i>
23	SUNDRIES <i>New.</i>	\$ 300.00	? <i>37.44</i>
TOTAL SPARE PARTS		: \$ 18,498.00	
TOTAL LABOUR CHARGES		: \$ 4,122.00	
GRANDTOTAL		: \$ 22,620.00	

29.265

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lij

Surveyed Date

: 30/01/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 03 Pairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0116/2018/GW 8-Feb-18 CHANG 1 of 1 SDN 7518 G Audi QS SPORT 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condensor, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,200.00	✓
2	To remove and renew front lock carrier and align to position.	\$ 3,000.00	1750v
TOTAL LABOURS :		\$ 4,200.00	
Parts			
1	FRONT REINFORCEMENT BEAM BRACKET - LH/RH <i>bf</i>	\$ 435.00	348
2	REINFORCEMENTT BEAM BOLT SET <i>new</i>	\$ 77.00	48.64
3	FRONT LOCK CARRIER <i>one</i>	\$ 1,124.00	899.00
4	RADIATOR SUPPORT - LH <i>cur</i>	\$ 40.00	27.60
5	LOCK CARRIER AIR GUIDE - CENTER <i>de</i>	\$ 40.00	36.72
6	FRONT BUMPER GRILLE - LOWER CTR <i>cur</i>	\$ 124.00	98.80
7	FRONT BUMPER STRIKER PLATE - INNER <i>cur</i>	\$ 213.00	170.40
8	FRONT FENDER TOP COVER - LH/RH <i>de</i>	\$ 70.00	54.56
9	FRONT WHEEL SPOILER - LH <i>tr</i>	\$ 139.00	111.20
10	LOCK CARRIER AIR GUIDE - LH <i>de</i>	\$ 50.00	36.96
11	COOLANT <i>new</i>	\$ 133.00	106.24
TOTAL PARTS :		\$ 2,445.00	
GRAND TOTAL :		\$ 6,645.00	

justin 12/2/18

For Premium Automobiles Pte Ltd

[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rebond</i>	\$ 2,248.00	✓
2	FRONT BUMPER SPOILER <i>Reps</i>	\$ 652.00	✓
3	FRONT BUMPER UNDERRUN BAR <i>Rebond</i>	\$ 407.00	✓
4	FRONT BUMPER CLOSING ELEMENT <i>Rebond</i>	\$ 147.00	✓
5	RADIATOR GRILLE <i>Rebond</i>	\$ 3,101.00	✓
6	INSCRIPTION "QUATTRO" <i>Re</i>	\$ 83.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>LH 2nd</i>	2 \$ 996.00 498.	
8	FRONT BUMPER OUTER GRILLE CLIP <i>?</i>	4 \$ 14.00	?
9	FRONT BUMPER COVER CAP- LH/RH <i>?</i>	\$ 74.00	?
10	FRONT BUMPER SENSOR <i>Re</i>	2 \$ 422.00	✓
11	FRONT BUMPER SENSOR SEAL RING <i>Re</i>	4 \$ 15.00	✓
12	HEADLIGHT WASHER LIFT CYLINDER - LH <i>Re</i>	\$ 123.00	✓
13	HEADLIGHT WASHER LIFT CYLINDER - RH <i>Re</i>	\$ 123.00	✓
14	HEADLIGHT WASHER PIPE HOSE <i>Re</i>	\$ 106.00	✓
15	LED HEADLIGHT-LH <i>?</i>	\$ 7,112.00	?
16	FOAM FILLER PIECE <i>Rebond</i>	\$ 244.00	✓
17	FRONT BUMPER CARRIER <i>?</i>	\$ 786.00	?
18	FRONT BUMPER TOP COVER <i>Re</i>	\$ 109.00	✓
SUB - TOTAL SPARE PARTS		\$ 16,762.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
19	LED HEADLIGHT MOUNTING ? <i>One</i>	\$	103.00 ?
20	LED HEADLIGHT BRACKET ?	\$	218.00 ?
21	FRONT WHEEL COVER - LH/RH <i>Two</i>	2 \$	1,090.00 ✓
22	FRONT NO. PLATE <i>Best</i>	S/N \$	25.00 ✓
23	SUNDRIES ?	\$	300.00 ?
	TOTAL SPARE PARTS	: \$	18,498.00
	TOTAL LABOUR CHARGES	: \$	4,122.00
	GRANDTOTAL	: \$	22,620.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0116/2018/GW
Date	:	27-Jan-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

7 days of repairs with added jobs.

jb 4 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Gan Fong Yin
Address	:	97 Hazel Park Terrace Singapore 678930
Telephone	:	(HP)97459128
Type of Claim	:	Own Damage Claims
Policy No.	:	1700056950
Vehicle No	:	SDN 7518 G
Model Code	:	Q5 Sport 2.0 TFSI qu
Model / Year	:	Sep-17
Engine No	:	DAX 012329
Chassis No	:	WAUZZZFVXH2045653
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Jan-18
Place of Accident	:	Junc Of Choa Chu Kang Rd & Woodlands Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDN 7518 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy. Front parking aid assy.	S/N \$ 480.00	\$ 480.00
2	To remove front fittings, remove and reinstall front bumper. Renew radiator grille, re-organise frontal crash management components. Reinstall all parts removed. Renew both wheel arc trim.	\$ 1,200.00	\$ 500.00
3	To respray front bumper, lower spoiler, lhs front fender, both arc trim.	\$ 2,250.00	\$ 1,100.00
4	Added labour charges - see attached	\$ 4,200.00	\$ 2,950.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	\$ 8,322.00	\$ 5,222.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,248.00	\$ 1,798.00
2	FRONT BUMPER SPOILER	\$ 652.00	\$ 521.60
3	FRONT BUMPER UNDERRUN BAR	\$ 407.00	\$ 325.20
4	FRONT BUMPER CLOSING ELEMENT	\$ 147.00	\$ 117.60
5	RADIATOR GRILLE	\$ 3,101.00	\$ 2,480.80
6	INSCRIPTION " QUATTRO "	\$ 83.00	\$ 66.16
7	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2 \$ 996.00	\$ 398.40
8	FRONT BUMPER OUTER GRILLE CLIP	4 \$ 14.00	
9	FRONT BUMPER COVER CAP- LH/RH	\$ 74.00	
10	FRONT BUMPER SENSOR	2 \$ 422.00	
11	FRONT BUMPER SENSOR SEAL RING	4 \$ 15.00	
12	HEADLIGHT WASHER LIFT CYLINDER - LH	\$ 123.00	
13	HEADLIGHT WASHER LIFT CYLINDER - RH	\$ 123.00	
14	HEADLIGHT WASHER PIPE HOSE	\$ 106.00	
15	LED HEADLIGHT-LH	\$ 7,112.00	
16	FOAM FILLER PIECE	\$ 244.00	\$ 195.20
17	FRONT BUMPER CARRIER	\$ 786.00	\$ 628.80
18	FRONT BUMPER TOP COVER	\$ 109.00	
SUB - TOTAL SPARE PARTS		\$ 16,762.00	\$ 6,531.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDN 7518 G.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	6,531.76
19	LED HEADLIGHT MOUNTING		\$ 103.00	\$ 82.40
20	LED HEADLIGHT BRACKET		\$ 218.00	
21	FRONT WHEEL COVER - LH/RH	2	\$ 1,090.00	\$ 872.00
22	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
23	SUPPLEMENTARY		\$ 2,445.00	\$ 1,938.32
24	SUNDRIES		\$ 300.00	\$ 37.44
	TOTAL SPARE PARTS	:	\$ 20,943.00	\$ 9,486.92
	TOTAL LABOUR CHARGES	:	\$ 8,322.00	\$ 5,222.00
	GRANDTOTAL	:	\$ 29,265.00	\$ 14,708.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

GST Reg No. 19-9902271-W		PA/OD/0116/2018/GW	
AIG Asia Pacific Insurance Pte Ltd		8-Feb-18	
78 Shenton Way		CHANG	
#07-16 AIG Building		1 of 1	
Singapore 079120		SDN 7518 G	
Attn: Mr. Adrian Ling - Motor Claims Dept		Audi Q5 SPORT 2.0 TFSI QU	
Tel: 6841 0055 / Fax: 6256 4315			
Estimate No.			
Date			
Service Advisor			
Pages			
Regn No			
Model No			
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condensor, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,200.00	\$ 1,200.00
2	To remove and renew front lock carrier and align to position.	\$ 3,000.00	\$ 1,750.00
TOTAL LABOURS :		\$ 4,200.00	\$ 2,950.00
Parts			
1	FRONT REINFORCEMENT BEAM BRACKET - LH/RH	\$ 435.00	\$ 348.00
2	REINFORCEMENTT BEAM BOLT SET	\$ 77.00	\$ 48.64
3	FRONT LOCK CARRIER	\$ 1,124.00	\$ 899.20
4	RADIATOR SUPPORT - LH	\$ 40.00	\$ 27.60
5	LOCK CARRIER AIR GUIDE - CENTER	\$ 40.00	\$ 36.72
6	FRONT BUMPER GRILLE - LOWER CTR	\$ 124.00	\$ 98.80
7	FRONT BUMPER STRIKER PLATE - INNER	\$ 213.00	\$ 170.40
8	FRONT FENDER TOP COVER - LH/RH	\$ 70.00	\$ 54.56
9	FRONT WHEEL SPOILER - LH	\$ 139.00	\$ 111.20
10	LOCK CARRIER AIR GUIDE - LH	\$ 50.00	\$ 36.96
11	COOLANT	\$ 133.00	\$ 106.24
TOTAL PARTS :		\$ 2,445.00	\$ 1,938.32
GRAND TOTAL :		\$ 6,645.00	\$ 4,888.32

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDN 7518 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0116/2018/MAS

23 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SDN 7518 G, Audi Q5 2.0 TFSI QU S-Tro

With reference to the above-mentioned vehicle no **SDN 7518 G**, claimant,
Mr. Gan Fong Yin, please find the related document per attached.

1. A copy of the Original invoice no. 85012501 – S\$15,203.54
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SDN 7518 G

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2018 14:00		31 Jan 2018 11:39 Edit Adj Rpt	S\$14,708.92 Edit Estimates	S\$14,708.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS																								
Insured: GAN FONG YIN, ID: S6977101G, Tel: +6597459128, Email: gfongyin@gmail.com																								
Vehicle Reg. No.: SDN7518G																								
Claim Type: OD / 3496887688SG																								
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911																								
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/02/2018]																								
Driver/Custodian: GAN FONG YIN (48 / Male), NRIC: S6977101G, Tel: +6597459128																								
View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED																								
- AIG_SG (09/05/2018): Alert - Adj Mandate Approved (S\$14708.92) - SDN7518G - Claim Handler: Dally Amri... - AIG_SG (09/04/2018): Alert - Adj Mandate Maintained - SDN7518G - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (31/01/2018): Alert - Adj Mandate Approved (S\$9923.00) - SDN7518G - Claim Handler: Dally Amri,... - AIG_SG (31/01/2018): SDN7518G / OD / 26/01/2018 / Coverage & Excess update																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete																								
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SDN7518G (3496887688SG)

OD

Jan 26 2018 2:20PM

[GAN FONG YIN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Video												1 per page		☒			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print				
1	26/01/18 23:49	Video - Accident [Linked Accident Report Documents]											Load MP4				
Assessment Reports												1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	31/01/18 15:27	Adjuster Immediate Advice											Load HTM				
2	03/04/18 15:08	Adjuster Immediate Advice											Load HTM				
Photos/Images												3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	31/01/18 14:07	General View											Load JPG	☒			
2	31/01/18 14:07	General View											Load JPG	☒			
3	31/01/18 14:07	General View											Load JPG	☒			
4	31/01/18 14:07	General View											Load JPG	☒			
5	31/01/18 14:07	General View											Load JPG	☒			
6	31/01/18 14:07	General View											Load JPG	☒			
7	31/01/18 14:07	General View											Load JPG	☒			
8	31/01/18 14:07	General View											Load JPG	☒			
9	31/01/18 14:08	General View											Load JPG	☒			
10	31/01/18 14:08	General View											Load JPG	☒			
11	31/01/18 14:08	General View											Load JPG	☒			
12	31/01/18 14:08	General View											Load JPG	☒			
13	31/01/18 14:08	General View											Load JPG	☒			
14	31/01/18 14:08	General View											Load JPG	☒			
15	31/01/18 14:08	General View											Load JPG	☒			
16	31/01/18 14:08	General View											Load JPG	☒			
17	31/01/18 14:08	General View											Load JPG	☒			
18	31/01/18 14:08	General View											Load JPG	☒			
19	31/01/18 14:08	General View											Load JPG	☒			
20	31/01/18 14:08	General View											Load JPG	☒			
21	31/01/18 14:08	General View											Load JPG	☒			
22	31/01/18 14:08	General View											Load JPG	☒			
23	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
24	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
25	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
26	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
27	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
28	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
29	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
30	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
31	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
32	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
33	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
34	03/04/18 15:14	Reinspection Photo											Load JPG	☒			
35	03/04/18 15:14	Reinspection Photo											Load JPG	☒			

36	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
37	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
38	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
39	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
40	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
41	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
42	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
43	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
44	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
45	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
46	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
47	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
48	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
49	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
50	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
51	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
52	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
53	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
54	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
55	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
56	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
57	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
58	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
59	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
60	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
61	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
62	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
63	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
64	03/04/18 15:14	Reinspection Photo	1	Load JPG	☒
			1 per page ☒		
Documentation					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	31/01/18 14:08	Singapore Accident Statement	1 Load PDF		
2	31/01/18 14:08	Certificate of Insurance	1 Load PDF		
3	31/01/18 14:08	Insured's Driving License	1 Load PDF		
4	31/01/18 14:09	ESTIMATE	1 Load PDF		
5	03/04/18 15:00	SUPPLEMENTARY	1 Load PDF		
6	20/04/18 08:11	1ST MARK ESTIMATE	1 Load PDF		
7	25/05/18 15:51	WORKSHOP INVOICE	1 Load PDF		
8	25/05/18 15:51	DISCHARGE VOUCHER	1 Load PDF		

Linked Accident Report Documents

			View Use Viewer ☒		
			1 per page ☒		
Video			Thumbnail	Print	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 Load MP4		
1	26/01/18 23:49	Video - Accident			
			1 per page ☒		
Assessment Reports			Thumbnail	Print	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 Load HTM		
1	26/01/18 23:52	Accident Statement			
			3 per page ☒		
Photos/Images			Thumbnail	Print	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 Load JPG	☒	
1	26/01/18 23:44	Accident Photo	1 Load JPG	☒	
2	26/01/18 23:44	Accident Photo	1 Load JPG	☒	
3	26/01/18 23:44	Accident Photo	1 Load JPG	☒	
4	26/01/18 23:44	Accident Photo	1 Load JPG	☒	
5	26/01/18 23:44	Accident Photo	1 Load JPG	☒	

Merimen e-Claims

6	26/01/18 23:44	Accident Photo	1	Load JPG	☒
7	26/01/18 23:45	Accident Photo	1	Load JPG	☒
8	26/01/18 23:45	Accident Photo	1	Load JPG	☒
9	26/01/18 23:45	Accident Photo	1	Load JPG	☒
10	26/01/18 23:45	Accident Photo	1	Load JPG	☒
11	26/01/18 23:45	Accident Photo	1	Load JPG	☒
12	26/01/18 23:45	Accident Photo	1	Load JPG	☒
13	26/01/18 23:45	Accident Photo	1	Load JPG	☒
14	26/01/18 23:45	Accident Photo	1	Load JPG	☒
15	26/01/18 23:51	Accident Photo	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Load JPG	☒
1	26/01/18 23:47	Sketch Plan	1	Load JPG	☒
2	26/01/18 23:47	Sketch Plan #2			

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001869/AVBN2

Date: 25/05/2018

REFERENCE

Insured/Claimant: GAN FONG YIN Policy No: 1700056950
Date of Loss: 26/01/2018 Nature of Claim: OD Claim No: 3496887688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDN7518G Engine No: DAX012329
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Chassis No: WAUZZZFVXH2045653
Reg. Date: 26/09/2017 (Man. Year: 2017) Odometer: 9518 km
Colour: Blue
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$190,000.00
Price:
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,943.00	9,486.92	11,456.08	54.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,322.00	5,222.00	3,100.00	37.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,265.00	14,708.92	14,556.08	49.74
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	28,765.00	14,208.92	14,556.08	50.60
+ GST 7.00/7.00% (S\$)	2,013.55	994.62	1,018.93	50.60
Nett Amount (S\$)	30,778.55	15,203.54	15,575.01	50.60

INSPECTION

Date of Assignment: 31/01/2018
Date Inspected: 30/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,248.00 FS	*1,798.00 FS
2	1	*FRONT BUMPER SPOILER	Deformed	652.00 FS	*521.60 FS
3	1	*FRONT BUMPER UNDERRUN BAR	Deformed	407.00 FS	*325.20 FS
4	1	*FRONT BUMPER CLOSING ELEMENT	Deformed	147.00 FS	*117.60 FS
5	1	*RADIATOR GRILLE	Cracked	3,101.00 FS	*2,480.80 FS
6	1	*INSCRIPTION QUATTRO	Necessary	83.00 FS	*66.16 FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	N/s Damaged	996.00 FS	*398.40 FS
8	4	*FRONT BUMPER OUTER GRILLE CLIP	Not Necessary	14.00 FS	*- FS
9	2	*FRONT BUMPER COVER CAP-LH/RH	Not Necessary	74.00 FS	*- FS
10	2	*FRONT BUMPER SENSOR	Not Necessary	422.00 FS	*- FS
11	4	*FRONT BUMPER SENSOR SEAL RING	Not Necessary	15.00 FS	*- FS
12	1	*HEADLIGHT WASHER LIFT CYLINDER-LH	Not Necessary	123.00 FS	*- FS
13	1	*HEADLIGHT WASHER LIFT CYLINDER-RH	Not Necessary	123.00 FS	*- FS
14	1	*HEADLIGHT WASHER PIPE HOSE	Not Necessary	106.00 FS	*- FS
15	1	*LED HEADLIGHT-LH	Not Necessary	7,112.00 FS	*- FS
16	1	*FOAM FILLER PIECE	Deformed	244.00 FS	*195.20 FS
17	1	*FRONT BUMPER CARRIER	Bent	786.00 FS	*628.80 FS
18	1	*FRONT BUMPER TOP COVER	Not Necessary	109.00 FS	*- FS
19	1	*LED HEADLIGHT MOUNTING	Cracked	103.00 FS	*82.40 FS
20	1	*LED HEADLIGHT BRACKET	Not Necessary	218.00 FS	*- FS
21	2	*FRONT WHEEL COVER-LH/RH	Necessary	1,090.00 FS	*872.00 FS
22	1	*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
23	1	*SUNDRIES	Necessary	300.00 FS	*37.44 FS
24	2	*FRONT REINFORCEMENT BEAM BRACKET-LH/RH	Bent	435.00 FS	*348.00 FS
25	1	*REINFORCEMENT BEAM BOLT SET	Necessary	77.00 FS	*48.64 FS
26	1	*FRONT LOCK CARRIER	Cracked	1,124.00 FS	*899.20 FS
27	1	*RADIATOR SUPPORT-LH	Cracked	40.00 FS	*27.60 FS
28	1	*LOCK CARRIER AIR GUIDE-CENTER	Deformed	40.00 FS	*36.72 FS
29	1	*FRONT BUMPER GRILLE-LOWER CTR	Cracked	124.00 FS	*98.80 FS
30	1	*FRONT BUMPER STRIKER PLATE-INNER	Cracked	213.00 FS	*170.40 FS
31	2	*FRONT FENDER TOP COVER-LH/RH	Deformed	70.00 FS	*54.56 FS
32	1	*FRONT WHEEL SPOILER-LH	Torn	139.00 FS	*111.20 FS
33	1	*LOCK CARRIER AIR GUIDE-LH	Deformed	50.00 FS	*36.96 FS
34	1	*COOLANT	Necessary	133.00 FS	*106.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,943.00 9,486.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY.FRONT PARKING AID ASSY	New	480.00	480.00
2	TO REMOVE FRONT DITTINGS,REMOVE AND REINSTALL FRONT BUMPER.RENEW RADIATOR GRILLE,RE-ORGANISE FRONTAL CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.RENEW BOTH WHEEL ARC TRIM	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER,LOWER SPOILER,LHS FRONT FENDER,BOTH ARC TRIM	New	2,250.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND TRANSFER AIRCON CONDENSOR,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
6	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION	New	3,000.00	1,750.00
Gross Labour Cost (S\$)			8,322.00	5,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >