

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO: 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB9576R -

AAD1801-317

Not Authorized
1/Sup 8

Vehicle No.:	SHC9576R - CANDY
Chassis No.:	KL1LA69RJBB122427
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	29.01.2018
Third Party Insurer :	AIG

PART		LIST	
1	1 Front Bumper	\$	<i>Bumper</i> 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
3	1 Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1 Front Bumper Retainer RH	\$	<i>Dir</i> 102.00 ✓
5	1 Radiator Grille (Grille A-Rad)	\$	<i>Sn</i> 367.00 X
6	1 Radiator Grille Top Cover	\$	<i>Sn</i> 45.02 X
7	1 Bumper Fog Lamp Cover RH	\$	<i>Sn</i> 32.40 X
8	1 Front Fender RH	\$	<i>R</i> 837.60 ✓
9	1 Front Fender Liner RH	\$	<i>C/R</i> 47.00 ✓
10	1 Headlamp RH	\$	<i>mgem</i> 816.00 ✓
11	1 Bonnet	\$	<i>R</i> 1,250.00
12	1 Bonnet Moulding	\$	<i>Sn</i> 161.97
13	1 Bonnet hinge RH	\$	<i>R</i> 36.00
14	1 Bonnet hinge LH	\$	<i>R</i> 36.00
15	1 Front Support Panel Assy	\$	<i>R</i> 1,222.32 X
16	1 Windscreen Washer Tank - Filler Neck	\$	<i>Sn</i> 4.80
17	1 Windscreen Washer Tank	\$	<i>Sn</i> 62.00
18	1 Windscreen Washer Tank Motor	\$	<i>Sn</i> 51.00
19	1 Front Shock Absorber Assy RH	\$	216.17 ?
20	1 Front Lower Arm RH	\$	283.00 ?
21	1 Front Knuckle Arm RH	\$	230.00 ?
22	1 Front Door RH	\$	<i>R</i> 1,133.00
23	1 Front Door Glass Guide RH Chrome Moulding	\$	<i>Sn</i> 60.00
24	1 Front Door Outer Handle RH	\$	<i>Sn</i> 125.00
25	1 Front Door Hinge Upper RH	\$	<i>R</i> 65.00
26	1 Front Door Hinge Lower RH	\$	<i>R</i> 65.00
27	1 Front Side View Mirror RH	\$	<i>Sn</i> 939.00
28	1 Side Rocker Panel Garnish RH	\$	<i>Sn</i> 236.40
29	1 Rear Door RH	\$	<i>R</i> 1,133.00

TOTAL	\$	11,294.68
10%	\$	1,129.47
	\$	10,165.21

Special Nett

1	1 Set	Front Fender Liner Clip RH	\$	<i>nn</i>	30.00	✓
2	1	Door Sticker "Trans-cab" RH	\$	<i>nn</i>	80.00	X
3	1	Door Sticker "6555-3333" RH	\$	<i>nn</i>	80.00	X
4	1set	Side Rocker Panel Garnish Clip RH	\$	<i>nn</i>	60.00	X
5	1	Rear Tyre RH	\$	<i>nn</i>	360.00	<i>40/m</i>
6	1	Rear Wheel Rim RH	\$	<i>nn</i>	254.00	<i>50/m</i>
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	X
9	1Set	Rear Bumper Parking Sensor	\$	<i>nn</i>	300.00	X
10	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	30.00	X
11	1Set	Rear Fender inner cowling clip RH	\$	<i>nn</i>	30.00	X

TOTAL	\$	1,404.00
TOTAL PARTS	\$	11,569.21

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 5,400.00 *400*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *30*

Putty and Spray Painting Of The Affected
 Portion.

\$ 5,600.00 *400*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To check steering geometry and computer wheel
 alignment

\$ 220.00 *60*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *20*

To dismantle and refit front end suspension,
 undercarriage parts, final checking and testing.

\$ 380.00 *?*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-317

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO: 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9576R

Towing Fees	\$	nn 120.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

TOTAL	\$	12,790.00
Over All Total	\$	24,359.21

REPAIR DAYS**28 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before, after spray painting
- To display damaged part for resurvey
- Parts price must be based on market price
- Third party survey on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claims, must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: