

12/02/2017

ASS. REC. BY:

REF: CS/CT18001877/TIVd3m2 Special Instruction:

Surveyor:
MerimenTaufik
joel Goh

ASSIGNMENT (Office)

of CTI

Date/Time: 31/1/18 @ 12:02pm

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7055 G

Insured:

at Workshop m/s

Sng Ah Tee

Tel: 6268 6183

of

Blk 3, Pioneer Rd North # 01-18

Policy No:

DMCVSN1526821702

Claim No:

SNM18D00489C01

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A. 25/01/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:35pm @ 31/1/18

Person Contacted:

samantha

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBC 7055G - CC3/CT18001721/K1K3	D.O.A.: 25/01/18
2/2/18	Revert by merimen	
5/2/18	Rec approved from Alfred by merimen	
5/2/18	Informed Samantha c/A on LS repair ex \$500 by email	
9/7/18	LS \$1600 confirmed by email (Ref 4037.40, 729)	

Survey Department Check List (Case Handler)

Reference No.: CS | CTI 1800 1877 | Twd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 9/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/21



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18001877/T1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-01-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBC 7055G
Policy No.	DMCVSN1526821702	Coverage (\$)	0.00
Claim No.	SNM18D00489C01	Excess (\$)	500.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	25/01/2018	Inspection Date	31/01/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joel Goh	
Date: 02 Feb 2018	

Preliminary Advice

Vehicle No	: GBC7055G	Accident Date	: 25/01/2018
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN1526821702
Assignment Date	: 31/01/2018	Excess	: S\$500.00
Date of Inspection	: 01/02/2018	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,637.40
Revised Amount	:S\$	2,008.15
Check Items (Estimated)	:S\$	1,774.50
Total	:S\$	3,782.65

Lump Sum Repair (ESTIMATED)	:S\$	3,050.00
-----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	32,212.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,788.00

Remarks

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm (D)

(X)

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

()

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	30 Jan 2018 Sendback Est	30 Jan 2018 14:00 \$55,637.40	31 Jan 2018 12:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HOE SENG (S.K) PTE LTD, Co. Reg. No.: 200822392R		
Vehicle Reg. No.:	GBC7055G	Date of Loss:	25/01/2018 11:00 - :59
Claim Type:	OD / SNM18D00489C01	Policy/Cover Note No.:	DMCVSN1526821702 (Comprehensive) Coverage: 17/07/2017 - 16/07/2018
		Excess:	\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/02/2018]		
Driver/Custodian:	WILSON S/O JOSEPH RAJOO (58 / Male), NRIC: S1342776C, Tel: +6597787570		
Adj Asg. Remarks:	OD SURVEY AND REVERT. EXCESS \$500.00 NO WAIVER		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPIING (31/01/2018): Cancellation of Assignment: GBC7055G

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 5 February 2018 4:28 PM
To: SAMANTHA TAN; SUR
Subject: GBC 7055G-DOA: 25/1/2018 (CHINA TAIPING OD)
Attachments: CAI MARKING.pdf

Dear Samantha,

As instructed by our client , please proceed to repair the insured vehicle **GBC 7055G on Lump Sum basis (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please see marking from China Taiping.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

GBC7055G (SNM18D00489C01)

OD

Jan 25 2018 11:00AM

[HOE SENG (S.K) PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 05/02/2018 14:12 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$2950.00) - GBC7055G - Claim Handler: Joel Goh

Approved:2950.00:Please proceed to authorize repairs at \$2,950.00 BEFORE Excess of \$500.00.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 9 July 2018 3:11 PM
To: 'Sharon Sng'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: GBC7055G - FINALISE & AFTER PAINT

Dear Sharon,

Confirmed Lump Sum \$1600 before excess \$500 and GST

No of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Monday, 9 July 2018 10:06 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: GBC7055G - FINALISE & AFTER PAINT

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2392R
Vehicle Details	
Vehicle No.:	GBC7055G
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2309980
Chassis No.:	JTFAT35Y10K202434
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	17 Jul 2013
First Registration Date:	17 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2023
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$59,001.00
COE Rebate Amount:	\$32,212.00
Total Rebate Amount:	\$32,212.00

The information contained herein is correct as at 31 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2392R

Vehicle Details

Vehicle No.: GBC7055G

Vehicle to be Exported: Yes

Intended De-registration Date: 31 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 MANUAL

Primary Colour: White

Manufacturing Year: 2013

Engine No.: 1KD2309980

Chassis No.: JTFAT35Y10K202434

Maximum Power Output: -

Open Market Value: \$24,970.00

Original Registration Date: 17 Jul 2013

First Registration Date: 17 Jul 2013

Transfer Count: 0

Actual ARF Paid: \$1,249.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$59,001.00

COE Rebate Amount: \$32,212.00

Total Rebate Amount: \$32,212.00

The information contained herein is correct as at 26 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 09:52
Date Of Accident	25/01/2018 11:15
Exact Location Of Accident	KAMPONG BAHRU RD BEFORE HOSPITAL DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7055G
Insured/Policyholder	
Name Of Registered Owner	HOE SENG (S.K) PTE LTD
Co Reg No	200822392R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67476384

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1526821702
Cover Note Number	

Driver

Name of Driver	WILSON S/O JOSEPH RAJOO
NRIC No	S1342776C
Date Of Birth	25/04/1959
Occupation	OUTDOOR
Date Of Driving Pass	27/08/1998
Driving Experience	19 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97787570
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 517C JURONG WEST ST 52 #04-565
Postcode	643517
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 25/01/2018 AT AROUND 1115HRS, I WAS TRAVELLING ALONG KAMPONG BAHRU RD AND I WAS ON THE EXTREME RIGHT 1ST LANE. WHILE DRIVING NEAR THE U TURN, SUDDENLY VEHICLE B JAMMED BRAKE AND I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO HIS VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2822X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KOH HOCK SENG
NRIC/Passport Number	S1319473D
Contact Number	96704933
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Accident Circumstances -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other workshop
☐ For record purpose
Policy No. DNCVSN1576821702
Insurer China Veh. No. ABC7055G

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: DMCVSN1526821702
Vehicle Reg. No.: **GBC7055G**
Driver Age/Info: 58 / MALE
TP Injury Involved? NO
Insured/Claimant: HOE SENG (S.K) PTE LTD
Driver: WILSON S/O JOSEPH RAJOO

Ref. No:
Date of Loss: 25/01/2018
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA DYNA 150, 3.0 D (M)
Vehicle Colour: WHITE
Engine No: 1KD2309980
Odometer: 5 KM

Vehicle Reg. Date: 17/07/2013

Chassis No: JTFAT35Y10K202434

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 9

Taiping 77445749
Ex \$ 500 Revent
12/2/18 1/2/18 @ 12pm
6 days
Lumpsum
Resurvey after repair

Description of Accident/Loss: ON 25/01/2018 AT AROUND 1115HRS, I WAS TRAVELLING ALONG KAMPONG BAHRU RD AND I WAS ON THE EXTREME RIGHT 1ST LANE. WHILE DRIVING NEAR THE U TURN, SUDDENLY VEHICLE B JAMMED BRAKE AND I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO HIS VEHICLE REAR PORTION.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

sur @ lkhantolan

COST OF CLAIMS

	Amount
Parts	3,807.40
Miscellaneous Items	0.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,637.40
+ GST 7.00% (\$\$)	394.62
Nett Amount (\$\$)	6,032.02

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jan 2018)
Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBC7055G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt *140.00 F
3	1		*FRT BUMPER BRACKET	0.00	0.00	bt *50.00 F
4	2		*FRT HEADLAMP LH- X RH- un	0.00	0.00	*370.00 F
5	2		*FRT HEADLAMP LOWER SEAL LH- nn RH- de	0.00	0.00	*30.00 F
6	1		*FRT GRILLE ASSY	0.00	0.00	mis *140.00 F
7	1		*FRT GRILLE EMBLEM	0.00	0.00	nel *28.00 F
8	10		*FRT GRILLE CLIP	0.00	0.00	nel *25.00 F
9	2		*FRT CORNER PANEL	0.00	0.00	*120.00 F
10	1		*FRT PANEL	0.00	0.00	Ry *300.00 F
11	1		*FRT PANEL DYNA LOGO	0.00	0.00	na *25.00 F
12	2		*FRT SUPPORT BEAM MOUNTING	0.00	0.00	? *140.00 F
13	2		*FRT SUPPORT BEAM MOUNTING BUSH	0.00	0.00	? *30.00 F
14	1		*FRT DOOR RH	0.00	0.00	Ry *550.00 F
15	1		*FRT DOOR HINGE RH	0.00	0.00	Ry *35.00 F
16	1		*FRT DOOR WEATHERSTRIPE RH	0.00	0.00	X nn *75.00 F
17	1		*FRT STEP GARNISH RH	0.00	0.00	at *95.00 F
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	X *35.00 F
19	1		*AIRCON BLOWER ASSY	0.00	0.00	? *450.00 F
20	1		*HEATER BLOWER ASSY	0.00	0.00	? *950.00 F
21	1		*ROC STICKER	0	0.00	at *20.00 FS
Sub Total (S\$)						3,628.00
+ Margin on L,N Items 5.00% (S\$)						179.40
Total Parts (S\$)						3,807.40

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CHECK WIRING	New	✓ 30.00
2	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	600 900.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600 900.00

Gross Labour Cost (S\$)

1,830.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co. Reg. No: 200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: DMCVSN1526821702
Vehicle Reg. No.: GBC7055G
Driver Age/Info: 58 / MALE
TP Injury Involved? NO
Insured/Claimant: HOE SENG (S.K) PTE LTD
Driver: WILSON S/O JOSEPH RAJOO

Ref. No:
Date of Loss: 25/01/2018
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA DYNA 150, 3.0 D (M)
Vehicle Colour: WHITE
Engine No: 1KD2309980
Odometer: 5 KM

Vehicle Reg. Date: 17/07/2013

Chassis No: JTFAT35Y10K202434

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 9

*Taiping 9744 5747
Ex \$ 500 Present
1/2/18 @ 12pm. Lumpsum
6 days. Reopening for repair*

Description of Accident/Loss: ON 25/01/2018 AT AROUND 1115HRS, I WAS TRAVELLING ALONG KAMPONG BAHRU RD AND I WAS ON THE EXTREME RIGHT 1ST LANE. WHILE DRIVING NEAR THE U TURN, SUDDENLY VEHICLE B JAMMED BRAKE AND I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO HIS VEHICLE REAR PORTION.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

surv @ lkkantoforum

COST OF CLAIMS

	Amount
Parts	3,807.40
Miscellaneous Items	0.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	5,637.40
+ GST 7.00% (\$)	394.62
Nett Amount (\$)	6,032.02

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jan 2018)
Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBC7055G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt ✓ *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt ✓ *140.00 F ✓
3	1		*FRT BUMPER BRACKET	0.00	0.00	bt ✓ *50.00 F ✓
4	2		*FRT HEADLAMP <i>LH-X RH-185</i>	0.00	0.00	*370.00 F <i>185</i>
5	2		*FRT HEADLAMP LOWER SEAL <i>LH-X RH-de-15</i>	0.00	0.00	*30.00 F <i>15</i>
6	1		*FRT GRILLE ASSY	0.00	0.00	an/s ✓ *140.00 F ✓
7	1		*FRT GRILLE EMBLEM	0.00	0.00	an ✓ *28.00 F ✓
8	10		*FRT GRILLE CLIP	0.00	0.00	an ✓ *25.00 F ✓
9	2		*FRT CORNER PANEL	0.00	0.00	*120.00 F X
10	1		*FRT PANEL	0.00	0.00	Rx ✓ *300.00 F X
11	1		*FRT PANEL DYNA LOGO	0.00	0.00	na ✓ *25.00 F ✓
12	2		*FRT SUPPORT BEAM MOUNTING	0.00	0.00	*140.00 F X
13	2		*FRT SUPPORT BEAM MOUNTING BUSH	0.00	0.00	? *30.00 F X
14	1		*FRT DOOR RH	0.00	0.00	Rx ✓ *550.00 F X
15	1		*FRT DOOR HINGE RH	0.00	0.00	Rx ✓ *35.00 F X
16	1		*FRT DOOR WEATHERSTRIPE RH	0.00	0.00	X ✓ *75.00 F X
17	1		*FRT STEP GARNISH RH	0.00	0.00	an ✓ *95.00 F ✓
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	X ✓ *35.00 F X
19	1		*AIRCON BLOWER ASSY	0.00	0.00	*450.00 F X
20	1		*HEATER BLOWER ASSY	0.00	0.00	? *950.00 F X
21	1		*ROC STICKER	0	0.00	an ✓ *20.00 FS

F=Franchise part, S=Sochett.

Sub Total (\$\$) *\$703* 3,628.00
 + Margin on L,N Items 5.00% (\$\$) *add 5% = 179.40* 179.40
 Total Parts (\$\$) *\$703 + 179.40 = 882.40* 3,807.40

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

P - 780.15
L - 1,230.00
2,010.15
? - 1,648.50
3,658.65

-2.1% = 2,926.92

4.5 - 2,950/-

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	600 900.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600 900.00
Gross Labour Cost (\$\$)			1230 1,830.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$ 2008.15
less 20% = \$ 1606.52
~ \$ 1600 / 45
before claim \$ 500 /
OK? 45 revert.
Shawn 9/27/2018

China marking

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Bik 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: DMCVSN1526821702
Vehicle Reg. No.: GBC7055G
Driver Age/Info: 58 / MALE
TP Injury Involved? NO
Insured/Claimant: HOE SENG (S.K) PTE LTD
Driver: WILSON S/O JOSEPH RAJOO

Ref. No:
Date of Loss: 25/01/2018
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA DYNA 150, 3.0 D (M)
Vehicle Colour: WHITE
Engine No: 1KD2309980
Odometer: 5 KM

Vehicle Reg. Date: 17/07/2013

Chassis No: JTFAT35Y10K202434

*Tanpin 77445749
Ex \$ 500 Resent
1/2/18 @ 12pm
Gday. Lumpyshun
Reasoning of the repair.*

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 9

Description of Accident/Loss: ON 25/01/2018 AT AROUND 1115HRS, I WAS TRAVELLING ALONG KAMPONG BAHRU RD AND I WAS ON THE EXTREME RIGHT 1ST LANE. WHILE DRIVING NEAR THE U TURN, SUDDENLY VEHICLE B JAMMED BRAKE AND I APPLIED MY BRAKE BUT MY VEHICLE SKID FORWARDS AND ACCIDENTALLY COLLIDED ONTO HIS VEHICLE REAR PORTION.

sur @ lkkauto.com

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	3,807.40
Miscellaneous Items	0.00
Labour	1,830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	5,637.40
+ GST 7.00% (\$)	394.62
Nett Amount (\$)	6,032.02

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Jan 2018)
 Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBC7055G)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt ✓ *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt ✓ *140.00 F
3	1		*FRT BUMPER BRACKET	0.00	0.00	bt ✓ *50.00 F
4	2		*FRT HEADLAMP LH-X RH-un 185	0.00	0.00	*370.00 F
5	2		*FRT HEADLAMP LOWER SEAL LH-X, RH-d-15	0.00	0.00	*30.00 F
6	1		*FRT GRILLE ASSY	0.00	0.00	mis ✓ *140.00 F
7	1		*FRT GRILLE EMBLEM	0.00	0.00	mis ✓ *28.00 F
8	10		*FRT GRILLE CLIP	0.00	0.00	mis ✓ *25.00 F
9	2		*FRT CORNER PANEL	0.00	0.00	*120.00 F
10	1		*FRT PANEL	0.00	0.00	Rp ✓ *300.00 F
11	1		*FRT PANEL DYNA LOGO	0.00	0.00	mis ✓ *25.00 F
12	2		*FRT SUPPORT BEAM MOUNTING	0.00	0.00	? ✓ *140.00 F
13	2		*FRT SUPPORT BEAM MOUNTING BUSH	0.00	0.00	? ✓ *30.00 F
14	1		*FRT DOOR RH	0.00	0.00	Rp ✓ *550.00 F
15	1		*FRT DOOR HINGE RH	0.00	0.00	Rp ✓ *35.00 F
16	1		*FRT DOOR WEATHERSTRIPE RH	0.00	0.00	X ✓ *75.00 F
17	1		*FRT STEP GARNISH RH	0.00	0.00	out ✓ *95.00 F
18	1		*FRT SIDE MIRROR (ROUND) LH	0.00	0.00	X ✓ *35.00 F
19	1		*AIRCON BLOWER ASSY	0.00	0.00	? ✓ *450.00 F
20	1		*HEATER BLOWER ASSY	0.00	0.00	? ✓ *950.00 F
21	1		*ROC STICKER	0	0.00	out ✓ *20.00 FS

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 3,628.00
 + Margin on L,N Items 5.00% (\$\$) 179.40
 Total Parts (\$\$) 3,807.40

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

P-780.15
 L-1,230.00
 2,010.15
 ? -1,648.50
 3,658.65

-2% = 2,926.92

45 - 2,950/-

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No Particulars		Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	600 900.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600 900.00
Gross Labour Cost (\$\$)			1,830.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT18001877/T1VD3N2
Date: 11/07/2018

REFERENCE

Insured/Claimant: HOE SENG (S.K) PTE LTD Policy No: DMCVSN1526821702
Date of Loss: 25/01/2018 Nature of Claim: OD Claim No: SNM18D00489C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC7055G	Engine No:	1KD2309980
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y10K202434
Reg. Date:	17/07/2013 (Man. Year: 2013)	Odometer:	191145 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,807.40	778.15	3,029.25	79.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,230.00	600.00	32.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,637.40	2,008.15	3,629.25	64.38
Approved Total (Overridden) (S\$)		1,600.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	5,637.40	1,100.00	4,537.40	80.49
+ GST 7.00/7.00% (S\$)	394.62	77.00	317.62	80.49
Nett Amount (S\$)	6,032.02	1,177.00	4,855.02	80.49

INSPECTION

Date of Assignment:	31/01/2018	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	01/02/2018	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jul 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7055G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	20.00 FS	*20.00 FS
2	1		*FRT BUMPER	Bent	140.00 F	*140.00 F
			(WCP)			
3	1		*FRT BUMPER BRACKET	Bent	50.00 F	*50.00 F
			(WCP)			
4	1		*FRT HEADLAMP	O/s Cracked/N/s Not Necessary	370.00 F	*185.00 F
			(WCP)			
5	1		*FRT HEADLAMP LOWER SEAL	O/s Deformed/N/s Not Necessary	30.00 F	*15.00 F
			(WCP)			
6	1		*FRT GRILLE ASSY	Missing	140.00 F	*140.00 F
			(WCP)			
7	1		*FRT GRILLE EMBLEM	Necessary	28.00 F	*28.00 F
			(WCP)			
8	10		*FRT GRILLE CLIP	Necessary	25.00 F	*25.00 F
			(WCP)			
9	2		*FRT CORNER PANEL	Not Necessary	120.00 F	*- F
			(WCP)			
10	1		*FRT PANEL	Repair	300.00 F	*- F
			(WCP)			
11	1		*FRT PANEL DYNA LOGO	Necessary	25.00 F	*25.00 F
			(WCP)			
12	2		*FRT SUPPORT BEAM MOUNTING	Not Necessary	140.00 F	*- F
			(WCP)			
13	2		*FRT SUPPORT BEAM MOUNTING BUSH	Not Necessary	30.00 F	*- F
			(WCP)			
14	1		*FRT DOOR RH	Repair	550.00 F	*- F
			(WCP)			
15	1		*FRT DOOR HINGE RH	Repair	35.00 F	*- F
			(WCP)			
16	1		*FRT DOOR WEATHERSTRIPE RH	Not Necessary	75.00 F	*- F
			(WCP)			
17	1		*FRT STEP GARNISH RH	Cut	95.00 F	*95.00 F
			(WCP)			
18	1		*FRT SIDE MIRROR (ROUND) LH	Not Necessary	35.00 F	*- F
			(WCP)			
19	1		*AIRCON BLOWER ASSY	Not Necessary	450.00 F	*- F
			(WCP)			
20	1		*HEATER BLOWER ASSY	Not Necessary	950.00 F	*- F
			(WCP)			
21	1		*ROC STICKER	Cut	20.00 FS	*20.00 FS
					Sub Total (\$\$)	3,628.00 743.00
					+ Margin on L,N Items 5.00/5.00% (\$\$)	179.40 35.15
					Total Parts (\$\$)	3,807.40 778.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	30.00
2	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	900.00	600.00
3	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	900.00	600.00
Gross Labour Cost (\$\$)			1,830.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >