

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD5125A - AIG

AAD1801-302

Not Authorized
Resurvey By painting 82334.57

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD5125A - JHOW
 VF1ABL15AUC283236
 RENAULT
 LATITUDE
 28.01.2018
AIG

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Per 100</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Per</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Per</i> 113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Per</i> 135.97
5	1	BUMEPR RETAINER RH REAR	\$	<i>Per</i> 44.99
6	1	BUMPER REFLECTOR RH	\$	<i>Per</i> 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Per</i> 135.97
8	1	BUMEPR RETAINER LH REAR	\$	<i>Per</i> 44.99
9	1	BUMPER REFLECTOR LH	\$	<i>Per</i> 43.61
10	1	BUMPER BEAM REAR	\$	<i>Per</i> 777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Per</i> 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Per</i> 225.95
13	1	BOOT REAR	\$	<i>Per</i> 2,872.68
14	1	BOOT FINISHER	\$	<i>Per</i> 470.06
15	1	BOOT WHEATERSTRIP	\$	<i>Per</i> 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Per</i> 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Per</i> 493.35
18	1	BOOT BADGE 'RENAULT'	\$	<i>Per</i> 225.36
19	1	BOOT BADGE	\$	<i>Per</i> 225.36
20	1	BOOT STRUT LH	\$	<i>Per</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Per</i> 276.08
22	1	BOOT HINGE LH	\$	<i>Per</i> 367.84
23	1	BOOT HINGE RH	\$	<i>Per</i> 367.84
24	1	BOOT SWITCH	\$	<i>Per</i> 168.13
25	1	BOOT LOCK	\$	<i>Per</i> 202.67
26	1	BOOT LOCK CATCH	\$	<i>Per</i> 74.40
27	2	LICENCE PLATE LAMP	\$	<i>Per</i> 50.52
28	2	BOOT RUBBER PLUG	\$	<i>Per</i> 221.81
29	1	FENDER PANEL REAR LH	\$	<i>Per</i> 3,299.13
30	1	WHEELARCH REAR LH	\$	<i>Per</i> 543.47
31	1	FENDER PANEL REAR RH	\$	<i>Per</i> 3,299.13
32	1	WHEELARCH REAR RH	\$	<i>Per</i> 543.47
33	1	TAILLAMP RH	\$	<i>Per</i> 552.55
34	1	TAILLAMP PANEL RH	\$	<i>Per</i> 986.70

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-302**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5125A - AIG

35	1	TAILLAMP LH	\$	552.55	}
36	1	TAILLAMP PANEL LH	\$	986.70	
37	1	OUTER PANEL REAR (End Panel)	\$	1,471.77	
38	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	
39	1	EXHAUST REAR	\$	7,489.05	
40	1	EXHAUST CAP REAR	\$	230.49	

TOTAL	\$	31,137.51
10%	\$	3,113.75
	\$	28,023.76

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	}
11	1SET	BOOT FINISHER CLIP	\$	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	30.00	
13	1	BOOT STICKER "6555-3333"	\$	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
16	1	TAILLAMP CLIP RH	\$	5.00	}
17	1	TAILLAMP CLIP LH	\$	5.00	
18	2	REAR WINDSCREEN SELANT	\$	80.00	}
19	1	WINDSCREEN MOULDING	\$	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
22	1	SPARE TYRE	\$	330.00	X

TOTAL	\$	2,124.02
TOTAL PARTS	\$	30,147.78

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 2201

To Rust-Proofing Of The Affected Areas.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2001 2,800.00
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
Towing Fees	\$	nn 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	37,857.78

(PARTS BY PARTS)
Repair Days

10 Days

20 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: