

22/03/2018

ASS. REC. BY:

REF: CS/FCI18001881/R17d3n2

Special Instruction:

Surveyor

CWS

ASSIGNMENT (Office)

From (Person):

Aung Yin Ming

of

FCI

Date/Time:

12:50pm @ 31/1/18

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 2040E

Insured:

SHC 0346S

at Workshop m/s

Prime Auto

Tel:

6861 0908

of

6 Benoi place

Policy No:

Claim No:

D18 000 934 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2018

05/02/18 @ 3pm owner waiting

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

12:53pm @ 31/1/18

Person Contacted:

Chrissy

Vehicle-IN (OUT)

| Date/Time | Action/Instruction (✓) Estimate       |                   |
|-----------|---------------------------------------|-------------------|
|           | SHD 2040E - CC3/AIG15004982/Kwa3q2    | D.O.A: 20/03/2015 |
|           | SHC 346S - NBA/LIP16013591/y          | D.O.A: 20/07/2016 |
|           | lump sum \$1100/- (Red: 1345.87; 55%) |                   |
|           |                                       |                   |
|           |                                       |                   |

DATE: 2014

REF:

62932

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHO 2040E Yr Regn: 2014 OUT

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HY 1.8 c.c. 1797

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 369233 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZVW301840455

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTAKE

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/01/18 D.O.I. 06/02/18

Survey held at PRIME AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR + O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS + SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp. (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 1100)

|     |
|-----|
| 110 |
| 50  |
| 50  |
| 22  |
| 232 |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001881/R1td3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-01-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                    |                |            |
|--------------|--------------------|----------------|------------|
| Insured Veh. | SHC 346S           | Veh. Inspected | SHD 2040E  |
| Policy No.   |                    | Coverage (\$)  | 0.00       |
| Claim No.    | D18000934MFSH      | Excess (\$)    | 0.00       |
| Assign From  | CWS (AUNG YIN MIN) | Assign Date    | 31/01/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |                                                                        |                 |
|----------------|------------------------------------------------------------------------|-----------------|
| Accident Date  | 24/01/2018                                                             | Inspection Date |
| Survey held at | PRIME AUTO CLAIMS SERVICE PTE LTD<br>6 BENOI PLACE<br>SINGAPORE 629927 |                 |

### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C  
GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

|                    |                                           |                               |
|--------------------|-------------------------------------------|-------------------------------|
| Date               | 30-01-2018                                | Our Ref No. D18000934MFSH     |
| Accident Date      | 24-01-2018                                | Claim Type. Third Party       |
| Insured Vehicle    | SHC0346S                                  | Third Party Vehicle. SHD2040E |
| Survey Location    | 6 Benoi Place                             |                               |
| Contact Person.    | CHRISY                                    |                               |
| Contact No.        | 68610908/ 0                               | Fax No. 65152948              |
| Survey Type        | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED: |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD              |                               |
| Contact Person     | NA                                        | Fax No. 68416315              |
| Contact Number.    | NA                                        |                               |

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                   |                                        |                         |
|-------------------|----------------------------------------|-------------------------|
| Cc : Workshop     | PRIME AUTO CLAIMS<br>SERVICE PTE. LTD. | Attention. NIL          |
| Cc : TP Solicitor | NA                                     | TP Solicitor Fax No. NA |
| Officer Incharge  | AUNGYM                                 |                         |

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234511)



PRI Documents



Close



## PRI Header Details

|                   |                                                                   |                                   |                                                                                                      |                      |                   |
|-------------------|-------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------------------------------------------------|----------------------|-------------------|
| Claim No          | D18000934MFSH                                                     | Policy No                         | D-18088937MFSH                                                                                       | Claimant S.No & Name | 1 & PRIME AU LTD. |
| Workshop Name     | PRIME AUTO CLAIMS SERVICE PTE. LTD.<br>(Contact Person : CHRISSY) | Survey Location & Contact Details | 6 Benoi Place<br>Mobile: 0 , Phone: 68610908 , Fax: 65152948<br>EmailId: CHRISSY@PRIMEAUTOCLAIMS.COM |                      |                   |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                                      | Instructions To Surveyor          | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:                                                            |                      |                   |
| Insured Name      | CITYCAB PTE LTD                                                   | Insured Vehicle No                | SHC0346S                                                                                             | TP Vehicle No        | SHD2040E          |
| PRI Recieved Date | 31-01-2018 02:25:56 PM                                            | Surveyor Appointed Date           | 31-01-2018 12:49:27 PM                                                                               | Surveyor Accept Date | 31-01-2018 0      |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 31-01-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                      |                |                       |         |                      |
|-----------|----------------------|----------------|-----------------------|---------|----------------------|
| Make      | Please Select Make ▼ | Model          | Please Select Model ▼ | Year    | Select Year ▼        |
| Chasis No | <input type="text"/> | Engine No      | <input type="text"/>  | Mileage | <input type="text"/> |
| Color     | <input type="text"/> | Cubic Capacity | <input type="text"/>  |         |                      |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

DANIS



# Prime Auto Claims Service Pte Ltd

GST Reg. No: 201606560M  
 5 Behol Place Singapore 629926  
 Tel: 6861 0908 Fax: 6515 2948

Date: 05.02.2018

First Capital Insurance Ltd  
 36 Robinson Road #16-01  
 City House  
 Singapore 068877

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2040E TOYOTA PRIUS HYBRID 1.8L A (2014)

## To Supply

- |         |                            |    |          |      |
|---------|----------------------------|----|----------|------|
| 1 ) 1pc | Front bumper               | \$ | 2,230.00 | DE   |
| 2 ) 1pc | Front bumper lower grille  | \$ | 320.85   | X 50 |
| 3 ) 1pc | Front bumper lower garnish | \$ | 158.31   | X 50 |
| 4 ) 1pc | Front bumper right lamp    | \$ | 152.00   | X 50 |

1230  
 25%  
 922.50

|                    |    |          |          |
|--------------------|----|----------|----------|
| Sub total parts    | \$ | 1,861.16 | 1280.00  |
| Less: 25% discount | \$ | (465.29) | - 320.00 |
|                    | \$ | 1,395.87 | 960.00   |

## L/charge

- |                                                                                                                                                                               |    |        |     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|--------|-----|
| 1 ) To remove front bumper rear bumper lower grille & front bumper right lamp. Replace front bumper, front bumper right lamp & the above parts. Align and adjust front bumper | \$ | 500.00 | 250 |
| 2 ) To putty, respray painting front bumper. To polish                                                                                                                        | \$ | 550.00 | 200 |

|                       |    |          |         |
|-----------------------|----|----------|---------|
| Sub total L/charges   | \$ | 1,050.00 | 450.00  |
| Estimated Grand Total | \$ | 2,445.87 | 1410.00 |

Rasue

Hp 90010068

2 days

4/5

06/02/18 @ 10:00

Repair after repair

less: 20% LS

LS

1100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

922.50

450.00

1372.50

20%

1098

40-81,100

2 days



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 05.02.2018

First Capital Insurance Ltd

36 Robinson Road #16-01

City House

Singapore 068877

Attn: Motor Claims Dept

RE: COST OF REPAIR TO VEHICLE SHD2040E TOYOTA PRIUS HYBRID 1.8L A (2014)

## To Supply

|     |     |                            |    |          |        |
|-----|-----|----------------------------|----|----------|--------|
| 1 ) | 1pc | Front bumper               | \$ | 1,230.00 | DE-    |
| 2 ) | 1pc | Front bumper lower grille  | \$ | 320.85   | *8 SVC |
| 3 ) | 1pc | Front bumper lower garnish | \$ | 158.31   | *8 SVC |
| 4 ) | 1pc | Front bumper right lamp    | \$ | 152.00   | *8 SVC |

|                    |    |          |
|--------------------|----|----------|
| Sub total parts    | \$ | 1,861.16 |
| Less: 25% discount | \$ | (465.29) |
|                    | \$ | 1,395.87 |

## L/charge

- |     |                                                                                                                                                                           |    |                       |
|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|-----------------------|
| 1 ) | To remove front bumper rear bumper lower grille & front bumper right lamp. Replace front bumper, front bumper right lamp & the above parts. Align and adjust front bumper | \$ | 500.00 <del>250</del> |
| 2 ) | To putty, respray painting front bumper. To polish                                                                                                                        | \$ | 550.00 <del>200</del> |

|                       |    |          |
|-----------------------|----|----------|
| Sub total L/charges   | \$ | 1,050.00 |
| Estimated Grand Total | \$ | 2,445.87 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Up 90010068

2 days

L/S

06/02/18 @ 10.00

Resurvey after repair



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                        |                              |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|------------------------------|------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                        | Ref : CS/FCI18001881/R1td3n2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                        | Date : 20-02-2018            |            |  |
|                                                                                                                                                                                        |                                                                        | Code : FCI2                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                        |                              |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 346S                                                               | Veh. Inspected               | SHD 2040E  |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088937MFSH                                                         | Coverage (\$)                | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D18000934MFSH                                                          | Excess (\$)                  | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | AUNGYM                                                                 | Assign Date                  | 31/01/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                        |                              |            |                                                                                     |
| Make & Model                                                                                                                                                                           | TOYOTA PRIUS HYBRID 1.8                                                | c.c                          | 1797       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                 | Year of Reg.                 | 2014       |                                                                                     |
| Chassis No.                                                                                                                                                                            | ZVW301840455                                                           | Colour                       | BROWN      |                                                                                     |
| Odometer                                                                                                                                                                               | 369233                                                                 | Steering                     | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                               | Modification                 | NIL        |                                                                                     |
| General                                                                                                                                                                                | FAIR                                                                   |                              |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                        |                              |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                   | Make                         | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 185/65 R15                                                             | WEST LAKE                    | 5 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 185/65 R15                                                             | WEST LAKE                    | 5 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 185/65 R15                                                             | WEST LAKE                    | 5 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 185/65 R15                                                             | WEST LAKE                    | 5 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                        |                              |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                        |                              |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                        |                              |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 24/01/2018                                                             | Inspection Date              | 06/02/2018 |                                                                                     |
| Survey held at                                                                                                                                                                         | PRIME AUTO CLAIMS SERVICE PTE LTD<br>6 BENOI PLACE<br>SINGAPORE 629927 |                              |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                        |                              |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                        |                              |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                        |                              |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                        | 2 Working Days               |            |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2040E

| Qty                                                                         | Description of Parts                                                                                                                                                        | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                                                                                                                                                                             |             |                           |                   |
| 1                                                                           | FRONT BUMPER                                                                                                                                                                | DEFORMED    | 1,230.00                  | 1,230.00          |
| 1                                                                           | FRONT BUMPER LOWER GRILLE                                                                                                                                                   | SERVICEABLE | 320.85                    | -                 |
| 1                                                                           | FRONT BUMPER LOWER GARNISH                                                                                                                                                  | SERVICEABLE | 158.31                    | -                 |
| 1                                                                           | FRONT BUMPER RIGHT LAMP                                                                                                                                                     | SERVICEABLE | 152.00                    | -                 |
|                                                                             | LESS 25% DISCOUNT                                                                                                                                                           |             | -465.29                   | -307.50           |
|                                                                             |                                                                                                                                                                             |             | 1,395.87                  | 922.50            |
| <b>LABOUR</b>                                                               |                                                                                                                                                                             |             |                           |                   |
|                                                                             | TO REMOVE FRONT BUMPER, REAR BUMPER LOWER GRILLE & FRONT BUMPER RIGHT LAMP. REPLACE FRONT BUMPER, FRONT BUMPER RIGHT LAMP & THE ABOVE PARTS. ALIGN AND ADJUST FRONT BUMPER. |             | 500.00                    | 250.00            |
|                                                                             | TO PUTTY, RESPRAY PAINTING FRONT BUMPER. TO POLISH.                                                                                                                         |             | 550.00                    | 200.00            |
|                                                                             |                                                                                                                                                                             |             | 1,050.00                  | 450.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                             |             | <b>2,445.87</b>           | <b>1,372.50</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                             |             |                           | <b>1,100.00</b>   |

Report Ref No. CS/FCI18001881/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.