

Surveyor

ASSIGNMENT (Office)

Merimen

From (Person):

Elaine Ngu

of

MSG

Date/Time

31/1/18 @ 11:33am

Estimated Cost:

Bill by

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 4939A

Insured:

SGA6150Y

at Workshop m/s

Cheng Hoe Motor

Tel:

6481 2001

of 10, AMK Ind. Prk 2A # 01-04

Policy No:

27388584 DMV

Claim No:

547825

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/01/2018

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

12:48pm @ 31/1/18

Person Contacted:

Dorilyn

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKU 4939A - X

SGA 6150Y - X

1/3/18

Send preli revised by merimen

29/3

@ 1345.44 Ca from E Ltd (Red 142.48, 10/1)

ASS. REC. BY:

REF: *mb**Kenneth*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *Chy 1/10*

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *02* days Res.: Yes or NoLum Sum: *1.31* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKU4839A* Yr Regn: *07 15*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: *Honda Jazz* c.c. *1498*Colour: *M. Grey* A/C: Insured / Std / NI / NASp. Reading: *31493* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTM GK 5850 FX 203550*Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: *185/55R16*

R: _____

BS / *DUN* / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. *3* mm R/Bal. *5* mmL/Bal. *3* mm L/Bal. *3* mmD.O.A. *28/1/18* D.O.I. *27/2/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/2 Rn post to Catherine

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) *2/4 = typist*

Report Format:

Lump Sum / I.B.I. (\$) *merimen**1345.44*Days Of Repair: *2*Resurvey No. of Trip: *1*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

*200**10**210*

RECEIVED 02 APR 2018

2/4/2018

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/800/884/Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 31/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001884/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 31-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGA 6150Y	Veh. Inspected	SKU 4939A	
Policy No.	27388584DMV	Coverage (\$)	0.00	
Claim No.	547825	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/01/2018	Inspection Date		
Survey held at	CHENG HOE MOTOR SERVICE 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT . SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jan 2018		31 Jan 2018 11:33 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOK YEW MENG , ID: S0002942D, Tel: +6596851386		
Main Claimant:	NG PUI TJU , ID: S7073710H		
Vehicle Reg. No.:	SKU4939A	Date of Loss:	26/01/2018 14:00 - :59
Claim Type:	TP / 547825	Policy/Cover Note No.:	27388584DMV (Comprehensive) Coverage: 24/11/2017 - 23/11/2018
Vehicle Reg. No. (Insured):	SGA6150Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2018]		
Driver/Custodian (Insured):	MOK MEI FENG () , NRIC: S8418024F, Tel: +6597454404		
Adj Asg. Remarks:	PLS CONTACT WORKSHOP BEFORE GOING DOWN AS THEY NEED ARRANGE CAR IN.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Elaine Ngu Siau Mei	Date:	01 Mar 2018
<u>Preliminary Advice</u>			

Insured Vehicle No	: SGA6150Y	Accident Date	: 26/01/2018
TP Vehicle No	: SKU4939A	Assignment Date	: 31/01/2018
Make	: HONDA JAZZ	Est. Duration of Repair	: 2.00
Date of Inspection	: 27/02/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,487.92
Revised Amount	:S\$	1,345.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,345.44
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3710H
Vehicle Details	
Vehicle No.:	SKU4939A
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B31000627
Chassis No.:	JHMGK5850FX203550
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$14,574.00
Original Registration Date:	30 Jul 2015
First Registration Date:	30 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$9,574.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2025
PARF Rebate Amount:	\$7,180.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$43,993.00
Total Rebate Amount:	\$51,173.00

The information contained herein is correct as at 30 Jan 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO.201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

ATTN: Motor Claim Department

FAX: 62257402

Estimate No: ES1890174/AMK

Date: 26 Feb 2018

Policy No: D17MTPV01010720

Veh Reg No: SKU4939A

Make/Model: HONDA JAZZ 1.5 VTIR
 CVT A

Chassis No: JHMGK5850FX203550

Engine No: L15B31000627

Reg. Date: 30/07/2015

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 26/01/2018

TP Veh Reg No: SGA6150Y

Estimate Repair Cost to Vehicle No :SKU4939A

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER RH SIDE RETAINER	15.60	1 PC	15.60	✓
2 REAR BUMPER CLIP	3.90	4 PC	15.60	X
3 REAR RH RIM 16"	828.70	1 PC	828.70	✓
			859.90	
		Less 20%	171.98	687.92
Labour				
4 REMOVE & REFIX REAR BUMPER:KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	300.00	1 LA	300.00	250
5 PUTTY & RESPRAY REAR BUMPER,REAR RH FENDER & ALL AFFECTED AREAS	450.00	1 LA	450.00	400
6 REMOVE & REFIX REAR RH RIM,TYRE & BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	20
			800.00	800.00
Total				SS 1,487.92
Add GST @ 7%				104.15
Total Amount Payable				SS 1,592.07

VEHICLE LYING AT:
 NO.10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL : 64812001

LKK Auto Consultants hence notify
 the Repairer of the following: For Cheng Hoe Motor Pte Ltd

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

DORLYN LI

AUTHORISED SIGNATURE

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001884/KVD3N2

Date: 04/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27388584DMV
Claimant Vehicle No :	SKU4939A	Insured Vehicle No :	SGA6150Y
Date of Loss:	26/01/2018	Nature of Claim:	TP
		Claim No:	547825

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU4939A		
Make & Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Engine No:	L15B31000627
Reg. Date:	30/07/2015 (Man. Year: 2015)	Chassis No:	JHMGK5850FX203550
Colour:	Metallic Grey	Odometer:	31493 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	687.92	675.44	12.48	1.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	670.00	130.00	16.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,487.92	1,345.44	142.48	9.58
+ GST 7.00/7.00% (S\$)	104.15	94.18	9.97	9.57
Nett Amount (S\$)	1,592.07	1,439.62	152.45	9.58

INSPECTION

Date of Assignment:	31/01/2018	
Date Inspected:	27/02/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2018)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU4939A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER RH SIDE RETAINER	Distorted	15.60 FL	*15.60 FL
2	4		*REAR BUMPER CLIP	Not Necessary	15.60 FL	*- FL
3	1		*REAR RH RIM 16	Dented/Scratched	828.70 FL	*828.70 FL
Sub Total (\$\$)					859.90	844.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					171.98	168.86
Total Parts (\$\$)					687.92	675.44

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER,KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	New	300.00	250.00
2	PUTTY & RESPRAY REAR BUMPER,REAR RH FENDER & ALL AFFECTED AREAS	New	450.00	400.00
3	REMOVE & REFIX REAR RH RIM,TYRE & BALANCE & REALIGN THE SAME	New	50.00	20.00
Gross Labour Cost (\$\$)			800.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >