

ASS. REC. BY: Tau fikh REF: CS/FCI18001886/T19d3n2
 Surveyor: CWS ASSIGNMENT (Office)
 From (Person): Eileen Lee of FCI Date/Time: 31/1/18 @ 9:36am
 Estimated Cost: _____ Bill to: _____
 OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SHD 1133C Insured: SHD 6818C
 at Workshop no: Komoco Tel: 6475 0123
 of 253 Alexandra Rd
 Policy No: D-18088936MFSH Claim No: D18000898MFSH
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 28/01/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____
 Date/Time: 10:13am @ 31/1/18 Person Contacted: Gary Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 1133C - CC4/AIG13000673/H1st 2y	D.O.A: 03/01/2013
	SHD 6818C - CC1/AXA16005402/H/wb 3y2	D.O.A: 20/03/2016
<u>01/2/18 @ 3:44pm</u>	<u>revised to Eileen Lee by email.</u>	

6/2/2017

Tan Jiah

REF:

FCL

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT
 Edited

Veh No: SHC1133C 2017 Jan.
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai 130 CC 1582
 Colour: Silver A/C Insured / Std / NI / NA
 So Reading: 84981 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: +M AD2814VHJ117506
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 77

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 31/1/80/1645
 Survey held at Komodo
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

92932-13, 4 days - e-mail to Goh. (Red \$1196.88, 29%)

RECEIVED 04 MAY 2018

Date/Time, File Pass to? ☐ : Preli. Report

11/04/15 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee

Transportation

1. S-RS \$

Phone

Cost

Cost

Cost

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Insp \$

☐

Week-end \$

Report Format:

Lump Sum / I.B.I. \$

7P
2932.13

135
50
50
36
271



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001886/T1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6818C	Veh. Inspected	SHD 1133C
Policy No.		Coverage (\$)	0.00
Claim No.	D18000898MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/01/2018	Inspection Date	31/01/2018
Survey held at	KOMOCO MOTORCYCLES PTE LTD 253 ALEXANDRA ROAD #01-04 SINGAPORE 159936		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date 30-01-2018 Our Ref No. D18000898MFSH

Accident Date 28-01-2018 Claim Type. Third Party

Insured Vehicle SHD6818C Third Party Vehicle. SHD1133C

Survey Location 23 CHANGI SOUTH AVENUE 2 #03-02

Contact Person. GARY SHI

Contact No. 62148880/ 65446671 Fax No. 62141511

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA Fax No. 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop PREMIER AUTOMOTIVE SERVICES PTE LTD Attention. NIL

Cc : TP Solicitor NA TP Solicitor Fax No. NA

Officer Incharge EILEEN LEE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234459)



PRI Documents



Close



PRI Header Details

Claim No	D18000898MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446671 , Phone: 62148880 , Fax: 62141511 EmailId: GARY.SHI@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6818C	TP Vehicle No	SHD1133C
PRI Recieved Date	30-01-2018 03:54:35 PM	Surveyor Appointed Date	31-01-2018 09:35:10 AM	Surveyor Accept Date	31-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	31-01-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 February 2018 3:44 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000898MFSH/1
Attachments: CSFCI18001886T1qd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHD 1133C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 31 January 2018 10:14 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000898MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 31 January 2018 9:36 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000898MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000898MFSH

Date: 01 Febuary 2018

Our Ref: CS/FCI18001886/T1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1133C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/01/2018 at the premises of M/s KOMOCO, and have the following to report:-

Workshop Estimate Amount	: S\$ 4,129.01 .
Revised Estimate Amount	: S\$ 2,216.26 .
"Check" Items Amount	: S\$ 1,209.23 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Jan-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1133 C

1 pc	Tailgate lower garnish	\$	362.61	cha
1 pc	Emblem I30	\$	27.80	all ✓
1 pc	Emblem CRDI	\$	29.40	all ✓
1 pc	Emblem Hyundai	\$	29.40	all ✓
1 pc	Rear bumper	\$	811.11	cha ✓
1 pc	Rear bumper sponge	\$	79.20	X n ✓
1 pc	Rear bumper reinforcement	\$	815.64	? ht ✓
1 pc	Rear bumper reinforcement centre	\$	79.20	? de ✓
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40	X n ✓
		\$	2,338.76	2155.16
Less 20%		\$	467.75	
		\$	1,871.01	1724.13

S/NETT

1 set	Rear bumper clips	\$	48.00	all ✓
1 set	Reverse sensor	\$	280.00	200 X n ✓
1 set	Tailgate sticker	\$	100.00	all ✓

Sundry

To dismantle and replace reverse sensor and test system

\$ nec 50.00 20
\$ 80.00 40.

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate, etc

\$ 700.00 400

To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel

\$ 850.00 600.

To apply rustproofing on the repaired and replaced panels

\$ 150.00 30 X n ✓

Total \$ 4,129.01 1208

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) on the repair
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification or alteration
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- (ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
- THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer

Signature:

Date:



Taufik 97495749
WP
Resurvey before paint
4 days
31/1/18 @ 1645.
sur@lkkauto.com
taufik@lkkauto.com

1724.13
1208
2932.13
4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001886/T1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6818C	Veh. Inspected	SHD 1133C	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000898MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ117506	Colour	SILVER	
Odometer	84981	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2018	Inspection Date	31/01/2018	
Survey held at	KOMOCO MOTORCYCLES PTE LTD 253 ALEXANDRA ROAD #01-04 SINGAPORE 159936			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1133C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LOWER GARNISH	CRACKED	362.61	362.61
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NECESSARY	29.40	29.40
1	REAR BUMPER	CRACKED	811.11	811.11
1	REAR BUMPER SPONGE	NOT NECESSARY	79.20	-
1	REAR BUMPER REINFORCEMENT	BENT	815.64	815.64
1	REAR BUMPER REINFORCEMENT CENTRE	DEFORMED	79.20	79.20
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20	NOT NECESSARY	104.40	-
	LESS 20% DISCOUNT		-467.75	-431.03
			1,871.01	1,724.13
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET TAILGATE STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			478.00	168.00
LABOUR				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	40.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE OF THE END PANEL,TAILGATE,ETC.		700.00	400.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,TAILGATE,TAILGATE LOWER GARNISH,END PANEL.		850.00	600.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			1,780.00	1,040.00
GRAND TOTAL			4,129.01	2,932.13



RECOMMENDED COST OF REPAIRS			2,932.13
-----------------------------	--	--	----------

Report Ref No. CS/FC18001886/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.