

22/03/2002

ASS. REC. BY:

REF: CS3 / AT 18001888 / Gbez

Special Instruction:

DAR 4 days

m k m

SUPERVISOR:

GQ

ASSIGNMENT (Office)

From (Person): NOOR Maresa

of ALH

Date/Time: 30/02/2018 4:29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AT 81Z

Insured:

SKW 68353

at Workshop m/s

Lightning Bike

Tel:

98513760

of

257A 3th Besar

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09-12-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

01-02-2018

H.O.D. Endorsement:

Date/Time: 30/02/2018 7:26pm

Person Contacted:

Muhammad

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	AT 81Z - NA / msh17023423 / h4
	SKW 68353 - X

DCA: 09/12/2017

PRS *XPR*

ALG

6/2/18

A7818

G

Business Car

20 TO WS TRPS/CO RES EVALUATION

TO PASS/STAY

STAY/STAY

257A Jalan Besar, 208931

NAME

REG NO

Damage No

STAY/STAY


Excess

Driver Name Muhammad @ 98518760

Vehicle No

Policy Condition

Remarks: The ven had commenced its repair at the time of inspection



STAY/STAY

OAD Accident Report Consistent? Yes or No

OAD Rep Seen Consistent? Yes or No

Est Repair 3 days Rep Yes or No

Est Cost Rep Yes or No

CL REP REP 24HRS Wp

Date Person Contacted Vehicle IN/OUT

Date Time Action Instruction

13/4 Submit DAR report

RECEIVED 13 APR 2018

Costs Refused

☐ Prelim Report
☐ Final Report

Prelim Report

Final Report

Costs Paid/Refused

Days Of Repair 3

Resurvey No of Trip

Surf Rep
of vehicle

A

Add Fee

☐ One day
☐ Two day
☐ Three day
☐ Four day
☐ Five day
☐ Six day
☐ Seven day
☐ Eight day
☐ Nine day
☐ Ten day

Repair Form

DAR

Costs Paid/Refused

Honda VFR 800 782
Red
80598

Engine

Crank

Gen Drive G Pen Root Burnt

Steering Rod G Jammed Leaked Burnt

Brake G Jammed Leaked Burnt

Mod G GEN STD AIR

Tyre Size

120/70ZR17

190/55ZR17

BS ZUL EXNOVA GH PS L24 MOTO HTSU PRISUM

TOYO/YOKO

Front

Rear

PSA

5

PSA

5

LSA

LSA

DOA

DOA

Surf Repair

w/s

06-02-18
6pm

Des of Damages At Yes or No

Yes

and

No

UC

Refused

Tha L/C Chassis Frame Body Structure affected quest to R/R

120

20

200

Catherine Chong (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Tuesday, 30 January, 2018 4:29 PM
To: 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: AIGENCRYPT - Pre repair inspection request - AT81Z VS SKW6835S (OI) DOA 09/12/2017
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW68... (62.7 KB); Fax92A9.tif

Hi,

Please refer to the enclosed request from **HOH Law Corporation**

Claim no : 0239367313SG003
Case Owner : Jaclyn Kesaval

If you have any queries/concerns, please let us know.
Kindly assist to assign Mr. Steven Foong as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services
AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

HOH 何进才律师馆

LAW CORPORATION

COMPANY REGISTRATION NO: 200302898Z
 ADVOCATES & SOLICITORS
 NOTARIES PUBLIC
 COMMISSIONERS FOR OATHS
 TRADE MARK AGENTS

BLK 209 #04-631
 NEW UPPER CHANGI ROAD
 SINGAPORE 460209

DIRECTORS

HOH CHRI CHA
 N SRINIVASAN

ASSOCIATE DIRECTORS

SHANKER KUMAR K
 NEO KEE HENG MARGARET
 HAN MEAN JUAN MICHAEL

ASSOCIATES

CHAI LI AILEEN
 JOSEPH K DOOSH

TEOH SECK WEI

TAN JIANHONG JOSEPH

NEO JIE MH JAMIE

LAM YI WEN RACHEL

KEYAN CHOO YI QI

何进才
 万雄

山查
 梁新登
 陈天元

胡文初
 欧秀

陈建宏

邱嘉敏

林依文

李瑞兴

CHAI MOON WEI

YEOW TIN TIN MARGARET
 BELINDER KAUR NJAR
 HARVINDARJIT SINGH BATH

LEE TZUN-TZEN
 PANG KISH WEE

VM VIOTHIYA

JOEL HENG ZHEN YUAN

HO KIN OMN

JEANNA LOE YUQING

蔡甘霖

姚玲玲
 阮思廷

蔡文

李俊贤
 彭翔为

陈洁霞

王荣清

何宜安

刘瑞晴

TEL : 6244 5755
 FAX : 6244 3052

WRITER DID : 6244 5762
 SECRETARY DID : 6244 5754

WRITER EMAIL : ho_ko@hoh.com.sg
 E-MAIL : bedok@hoh.com.sg
 WEBSITE : www.hoh.com.sg

Please send all correspondences, documents and facsimile transmissions to the abovementioned Office. Facsimile numbers are not for service of Court documents.

Our Ref: MH/ZA/20180040050PI/gl
 Your Ref: SKW 6835 S

30 January 2018

M/s AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16
 Singapore 079120

BY FAX (6835 7416) & POST

Attention: Motor Claims Department

Dear Sirs,

**PERSONAL INJURY - ACCIDENT ON KITCHENER ROAD & VERDUN ROAD JUNCTION
 INVLG AT 81 Z & SKW 6835 S**

We refer to the above matter.

We act for the owner of vehicle no. AT 81 Z, Muhammad S/o Mansoor Hallaj who has appointed the undermentioned workshop to repair his motor vehicle no. AT 81 Z.

Please be informed that the said vehicle can be inspected at:

M/s Lightning Bike Pte Ltd
 257A Jalan Besar
 Singapore 208931

Contact person: Muhammad S/o Mansoor Hallaj (Handphone No. 9851 8760)

If you fail to conduct the pre-repair inspection within the next (2) working days excluding Saturday, Sunday or Public Holiday, our client shall instruct the above workshop to commence repairs thereafter without further reference to you.

Yours faithfully

HOH LAW CORPORATION

Motorcycle

NAC	INC	Item	CON	ACC	Qty
10001	991886	Front Number Plate			
10001	995065	Front Tyre			
3002	995095	Front Rim	SCR	✓	
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	SCR	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield	CRK	✓	
3018	992134	Front Wing Mirror	CRK	✓	
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone			
3030	992299	Handle Bar			
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH	DM	✓	
3034	992300	Handle Bar Balancer RH			
3035	992179	Fuel Tank			
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever	DM	✓	
3038	992293	Hand Brake Lever			
3039	991119	Side Fairing	CUT	✓	
3040	994220	Side Fairing Top Garnish	SCR	✓	
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield			
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
3046	993378	Rear Fairing			
3047	991121	Fairing Stopper	CUT	✓	
3048	991117	Fairing Lower			

Vehicle No: AT 81 Z

[illegible]

No of Items

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2018 Edit Reg		30 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	FOO SAY PHANG, ID: S1271831D		
Main Claimant:	MUHAMMAD S/O MANSOOR HALLAJ		
Vehicle Reg. No.:	AT81Z	Date of Loss:	09/12/2017 00:00 - :59
Claim Type:	TP / 0239367313SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKW6835S	Policy No. (Claimant):	
		Excess:	
Repairer:	Lightning Bike Pte Ltd (HQ) 257A Jalan Besar, 208931 Jalan Besar - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/04/2018]		
Claimant's Solicitor:	HOH LAW CORPORATION - Tel: 62445755		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (04/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*AT81Z (0239367313SG)
[SKW6835S]
TP
MUHAMMAD S/O MANSOOR HALLAJ
Dec 9 2017 12:00AM
[FOO SAY PHANG]
Lightning Bike Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	13/04/18 09:41	General View											Load JPG	☒		
2	13/04/18 09:41	General View											Load JPG	☒		
3	13/04/18 09:41	General View											Load JPG	☒		
4	13/04/18 09:41	General View											Load JPG	☒		
5	13/04/18 09:41	General View											Load JPG	☒		
6	13/04/18 09:41	General View											Load JPG	☒		
7	13/04/18 09:41	General View											Load JPG	☒		
8	13/04/18 09:41	General View											Load JPG	☒		
9	13/04/18 09:41	General View											Load JPG	☒		
10	13/04/18 09:41	General View											Load JPG	☒		
11	13/04/18 09:41	General View											Load JPG	☒		
12	13/04/18 09:41	General View											Load JPG	☒		
13	13/04/18 09:41	General View											Load JPG	☒		
14	13/04/18 09:41	General View											Load JPG	☒		
15	13/04/18 09:41	General View											Load JPG	☒		
16	13/04/18 09:41	General View											Load JPG	☒		
17	13/04/18 09:41	General View											Load JPG	☒		
18	13/04/18 09:41	General View											Load JPG	☒		
19	13/04/18 09:41	General View											Load JPG	☒		
20	13/04/18 09:41	General View											Load JPG	☒		
21	13/04/18 09:41	General View											Load JPG	☒		
22	13/04/18 09:41	General View											Load JPG	☒		
23	13/04/18 09:41	General View											Load JPG	☒		
24	13/04/18 09:41	General View											Load JPG	☒		
25	13/04/18 09:41	General View											Load JPG	☒		
26	13/04/18 09:41	General View											Load JPG	☒		
27	13/04/18 09:41	General View											Load JPG	☒		
28	13/04/18 09:41	General View											Load JPG	☒		
29	13/04/18 09:41	General View											Load JPG	☒		
30	13/04/18 09:41	General View											Load JPG	☒		
31	13/04/18 09:41	General View											Load JPG	☒		
32	13/04/18 09:41	General View											Load JPG	☒		
33	13/04/18 09:41	General View											Load JPG	☒		
34	13/04/18 09:41	General View											Load JPG	☒		
35	13/04/18 09:41	General View											Load JPG	☒		
36	13/04/18 09:41	General View											Load JPG	☒		
37	13/04/18 09:41	General View											Load JPG	☒		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/04/18 09:41	General View	 Load JPG	☒
39	13/04/18 09:41	General View	 Load JPG	☒
40	13/04/18 09:41	General View	 Load JPG	☒
41	13/04/18 09:41	General View	 Load JPG	☒
42	13/04/18 09:41	General View	 Load JPG	☒
43	13/04/18 09:41	General View	 Load JPG	☒
44	13/04/18 09:41	General View	 Load JPG	☒
45	13/04/18 09:41	General View	 Load JPG	☒
46	13/04/18 09:41	General View	 Load JPG	☒
47	13/04/18 09:41	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 12:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18001888/GBE2

Date: 16/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle
No : AT81Z

Insured Vehicle No : SKW6835S

Date of Loss: 09/12/2017

Nature of Claim: TP

Claim No: 0239367313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: AT81Z

Make & Model: HONDA VFR800, 782cc

Reg. Date: (Man. Year:)

Colour: Red

Engine Capacity: 782 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: HIDDEN

Odometer: 80598 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17

Rear Tyre Size: 190/55Z R17

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2018

Date Inspected: 06/02/2018

Inspected At:

Lightning Bike Pte Ltd (HQ)
257A Jalan Besar
Singapore 208931

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Scratched	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
3	1		*FRONT WINDSHIELD	Cracked	0.00 F	*- F
4	1		*FRONT WING MIRROR	Cracked	0.00 F	*- F
5	1		*HANDLE BAR BALANCER LH	Damaged	0.00 F	*- F
6	1		*CLUTCH LEVER	Damaged	0.00 F	*- F
7	1		*SIDE FAIRING	Cut	0.00 F	*- F
8	1		*SIDE FAIRING TOP GARNISH	Scratched	0.00 F	*- F
9	1		*FAIRING STOPPER	Cut	0.00 F	*- F
10	1		*FRONT FOOT REST	Damaged	0.00 F	*- F
11	1		*REAR FOOT REST BRACKET	Dented	0.00 F	*- F
12	1		*REAR FENDER WHEEL GUARD	Scratched	0.00 F	*- F
13	1		*REAR SUB FRAME	Scratched	0.00 F	*- F
14	1		*SIDE BOX	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >