

ASS. REC. BY

REF: CS/MSG18601889/Kvd3n2

Merimen

Kenneth

ASSIGNMENT (Office)

From (Person)

Irene Tan

MSIG

31/1/18 @ 9:19pm

Estimated Cost

Est. No.

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SHC 5588C

Insured

SLH 5352S

at Workshop no.

Trans-Cab

Tel

62130993

of

No. 2 AMK str 63

Policy No.

28851283AVW

Claim No.

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

26/01/2018

CA / REV / REP. / REV 24 HRS

1wp

NO. Of Endorsement

Date/Time

9:21am @ 31/1/18

Person Contacted

jiang how

Vehicle

OUT

Date/Time

Action/Instruction (✓ Estimate)

SHC 5588C - CS/AWA/6013140/Kvbco

D.O.A: 12/07/2016

SLH 53

1/2/18

Send preli revised by merimen

MSIG

31/1/18

SHC 5588C

09 14

Estimated Cost

COFFERS COFFERS COFFERS COFFERS

SHC 5588C
Trans - Cab

Make

Model

Policy No

Damage

Sum Insured

Excess

Client's Record

Make of Van

Policy Condition

Remark: The van had commenced its
repair at the time of inspection.



Body or Market Value

QAC Accident Report Consistent? Yes or No

QAC PP Report Consistent? Yes or No

Est Repair 02 days Res Yes or No

Est Sum 1.5.1 Res Yes or No

QAC REV REP 24 HRS ^{up}

Date Person Contacted

Vehicle IN/OUT

Make Model Year Color

Make Model

Make Renault Latitude 1995

Color M. White / Red

So. Reseng 351272

Engine

QAC VI-1 ABC 15 AUC 279380

Gear Done Good / Bad / Poor / Burnt

Steering Inspected Jammed / Leaked / Burnt

Brake Inspected Jammed / Leaked / Burnt

Mod C SRM STD A/RM

Tyre Size Citi 215/60R16

Westlake

BS/DUN/EXNOVA/GR/FS/LDA/MIC/CHTSU/PR/SUM

TOYO/YOKO

Front

R.Ba. 8 mm

L.Ba. 8 mm

D.O.A. 26/1/18

Survey report

Rear

R.Ba. 9 mm

L.Ba. 9 mm

D.O.A. 31/1/18

Deal of Damages Fr. Rear O/S N/S U/C Roaches

o/s Area

The U/C Chassis frame Body Structural affected due to collision

Date Time Action Instruction

1/2 M4 pass to Catherine
5 500t \$ 700 (Red 33, 701.66, 979)

RECEIVED 02 FEB 2018

One Time Repairs



Prel. Report

Days Of Repair 2



Final Report

Resurvey No. of Trip 1

One Time Repairs

1p - typist

Add Fee



Site Fee \$



Travel Fee \$



Labour Fee \$



Material Fee \$

Repair Fee

mer, men

Comp Sum

101: \$ 700p

Survey Fee

Transport

Labour

Material

Other

Total

300

10

310

Survey Department Check List (Case Handler)

Reference No.: CS | MSG 1800 1889 | Kvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON | 12/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001889/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 31-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLH 5352S	Veh. Inspected	SHC 5588C
Policy No.	28851283AVW	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/01/2018	Inspection Date	31/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2018		31 Jan 2018 09:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HAMZAH BIN ABDULLAH TALIB, ID: S1135557I		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5588C	Date of Loss:	26/01/2018 22:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28851283AVW (Comprehensive)
Vehicle Reg. No. (Insured):	SLH5352S	Policy No. (Claimant):	Coverage: 08/11/2017 - 07/11/2018
		Excess:	S\$2,000.00
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 01 Feb 2018

Preliminary Advice

Insured Vehicle No	: SLH5352S	Accident Date	: 26/01/2018
TP Vehicle No	: SHC5588C	Assignment Date	: 31/01/2018
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 2.00
Date of Inspection	: 31/01/2018		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,401.66
Revised Amount	:S\$	700.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	700.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5588C
Vehicle to be Exported:	Yes
Intended De-registration Date:	29 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001926
Chassis No.:	VF1ABL15AUC279380
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$29,577.00
Total Rebate Amount:	\$38,950.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 10:12
Date Of Accident	26/01/2018 22:55
Exact Location Of Accident	CTE (ANG MO KIO AVENUE 5)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5588C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM DAT MING
NRIC No	S1310510C
Date Of Birth	21/06/1958
Occupation	OUTDOOR
Date Of Driving Pass	02/04/1979
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97610497
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 145 SERANGOON NORTH AVENUE 1 #03-381
Postcode	550145
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 108 SERANGOON NORTH AVENUE 1 #01-709 , POSTCODE: 550108 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2849999 - FAX NO: 63431742
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180127/2071

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH5352S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

CTE

(Ang Mo Kio Avenue 5)

A: SMC 888

B: SMC 525

1 2 3 4 5

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GLARMC SketchPlanForm_V3

2

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180127/2071

1 of 3

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

Report No. T/20180127/2071

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/01/2018 13:35	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: LIM DAT MING		Address: APT BLK 145 SERANGOON NORTH AVENUE 1 #03-381 SINGAPORE 550145	
ID Type / ID No.: NRIC NO / S1310510C		Contact No.: Home/Office: Mobile: 97610497	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 59	Date of Birth: 21/06/1958	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

Serangoon North NPP
Blk 108 Serangoon North Ave 1
#01-709 Singapore 550108
Tel: 1800 284 9999

General Information of the Accident			
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 2255hrs 26/01/2018 40:55
Location: Along Road 1 CENTRAL EXPRESSWAY		Type of Location: Flyover	
Merging lane coming in from Ang Mo Kio Avenue 5			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction		Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHC5588C	Car				Slightly Damaged	1
SLH5362	Car		SN 154		No Damage	0



Signature: _____

Singapore Police Force



SINGAPORE
POLICE FORCE



T/20180127/2071

2 of 3

Report No. T/20180127/2071

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

CONTINUATION OF REPORT

Brief Details.

On the 26/01/2018 at about 2255 hrs, I was driving my cab (SHC5588C) along Ang Mo Kio 5 up to Central Expressway. During the merging lane at the Expressway, a car SLH5352C came from my rear right and hit onto the right rear of my car, causing scratches. I signaled to the driver asking him to stop his vehicle however, he did not do so and thus, I decided to follow him up to Seletar Country Club, where I stopped him but however, he refused to give me his particulars. I wish to state that during the incident no one is injured and no ambulance nor traffic police attended to me and also, I have an in car camera with me. I am thus lodging this report for my company action and also for my insurance purpose.



**SINGAPORE
POLICE FORCE**



T/20180127/2071

3 of 3

Report No. T/20180127/2071

Police Station Of Origin:
Serangoon North NPP
108 Serangoon North Ave 1 #01-709
SINGAPORE 550108
Tel No: 1800-2849999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 KOO LAY SIONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
27/01/2018 13:35

Officer In Charge Of Case:

TP / HRT /

SSI 2 SOH PENG SUI

Contact No.: 6547617

Classification Of Case:

SN 154

Authentication Stamp

NP168



Signature: _____
Singapore Police Force

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB5588C -**AAD1801-295***Not Authorized*
6500

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5588C - CANDY

VF1ABL15AUC279380

RENAULT

LATITUDE

26.01.2018

MSIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	Sn 1,108.46
2	1	BUMPER LOWER REAR	\$	Sn 768.84
3	1	BUMPER BRACKET CTR REAR	\$	Sn 113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn 135.97
5	1	BUMEPR RETAINER RH REAR	\$	Sn 44.99
6	1	BUMPER REFLECTOR RH	\$	Sn 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn 135.97
8	1	BUMEPR RETAINER LH REAR	\$	Sn 44.99
9	1	ROCKER PANEL OUTER RH	\$	N 987.49
10	1	FENDER PANEL REAR RH	\$	N 3,299.13
11	1	WHEELARCH REAR RH	\$	Sn 543.47
12	1	TAILLAMP RH	\$	Sn 552.55
13	1	TAILLAMP PANEL RH	\$	N 986.70
14	1	EXHAUST REAR	\$	N 7,489.05
15	1	EXHAUST CAP REAR	\$	N 230.49
16	1	DOOR PANEL REAR RH	\$	N 2,844.66
17	1	DOOR GUIDE REAR RH	\$	Sn 176.82
18	1	DOOR HINGE UPPER RH	\$	N 274.50
19	1	DOOR HINGE LOWER RH	\$	N 300.55
20	1	DOOR CHECK REAR RH	\$	Sn 203.06
21	1	DOOR LOCK REAR RH	\$	N 908.75
22	1	DOOR GRAB HANDLE REAR RH	\$	Sn 210.96
23	1	DOOR HANDLE OUTER REAR RH	\$	Sn 126.49
24	1	DOOR HANDLE CAP REAR RH	\$	Sn 35.52
25	1	DOOR HANDLE SEAL REAR RH	\$	Sn 7.89
26	1	DOOR HANDLE COVER REAR RH	\$	Sn 13.22
27	1	DOOR HANDLE MODULE REAR RH	\$	Sn 133.60
28	1	DOOR FINISHER REAR RH	\$	Sn 423.10
29	1	DOOR WHEATHESTRIIP REAR RH	\$	Sn 410.66
30	1	DOOR SEAL REAR RH	\$	Sn 162.02
31	1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn 334.69
32	1	DOOR MOULDING REAR RH	\$	Sn 176.82
33	1	DOOR PANEL FRT RH	\$	N 2,844.66

X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-295

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB5588C -

TOTAL	\$	26,073.16
10%	\$	2,607.32
	\$	23,465.84

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	Nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	Nn	33.00	
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	Nn	10.00	
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	Nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	Nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	Nn	66.00	
8	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	
9	1	TAILLAMP CLIP RH	\$	Nn	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	Nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	Nn	80.00	
12	1	WINDSCREEN MOULDING	\$	Sn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Nn	100.00	
14	1	CAP HUB RH RR	\$	Sn	35.00	
15	1	RIM RH RR	\$	Sn	385.00	
16	1	TYRE RH RR	\$	Sn	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	Nn	80.00	
18	1	DOOR STICKER "Classic"	\$	Nn	30.00	
19	1	DOOR STICKER "6555-3333"	\$	Nn	80.00	

TOTAL	\$	2,225.82
TOTAL PARTS	\$	25,691.66

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
To reinstall rear bumper parking sensor.	\$	Nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	Nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	Nn 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-295**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB5588C -

To repair and realign rear exhaust pipe.	\$	~ 170.00 X
Towing Fees	\$	~ 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X

TOTAL	\$	7,710.00
Over All Total	\$	33,401.66

(PARTS BY PARTS)**Repair Days****10 Days**
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001889/KVD3N2

Date: 06/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28851283AVW
Claimant Vehicle No :	SHC5588C	Insured Vehicle No :	SLH5352S
Date of Loss:	26/01/2018	Nature of Claim:	TP
		Claim No:	548230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5588C	Engine No:	M9R8839C001926
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC279380
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	351272 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,691.65	60.00	25,631.65	99.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	640.00	7,070.00	91.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,401.65	700.00	32,701.65	97.90
+ GST 7.00/7.00% (S\$)	2,338.12	49.00	2,289.12	97.90
Nett Amount (S\$)	35,739.77	749.00	34,990.77	97.90

INSPECTION

Date of Assignment:	31/01/2018	Inspected At:	Trans-cab Auto Services Pte Ltd
Date Inspected:	31/01/2018		No 2 Ang Mo Kio Street 63
			Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2018)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5588C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Serviceable	1,108.46 FL	*- FL
2	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*ROCKER PANEL OUTER RH	Repair	987.49 FL	*- FL
10	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
11	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
12	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
13	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
14	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
15	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
16	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
17	1		*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*- FL
18	1		*DOOR HINGE UPPER RH	Repair	274.50 FL	*- FL
19	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
20	1		*DOOR CHECK REAR RH	Serviceable	203.06 FL	*- FL
21	1		*DOOR LOCK REAR RH	Repair	908.75 FL	*- FL
22	1		*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*- FL
23	1		*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*- FL
24	1		*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*- FL
25	1		*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*- FL
26	1		*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*- FL
27	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*- FL
28	1		*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*- FL
29	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	410.66 FL	*- FL
30	1		*DOOR SEAL REAR RH	Serviceable	162.02 FL	*- FL
31	1		*DOOR WAIST SEAL OUTER REAR RH	Serviceable	334.69 FL	*- FL
32	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
33	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
36	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
40	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
41	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
42	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
43	1		*SET WHEELARCH CLIP RR RH	Not Necessary	66.00 FS	*- FS
44	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*-FS
46	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
47	1		*CAP HUB RH RR	Serviceable	35.00 FS	*-FS
48	1		*RIM RH RR	Serviceable	385.00 FS	*-FS
49	1		*TYRE RH RR	Serviceable	330.00 FS	*-FS
50	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
51	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*-FS
52	1		*DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,298.97	60.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,607.32	0.00
Total Parts (\$\$)	25,691.65	60.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	-
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TOWING FEES	New	120.00	-
8	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
11	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
Gross Labour Cost (\$\$)			7,710.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >