

REPORT

ASS. REC. BY

REF: CS/FCI18001892/11q03 m2

Special Instructions

ASSIGNMENT (Office)

From (Person): WIS Serene Ter of FCI Date/Time: 10:07am @ 3/1/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No:

SLS 8126B

Insured:

SH 65592

at Workshop m/s

Pegasus Engineering

Tel:

68581846

of

SI Defu Lane 10

Policy No:

D-18088936 MFSH

Claim No:

D18000889 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Signature:

Date/Time:

10:15am @ 3/1/18

Person Contacted:

Sharon

Vehicle: D18000889

Date/Time

Action/Instructions

✓

SLS 8126 B - X

SH 65592-CC3 / TM116 022672 / Hlvbn2

D.O.A: 26/11/2016

12/3/18 @ 2pm revised to Serene by email.

marcus

FCI

27/2/18

SKS8126B

1017

① NS TR RES / CD RES / EVA / INV / M

To Road / Street

SKS 8126B

to Road / Street

Tan Him / P2 sasus

to

SI Defu June 10

to

SH 65-292

to

to

to

to

to

10am-10:30am
owner waiting

to

Policy Condition

Remark: The van had commenced its
repair at the time of inspection



to

to

Consistent? Yes or No

to

Consistent? Yes or No

to

days Yes or No

to

days Yes or No

to

24 HRS 'wup'

to

Person Connected

Vehicle In / Out

to

27/2/18 continued a/s @ 950 with willian.
Used \$904, 492

6A1

made 3

Grey

30809

JM6BN22AFH/0159447



205/60R16

BS DUN BEND A BY PS LIA MIO CHTEL PP SLV

TOYO YOKO

Triangle

to

6

to

6

to

209/118

to

27/2/18

to

Reel 115.

The U.C. chassis frame body structure affected due to collision

RECEIVED 02 MAR 2018

to



Preliminary Report

Final Report

to

Days Of Repair

2

Repair/No. of Trip

to

7P

950

100
50
19

169



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001892/Uqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6559Z	Veh. Inspected	SLS 8126B
Policy No.		Coverage (\$)	0.00
Claim No.	D18000889MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/01/2018	Inspection Date
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000889MFSH

Date: 02 March 2018

Our Ref: CS/FCI18001892/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 8126B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/02/2018 at the premises of M/s PEGASUS ENGINEERING, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,854.00</u>
Revised Estimate Amount	: S\$ <u>950.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (*Nivitha*): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	<input checked="" type="checkbox"/>			
C Customer Code	<input checked="" type="checkbox"/>			
N Assign From	<input checked="" type="checkbox"/>			
C Assign Date	<input checked="" type="checkbox"/>			
C Veh No (Inspected)	<input checked="" type="checkbox"/>			
C Veh No (Insured)	<input checked="" type="checkbox"/>			
C D.O.A	<input checked="" type="checkbox"/>			
C Policy No	<input checked="" type="checkbox"/>			
C Claim No	<input checked="" type="checkbox"/>			
C Insurance Authorisation (CA /REV/REP)	<input checked="" type="checkbox"/>			
C Report Type	<input checked="" type="checkbox"/>			
C Weekend Charges	<input checked="" type="checkbox"/>			
N Survey held at/Repairer	<input checked="" type="checkbox"/>			
C Excess	<input checked="" type="checkbox"/>			

Surveyor (*Mavan*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	<input checked="" type="checkbox"/>	
C Regn Month/Year	<input checked="" type="checkbox"/>	
N Vehicle Type	<input checked="" type="checkbox"/>	
N Make & Model	<input checked="" type="checkbox"/>	
C Engine Capacity. (C.C)	<input checked="" type="checkbox"/>	
N Colour	<input checked="" type="checkbox"/>	
C Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>	
C Chassis No	<input checked="" type="checkbox"/>	
N General Condition	<input checked="" type="checkbox"/>	
N Steering	<input checked="" type="checkbox"/>	
N Brake	<input checked="" type="checkbox"/>	
N Modification (Modi)	<input checked="" type="checkbox"/>	
C Tyre Size	<input checked="" type="checkbox"/>	
N Tyre Make	<input checked="" type="checkbox"/>	
C Tyre Balance	<input checked="" type="checkbox"/>	
C Date of Inspection	<input checked="" type="checkbox"/>	
N Survey held	<input checked="" type="checkbox"/>	
N Des.of Damages	<input checked="" type="checkbox"/>	

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>	
----------------------------------------	-------------------------------------	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	<input checked="" type="checkbox"/>	
C Market Value for OD cases	<input checked="" type="checkbox"/>	
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)	<input checked="" type="checkbox"/>	
C Days of repair	<input checked="" type="checkbox"/>	
C Finalised Amount	<input checked="" type="checkbox"/>	
C Re-inspection Cases to Finalize within 5 Days	<input checked="" type="checkbox"/>	

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	<input checked="" type="checkbox"/>	
---------------------------	-------------------------------------	--

Check By:

[Signature] 01/3/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-01-2018	Our Ref No. D18000889MFSH
Accident Date	20-01-2018	Claim Type. Third Party
Insured Vehicle	SH6559Z	Third Party Vehicle. SLS8126B
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE: EST. COR - \$1,983.78	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234449)



PRI Documents



Close



PRI Header Details

Claim No	D18000889MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR - \$1,983.78		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6559Z	TP Vehicle No	SLS8126B
PRI Recieved Date	29-01-2018 10:37:36 PM	Surveyor Appointed Date	31-01-2018 10:06:31 AM	Surveyor Accept Date	31-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	31-01-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--------------------------------------------

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 2 March 2018 2:00 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000889MFSH/1
Attachments: CSFCI18001892Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLS 8126B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 31 January 2018 10:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000889MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 31 January 2018 10:07 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000889MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

Vehicle Details

Vehicle No.: SLS8126B

Vehicle to be Exported: Yes

Intended De-registration Date: 22 Jan 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 SEDAN 1.5 AT EU6

Primary Colour: Grey

Manufacturing Year: 2017

Engine No.: P520452013

Chassis No.: JM6BN22A8H0159447

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$15,108.00

Original Registration Date: 06 Oct 2017

First Registration Date: 06 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$10,108.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 05 Oct 2027

PARF Rebate Amount: \$7,581.00

Intended COE Rebate Details

COE Expiry Date: 05 Oct 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLS8126B
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520452013
Chassis No.:	JM6BN22A8H0159447
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,108.00
Original Registration Date:	06 Oct 2017
First Registration Date:	06 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$10,108.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Oct 2027
PARF Rebate Amount:	\$7,581.00
Intended COE Rebate Details	
COE Expiry Date:	05 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$49,562.00
Total Rebate Amount:	\$57,143.00

The information contained herein is correct as at 27 Feb 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
Survey only
LKK
27/02/2018 @ 1020 hrs

Quotation No : QO18/01-1186	Quotation Date : 23/01/2018	Terms : 30 DAYS
Vehicle No : SLS8126B	Chassis No : JM6BN22A8H0159447	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: FIRST CAPITAL ; TP VEHICLE NUMBER: SH6559Z ; DATE OF ACCIDENT: 20.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>20/7011</i>	1	1,075.0000	1,075.00
2	REAR BUMPER CLIPS <i>100</i>	6	5.0000	30.00
3	LESS 20% (ITEMS 1-2)	1	-221.0000	-221.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
5	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	350.0000	350.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	500.0000	500.00

N. of Approval
LKK
2/5 # 950/2
2 day
27/2/18

1-1105
884
1204

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total
GST(7.00%)
Total (SGD)

1,854.00
129.78
1,983.78


Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18001892/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6559Z	Veh. Inspected	SLS 8126B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18000889MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0159447	Colour	GREY	
Odometer	30809	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/01/2018	Inspection Date	27/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8126B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / TORN NECESSARY	1,075.00	1,075.00
6	REAR BUMPER CLIPS @\$5.00		30.00	30.00
	LESS 20% DISCOUNT		-221.00	-221.00
			884.00	884.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. }		350.00	120.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR. }		120.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		500.00	200.00
			970.00	320.00
	GRAND TOTAL		1,854.00	1,204.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CS/FCI18001892/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.