

Not Authorized
 1. B.1
 Resurvey B & paint
 3 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 8208 Z
 MAKE : HONDA
 MODEL : CRV 2.4 5AT 2WD S/R
 YEAR : 2015
 CHASSIS NO : MRHRM3850GP000073

SURVEYOR NAME :
 DATE OF SURVEY : 31 JAN 2018
 TIME OF SURVEY :

DATE : 31-Jan-18
 DATE OF ACCIDENT : 26-Jan-18
 THIRD PARTY REF : SLP 5674 X / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				\$ 498.20
1 pc	Front Bumper Reinforcement				\$ 246.20
1 pc	N/S Front Bumper Retainer				\$ 11.90
1 pc	Front Bumper Lower				\$ 482.00
1 pc	Front Bumper Centre Lid				\$ 154.50
1 pc	N/S Front Bumper Fog Lamp				\$ 246.50
1 pc	N/S Front Bumper Fog Lamp Chrome Cover				\$ 46.60
1 pc	N/S Headlamp				\$ 1,448.00
					\$ 3,133.90
	Less 20%				\$ 626.78
					\$ 2,507.12
	To putty & spray painting.				\$ 450.00
	To check front wiring and focus headlamp				\$ 30.00
	Labour Charges.				\$ 300.00
TG-RA/-					\$ 3,287.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co Reg No. 199307277D GST Reg No. M2-0019086-0