

Version:

ASS. REC. BY:

REF CS/QBE1800+907/R/1/3/2

Name: Rasul

ASSIGNMENT (Office)

From (Person): Joyce Foo

QBE

Date/Time: 31/1/18 @ 10.59am

Estimated Cost:

Bill to:

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WC 3086U

Insured:

at Workshop / m/s Tan Him Motor Woon Meng Tel: 6858 5151 6316 1131 / 9298431

of 51 Defu Lane 10 Sg Kadut.

Policy No:

Claim No: VC011138

Sum Insured:

Excess: \$2000.00

Make of Veh:
(Client's Record):

D.O.A. 29/01/2018

CA (REV) / REP. / REV 24 HRS

01/02/2018

R.O.D. Endorsement:

Date/Time: 11:34am @ 31/1/18

Person Contacted:

William

Vehicle: OUT

Date/Time	Action/Instruction (✓) Estimate
	WC 3086U-X
07/2/18 @ 4.42pm	revert to Joyce Foo by email.
14/3/18 @ 9.53am	Jenny Joh informed C/A & Ex: \$2000 by email.
19/3/18 @ 9.59am	Informed Ms Heng C/A on LS basis & Ex: \$2000 by email.
19/9/18 @ 4.20pm	Rasul finalised with Ms Heng LS \$45200, 17 days. (Cred \$20707.90, 31%)

Signature: *[Handwritten Signature]*

REF:

5861H

ASSIGNMENT

From: _____ Date: _____

Veh No: WC 3086U Yr Regn: 2009 / 86P

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: WC 3086U

Make: MITSUBISHI Fuso FUSO cc 12882

at Workshop m/s Woon Meng

Colour WHITE A/C: Insured / Std / NI / NA

of 42, Sungei Kuning NE

Sp. Reading 303466 T/Radio: Insured / Std / NI / NA

Insured: QBE / OD

Eng/No: _____

Policy No. _____

C/No: FV51JKA00059

Claims No. _____

Gen. Cond: Good Fair / Poor / Burnt

Sum Insured: _____ Excess: 2000

Steering: Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Order / Jammed / Leaked / Burnt or


Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 11-00R20

Remark: The veh had commenced its repair at the time of inspection. *? too high*



R: - - 2/0

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Bal. or Market Value: 92K

TOYO / YOKO or KAPSEN

IDAC Accident Rpt: _____ Consistent?: Yes or No

Front 8 mm Rear 8/8 mm

GIA / PR Seen: _____ Consistent?: Yes or No

R/Bal. 8 mm R/Bal. 8/8 mm

Est. Repairs: 17 days Res.: Yes or No

L/Bal. 8 mm L/Bal. 8/8 mm

Lum Sum: _____ % 3 Val.: Yes or No

D.O.A. 29/01/18 D.O.I. 05/02/18

CA / REV / REP. / 24 HRS

Survey held at Woon Meng

Date: _____ Person Contacted: _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 SEP 2018

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 17

1) : Final Report

Resurvey No. of Trip: 1

Survey Fee: 300

Date/Time, File Return to?

Transportation: _____

2) _____

Add Fee: : Site Insp (\$ _____) : S-RS (\$ _____)

Report Format: OD

: Interview (\$ _____) : Photos

Lump Sum / I.B.I. (\$ 4500)

: Tech. Invs (\$ _____) : Others

: Weekend (\$ _____)

TOTAL

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE18001907/R1qd3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 31-01-2018	
		Code : QBE	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	WC 3086U
Policy No.		Coverage (\$)	0.00
Claim No.	VC011138	Excess (\$)	2,000.00
Assign From	JOYCE FOO	Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/01/2018	Inspection Date	
Survey held at	WOON MENG MOTOR PTE LTD 42 SUNGEI KADUT AVENUE SINGAPORE 729666		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Wednesday, 31 January 2018 10:59 AM
To: assignments
Subject: FW: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018
Attachments: 30012018185717.pdf

Hi team,

FYNa please. OD claim.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [mailto:joyce.foo@qbe.com]
Sent: Wednesday, 31 January, 2018 8:55 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Jenny Toh <jenny.toh@qbe.com>
Subject: FW: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Our Ref. VC011138


Hi

Please arrange OD survey. Policy excess \$2000/-.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Wei Shong [mailto:wei.shong@tlmotor.com.sg]

Sent: Tuesday, 30 January, 2018 6:52 PM

To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>

Cc: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>

Subject: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Our ref: -WC3086U

Dear Jenny,

Please arrange for survey as soon as possible, vehicle in our premises.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte I
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shiau Chan (LKKAuto)

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Monday, 17 September 2018 4:20 PM
To: Rasul (LKKAuto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: WC 3086U

Dear Rasul

Accept your offer \$45,200.00

Thank you.


Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, 17 September 2018 1:54 PM
To: Woon Meng <woonmeng@singnet.com.sg>
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: WC 3086U

Hi Ms Heng,

Finalised amount is \$ 45,200.00 / 17 days lump sum
Kindly confirm
Take note : Finalised amount is subjected to insurance approval

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Woon Meng [<mailto:woonmeng@singnet.com.sg>]
Sent: Monday, 17 September, 2018 10:15 AM
To: Rasul (LKKAuto)
Subject: RE: Pending Finalised offer
Importance: High

Dear Rasul,

We refer to the matter below for your kind attention.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 19 March 2018 9:59 AM
To: woonmeng@singnet.com.sg
Cc: SUR
Subject: VEHICLE WC 3086U (DOA: 29/01/2018)

Dear Ms Heng,

As instructed by our client QBE Insurance , please proceed to repair the insured vehicle **WC 3086U at repair cost on Lump Sum basis. (Excess \$2,000/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Monday, 19 March 2018 9:53 AM
To: Shiau Chan (LKKAuto); Joyce Foo; assignments
Cc: SUR
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Shiau Chan

Authorise repair, excess \$2000.00 apply.

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Monday, 19 March, 2018 9:36 AM
To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Jenny,

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 March 2018 10:58 AM
To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Jenny,

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Monday, 26 February 2018 1:42 PM

To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Jenny,

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)

Sent: Friday, 9 February 2018 10:35 AM

To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Jenny,

The vehicle repair on Lump Sum basis and its still within economical for repair.

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh [<mailto:jenny.toh@qbe.com>]

Sent: Friday, 9 February 2018 10:11 AM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Hi Shiau Chan


Just to check with you the cost of repair is parts by parts or lump sum repair?

Is economical to repair?

Regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Friday, 9 February, 2018 9:40 AM
To: Joyce Foo <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>; Jenny Toh <jenny.toh@qbe.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Jenny,

Please refer to the attached of WC 3086U's LTA rebate.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 8 February 2018 2:59 PM
To: 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Joyce,

Kindly advise on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 7 February 2018 4:42 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Joyce,

Enclosed herewith preliminary advice of WC 3086U.
Please noted that the vehicle will repair at M/s: Wong Meng Motor Pte Ltd.

Repair cost economical.
We have not authorise repair.

Kindly advice on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 31 January 2018 11:43 AM
To: 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [<mailto:joyce.foo@qbe.com>]
Sent: Wednesday, 31 January, 2018 8:55 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Jenny Toh <jenny.toh@qbe.com>
Subject: FW: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Our Ref. VC011138


Hi

Please arrange OD survey. Policy excess \$2000/-.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Wei Shong [<mailto:wei.shong@tlimotor.com.sg>]
Sent: Tuesday, 30 January, 2018 6:52 PM
To: Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>
Cc: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Subject: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Our ref: -WC3086U

Dear Jenny,

Please arrange for survey as soon as possible, vehicle in our premises.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte I
51 Defu Lane 10
Singapore 539216
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan L Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the

intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 7 February 2018 4:42 PM
To: Admin-D (LKKAuto); 'Joyce Foo'; assignments
Cc: SUR
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018
Attachments: CSQBE18001907R1qb.pdf

Dear Joyce,

Enclosed herewith preliminary advice of WC 3086U.
Please noted that the vehicle will repair at M/s: Wong Meng Motor Pte Ltd.

Repair cost economical.
We have not authorise repair.

Kindly advice on authorisation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 31 January 2018 11:43 AM
To: 'Joyce Foo' <joyce.foo@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo [<mailto:joyce.foo@qbe.com>]
Sent: Wednesday, 31 January, 2018 8:55 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Jenny Toh <jenny.toh@qbe.com>
Subject: FW: OD Claim - Accident involving WC3086U and WC5400H on 29.01.2018

Our Ref. VC011138

Hi



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: VC011138

Date: 07th February 2018

Our Ref: CS/QBE18001907/R1qd3

Without Prejudice

The Motor Claims Department
QBE Insurance

Attn: Joyce

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. WC 3086U .

We thank you for the instruction on 31/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/02/2018 at the premises of M/s WOON MENG and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 65,907.90</u> .
Revised Estimate Amount	: <u>S\$ 31,623.70</u> .
"Check" Items Amount	: <u>S\$ 22,195.50</u> .
Market Value	: <u>S\$ 92,000.00</u> .
LTA Reimbursement Value	: <u>S\$ 2,670.00</u> .
Nett Value	: <u>S\$ 89,330.00</u> .

Description of Damage:
The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical

Days of repair: 17 days.

We have not authorized repair.

Yours faithfully

Rasul
Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5861H
Vehicle Details	
Vehicle No.:	WC3086U
Vehicle to be Exported:	No
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JKM4RDEA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6M70414299
Chassis No.:	FV51JKA00059
Maximum Power Output:	-
Open Market Value:	\$86,824.00
Original Registration Date:	07 Sep 2009
First Registration Date:	07 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$4,342.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	06 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,501.00
COE Rebate Amount:	\$2,670.00
Total Rebate Amount:	\$2,670.00

The information contained herein is correct as at 07 Feb 2018

OK

92,000
 2,670

 89,330
 ==

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GI&A Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 17:24
Date Of Accident	29/01/2018 15:00
Exact Location Of Accident	SENGKANG WEST ROAD X SENGKANG INDUSTRIAL AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC3086U
Insured/Policyholder	
Name Of Registered Owner	SINMIX PTE LTD
Co Reg No	200705861H
Email Address	CHEWHONG.SEE@SINMIX.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65011627
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FV51JKM4RDEA
Exact Purpose for which vehicle was being used at time of accident	CEMENT TRUCK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	8-V0014300-MVA-R001
Cover Note Number	22/11/2017 TO 30/11/2020
Driver	
Name of Driver	CHEW PENG WENG
NRIC No	S1418180F
Date Of Birth	21/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	21/04/1983
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86618719
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLOCK 31 BENDEMEER ROAD
#12-847
Postcode 330031
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

On 29/01/2018 at about 1500hrs, I was driving my vehicle (A: WC3086U) on the second lane from right along Sengkang West Road turning right into Sengkang Industrial Avenue 1. Suddenly the vehicle (B: WC5400H) which was travelling in front of me make an emergency stop, I immediately applied my brake to avoid collision but to not avail. Thus, my vehicle's front portion hit onto rear portion of vehicle B. Nobody was injured in this accident. Both vehicles have no passenger on board.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WC5400H
Vehicle Make/Model/Colour
Details Of Properties CEMENT TRUCK
Vehicle Category COMMERCIAL VEHICLE
Name of Driver SHEIK ISMAIL MUZEEBUR RAHIMAN
NRIC/Passport Number G5245027L
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR PORTION
No. Of Passenger (Including Driver) 1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 30/1/18


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 29/01/18 @ 17:40h


 Reporting Centre Personal's Signature
 Name: Lim Nee Sheng
 NRIC/FIN No.: G16864052K

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to CIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/1/18

Driver's Signature
(If driver is not the policyholder)

Date & Time: 20/1/18 01:17 pm

Reporting Centra Personnel's Signature

Name: Lam Wai Shing
NRIC/FIN No.: C6864057R

INQUIRY REPORT

Employee name : Chew Peng Weng (S1418180F)
Nature of incident : Accident
Date of inquiry : 30/1/18
Starting Time : 3:30pm
Ending Time : 3:45pm

PART 1 – INTRODUCTION

This inquiry is on the accident involving WC 3086 U and a third party vehicle WC 5400 H on 29/01/2018 along Seng Kang West Road L/P 86 F.

ART 2 – MEMBERS OF INQUIRY

Date : 30/1/2018
Name : Yap Kwek Choi
Offender's Name : Chew Peng Weng

PART 3 – EMPLOYEES' STATEMENT

On 29/1/2018 at 1500 hrs, I was driving my vehicle (WC 3086U) on the second lane from the right along Seng Kang West Road. When I going to turn right into Seng Kang Industrial Ave 1 , near L/P 86F junction, Suddenly the vehicle WC 5400H (Island concrete truck, Sheik Ismail Muzeebur Rahiman, G5245027L) which is travelling in front of me make an emergency stop. I immediately applied my brake to avoid collision but do not available. Thus, my front portion hit onto the rear portion of his vehicle.

Nobody was injured in this accident. Both vehicles have no passenger on board. This cause my front portion badly damage

Acknowledged by



Offender Name : Chew Peng Weng
Date : 30/1/2018

PART 4 – ANALYSIS OF THE INCIDENT

Based on the statement given by Mr Chew Peng Weng , he was at fault in causing the accident

PART 5 – RECOMMENDATION ON THE APPROPRIATE PENALTY

According to the Letter of Undertaking, under terms and condition, Sinmix Pte Ltd has the right recover the cost of repair and / or insurance excess (as charged by the insurer) from the employee(s) who caused the accident. Hence Chew Peng Weng is required to bear 50% insurance excess which amount to \$1,000.00

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Adress : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

OD Claim

To : QBE Insurance (Singapore) Pte Ltd
 Motor Claims Dept

Date : 05 Feb 2018

Dear Sirs :

Fax : 65333270

RE : ESTIMATE COST FOR MITSUBISHI FV51 - WC3086U
ALONG SENGKANG WEST ROAD & SENGKANG INDUSTRIAL AVE 1
ON 29/02/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front pnal inner	1pc	\$ 1,950.00 <i>PA /</i>
2	Front panel beam	1pc	\$ 950.00 <i>PA /</i>
3	Front windscreen glass	1pc	\$ 1,500.00 <i>Bro /</i>
4	Front windscreen rubber	1pc	\$ 350.00 <i>rec /</i>
5	Front erp bracket.	1pc	\$ 15.00 <i>rec /</i>
6	Front wiper panel.	1pc	\$ 320.00 <i>PA /</i>
7	Front wiper blade @\$35ea.	3pcs	\$ 105.00 <i>cut /</i>
8	Front wiper arm @\$290ea.	<i>1pc</i> 2 pcs	\$ 580.00 <i>PA - 290</i>
9	Front wiper link.	1pc	\$ 480.00 <i>? PA /</i>
10	Front wiper nozzle @\$48ea.	<i>1pc</i> 2 pcs	\$ 96.00 <i>PA - 48</i>
11	Front panel hinge @\$78ea.	2pcs	\$ 156.00 <i>? Bro /</i>
12	Front panel handle @\$140ea.	2pcs	\$ 280.00 <i>Bro /</i>
13	Front panel upper grille	1pc	\$ 420.00 <i>CRA /</i>
14	Front panel lower grille	1pc	\$ 580.00 <i>CRA /</i>
15	Emblem.	1pc	\$ 220.00 <i>NA /</i>
16	Front panel lock @\$110ea.	1pc	\$ 220.00 <i>? PA /</i>
17	Front panel lock eye@\$48ea.	1pc	\$ 96.00 <i>? PA /</i>
18	Front panel center lock	1pc	\$ 160.00 <i>PA /</i>
Sum Carried Forward			\$ 8,478.00

8140

Sum Carried Forward

\$ 8,478.00

19	Front panel center lock eye	1pc	\$	48.00	? BT -
20	Front panel absorber	1pc	\$	320.00	? BT -
21	Front roof top handle o/s.	1pc	\$	95.00	CRA -
22	Front corner lamp	1pc	\$	220.00	? X SUZ
23	Front mirror stay n/s.	1pc	\$	650.00	BT -
24	Front mirror under n/s.	1pc	\$	180.00	SEA -
25	Front mirror arm, lower	1pc	\$	130.00	BT -
26	Front corner panel n/s.	1pc	\$	850.00	CRA -
27	Front corner panel bracket n/s.	1pc	\$	380.00	MAN - CRA -
28	Water tank	1pc	\$	290.00	DE -
29	Air con pipe beam	1pc	\$	280.00	? BT -
30	Heater pipe @\$120ea.	1pc	\$	240.00	? BT -
31	Air hose barcket	1pc	\$	480.00	? X SUZ
32	Air pipe @\$120EA	2pcs	\$	240.00	BT -
33	Front cable valve.	1pc	\$	680.00	? CRA -
34	Front cabin bracket.	1pc	\$	650.00	? X SUZ
35	Front cabin crossmember	1pc	\$	1,950.00	? BT -
36	Front crane bracket shaft.	1pc	\$	850.00	? X SUZ
37	Front cabin absorber @\$220ea	1pc 2pcs	\$	440.00	DUL - 220
38	Air belon @\$320ea	2pcs	\$	640.00	? ACT -
39	Radiator.	1pc	\$	3,700.00	BT -
40	Inter cooler.	1pc	\$	5,220.00	BT -
41	Rad fan.	1pc	\$	850.00	? CRA -
42	Rad cowling.	1pc	\$	380.00	? ME -
43	Rad rubber	1pc	\$	250.00	? ME -
44	Air con blower	1pc	\$	850.00	? X SUZ
45	Air con heater	1pc	\$	1,250.00	? BHO -
46	Air con coil	1pc	\$	1,800.00	? BHO -
47	Air con condenser	1pc	\$	1,950.00	? BT -
48	Front bumper	1pc	\$	1,850.00	BT -
49	Front headlamp bracket @\$580ea.	1pc 2pcs	\$580	1,160.00	LH - CRA / RH - CRA -
50	Front bumper top garnish center.	1pc	\$	220.00	DE -
51	Front bumper center cover @\$150ea	2pcs	\$	300.00	DE -
52	Front headlamp @\$1050ea.	2pcs	\$	2,100.00	LH - CRA / RH - CRA -
	Sum Carried Forward			\$ 39,971.00	

27643

31493

Sum Carried Forward

\$ 39,971.00 8215

53	Front headlamp grille @\$220ea.	2pcs	\$	440.00	CRA ✓
54	Front fog lamp @\$250ea.	2pcs	\$	500.00	BR ✓
55	Front fog lamp grille @\$180ea.	2pcs	\$	360.00	MIS ✓
56	Front bumper side @\$240ea.	2pcs	\$	480.00	X SVL ✓
57	Front bumper sensor @\$150ea.	2pcs	\$	300.00	X SVL ✓
58	Front bumper air duct @\$200ea	2pcs	\$	400.00	X SVL ✓
59	Front step panel upper n/s.	1pc	\$	550.00	PT ✓
60	Front step aluminium inner n/s.	1pc	\$	155.00	BT ✓
61	Front step aluminium lower n/s.	1pc	\$	160.00	BT ✓
62	Front step aluminium bracket n/s @\$380ea	1pc - 2pcs	\$	760.00	BT - 380 ✓
63	Front step aluminium n/s.	1pc	\$	180.00	BT ✓
64	Chassis crossmember	1pc	\$	800.00	BR ✓
65	Front dashboard assy	1pc	\$	1,950.00	DE ✓
66	Front dashboard center grille @\$180ea	2pcs	\$	360.00	? CR ✓
67	Front dashboard radio cover	1pc	\$	450.00	? CR ✓
68	Gear box cover	1pc	\$	280.00	? CR ✓
69	Gear box center	1pc	\$	1,650.00	? CR ✓
			\$	49,746.00	
			\$	7,461.90	
			\$	57,207.90	

Sum Carried Forward

43998
+ 15%
50,597.70

Add 15%

9775

Sum Carried Forward

\$ 57,207.90

Labour Charge & Misc

Towing fee.		\$	150.00	
To remove & refix roof top trim and inner seat.	}	\$	250.00	150
To R & R front cabin.		\$	1,500.00	800
To R & R front radiator and inter cooler.		\$	450.00	200
To remove & refix front dashboard.		\$	380.00	250
To remove & refix wiring and lighting.		\$	300.00	100
To R & R front windscreen glass.		\$	120.00	
To R & R air con system and top up air con gas.	}	\$	350.00	200
To repair & weld chassis crossmember		\$	4,000.00	3000
To putty & spray painting.		\$	1,200.00	1000
Total		\$	<u>65,907.90</u>	

5970

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

50,597.70
5970.100

56,567.70
20%
45,254.16

45,200
17 days
Resy after repair

Gasul
4p 900 10068
17 days
L/S
19/3/18

05/02/18 @ 1630
EXCESS: 2000
REVERT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE18001907/R1qd3e2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 15-10-2018	
		Code : QBE	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	WC 3086U
Policy No.	8-V0014300-MVA-R001	Coverage (\$)	0.00
Claim No.	VC011138	Excess (\$)	2,000.00
Assign From	JOYCE FOO	Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI FUSO FV51	c.c	12882
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	FV51JKA00059	Colour	WHITE
Odometer	303466	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	11.00 R20	KAPSEN	8 mm
L/H Front Tyre	11.00 R20	KAPSEN	8 mm
R/H Rear Tyre	11.00 R20 (D/D)	KAPSEN	8/8 mm
L/H Rear Tyre	11.00 R20 (D/D)	KAPSEN	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/01/2018	Inspection Date	05/02/2018
Survey held at	WOON MENG MOTOR PTE LTD 42 SUNGEI KADUT AVENUE SINGAPORE 729666		
5a. Remarks			
A)THE MARKET VALUE IS S\$92,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		17 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WC 3086U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	GEAR BOX CENTER (WCP)	CRACKED	1,650.00	1,650.00
1	FRONT PNAL INNER (WCP)	BENT	1,950.00	1,950.00
1	FRONT PANEL BEAM (WCP)	BENT	950.00	950.00
1	FRONT WINDSCREEN GLASS (WCP)	BROKEN	1,500.00	1,500.00
1	FRONT WINDSCREEN RUBBER (WCP)	NECESSARY	350.00	350.00
1	FRONT ERP BRACKET (WCP)	NECESSARY	15.00	15.00
1	FRONT WIPER PANEL (WCP)	BENT	320.00	320.00
3	FRONT WIPER BLADE @\$35.00 (WCP)	CUT	105.00	105.00
2	FRONT WIPER ARM @\$290.00 (WCP)	BENT-1PC ONLY	580.00	290.00
1	FRONT WIPER LINK (WCP)	BENT	480.00	480.00
2	FRONT WIPER NOZZLE @\$48.00 (WCP)	BENT-1PC ONLY	96.00	48.00
2	FRONT PANEL HINGE @\$78.00 (WCP)	BROKEN	156.00	156.00
2	FRONT PANEL HANDLE @\$140.00 (WCP)	BROKEN	280.00	280.00
1	FRONT PANEL UPPER GRILLE (WCP)	CRACKED	420.00	420.00
1	FRONT PANEL LOWER GRILLE (WCP)	CRACKED	580.00	580.00
1	EMBLEM (WCP)	NECESSARY	220.00	220.00
2	FRONT PANEL LOCK @\$110.00 (WCP)	BENT	220.00	220.00
2	FRONT PANEL LOCK EYE @\$48.00 (WCP)	BENT	96.00	96.00
1	FRONT PANEL CENTER LOCK (WCP)	BENT	160.00	160.00
1	FRONT PANEL CENTER LOCK EYE (WCP)	BENT	48.00	48.00
1	FRONT PANEL ABSORBER (WCP)	BENT	320.00	320.00
1	FRONT ROOF TOP HANDLE O/S (WCP)	CRACKED	95.00	95.00
1	FRONT CORNER LAMP (WCP)	SERVICEABLE	220.00	-
1	FRONT MIRROR STAY N/S (WCP)	BENT	650.00	650.00
1	FRONT MIRROR UNDER N/S (WCP)	SCRATCHED	180.00	180.00
1	FRONT MIRROR ARM, LOWER (WCP)	BENT	130.00	130.00
1	FRONT CORNER PANEL N/S (WCP)	CRACKED	850.00	850.00
1	FRONT CORNER PANEL BRACKET N/S (WCP)	CRACKED	380.00	380.00
1	WATER TANK (WCP)	DEFORMED	290.00	290.00
1	AIR CON PIPE BEAM (WCP)	BENT	280.00	280.00
2	HEATER PIPE @\$120.00 (WCP)	BENT	240.00	240.00

Report Ref No. CS/QBE18001907/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR HOSE BRACKET (WCP)	SERVICEABLE	480.00	-
2	AIR PIPE @\$120.00 (WCP)	BENT	240.00	240.00
1	FRONT CABLE VALVE (WCP)	CRACKED	680.00	680.00
1	FRONT CABIN BRACKET (WCP)	SERVICEABLE	650.00	-
1	FRONT CABIN CROSSMEMBER (WCP)	BENT	1,950.00	1,950.00
1	FRONT CRANE BRACKET SHAFT (WCP)	SERVICEABLE	850.00	-
2	FRONT CABIN ABSORBER @\$220.00 (WCP)	DISLodge-1PC ONLY	440.00	220.00
2	AIR BELON @\$320.00 (WCP)	ACTIVATED	640.00	640.00
1	RADIATOR (WCP)	BENT	3,700.00	3,700.00
1	INTER COOLER (WCP)	BENT	5,220.00	5,220.00
1	RAD FAN (WCP)	CRACKED	850.00	850.00
1	RAD COWLING (WCP)	DEFORMED	380.00	380.00
1	RAD RUBBER (WCP)	NECESSARY	250.00	250.00
1	AIR CON BLOWER (WCP)	SERVICEABLE	850.00	-
1	AIR CON HEATER (WCP)	BROKEN	1,250.00	1,250.00
1	AIR CON COIL (WCP)	BROKEN	1,800.00	1,800.00
1	AIR CON CONDENSER (WCP)	BENT	1,950.00	1,950.00
1	FRONT BUMPER (WCP)	BENT	1,850.00	1,850.00
2	FRONT HEADLAMP BRACKET @\$580.00 (WCP)	N/S CRACKED / O/S SERVICEABLE	1,160.00	580.00
1	FRONT BUMPER TOP GARNISH CENTER (WCP)	DEFORMED	220.00	220.00
2	FRONT BUMPER CENTER COVER @\$150.00 (WCP)	DEFORMED	300.00	300.00
2	FRONT HEADLAMP @\$1050.00 (WCP)	CRACKED	2,100.00	2,100.00
2	FRONT HEADLAMP GRILLE @\$220.00 (WCP)	CRACKED	440.00	440.00
2	FRONT FOG LAMP @\$250.00 (WCP)	BROKEN	500.00	500.00
2	FRONT FOG LAMP GRILLE @\$180.00 (WCP)	MISSING	360.00	360.00
2	FRONT BUMPER SIDE @\$240.00 (WCP)	SERVICEABLE	480.00	-
2	FRONT BUMPER SENSOR @\$150.00 (WCP)	SERVICEABLE	300.00	-
2	FRONT BUMPER AIR DUCT @\$200.00 (WCP)	SERVICEABLE	400.00	-
1	FRONT STEP PANEL UPPER N/S (WCP)	BENT	550.00	550.00
1	FRONT STEP ALUMINIUM INNER N/S (WCP)	BENT	155.00	155.00
1	FRONT STEP ALUMINIUM LOWER N/S (WCP)	BENT	160.00	160.00
2	FRONT STEP ALUMINIUM BRACKET N/S @\$380.00 (WCP)	BENT-1PC ONLY	760.00	380.00

Report Ref No. CS/QBE18001907/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STEP ALUMINIUM N/S (WCP)	BENT	180.00	180.00
1	CHASSIS CROSSMEMBER (WCP)	BENT	800.00	800.00
1	FRONT DASHBOARD ASSY (WCP)	DEFORMED	1,950.00	1,950.00
2	FRONT DASHBOARD CENTER GRILLE @\$180.00 (WCP)	CUT	360.00	360.00
1	FRONT DASHBOARD RADIO COVER (WCP)	CRACKED	450.00	450.00
1	GEAR BOX COVER (WCP)	CRACKED	280.00	280.00
	COST PLUS 15%		7,461.90	6,599.70
			57,207.90	50,597.70
	LABOUR			
	TOWING FEE.		150.00	150.00
	TO REMOVE & REFIX ROOF TOP TRIM AND INNER SEAT. TO R&R FRONT CABIN.		250.00	150.00
	TO R&R FRONT RADIATOR AND INTER COOLER.		1,500.00	800.00
	TO REMOVE & REFIX FRONT DASHBOARD.		450.00	200.00
	TO REMOVE & REFIX WIRING AND LIGHTING.		380.00	250.00
	TO R&R FRONT WINDSCREEN GLASS.		300.00	100.00
	TO R&R AIR CON SYSTEM AND TOP UP AIR CON GAS.		120.00	120.00
	TO REPAIR & WELD CHASSIS CROSSMEMBER.		350.00	200.00
	TO PUTTY & SPRAY PAINTING.		4,000.00	3,000.00
			1,200.00	1,000.00
			8,700.00	5,970.00
	GRAND TOTAL		65,907.90	56,567.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			45,000.00

Report Ref No. CS/QBE18001907/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.