

22/03/2018

ASS. REC. BY:

REF:

CS / E1218001908 / Uqbnz

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

E12

Date/Time:

01/02/2018 1015am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 81163E

Insured:

XD 5455H

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

XD 5455H / RH / PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3001-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

01/02/2018 1033am

Person Contacted:

Nancy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

01/2/18@ 3:48pm Informed Steven Lim, we are pending estimate from repairer.
 02/2/18@ 11:11am revised to Steve Lim by email.

08/11/13) wef

ASS. REC. BY: *Marius*

REF:

EN. /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *GBC8463E*at Workshop m/s *Al.*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *850k*IPAC Accident Rpt: *2* Consistent? : Yes or NoGla / PR Seen: *2* Consistent? : Yes or NoEst. Repairs: *10* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1534H

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *GBC8463E* Yr Regn: *1.14*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(m)*Make: *Toyota Hiace* c.c. *2982*Colour: *Silver* A/C: Insured / Std / NI / NASp. Reading: *70669* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTFHT02P20013112*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *NW* / S/Rim / STD A/Rim orTyre Size: F: *195 R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6* mm Rear *6* mmR/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *30/1/18* D.O.I. *31/1/18*Survey held at *1/2*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear wheel

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *27/2/18 started*
*have G.A. already.**7/2/18 confirmed L/S \$11500 with Alan (Ref \$17638.70, 61%)*

RECEIVED 7 FEB 2018

Date/Time, File Pass to? ☐ : Preli. Report1) *07/2/18* ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *10*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

TOTAL

350

Report Format: *TP*Lump Sum / I.B.I. (\$) *11500*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18001908/Uqb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 31-01-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5455H	Veh. Inspected	GBC 8463E
Policy No.		Coverage (\$)	0.00
Claim No.	XD5455H/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/01/2018	Inspection Date	31/01/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: C9/EH118001908/UG6
Policy Type: OD / TP / TP RES / TL / EVA

GBC 8463E

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Maver): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo uploaded

✓		
---	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 1 February, 2018 10:25 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018
Attachments: XD5455H - SAS.pdf; GBC8463E - SAS.pdf; GBC8463E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 01.02.2018
Our Reference: XD 5455H/RH/pl
Your Reference: GBC 8463E

To: FASTECH AUTO PTE LTD

Sent via Fax ☐
or
Email ☐ nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBC 8463E
Insured's Vehicle: XD 5455H
Date Of Accident: 30.01.2018

We acknowledge receipt of your request for PRS on: 31.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by: Pei Li 6829 9194 claims@ergo.com.sg
Signature: [Signature] FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 February 2018 11:11 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); Steve Lim
Cc: assignments; SUR
Subject: RE: XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018
Attachments: CSEGI18001908Uqb.pdf

Dear Steve,

Enclosed herewith preliminary advice of GBC 8463E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 February 2018 3:48 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; Steve Lim <steve.lim@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018

Dear Steven,

Please be informed that we have inspected the vehicle GBC 8463E on 31/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 1 February 2018 10:31 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD5455H/RH/pl

Date: 07th February 2018

Our Ref: CS/EG118001908/Uqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBC 8463E


We thank you for the instruction on 01/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/01/2018 at the premises of M/s FASTECH AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>29,138.70</u>
Revised Estimate Amount	: S\$ <u>11,500.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion & rear windscreen.



Comments/ Present Status:

Damages consistent.

Days of repair: 10 days.

We have NOT authorise repair.

Yours faithfully

MARCUS CHUA
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 February 2018 3:48 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); 'Steve Lim'
Cc: assignments; SUR
Subject: RE: XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018

Dear Steven,

Please be informed that we have inspected the vehicle GBC 8463E on 31/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 1 February 2018 10:31 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 1 February, 2018 10:25 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : XD5455H / TP : GBC8463E/LKK / DOA : 30/01/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1534H
Vehicle Details	
Vehicle No.:	GBC8463E
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2361280
Chassis No.:	JTFHT02P200131121
Maximum Power Output:	-
Open Market Value:	\$27,502.00
Original Registration Date:	20 Jan 2014
First Registration Date:	20 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$1,376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,046.00
COE Rebate Amount:	\$22,108.00
Total Rebate Amount:	\$22,108.00

The information contained herein is correct as at 31 Jan 2018

OK

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



ANNOUNCING Heritage Auto Enterprise Pte Ltd
as sgCarMart Premium Dealer for the 5th Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Year Coe Renewal Toyota Estima 2.4A



\$6800 Downpayment Monthly
From \$938 Onwards. Lowest
3.68%P.A.BGV Cars Financing
GV Credit Pte Ltd - Standard

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

TOYOTA HIACE

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA HIACE	Any	Any	2014	Any	Any	Any	Available
	Toyota Hiace Fuel Type: Diesel Think One Automobile & Trading Posted: 01-Feb-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota	\$55,800	\$9,040 /yr	03-Apr-2014	2,982 cc	86,000 km	Van	Available
	Toyota Hiace Fuel Type: Diesel Amazing Condition, Full Agent Service! Best Used Quality You Can Find In Town. Well Known Low Maintenance Cost. Final Choice For Your Business. High Loan And High Trade In Available. Call Or Whatsapp ... ABWIN Bus Pte Ltd Posted: 30-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota	\$59,800	\$9,170 /yr	08-Aug-2014	2,982 cc	-	Van	Available
	Toyota Hiace Fuel Type: Diesel 5 Door Toyota Hiace From Borneo Motor. Serviced And Maintained At Borneo Motor. Original Condition. No Touch Up Of Paint Work And Interior Is As Good As New. See To Believe! In House Loan And Trade In... Abwin Trading Posted: 26-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota	\$59,800	\$8,950 /yr	07-Oct-2014	2,982 cc	100,000 km	Van	Available
	Toyota Hiace Fuel Type: Diesel Season Parking At Multi-Storey Carpark \$110. Enter All Multi-Storey Carpark Above 1.9m. Call Us Now! ABWIN Bus Pte Ltd Posted: 23-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota	\$54,800	\$9,180 /yr	22-Jan-2014	2,982 cc	-	Van	Available
	Toyota Hiace Fuel Type: Diesel Extremely Well Maintained Toyota Hiace. 1 Owner With Full Servicing Record With Borneo Motors. All Wear & Tear Replaced, Seats And Paintwork In Original Condition. View To Believe. Car (S) Pte Ltd Posted: 22-Jan-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota	\$57,800	\$8,720 /yr	17-Sep-2014	2,982 cc	-	Van	Available

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & GPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used TOYOTA HIACE, TOYOTA HIACE Singapore, used TOYOTA HIACE Singapore, used vehicles Singapore or even buy used TOYOTA HIACE Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

FASTECH AUTO PTE LTD

VEH NO:GBC 8463E

QTY

PARTICULAR

AMOUNTS\$

LIST ITEM:

1PCS	REAR WIND SCREEN	shattered 1420.10	\$1,488.10	/
1PCS	REAR WIND SCREEN MOULDING	ner	\$110.00	/
1PCS	TAILGATE	body 1869.30	\$2,150.70	/
1PCS	TAILGATE INNER LOCK	twi/gm	\$395.60	/
1PCS	TAILGATE LOCK STRICKER	11	\$40.10	X
1PCS	TAILGATE INNER TRIM BOARD	merged/10.1 ner	\$385.20	/
1SET	TAILGATE INNER TRIM BOARD CLIPS	ner	\$50.00	/
1PCS	TAILGATE OUTER HANDLE	cut/cut	\$266.50	/
1PCS	TAILGATE REAR LOGO	ner	\$45.90	/
1PCS	TAILGATE WEATHERSTRIP	twi	\$395.10	/
2PCS	TAILLAMPS @\$303.10	500	\$606.20	/
2PCS	TAILLAMP LOWER APRON GARNISHS @\$169.30	20/merged	\$338.60	/
2PCS	TAILLAMP FILTER PANELS @\$245.10	500	\$490.20	/
1PCS	REAR BUMPER	20/20	\$599.30	/
4PCS	REAR BUMPER LOWER BRACKETS@\$45.00	11	\$180.00	X
1SET	REAR BUMPER CLIPS	20	\$50.00	/
1PCS	REAR END PANEL OUTER	3.500	\$499.50	/
1PCS	REAR ENDPANEL INNER	3.500	\$1,012.10	/
1PCS	REAR END PANEL TOP STEEL PLATE	20	\$269.10	/
1PCS	REAR FLOOR PANEL	1	\$2,410.10	X
1PCS	REAR SPARE TYRE BRACKET	11	\$263.50	X
1PCS	REAR SPARE TYRE BRACKET HOOK	11	\$66.50	X
2PCS	REAR BUMPER SIDE HOLDERS@\$155.00	cro/20	\$230.00	/
1PCS	REAR EXHAUST PIPE	11	\$971.00	X
2PCS	REAR EXHAUST PIPE MOUNTINGS @\$65.00	11	\$130.00	X
2PCS	REAR FENDERS@ 2450.00	11 20/500/200 0/50 2250.10	\$4,900.00	120
1PCS	REAR THIRD BRAKE LIGHT	one	\$355.30	/
1PCS	REAR WIPER ARM	20	\$195.80	/
1PCS	REAR WIPER MOTOR	twi/gm	\$645.10	/
1PCS	REAR WIPER BLADE	11	\$86.50	X
2PCS	TAILLAMP INNER RAIL PANELS 489.60	1.500/tw	\$979.20	/
1PCS	REAR AIR VENT	11	\$95.50	X
1PCS	REAR WINDSCREEN SEALANT	ner	\$60.00	405.2
1PCS	TAILGATE 70km/h STICKER	ner	\$15.00	105.2
1PCS	HIACE STICKER	ner	\$35.00	/
1PCS	TOYOTA STICKER	ner	\$38.00	/
1SET	REAR WINDSCREEN SOLAR FILM	NF	\$300.00	X
1SET	REAR REVERSE SENSOR	shut	\$280.00	2005.2
1SET	REAR REVERSE CAMERA	NF	\$380.00	X

25%

12866.2
9649.65

not Adboard
note
2/5 11500
3/1/18
the job after again
10 day

		\$21,808.70	
TO CHECK WIRING		\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	100
TO TRANSFER TAILGATE COMPONENTS		\$100.00	60
TO DISMANTLE & REPLACING REVERSE CAMERA	11	\$100.00	X
TO SPRAY RUST PROOFING		\$120.00	✓
TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS		\$4,000.00	2300
TO PUTTY & SPRAY PAINTING		\$2,500.00	1300
TO DISMANTLE AND REFIX FUEL TANK	11	\$100.00	X
TOTAL		\$29,138.70	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18001908/Uqbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 08-02-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5455H	Veh. Inspected	GBC 8463E	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD5455H/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTFHT02P200131121	Colour	SILVER	
Odometer	70669	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/01/2018	Inspection Date	01/02/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8463E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WIND SCREEN	SHATTERED	1,488.10	1,420.10
1	REAR WIND SCREEN MOULDING	NECESSARY	110.00	110.00
1	TAILGATE	BADLY DENTED	2,150.70	1,969.30
1	TAILGATE INNER LOCK	TWISTED / JAMMED	395.60	395.60
1	TAILGATE LOCK STRICKER	NOT NECESSARY	40.10	-
1	TAILGATE INNER TRIM BOARD	WARPED / TORN	385.20	385.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE OUTER HANDLE	CUT / CRACKED	266.50	266.50
1	TAILGATE REAR LOGO	NECESSARY	45.90	45.90
1	TAILGATE WEATHERSTRIP	TWISTED	395.10	395.10
2	TAILLAMPS @\$303.10	BROKEN	606.20	606.20
2	TAILLAMP LOWER APRON GARNISHS @\$169.30	DENTED / WARPED	338.60	338.60
2	TAILLAMP FILTER PANELS @\$245.10	BADLY DENTED	490.20	490.20
1	REAR BUMPER	DENTED / DEFORMED	599.30	599.30
4	REAR BUMPER LOWER BRACKETS @\$45.00	NOT NECESSARY	180.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL OUTER	BADLY DENTED	499.50	499.50
1	REAR END PANEL INNER	BADLY DENTED	1,012.10	1,012.10
1	REAR END PANEL TOP STEEL PLATE	BENT	269.10	269.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,410.10	-
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	263.50	-
1	REAR SPARE TYRE BRACKET HOOK	NOT NECESSARY	66.50	-
2	REAR BUMPER SIDE HOLDERS @\$155.00	CRACKED / BENT	230.00	230.00
1	REAR EXHAUST PIPE	NOT NECESSARY	971.00	-
2	REAR EXHAUST PIPE MOUNTINGS @\$65.00	NOT NECESSARY	130.00	-
2	REAR FENDERS @\$2450.00	N/S BADLY DENTED/BUCKLED/O/S TO REPAIR SEE LABOUR	4,900.00	2,250.10
1	REAR THIRD BRAKE LIGHT	CRACKED	355.30	355.30

Report Ref No. CS/EG18001908/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WIPER ARM	BENT	195.80	195.80
1	REAR WIPER MOTOR	TWISTED / JAMMED	645.10	645.10
1	REAR WIPER BLADE	NOT NECESSARY	86.50	-
2	TAILLAMP INNER RAIL PANELS @\$489.60	BADLY DENTED / TWISTED	979.20	979.20
1	REAR AIR VENT	NOT NECESSARY	95.50	-
1	HIACE STICKER	NECESSARY	35.00	35.00
1	TOYOTA STICKER	NECESSARY	38.00	38.00
1	SET REAR WINDSCREEN SOLAR FILM	NOT FITTED	300.00	-
1	SET REAR REVERSE CAMERA	NOT FITTED	380.00	-
	LESS 25% DISCOUNT		-	-3,407.80
			21,453.70	10,223.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	15.00	10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			355.00	250.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	100.00
	TO TRANSFER TAILGATE COMPONENTS.		100.00	60.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND O/S REAR FENDER.		4,000.00	2,300.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,300.00
	TO DISMANTLE AND REFIX FUEL TANK.	NOT NECESSARY	100.00	-
			7,330.00	3,960.00
	GRAND TOTAL		29,138.70	14,433.40

Report Ref No. CS/EG18001908/Uqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,500.00
---	--	--	-----------

Report Ref No. CS/EGI18001908/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.