

REPAIR DETAILS

REFERENCE

Vehicle Reg No. : SJP9912G
Make & Model : TOYOTA COROLLA ALTIS 1.6 AUTO
Chassis No. : MR053ZEE106143688
Engine No. : 3ZZ4881944
Year of Manufacture : 2009
Labour : REPAIRER'S
TP Vehicle Reg No. : SJZ9682S
DOA & Location : 26/01/2018 ALONG OPHIR ROAD TOWARDS QUEENS ST
Our Ref : SJP9912G / LIM CHOON KIM

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	FRONT BUMPER		\$ 486.15 <i>sur</i>
2	1	L/F FENDER		\$ 695.10 <i>R</i>
3	1	L/F HEADLAMP		\$ 467.25 <i>sur</i>
4	10	BUMPER CLIP		\$ 52.50 <i>sur</i>
5	10	FENDER CLIP		\$ 52.50 <i>sur</i>
6	1	L/F FENDER EMBLEM VVTI		\$ 56.70 <i>sur</i>
7	1	L/F BUMPER RETAINER		\$ 70.35 <i>sur</i>
8	1	R/F BUMPER RETAINER		\$ 70.35 <i>X</i>
9	1	L/F DOOR		\$ 1,051.05 <i>X</i>
10	1	L/F UPPER DOOR HINGE		\$ 72.45 <i>X</i>
11	1	L/F LOWER DOOR HINGE		\$ 72.45 <i>X</i>
12	1	L/F DOOR CHROME		\$ 32.55 <i>X</i>
Sub-Total (S\$)				\$ 3,179.40
SAAA List Item Discount 25% (S\$)				\$ 794.85
Sub-Total (S\$)				\$ 2,384.55

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,200.00 <i>400 300</i>
2	SPRAYPAINTING	\$ 1,200.00 <i>600 400</i>
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 50.00 <i>30</i>
4	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	\$ 150.00 <i>X</i>
Total Labour (S\$)		\$ 2,600.00

Total Parts (S\$)	\$ 2,384.55
Total Labour (S\$)	\$ 2,600.00
Total (S\$)	\$ 4,984.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 90010068
4 days
4/3
26/02/18 @ 1115
Resy after repair