

REPAIR DETAILS		
REFERENCE		
Vehicle Reg No.	: SJP9912G	
Make & Model	: TOYOTA	COROLLA ALTIS 1.6 AUTO
Chassis No.	: MR053ZEE106143688	
Engine No.	: 3ZZ4881944	
Year of Manufacture	: 2009	
Labour	: REPAIRER'S	
TP Vehicle Reg No.	: SJZ9682S	
DOA & Location	: 26/01/2018	ALONG OPHIR ROAD TOWARDS QUEENS ST
Our Ref	: SJP9912G	/ LIM CHOON KIM

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	FRONT BUMPER		\$ 486.15
2	1	L/F FENDER		\$ 695.10
3	1	L/F HEADLAMP		\$ 467.25
4	10	BUMPER CLIP		\$ 52.50
5	10	FENDER CLIP		\$ 52.50
6	1	L/F FENDER EMBLEM VVTI		\$ 56.70
7	1	L/F BUMPER RETAINER		\$ 70.35
8	1	R/F BUMPER RETAINER		\$ 70.35
9	1	L/F DOOR		\$ 1,051.05
10	1	L/F UPPER DOOR HINGE		\$ 72.45
11	1	L/F LOWER DOOR HINGE		\$ 72.45
12	1	L/F DOOR CHROME		\$ 32.55
Sub-Total (\$\$)				\$ 3,179.40
SAAA List Item Discount 25% (\$\$)				\$ 794.85
Sub-Total (\$\$)				\$ 2,384.55

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,200.00
2	SPRAYPAINTING	\$ 1,200.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 50.00
4	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	\$ 150.00
Total Labour (\$\$)		\$ 2,600.00

Total Parts (\$\$)	\$ 2,384.55
Total Labour (\$\$)	\$ 2,600.00
Total (\$\$)	\$ 4,984.55