

INS. CASE OWNER:

MARVIN

CC 4/111800 1913, U p6352

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

31/1/18

Date / Time:

30/1/18

Registered in Merimen:

31/1/18

Pre-assign / CCU / FTE

SHA 5984C

Claim No.:

MT18V10813

Policy No.:

M100005

Make / Model:

TOYOTA

Place of Accident:

HARLOCK KROSS ENTRANCE  
UP 4-POINT HOTEL

Insured Vehicle No.:

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

20/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PECK WEN HONG

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SEE 3995



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yew  
Tee

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
1/2/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
1/2/18	Documentation Check List:	Handler Typist
1/2/18	Notification ltr (if non-pickup)	<input type="checkbox"/>
1/2/18	After call ltr to OI:	<input type="checkbox"/>
2/2/18	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher: (On)	<input checked="" type="checkbox"/>
	Final Repair Bill: (On)	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
1/2/18	PRELIMINARY ADVICE	Date/Time: Sent By:
26/3/18	FINALIZATION	Date/Time: Confirm with:
28/4/18	FINAL SETTLEMENT	Date/Time: Confirm with: Shaun
	Final Liability:	% (Agreed / Assessed) BOLA S/N No.:
	Repair Cost:	\$S 4952.00
	Loss of Rental (LOR):	\$S ( days)
	Loss of Use (LOU):	\$S 500.00 (\$100 x 5 days)
	Loss of Income (LOI):	\$S (\$ x days)
	LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
	GIA/LTA Search	\$S 29.00
	Medical:	\$S -
	Disbursement:	\$S - (e.g. Tow/ Independent)
	Legal Cost	\$S -
	Total:	\$S 5451.00 Global Sum \$S:
	FINAL PAYMENT	Date/Time: Confirm with: Shaun
	Payee 1:	\$S 5451.00 Name 1: Yew Tee Automobile Tech Pte Ltd
	Payee 2: (Strike if N.A.)	\$S Name 2:
	Payee 3: (Strike if N.A.)	\$S Name 3:

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SKE 3999S  
 at Workshop m/s you see woodland  
 of SHIA 5984C  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 25kIDAC Accident Rpt: 2 Consistent? : Yes or NoGIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKE 3999S Yr Regn: 28/6/08  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: Bmw 320i c.c. 1995  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 109652 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: W3AUV676010NL 62372  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/1/18

Survey held at \_\_\_\_\_

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 31/1/18Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Smt. LTA 20366 net 4634ashy 4000.5/2/18 confirmed L/S & 4600 with shgMV: \$25000 (est)LTA Rebate: \$20366. W (est)Net Value: \$4634 (est)(Red \$ 1710.31 / 72%).

Date/Time, File Pass to? \*

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

) S + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_)




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18001913/Upb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 31-01-2018	
			Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 5984C	Veh. Inspected	SKE 3999S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	26/01/2018	Inspection Date		
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

## Policy Particulars: -THIRD PARTY CLAIM

Insured veh.	SKE3999S	Excess.	NIL
Policy No.	DMPPHQ17-002170	Coverage.	Comprehensive
Claiming Against.	SHA5984C INDIA		
Insured Under.	EQ		

## Vehicle Particulars & Condition

Make & Model	BMW 320i
Engine No.	B553I055N46B20BD
Chassis No.	WBAVG76010NL62372
Odometer	
Engine CC.	1998
Year Of Reg.	2008
Colour.	Grey
Parf/COE Rebate.	\$ 20,383.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

## Description Of Damages

Front portion damaged.

## General Information

Accident Date. 26/1/2018  
Survey held at

Yew Tee Automobile Tech Pte Ltd

Blk 6, unit 399F woodlands road, Yew Tee Ind. Est, Singapore 678006

## Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS  
KINDLY LET US HAVE THE LIABILITY SOON.

## Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

Not Authorised  
L/S # 4600/c  
Take photo after  
repair  
5 day  
31/1/18

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
1	Front bumper <i>dis fix</i>	\$ 920.40 /
1	Front bumper side retainer LH <i>but</i>	\$ 25.00 /
1	Front bumper side retainer RH <i>but</i>	\$ 25.00 /
1	Front bumper bracket LH <i>but</i>	\$ 15.00 /
1	Front bumper bracket RH <i>but</i>	\$ 15.00 /
1	Front bumper reinforcement <i>DD 512</i>	\$ 530.00 /
1	Front bumper fog lamp LH <i>11</i>	\$ 225.00 X
1	Front bumper fog lamp RH <i>11</i>	\$ 225.00 X
1	Front bumper fog lamp cover LH <i>11</i>	\$ 55.00 X
1	Front bumper fog lamp cover RH <i>11</i>	\$ 55.00 X
1	Front bumper lower grille <i>11</i>	\$ 56.55 X
1	Front bumper under cover <i>11</i>	\$ 230.00 X
1	Front brace panel <i>7~1</i>	\$ 36.00 /
1	Front grille LH <i>one</i>	\$ 117.95 /
1	Front grille RH <i>one</i>	\$ 117.95 /
1	Bonnet <i>but</i>	\$ 880.00 /
1	Bonnet hinges LH <i>R</i>	\$ 79.95 X
1	Bonnet hinges RH <i>R</i>	\$ 79.95 X
1	Bonnet logo <i>one</i>	\$ 76.55 /
1	Bonnet centre lever <i>7~1</i>	\$ 37.55 /
1	Bonnet lock catch LH <i>but</i>	\$ 45.00 /
1	Bonnet lock catch RH <i>but</i>	\$ 45.00 /
1	Bonnet rubber <i>one</i>	\$ 25.00 /
1	Bonnet chrome moulding LH <i>one</i>	\$ 65.00 /
1	Bonnet chrome moulding RH <i>one</i>	\$ 65.00 /
1	Front headlamp LH <i>one 1545.11</i>	\$ 1,780.00 /
1	Front headlamp RH <i>one 1545.11</i>	\$ 1,780.00 /
1	Front headlamp panel lock LH <i>but</i>	\$ 115.45 /
1	Front headlamp panel lock RH <i>but</i>	\$ 115.45 /
1	Front headlamp lower bracket LH <i>11</i>	\$ 38.00 X
1	Front headlamp lower bracket RH <i>11</i>	\$ 38.00 X
1	Front fender LH <i>R</i>	Rpr
1	Front fender RH <i>R</i>	Rpr
1	Front fender inner shield LH <i>De</i>	\$ 124.00 /
1	Front fender inner shield RH <i>De</i>	\$ 124.00 /
1	Front windscreen pillar LH <i>R</i>	Rpr
1	Front windscreen pillar RH <i>R</i>	Rpr

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

Qty.	Description Of Parts	Pricing
1	Front support panel <i>suc</i>	\$ 544.45 ✓
1	Front support panel top garnish <i>cu</i>	\$ 120.40 ✓
1	Front support panel air intake duct <i>cu</i>	\$ 265.85 ✓
1	Air con condenser <i>su</i>	\$ 955.60 <i>2</i>
1	Air con condenser top air guide <i>11</i>	\$ 102.40 <i>2</i>
1	Radiator <i>su</i>	\$ 654.45 <i>2</i>
1	Radiator top hose <i>su</i>	\$ 127.60 <i>X</i>
1	Radiator bottom hose <i>11</i>	\$ 108.70 <i>X</i>
1	Radiator fan cowling c/w motor <i>11</i>	\$ 1,082.05 <i>2</i>
1	Front chassis member LH <i>11</i>	\$ 893.25 <i>a</i>
1	Front chassis member RH <i>11</i>	Rpr <i>X</i>
1	Air cleaner intake duct <i>11</i>	\$ 102.40 <i>2</i>
1	Air cleaner box <i>11</i>	\$ 383.50 <i>2</i>
1	Engine top cover <i>cu</i>	\$ 285.35 ✓
1	Power steering tank <i>11</i>	\$ 180.00 <i>X</i>
		List \$ 13,968.75
		Less 5% \$ 698.44 <i>7743.17</i>
		Total \$ 13,270.31
1	Front bumper clips (1 set) <i>11</i>	\$ 45.00 ✓
1	Front number plate <i>11</i>	\$ 45.00 <i>40</i>
2	Front fender inner shield clips <i>11</i>	\$ 70.00 <i>50</i>
		S/N \$ 160.00 <i>135</i>



# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<b><u>LABOUR</u></b>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 80.00 30
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 100.00 30
	To remove and refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	\$ 180.00 100
	Towing charges - king lorry	\$ 120.00 30
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,300.00 800
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,100.00 1000
	LABOUR	\$ 2,880.00 2010
	Sub Total.	\$ 16,310.31
	7% GST	\$ 1,141.72
	Grand Total	\$ 17,452.03

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 31 January 2018 9:30 AM  
**To:** YT(HQ); 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** info@yewteegroup.com; Natalie Lee  
**Subject:** RE: Accident involving SKE3999S (EQ) claiming against SHA5984C (India)  
**Attachments:** SKE3999S\_26012018.pdf; SKE3999S Estimate.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKE3999S and let us have your report urgently.

This claim will be handled by Ms Natalie.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

10.25 am @ 31/01/2018

Person @ Ms. Lei  
Vehicle In  
SUR @ Marcus

---

**From:** YT(HQ) [mailto:utauto@singnet.com.sg]

**Sent:** 30 January, 2018 6:11 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>

**Cc:** info@yewteegroup.com

**Subject:** RE: Accident involving SKE3999S (EQ) claiming against SHA5984C (India)

Hi Motor Dept,

- We choose LKK Auto Consultants Pte Ltd

Thanks.

Best Regards

*Sky Teh*

9747 1475

Website: [www.yewteegroup.com](http://www.yewteegroup.com)

Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)

Like Us On Facebook

Director of

**-YEW TEE AUTOMOBILE TECH PTE LTD**



**WEST HQ:**

Blk 6 Woodlands Road 399F  
Yew Tee Ind. Est  
Singapore 678006  
DID: 6765 3373 / 6762 2081 / 6764 9042  
Fax: 6760 4895  
Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

**EAST Branch Office:**

Synergy@KB, 25 Kaki Bukit Road 4  
Unit No #01-60/61  
Singapore 417800  
DID: 6702 3113 (3 Lines)  
Fax: 6702 3773  
Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

**NORTH Branch:**

Mega@Woodlands  
39 Woodlands Close #01-12  
Singapore 737856



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]  
**Sent:** Tuesday, 30 January, 2018 4:13 PM  
**To:** YT(HQ)  
**Subject:** RE: Accident involving SKE3999S (EQ) claiming against SHA5984C (India)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** YT(HQ) [<mailto:utauto@singnet.com.sg>]  
**Sent:** 30 January, 2018 2:09 PM  
**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>  
**Cc:** [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)  
**Subject:** Accident involving SKE3999S (EQ) claiming against SHA5984C (India)

Hi Motor Claims,

Attached report and estimate.

Kindly arrange PRI at Yew Tee HQ.

Kindly let us have the list of surveyor to choose for conduct the pre-repair survey.

Kindly let us have the officer-in-charge too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



**Yew Tee Automobile Tech Pte Ltd**

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	31 Jan 2018 15:40	<b>Clim Veh Model Changed</b>	(201443) BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A).	[A] Lau Shu Pei
2	31 Jan 2018 15:40	<b>Clim Created</b>	Reg No: SKE3999S. Acct Date: 2018/01/26. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: EQ Insurance Company Ltd (HQ). Workshop: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	[A] Lau Shu Pei
3	31 Jan 2018 15:40	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	31 Jan 2018 15:40	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/02/09	[A] Lau Shu Pei
5	31 Jan 2018 15:40	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	31 Jan 2018 15:40	<b>Label Added</b>	(30653):Direct Settlement.	[A] Lau Shu Pei
7	31 Jan 2018 15:40	<b>Adj Adjuster Assigned</b>	[None] -> MARCUS CHUA	[A] Lau Shu Pei
8	01 Feb 2018 09:26	<b>Clim Dtl Modified</b>	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 199303821R.	[A] Lau Shu Pei
9	01 Feb 2018 11:43	<b>Adj Mandate Request</b>	Cur.Req:0.00:PODS Liability: 100% Remarks: BOLA 5(b). Insured driver made right turn and collided with 3rd party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

## Claim Audit .

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	31 Jan 2018 15:40	<b>Clim Veh Model Changed</b>	(201443) BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A).	[A] Lau Shu Pei
2	31 Jan 2018 15:40	<b>Clim Created</b>	Reg No: SKE3999S. Acct Date: 2018/01/26. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: EQ Insurance Company Ltd (HQ). Workshop: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	[A] Lau Shu Pei
3	31 Jan 2018 15:40	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	31 Jan 2018 15:40	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/02/09	[A] Lau Shu Pei
5	31 Jan 2018 15:40	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	31 Jan 2018 15:40	<b>Label Added</b>	(30653):Direct Settlement.	[A] Lau Shu Pei
7	31 Jan 2018 15:40	<b>Adj Adjuster Assigned</b>	[None] -> MARCUS CHUA	[A] Lau Shu Pei
8	01 Feb 2018 09:26	<b>Clim Dtl Modified</b>	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: -> 199303821R.	[A] Lau Shu Pei
9	01 Feb 2018 11:43	<b>Adj Mandate Request</b>	Cur.Req:0.00:PODS Liability: 100% Remarks: BOLA 5(b). Insured driver made right turn and collided with 3rd party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG
10	01 Feb 2018 17:22	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/02/09	[1] NATALIE LEE
11	01 Feb 2018 17:22	<b>Adj Mandate Set</b>	Approved:0.00.	[1] NATALIE LEE

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Friday, 2 February 2018 7:52 AM  
**To:** 'YT(HQ)'  
**Subject:** ACCIDENT INVOLVING SHA 5984C(III) & SKE 3999S ON 26/01/2018 \*Our Ref: CC4/III18001913/Upb3

Your ref: **SKE 3999S**  
Our Ref: CC4/III18001913/Upb3

**WITHOUT PREJUDICE**

Dear Sir/Madam,

### **ACCIDENT INVOLVING SHA 5984C(III) & SKE 3999S ON 26/01/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

### AUDIT TRAIL

No.	On	Audit	Remarks	By
1	31 Jan 2018 15:40	<b>Clm Veh Model Changed</b>	(201443) BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A).	[A] Lau Shu Pei
2	31 Jan 2018 15:40	<b>Clm Created</b>	Reg No: SKE3999S. Acct Date: 2018/01/26. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: EQ Insurance Company Ltd (HQ). Workshop: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	[A] Lau Shu Pei
3	31 Jan 2018 15:40	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	31 Jan 2018 15:40	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/02/09	[A] Lau Shu Pei
5	31 Jan 2018 15:40	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	31 Jan 2018 15:40	<b>Label Added</b>	(30653):Direct Settlement.	[A] Lau Shu Pei
7	31 Jan 2018 15:40	<b>Adj Adjuster Assigned</b>	[None] -> MARCUS CHUA	[A] Lau Shu Pei
8	01 Feb 2018 09:26	<b>Clm Dtl Modified</b>	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: -> 199303821R.	[A] Lau Shu Pei
9	01 Feb 2018 11:43	<b>Adj Mandate Request</b>	Cur.Reg:0.00:PODS Liability: 100% Remarks: BOLA 5(b). Insured driver made right turn and collided with 3rd party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG
10	01 Feb 2018 17:22	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/02/09	[1] NATALIE LEE
11	01 Feb 2018 17:22	<b>Adj Mandate Set</b>	Approved:0.00.	[1] NATALIE LEE
12	10 Apr 2018 12:33	<b>Adj Rpt Initiated</b>		[A] Lau Shu Pei
13	10 Apr 2018 12:33	<b>Clm Dtl Modified</b>	JPJ Reg. Date: -> 2008/06/28.	[A] Lau Shu Pei
14	10 Apr 2018 12:33	<b>Clm Details Notified</b>		[A] Lau Shu Pei
15	23 Apr 2018 13:11	<b>Clm Dtl Modified</b>	Driver Name: -> PECK WENG KONG.	[A] NUR SHAQILAH BTE ABDOL WAHAB
16	27 Apr 2018 08:50	<b>Adj Mandate Request</b>	Cur.Reg:\$451.00:PODS Liability: 100% Quantum:(a)CORw/GST:\$4,922.00 + (b)LOU (5days x \$100):\$500.00 + (c)GIA rpt search fee:\$29.00 = Total: \$5,451.00 Vehicle Model: BMW 320I (1995cc). For your approval pls.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

### ACTIVITY

[10/04/2018 12:33] Lau Shu Pei :  
PREPARING MANDATE REPORT

### Merimen Billing for this case - Transaction History

Ref Number	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1772216	10/04/2018 12:33	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKE3999S	SHA5984C	10.70



## Print Received Message

This mail is associated with :

**\*SKE3999S (MCT18010813)**

**[SHA5984C]**

TP

WONG CHOON YEN

Jan 26 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]

Yew Tee Automobile Tech Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 27/04/2018 16:14 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$5451.00) - SKE3999S - Claim Handler: NATALIE LEE

Approved:5451.00.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 28 April 2018 4:07 PM  
**To:** 'YT(HQ)'  
**Subject:** RE: ACCIDENT INVOLVING SHA 5984C(III) & SKE 3999S ON 26/01/2018 \*Our Ref: CC4/III18001913/Upb3  
**Attachments:** DV\_SKE 3999S.pdf

### Without Prejudice

Hi,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,922.00
2. Loss of Use (5days x \$100.00)	\$ 500.00
4. LTA/GIA Search Fee	\$ 29.00
Total	<b>\$ 5,451.00</b>

Please duly sign the **DV** enclosed and return back with the following documents for our necessary action: -

- Original Repair invoice(\$4,600.00 + 7% = \$4,922.00)

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Friday, 2 February 2018 7:52 AM  
**To:** 'YT(HQ)' <[utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)>  
**Subject:** ACCIDENT INVOLVING SHA 5984C(III) & SKE 3999S ON 26/01/2018 \*Our Ref: CC4/III18001913/Upb3

Your ref: **SKE 3999S**  
Our Ref: CC4/III18001913/Upb3

**WITHOUT PREJUDICE**

Dear Sir/Madam,

**ACCIDENT INVOLVING SHA 5984C(III) & SKE 3999S ON 26/01/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 <a href="#">Edit Reg</a>		31 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	WONG CHOON YEN, ID: S7930980Z		
Vehicle Reg. No.:	SKE3999S	Date of Loss:	26/01/2018 17:00 - :59 [114 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18010813	Policy/Cover Note No.:	MC00016
Vehicle Reg. No. (Insured):	SHA5984C	Policy No. (Claimant):	DMPPHQ17-002170
		Excess:	
Repairer:	Yew Tee Automobile Tech Pte Ltd (HQ) Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate, 678006 Woodlands - Tel: 67622081		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/02/2018]		
Driver/Custodian (Insured):	PECK WENG KONG (), NRIC: S1569175A		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III\_SG (27/04/2018): Alert - Adj Mandate Approved (S\$5451.00) - SKE3999S - Claim Handler: NATALIE LEE
- III\_SG (01/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SKE3999S - Claim Handler: NATALIE LEE

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKE3999S (MCT18010813)**  
**[SHA5984C]**

**TP**

































**WONG CHOON YEN**








































**Jan 26 2018 5:00PM**

**[COMFORT TRANSPORTATION PTE LTD]**  
**Yew Tee Automobile Tech Pte Ltd**
















[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
24	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
25	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
26	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
27	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
28	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
29	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
30	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
31	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
32	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
33	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
34	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/01/18 21:07	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	31/01/18 21:07	General View	 Load JPG	✓
37	31/01/18 21:07	General View	 Load JPG	✓
38	31/01/18 21:07	General View	 Load JPG	✓
39	31/01/18 21:07	General View	 Load JPG	✓
40	31/01/18 21:07	General View	 Load JPG	✓
41	31/01/18 21:07	General View	 Load JPG	✓
42	31/01/18 21:07	General View	 Load JPG	✓
43	31/01/18 21:07	General View	 Load JPG	✓
44	31/01/18 21:07	General View	 Load JPG	✓
45	31/01/18 21:07	General View	 Load JPG	✓
46	31/01/18 21:07	General View	 Load JPG	✓
47	31/01/18 21:07	General View	 Load JPG	✓
48	31/01/18 21:07	General View	 Load JPG	✓
49	31/01/18 21:07	General View	 Load JPG	✓
50	31/01/18 21:07	General View	 Load JPG	✓
51	31/01/18 21:07	General View	 Load JPG	✓
52	31/01/18 21:07	General View	 Load JPG	✓
53	31/01/18 21:07	General View	 Load JPG	✓
54	31/01/18 21:07	General View	 Load JPG	✓
55	31/01/18 21:07	General View	 Load JPG	✓
56	31/01/18 21:07	General View	 Load JPG	✓
57	31/01/18 21:07	General View	 Load JPG	✓
58	31/01/18 21:07	General View	 Load JPG	✓
59	31/01/18 21:07	General View	 Load JPG	✓
60	31/01/18 21:07	General View	 Load JPG	✓
61	31/01/18 21:07	General View	 Load JPG	✓
62	31/01/18 21:07	General View	 Load JPG	✓
63	31/01/18 21:07	General View	 Load JPG	✓
64	31/01/18 21:07	General View	 Load JPG	✓
65	31/01/18 21:07	General View	 Load JPG	✓
66	31/01/18 21:07	General View	 Load JPG	✓
67	31/01/18 21:07	General View	 Load JPG	✓
68	31/01/18 21:07	General View	 Load JPG	✓
69	31/01/18 21:07	General View	 Load JPG	✓
70	31/01/18 21:07	General View	 Load JPG	✓
71	31/01/18 21:07	General View	 Load JPG	✓
72	31/01/18 21:07	General View	 Load JPG	✓
73	31/01/18 21:07	General View	 Load JPG	✓
74	31/01/18 21:07	General View	 Load JPG	✓
75	31/01/18 21:07	General View	 Load JPG	✓
76	31/01/18 21:07	General View	 Load JPG	✓
77	31/01/18 21:07	General View	 Load JPG	✓
78	31/01/18 21:07	General View	 Load JPG	✓
79	31/01/18 21:07	General View	 Load JPG	✓
80	31/01/18 21:07	General View	 Load JPG	✓
81	31/01/18 21:07	General View	 Load JPG	✓
82	31/01/18 21:07	General View	 Load JPG	✓
83	31/01/18 21:07	General View	Load JPG	✓



Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	31/01/18 21:07	General View	 Load JPG	✓
85	31/01/18 21:07	General View	 Load JPG	✓
86	31/01/18 21:07	Chassis Number	 Load JPG	✓
87	31/01/18 21:07	General View	 Load JPG	✓
88	24/03/18 10:44	Reinspection Photo	 Load JPG	✓
89	24/03/18 10:44	Reinspection Photo	 Load JPG	✓
90	24/03/18 10:44	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 15:40	EMAIL FROM III DD 31012018	 Load PDF	
2	31/01/18 15:40	TP GIA REPORT	 Load PDF	
3	31/01/18 15:40	TP ESTIMATE	 Load PDF	
4	01/02/18 16:25	TP ESTIMATE- MARKED	 Load PDF	
5	23/04/18 14:18	GIA SEARCH	 Load PDF	
6	23/04/18 14:18	LOD	 Load PDF	
7	23/05/18 16:05	AUTHORISATION TO ACT	 Load PDF	
8	23/05/18 16:05	DISCHARGE VOUCHER	 Load PDF	
9	23/05/18 16:05	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 09:10	Singapore Accident Statement	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18001913/UPB3S2  
 Date: 23/05/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016  
 Claimant Vehicle No: SKE3999S Insured Vehicle No: SHA5984C  
 Date of Loss: 26/01/2018 Nature of Claim: TP Claim No: MCT18010813

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKE3999S  
 Make & Model: BMW 320i, 2.0 ABS D/AB 2WD 2DR GAS/D (A) Engine No: B553I055N46B20BD  
 Reg. Date: 28/06/2008 (Man. Year: 2008) Chassis No: WBAVG76010NL62372  
 Colour: Grey Odometer: 109652 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,430.31	7,491.01	5,939.30	44.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	2,010.00	870.00	30.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,310.31</b>	<b>9,501.01</b>	<b>6,809.30</b>	<b>41.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
(S\$)	16,310.31	4,600.00	11,710.31	71.80
+ GST 7.00/7.00% (S\$)	1,141.72	322.00	819.72	71.80
<b>Nett Amount (S\$)</b>	<b>17,452.03</b>	<b>4,922.00</b>	<b>12,530.03</b>	<b>71.80</b>
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		29.00		
<b>Nett Liability (S\$)</b>		<b>5,451.00</b>		

## INSPECTION

Date of Assignment: 31/01/2018  
 Date Inspected: 31/01/2018 Inspected At: Yew Tee Automobile Tech Pte Ltd (HQ)  
 678006 Woodlands  
 678006 Woodlands  
 Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2018)

Parts: M1-COUPE BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE3999S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	920.40 FL	*855.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Bent	25.00 FL	*25.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Bent	25.00 FL	*25.00 FL
4	1		*FRONT BUMPER BRACKET LH	Bent	15.00 FL	*15.00 FL
5	1		*FRONT BUMPER BRACKET RH	Bent	15.00 FL	*15.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	530.00 FL	*512.00 FL
7	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	225.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	225.00 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	55.00 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	55.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	56.55 FL	*- FL
12	1		*FRONT BUMPER UNDER COVER	Not Necessary	230.00 FL	*- FL
13	1		*FRONT BRACE PANEL	Twisted	36.00 FL	*36.00 FL
14	1		*FRONT GRILLE LH	Cracked	117.95 FL	*117.95 FL
15	1		*FRONT GRILLE RH	Cracked	117.95 FL	*117.95 FL
16	1		*BONNET	Buckled	880.00 FL	*880.00 FL
17	1		*BONNET HINGES LH	Repair	79.95 FL	*- FL
18	1		*BONNET HINGES RH	Repair	79.95 FL	*- FL
19	1		*BONNET LOGO	Necessary	76.55 FL	*76.55 FL
20	1		*BONNET CENTRE LEVER	Twisted	37.55 FL	*37.55 FL
21	1		*BONNET LOCK CATCH LH	Bent	45.00 FL	*45.00 FL
22	1		*BONNET LOCK CATCH RH	Bent	45.00 FL	*45.00 FL
23	1		*BONNET RUBBER	Necessary	25.00 FL	*25.00 FL
24	1		*BONNET CHROME MOULDING LH	Cracked	65.00 FL	*65.00 FL
25	1		*BONNET CHROME MOULDING RH	Cracked	65.00 FL	*65.00 FL
26	1		*FRONT HEADLAMP LH	Cracked	1,780.00 FL	*1,545.11 FL
27	1		*FRONT HEADLAMP RH	Cracked	1,780.00 FL	*1,545.11 FL
28	1		*FRONT HEADLAMP PANEL LOCK LH	Bent	115.45 FL	*115.45 FL
29	1		*FRONT HEADLAMP PANEL LOCK RH	Bent	115.45 FL	*115.45 FL
30	1		*FRONT HEADLAMP LOWER BRACKET LH	Not Necessary	38.00 FL	*- FL
31	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	38.00 FL	*- FL
32	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
33	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
34	1		*FRONT FENDER INNER SHIELD LH	Deformed	124.00 FL	*124.00 FL
35	1		*FRONT FENDER INNER SHIELD RH	Deformed	124.00 FL	*124.00 FL
36	1		*FRONT WINDSCREEN PILLAR LH (NPA)	Repair	0.00 FL	*- FL
37	1		*FRONT WINDSCREEN PILLAR RH (NPA)	Repair	0.00 FL	*- FL
38	1		*FRONT SUPPORT PANEL	Buckled	544.45 FL	*544.45 FL
39	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	120.40 FL	*120.40 FL
40	1		*FRONT SUPPORT PANEL AIR INTAKE DUCT	Cracked	265.85 FL	*265.85 FL
41	1		*AIR CON CONDENSER	Serviceable	955.60 FL	*- FL
42	1		*AIR CON CONDENSER TOP AIR GUIDE	Not Necessary	102.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RADIATOR	Serviceable	654.45 FL	*- FL
44	1		*RADIATOR TOP HOSE	Serviceable	127.60 FL	*- FL
45	1		*RADIATOR BOTTOM HOSE	Not Necessary	108.70 FL	*- FL
46	1		*RADIATOR FAN COWLING C/W MOTOR	Not Necessary	1,082.05 FL	*- FL
47	1		*FRONT CHASSIS MEMBER LH	Repair	893.25 FL	*- FL
48	1		*FRONT CHASSIS MEMBER RH (NPA)	Repair	0.00 FL	*- FL
49	1		*AIR CLEANER INTAKE DUCT	Not Necessary	102.40 FL	*- FL
50	1		*AIR CLEANER BOX	Not Necessary	383.50 FL	*- FL
51	1		*ENGINE TOP COVER	Cracked	285.35 FL	*285.35 FL
52	1		*POWER STEERING TANK	Not Necessary	180.00 FL	*- FL
53	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
54	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*40.00 FS
55	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	70.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,128.75</b>	<b>7,878.17</b>
<b>- List Item Discount on L Items 5.00/5.00% (S\$)</b>	<b>698.44</b>	<b>387.16</b>
<b>Total Parts (S\$)</b>	<b>13,430.31</b>	<b>7,491.01</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	80.00	30.00
2	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.	New	100.00	30.00
3	TO REMOVE AND REFIT AIR-CON COMPRESSOR, AIR-CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS.	New	180.00	100.00
4	TOWING CHARGES - KING LORRY.	New	120.00	50.00
5	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,300.00	800.00
6	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE.	New	1,100.00	1,000.00
Gross Labour Cost (\$\$)			2,880.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >