

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: -THIRD PARTY CLAIM

Insured veh.	SKE3999S	Excess.	NIL
Policy No.	DMPPHQ17-002170	Coverage.	Comprehensive
Claiming Against.	SHA5984C	INDIA	
Insured Under.	EQ		

Vehicle Particulars & Condition

Make & Model	BMW 320i
Engine No.	B553I055N46B20BD
Chassis No.	WBAVG76010NL62372
Odometer	
Engine CC.	1998
Year Of Reg.	2008
Colour.	Grey
Parf/COE Rebate.	\$ 20,383.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 26/1/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd

Blk 6, unit 399F woodlands road, Yew Tee Ind. Est, Singapore 678006

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

Not Adhered
here
L/S
Take photos of the
up
5 day
3/1/18

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Front bumper <i>Dis</i>	\$ 920.40 /
1	Front bumper side retainer LH <i>but</i>	\$ 25.00 /
1	Front bumper side retainer RH <i>but</i>	\$ 25.00 /
1	Front bumper bracket LH <i>but</i>	\$ 15.00 /
1	Front bumper bracket RH <i>but</i>	\$ 15.00 /
1	Front bumper reinforcement <i>DD</i>	\$ 530.00 /
1	Front bumper fog lamp LH <i>11</i>	\$ 225.00 <i>x</i>
1	Front bumper fog lamp RH <i>11</i>	\$ 225.00 <i>x</i>
1	Front bumper fog lamp cover LH <i>11</i>	\$ 55.00 <i>x</i>
1	Front bumper fog lamp cover RH <i>11</i>	\$ 55.00 <i>x</i>
1	Front bumper lower grille	\$ 56.55 ?
1	Front bumper under cover	\$ 230.00 -
1	Front brace panel <i>Tw1</i>	\$ 36.00 /
1	Front grille LH <i>one</i>	\$ 117.95 /
1	Front grille RH <i>one</i>	\$ 117.95 /
1	Bonnet <i>but</i>	\$ 880.00 /
1	Bonnet hinges LH <i>R</i>	\$ 79.95 <i>x</i>
1	Bonnet hinges RH <i>R</i>	\$ 79.95 <i>x</i>
1	Bonnet logo <i>nu</i>	\$ 76.55 /
1	Bonnet centre lever <i>Tw1</i>	\$ 37.55 /
1	Bonnet lock catch LH <i>but</i>	\$ 45.00 /
1	Bonnet lock catch RH <i>but</i>	\$ 45.00 /
1	Bonnet rubber <i>nu</i>	\$ 25.00 /
1	Bonnet chrome moulding LH <i>one</i>	\$ 65.00 /
1	Bonnet chrome moulding RH <i>one</i>	\$ 65.00 /
1	Front headlamp LH <i>one</i>	\$ 1,780.00 /
1	Front headlamp RH <i>one</i>	\$ 1,780.00 /
1	Front headlamp panel lock LH <i>but</i>	\$ 115.45 /
1	Front headlamp panel lock RH <i>but</i>	\$ 115.45 /
1	Front headlamp lower bracket LH	\$ 38.00 ?
1	Front headlamp lower bracket RH	\$ 38.00 ?
1	Front fender LH <i>11</i>	Rpr <i>q</i>
1	Front fender RH <i>11</i>	Rpr <i>q</i>
1	Front fender inner shield LH <i>De</i>	\$ 124.00 /
1	Front fender inner shield RH <i>De</i>	\$ 124.00 /
1	Front windscreen pillar LH <i>11</i>	Rpr <i>x</i>
1	Front windscreen pillar RH <i>11</i>	Rpr <i>x</i>

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front support panel <i>buc</i>	\$ 544.45 ✓
1	Front support panel top garnish <i>cu</i>	\$ 120.40 ✓
1	Front support panel air intake duct <i>cu</i>	\$ 265.85 ✓
1	Air con condenser	\$ 955.60 ?
1	Air con condenser top air guide	\$ 102.40 ?
1	Radiator	\$ 654.45 ?
1	Radiator top hose <i>twi</i>	\$ 127.60 ✓
1	Radiator bottom hose <i>11</i>	\$ 108.70 x
1	Radiator fan cowling c/w motor	\$ 1,082.05 ?
1	Front chassis member LH <i>n</i>	\$ 893.25 a
1	Front chassis member RH <i>n</i>	Rpr x
1	Air cleaner intake duct	\$ 102.40 ?
1	Air cleaner box	\$ 383.50 ?
1	Engine top cover <i>cu</i>	\$ 285.35 ✓
1	Power steering tank <i>11</i>	\$ 180.00 x
		List \$ 13,968.75
		Less 5% \$ 698.44
		Total \$ 13,270.31
1	Front bumper clips (1 set) <i>nee</i>	\$ 45.00 ✓
1	Front number plate <i>but</i>	\$ 45.00 40
2	Front fender inner shield clips <i>nee</i>	\$ 70.00 50
		S/N \$ 160.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 80.00 30
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 100.00 30
	To remove and refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	\$ 180.00 100
	Towing charges - king lorry	\$ 120.00 ?
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,300.00 800
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,100.00 1000
	LABOUR	\$ 2,880.00
	Sub Total.	\$ 16,310.31
	7% GST	\$ 1,141.72
	Grand Total	\$ 17,452.03

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.