

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

ON BEHALF OF OWNER :

## Policy Particulars: -THIRD PARTY CLAIM

|                   |                 |           |               |
|-------------------|-----------------|-----------|---------------|
| Insured veh.      | SKE3999S        | Excess.   | NIL           |
| Policy No.        | DMPPHQ17-002170 | Coverage. | Comprehensive |
| Claiming Against. | SHA5984C        | INDIA     |               |
| Insured Under.    | EQ              |           |               |

## Vehicle Particulars & Condition

|                  |                   |
|------------------|-------------------|
| Make & Model     | BMW 320i          |
| Engine No.       | B553I055N46B20BD  |
| Chassis No.      | WBAVG76010NL62372 |
| Odometer         |                   |
| Engine CC.       | 1998              |
| Year Of Reg.     | 2008              |
| Colour.          | Grey              |
| Parf/COE Rebate. | \$ 20,383.00      |

## Conditions Of Tyres

|                | Size | Make |
|----------------|------|------|
| R/H Front Tyre |      |      |
| L/H Front Tyre |      |      |
| R/H Rear Tyre  |      |      |
| L/H Rear Tyre  |      |      |

## Description Of Damages

Front portion damaged.

## General Information

Accident Date. 26/1/2018  
Survey held at

**Yew Tee Automobile Tech Pte Ltd**

**Blk 6, unit 399F woodlands road, Yew Tee Ind. Est, Singapore 678006**

## Remarks

**A) THE SURVEY WAS CONDUCTED ON A "LUMPSUM" BASIS  
KINDLY LET US HAVE THE LIABILITY SOON.**

## Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

| <u>Qty.</u> | <u>Description Of Parts</u>     | <u>Pricing</u> |
|-------------|---------------------------------|----------------|
| 1           | Front bumper                    | \$ 920.40      |
| 1           | Front bumper side retainer LH   | \$ 25.00       |
| 1           | Front bumper side retainer RH   | \$ 25.00       |
| 1           | Front bumper bracket LH         | \$ 15.00       |
| 1           | Front bumper bracket RH         | \$ 15.00       |
| 1           | Front bumper reinforcement      | \$ 530.00      |
| 1           | Front bumper fog lamp LH        | \$ 225.00      |
| 1           | Front bumper fog lamp RH        | \$ 225.00      |
| 1           | Front bumper fog lamp cover LH  | \$ 55.00       |
| 1           | Front bumper fog lamp cover RH  | \$ 55.00       |
| 1           | Front bumper lower grille       | \$ 56.55       |
| 1           | Front bumper under cover        | \$ 230.00      |
| 1           | Front brace panel               | \$ 36.00       |
| 1           | Front grille LH                 | \$ 117.95      |
| 1           | Front grille RH                 | \$ 117.95      |
| 1           | Bonnet                          | \$ 880.00      |
| 1           | Bonnet hinges LH                | \$ 79.95       |
| 1           | Bonnet hinges RH                | \$ 79.95       |
| 1           | Bonnet logo                     | \$ 76.55       |
| 1           | Bonnet centre lever             | \$ 37.55       |
| 1           | Bonnet lock catch LH            | \$ 45.00       |
| 1           | Bonnet lock catch RH            | \$ 45.00       |
| 1           | Bonnet rubber                   | \$ 25.00       |
| 1           | Bonnet chrome moulding LH       | \$ 65.00       |
| 1           | Bonnet chrome moulding RH       | \$ 65.00       |
| 1           | Front headlamp LH               | \$ 1,780.00    |
| 1           | Front headlamp RH               | \$ 1,780.00    |
| 1           | Front headlamp panel lock LH    | \$ 115.45      |
| 1           | Front headlamp panel lock RH    | \$ 115.45      |
| 1           | Front headlamp lower bracket LH | \$ 38.00       |
| 1           | Front headlamp lower bracket RH | \$ 38.00       |
| 1           | Front fender LH                 | Rpr            |
| 1           | Front fender RH                 | Rpr            |
| 1           | Front fender inner shield LH    | \$ 124.00      |
| 1           | Front fender inner shield RH    | \$ 124.00      |
| 1           | Front windscreen pillar LH      | Rpr            |
| 1           | Front windscreen pillar RH      | Rpr            |

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

| <u>Qty.</u> | <u>Description Of Parts</u>         | <u>Pricing</u>     |
|-------------|-------------------------------------|--------------------|
| 1           | Front support panel                 | \$ 544.45          |
| 1           | Front support panel top garnish     | \$ 120.40          |
| 1           | Front support panel air intake duct | \$ 265.85          |
| 1           | Air con condenser                   | \$ 955.60          |
| 1           | Air con condenser top air guide     | \$ 102.40          |
| 1           | Radiator                            | \$ 654.45          |
| 1           | Radiator top hose                   | \$ 127.60          |
| 1           | Radiator bottom hose                | \$ 108.70          |
| 1           | Radiator fan cowling c/w motor      | \$ 1,082.05        |
| 1           | Front chassis member LH             | \$ 893.25          |
| 1           | Front chassis member RH             | Rpr                |
| 1           | Air cleaner intake duct             | \$ 102.40          |
| 1           | Air cleaner box                     | \$ 383.50          |
| 1           | Engine top cover                    | \$ 285.35          |
| 1           | Power steering tank                 | \$ 180.00          |
|             |                                     | List \$ 13,968.75  |
|             |                                     | Less 5% \$ 698.44  |
|             |                                     | Total \$ 13,270.31 |
| 1           | Front bumper clips (1 set)          | \$ 45.00           |
| 1           | Front number plate                  | \$ 45.00           |
| 2           | Front fender inner shield clips     | \$ 70.00           |
|             | S/N                                 | \$ 160.00          |

# YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

ROC: 200311009C GST: 200311009C

Website: [www.ytauto.com.sg](http://www.ytauto.com.sg)

| <u>Qty.</u>          | <u>Description Of Parts</u>                                                                                                                                                                         | <u>Pricing</u>             |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|
| <b><u>LABOUR</u></b> |                                                                                                                                                                                                     |                            |
|                      | To apply undercoating on the repaired and replaced panels for rust protection.                                                                                                                      | \$ 80.00                   |
|                      | To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.                                                                                                  | \$ 100.00                  |
|                      | To remove and refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.                                                                                       | \$ 180.00                  |
|                      | Towing charges - king lorry                                                                                                                                                                         | \$ 120.00                  |
|                      | To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.                     | \$ 1,300.00                |
|                      | To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available. | \$ 1,100.00                |
|                      | LABOUR                                                                                                                                                                                              | <u>\$ 2,880.00</u>         |
|                      | Sub Total.                                                                                                                                                                                          | \$ 16,310.31               |
|                      | 7% GST                                                                                                                                                                                              | <u>\$ 1,141.72</u>         |
|                      | Grand Total                                                                                                                                                                                         | <u><u>\$ 17,452.03</u></u> |

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.