



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 26th January 2018
Motor Claims Department
Indian International Insurance Pte Ltd
64 Cecil St #05-00
10 B Building
Singapore 048711

Dear Sirs,

Re: Cost of repair to Yamaha C20300A/XMA300 - TBM 24566

1 pc of Windscreens	240.00 MIS
" Brake lever	75.00 SCR
1 set of Mirror	140.00 SCR
1 pc of Front fairing	410.00 SCR
1 set of Centre fairing	560.00 SCR
1 pc of Lower cowling	240.00 SCR
" Exhaust pipe guard	140.00 SCR
1 set of Footrest plate	360.00 SCR
" Side box	price? - 540.00 SCR
1 pc of Main stand	150.00 X
" Handle bar	220.00 X

3,330.00

333.30

2,996.70

Less 10%

Net

Insurance

Labour

20.00

20.00

240.00 180

3,276.70

HP 90010068

2 days

P/P

01/02/18 @ 1445

Resurvey by repair

Tel 6247 6100

Email: motorclaim@iii.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR