

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

29/01/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- SFU5537D

Veh Model :- TOYOTA COROLLA

Estimate# :- CK416975

Claim # :-

ACC. Date :- 28/01/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT	1 PC	865.10	865.10
2.	REAR BOOT LOGO	1 PC	86.30	86.30
3.	REAR BOOT EMBLEM "1.6"	1 PC	67.10	67.10
4.	REAR BOOT EMBLEM "E"	1 PC	56.20	56.20
5.	REAR BOOT EMBLEM "VVTI"	1 PC	67.10	67.10
6.	REAR BOOT EMBLEM "COROLLA"	1 PC	89.60	89.60
7.	REAR BOOT EMBLEM "ALTIS"	1 PC	89.60	89.60
8.	REAR BOOT LOCK	1 PC	141.20	141.20
9.	REAR BOOT RUBBER	1 PC	172.30	172.30
10.	REAR BOOT LAMP RH	1 PC	165.80	165.80
11.	TAILLAMP L+R	2 PC	278.30	556.60
12.	TAILLAMP CLIPS	2 PC	4.10	8.20
13.	TAILLAMP LOWER PANEL RIVET	8 PC	6.00	48.00
14.	REAR PANEL - photo	1 PC	693.20	693.20
15.	REAR PANEL INNER TRIM	1 PC	166.70	166.70
16.	REAR BUMPER	1 PC	692.10	692.10
17.	REAR BUMPER RETAINER L+R	2 PC	52.30	104.60
18.	REAR BUMPER SIDE SHIELD RH	1 PC	86.50	86.50
19.	REAR BUMPER CLIPS	10 PC	5.10	51.00
LIST TOTAL S\$				4,207.20
25% DISCOUNT S\$				-1,051.80
				3,155.40
SPECIAL NET ITEMS :				
1.	REAR BUMPER LOWER SPOILER	1 PC	550.00	550.00
2.	REAR BUMPER SENSOR	1 PC	250.00	250.00
SPECIAL NET TOTAL S\$				800.00
LABOUR :				
TO CUT/WELD REAR PANEL, TO REPAIR REAR FLOOR PANEL, TAILLAMP LOWER PANEL, REMOVE AND REFIX DAMAGED PARTS. STRAIGHTEN AND RELAIN				700
AFFECTED AREAS				840.00
TO SPRAY AFFECTED AREAS				700
				850.00
TO REMOVE AND REFIX LUGGAGE COMPARTMENT SIDE GARNISH, SIDE TRIM BOARD, CARPET AND OTHER ATTACHMENT PARTS				40
				80.00
TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE				30
				60.00
TO RUST PROOF AFFECTED AREAS				30
				60.00
LABOUR TOTAL S\$				1,890.00

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: **(65) 6272 3892**
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

29/01/2018

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 130598

Veh # :- SFU5537D

Veh Model :- TOYOTA COROLLA

Estimate# :- CK416975

Claim # :-

ACC. Date :- 28/01/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,845.40

GST @ 7 % 409.18

AMOUNT DUE S\$ 6,254.58

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanglin 97495749
- WP

31/1/18 @ 6/5pm

Lumpsum

Resurvey after repair -

5 days.

sur @ lkkauto.com