

22/01/2002

81

ASS. REC. BY:

REF: CS/CTI18001922/R/ed302 Special Instruction:

Surveyor:

Merimen

Rasul

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time:

30/1/18 @ 5.30pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 6447L

Insured:

SFP 8615T

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Road

Policy No:

DMPCSN 3006911800

Claim No:

SNM18D00559C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/01/2018

CA / REV / REP. / REV 24 HRS 'wup'

H.O.D. Endorsement:

Date/Time:

11:28am @ 31/1/18

Person Contacted:

Caroline

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLE 6447L-X

SFP 8615T-X

13/2 3.37pm

Caroline said owner revert to OD claim under CTI and Eddie already survey and finalised with them.

13/2


Submit preli report.

REF: 9462A

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLE 6447L  
 at Workshop n/s PERFORMANCE  
 of \_\_\_\_\_  
 Insured: CTI / TP  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition) Hm  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLE 6447L Yr Regn: 2016 July  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: F.M.W 1160 C.O. 1496  
 Colour: WHITE A/C: Insured / Std / NI / NA  
 Sp. Reading: 27088 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBA 1V720X0V724662  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / STD A/Rim / STD A/Rim or  
 Tyre Size: F: 205/55R16  
 R: 7  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 26/01/18 D.O.I. 01/02/18  
 Survey held at PERFORMANCE  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
 RECEIVED 13 FEB 2019

Date/Time, File Pass to? ☒ : Preli. Report  
☐ : Final Report  
 Days Of Repair: 7  
 Resurvey No. of Trip: - Survey Fee: 220  
 Date/Time, File Return to? 2  
 Add Fee: ☐ : Site Insp (\$ -)  
☐ : Interview (\$ -)  
☐ : Tech. Invs (\$ -)  
☐ : Weekend (\$ -)  
 Report Format : TP  
 Lump Sum / I.B.I: (\$ -)  
 TOTAL 220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18001922/R1rd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-01-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFP 8615T	Veh. Inspected	SLE 6447L
Policy No.	DMPCSN3006911800	Coverage (\$)	0.00
Claim No.	SNM18D00559C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	31/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	26/01/2018	Inspection Date	31/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2018		30 Jan 2018 17:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	YUEN DA-WEN DAVID, ID: S8019402A		
Vehicle Reg. No.:	SLE6447L	Date of Loss:	26/01/2018 00:00 - :59
Claim Type:	TP / SNM18D00559C02	Policy/Cover Note No.:	DMPCSN3006911800
Vehicle Reg. No. (Insured):	SFP8615T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/02/2018]		
Adj Asg. Remarks:	EST \$15,915.13 , CASE W/O SJE		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/01/2018 18:00
Date Of Accident	26/01/2018 17:55
Exact Location Of Accident	ALEXANDRA RD TWDS GANGES AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE6447L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YUEN DA-WEN DAVID
NRIC No	S8019402A
Email Address	DAVID_YUEN13@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96407674
Alternative Phone No	OFFICE-63190184

### Vehicle Particulars

Manufacturer	BMW
Model	116D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	YUEN DA-WEN DAVID
NRIC No	S8019402A
Date Of Birth	13/06/1980
Occupation	INDOOR
Date Of Driving Pass	26/08/2010
Driving Experience	7 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96407674
Fax Number	
Contact Number	OFFICE-63190184
EMail Address	DAVID_YUEN13@YAHOO.COM.SG

Address	BLK 167 YISHUN RING RD #07-747
Postcode	760167
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFP8615T
Vehicle Make/Model/Colour	TOYOTA CAMRY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JEFFREY
NRIC/Passport Number	S8817803C
Contact Number	91909909
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
29 Jan 2018, 0830hrs

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN

1. What is the main purpose of the study?  
 2. What are the research objectives?  
 3. What is the research methodology?  
 4. What are the results of the study?  
 5. What are the conclusions of the study?  
 6. What are the limitations of the study?  
 7. What are the implications of the study?  
 8. What are the future research directions?  
 9. What are the contributions of the study?  
 10. What are the key findings of the study?

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It was around 1755hrs, daylight with light rain. The road is wet, traffic was heavy and slow. I was driving along Alexandra Road towards Fringes Avenue. Somewhere near the stretch of road, outside Alexandra Primary School. I began to slow down my car for red light traffic ahead. As my car was about to come to a stop. Suddenly, I felt a strong impact from the rear. I switched on my hazard light and alighted my car to check on the situation. That was when I realised a car had crashed into the rear of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:



SLE6447L

BMW Dealer

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 JAN 2018

**E S T I M A T E**

Page No. : 1 of 2

Estimate No. : b1 45674  
Date Estimated : 27/01/2018  
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -  
YUEN DA-WEN DAVID  
APT BLK 646 YISHUN STREET 61  
06-344  
SINGAPORE  
SINGAPORE 760646

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6447L	V724662	28/07/2016	116d	0

DESCRIPTIONVALUE

To replace rear bumper & attachments including to knock out boot lid, tail panel, trunk floor panel and dented area caused by the accident

2975 3,825.00

To respray rear bumper, boot lid, tail panel and trunk floor panel

2877 3,187.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

748 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

To replace engine mountings including re-alignment of engine block to body frame.

577 679.00

To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.

577 679.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To supply rear emboss number plate.

74 83.00

Sundries.

150.00

Total Labour 1: 10,029.00

DESCRIPTIONQTY PRICVALUE

Rubber Mount

2 33.65

67.30

TAILPIPE END PIECE ALU LOOK

1 99.65

542 99.65

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 45674  
Date Estimated : 27/01/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6447L	V724662	28/07/2016	116d	0

DESCRIPTION	QTY	PRIC	VALUE
REAR LH SILENCER BRACKET	1	41.70	41.70
CLAMPING BUSH D=65.2MM	1	54.30	54.30
FRONT PIPE	1	492.70	492.70
MUFFLER CLAMP D=63.2MM	1	41.80	41.80
REAR SILENCER	1	864.80	864.80
LH ENGINE MOUNT	1	193.70	193.70
RH ENGINE MOUNT	1	193.70	193.70
GEARBOX MOUNTING	2	38.80	77.60
REAR BUMPER CARRIER	1	375.90	375.90
REAR BUMPER CENTRE GUIDE (M)	1	56.05	56.05
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER LH MOUNT	1	141.65	141.65
REAR BUMPER RH MOUNT	1	141.65	141.65
REAR BUMPER PANEL PRIMED	1	880.25	880.25
REAR PDC HOLDER SET	1	22.55	22.55
EMBLEM GROMMET	2	0.80	1.60
# HEAT INSULATOR REAR SILENCER	1	60.10	60.10
PLAQUE 82MM	1	67.80	67.80
# LH REFLECTOR	1	34.35	34.35
RH REFLECTOR	1	34.35	34.35
NUMBER PLATE LIGHT LED	2	23.20	46.40
DECOUPLING RING PDC TORQUE CONVERTE	2	4.95	9.90
# RR PDC SENSOR ALPINWEISS (30	2	368.80	737.60
(DG) ADHESIVE SET K6	1	53.05	53.05

Total Parts : 4,844.95

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date/Time 01/02/18 @ 1210 Excess S\$

Surveyor's Name RASUL Sign

Surveyor's Tel. 90010068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS QUOTED BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Labour 1 : 10,029.00

Parts : 4,844.95

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,041.18

Grand Total : 15,915.13

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)

























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2018		30 Jan 2018 17:30 <a href="#">Edit Adj Rpt</a>	<b>S\$8,805.35</b> <a href="#">Edit Estimates</a>	<b>S\$8,805.35</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>YUEN DA-WEN DAVID</b> , ID: S8019402A								
Vehicle Reg. No.:	<b>SLE6447L</b>	Date of Loss:	26/01/2018 00:00 - :59 [17 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D00559C02</b>	Policy/Cover Note No.:	DMPCSN3006911800						
Vehicle Reg. No. (Insured):	<b>SFP8615T</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 08/02/2018]								
Adj Asg. Remarks:	EST \$15,915.13 , CASE W/O SJE								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLE6447L (SNM18D00559C02)  
[SFP8615T]  
TP  
YUEN DA-WEN DAVID  
Jan 26 2018 12:00AM  
[-]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
2	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
3	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
4	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
5	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
6	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
7	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
8	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
9	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
10	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
11	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
12	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
13	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
14	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
15	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
16	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
17	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
18	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
19	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
20	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
21	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
22	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
23	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
24	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
25	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
26	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
27	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
28	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
29	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
30	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
31	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
32	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
33	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
34	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
35	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
36	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	
37	13/02/19 15:46	General View								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/02/19 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/18 17:29	REPAIR EST	 Load TIF	
2	30/01/18 17:29	TP GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18001922/T1RD3E2

Date: 13/02/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3006911800

Claimant Vehicle  
No: SLE6447LInsured Vehicle  
No: SFP8615T

Date of Loss: 26/01/2018

Nature of Claim: TP

Claim  
No: SNM18D00559C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLE6447L

Make &amp; Model: BMW 116D, 1.6 (A)

Reg. Date: 28/07/2016 (Man. Year: 2016)

Colour: White

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 30369576B37D15A

Chassis No: WBA1V720X0V724662

Odometer: 27088 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,077.95	2,202.35	2,875.60	56.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,796.00	6,603.00	3,193.00	32.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,873.95</b>	<b>8,805.35</b>	<b>6,068.60</b>	<b>40.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,041.18</b>	<b>616.37</b>	<b>424.81</b>	<b>40.80</b>
<b>Nett Amount (S\$)</b>	<b>15,915.13</b>	<b>9,421.72</b>	<b>6,493.41</b>	<b>40.80</b>

## INSPECTION

Date of Assignment: 30/01/2018

Date Inspected: 01/02/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,675.75 NETT)



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2019)
<b>Parts:</b> 144	BMW 116D 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLE6447L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	2		*RUBBER MOUNT	* Check	67.30 FS	*- FS
4	1		*TAILPIPE END PIECE ALU LOOK	Scratched	99.65 FS	*99.65 FS
5	1		*REAR LH SILENCER BRACKET	* Check	41.70 FS	*- FS
6	1		*CLAMPING BUSH D=65.2MM	* Check	54.30 FS	*- FS
7	1		*FRONT PIPE	* Check	492.70 FS	*- FS
8	1		*MUFFLER CLAMP D=63.2MM	* Check	41.80 FS	*- FS
9	1		*LH ENGINE MOUNT	* Check	193.70 FS	*- FS
10	1		*RH ENGINE MOUNT	* Check	193.70 FS	*- FS
11	2		*GEARBOX MOUNTING	* Check	77.60 FS	*- FS
12	1		*REAR BUMPER CARRIER	* Check	375.90 FS	*- FS
13	1		*REAR BUMPER CENTRE GUIDE (M)	* Check	56.05 FS	*- FS
14	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	54.50 FS	*- FS
15	1		*REAR BUMPER LH MOUNT	* Check	141.65 FS	*- FS
16	1		*REAR BUMPER RH MOUNT	* Check	141.65 FS	*- FS
17	1		*REAR BUMPER PANEL PRIMED	Deformed	880.25 FS	*880.25 FS
18	1		*SET REAR PDC HOLDER	* Check	22.55 FS	*- FS
19	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
20	1		*#HEAT INSULATOR REAR SILENCER	Bent	60.10 FS	*60.10 FS
21	1		*PLAQUE 82MM	* Check	67.80 FS	*- FS
22	1		*#LH REFLECTOR	* Check	34.35 FS	*- FS
23	1		*RH REFLECTOR	Not Necessary	34.35 FS	*- FS
24	2		*NUMBER PLATE LIGHT LED	* Check	46.40 FS	*- FS
25	2		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	9.90 FS	*9.90 FS
26	2		*#RR PDC SENSOR ALPINWEISS (30	* Check	737.60 FS	*- FS
27	1		*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
28	1		*REAR SILENCER	Bent	864.80 FS	*864.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **5,077.95**      **2,202.35**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT BOOT LID, TAIL PANEL, TRUNK FLOOR PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	3,825.00	2,975.00
2	TO RESPRAY REAR BUMPER, BOOT LID, TAIL PANEL AND TRUNK FLOOR PANEL	New	3,197.00	2,877.00
3	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK (* Check)	New	531.00	0.00
4	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
5	TO REPLACE ENGINE MOUNTINGS INCLUDING RE-ALIGNMENT OF ENGINE BLOCK TO BODY FRAME (* Check)	New	679.00	0.00
6	TO REPLACE GEARBOX MOUNTINGS INCLUDING RE-ALIGNMENT OF GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM (* Check)	New	679.00	0.00
7	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>9,796.00</b>	<b>6,603.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >