

ASS. REC. BY:

REF: CS/MSG/18001928/Titd302

Survivor

Taufik

ASSIGNMENT (Office)

From (Person)

Monica chung

of

MSG

Date/Time

31/11/18 @ 9.56am

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 3840R

Insured:

SJL 1088)

at Workshop m/s

Komoco Motors

Tel:

64735588

of

253 Alexandra Motors

Policy No:

A28634851 QMY

Claim No:

547219

Sum Insured

Excess:

Make of Veh:

D.O.A.

21/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS / up

H.O.D. Endorsement:

Date/Time

11:33am @ 31/11/18

Person Contacted

Zoey

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ3840R-X

SJL10881-CVI/VAL18001458/CV

D.O.A.: 21/01/18

6/2-

Report via menmen

Part by Part \$29,433.24 (Red: 7028; 19%)


Tuplin

REP

MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OO (TP) / WS / TP RES / OO RES / EVA / INV / MV
 To inspect vehicle No: _____
 At Workshop No: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value: **9100K**
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: **Engine** Vehicle: IN / OUT

Date Time Action / Instruction **64735588**
Price ok!

Vehicle: **SLQ 3840R** or Regn: **2017 July**
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or
 Make: **Hyundai Santa Fe** or **1999.**
 Colour: **Black** or Insured: Std / Nil / NA
 Sp. Reason: **14899.** or T. Regn: Insured / Std / Nil / NA
 Engine: _____
 C No: **KMH E341CMH A271224**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: Nil / 8 Rim / STD A/Rim or
 Tyre Size: F: **235/45R18**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI
 TOYO / YOKO or **Michelin**
 Front: _____ Rear: _____
 R. Bal: **6** mm R. Bal: **6** mm
 L. Bal: **6** mm L. Bal: **6** mm
 D.O.A: _____ D.O: **5/2/18**
 Survey held at: **Komoco Motor**
 Des. of Damages: ☒ Front / ☒ Rear / O/S / NS / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED at G. AUG 2018

6/8/2018

Date Time Pre Pass or
6/8 Typist
 Date Time Pre Return or
☐ Prel. Report
☒ Final Report

Days Of Repair: **12**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ Test only \$
☐ Rep. & C. \$

Report Format: **TP**
 Lump Sum: **29,933.24**

Survey Fee: **350**
 Transport: _____
 Fuel: _____
 Other: _____
350

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		31 Jan 2018 09:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JOEL CHAN KUM HOONG, ID: S1812061E, Tel: +6596610947, Email: joe3023@gmail.com		
Main Claimant:	KOMOCO CAR RENTALS PTE LTD, Co. Reg. No.: 199500095K		
Vehicle Reg. No.:	SLQ3840R	Date of Loss:	21/01/2018 16:00 - :59
Claim Type:	TP / 547219	Policy/Cover Note No.:	A28634851QMY (Comprehensive) Coverage: 01/12/2017 - 30/11/2018
Vehicle Reg. No. (Insured):	SJL1088J	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Komoco Motors Pte Ltd (HQ) 253 ALEXANDRA ROAD, #01-01, 159936 Alexandra - Tel: 64735588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2018]		
Driver/Custodian (Insured):	JOEL CHAN KUM HOONG (51 / Male), NRIC: S1812061E, Tel: +6596610947		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001928/T1td3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 1088J	Veh. Inspected	SLQ 3840R
Policy No.	A28634851QMY	Coverage (\$)	0.00
Claim No.	547219	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/01/2018	Inspection Date
Survey held at	KOMOCO MOTORCYCLES PTE LTD 253 ALEXANDRA ROAD #01-04 SINGAPORE 159936	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199007190R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 06 Feb 2018

Preliminary Advice

Insured Vehicle No	: SJL1088J	Accident Date	: 21/01/2018
TP Vehicle No	: SLQ3840R	Assignment Date	: 31/01/2018
Make	: HYUNDAI SONATA LF	Est. Duration of Repair	: 14.00
Date of Inspection	: 05/02/2018		
Inspection At	: KOMOCO MOTORS PTE LTD (HQ) 253 ALEXANDRA ROAD, #01-01 SINGAPORE 159936		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,203.44
Revised Amount	:S\$	16,499.68
Check Items (Estimated)	:S\$	13,259.28
Total	:S\$	29,758.96
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

588	2560		
133.2	1750		
29.7	320		
356.4	320		
31.9	40		
31.9	40		
435.3	180	47.9	
42	108	324.7	
142.7	40	93.1	
142.7	5358	1660.1	
36.7		1660.1	
36.7		14.6	
51		14.6	
1241.6		63.7	
348.1		783.6	
27.5		332.7	
168.4		913.5	
99.5		538.7	
124	16499.68	63.7	
1855.9		216.2	
12		982.3	
794.2		47.8	
868		41.7	
171.2		645.6	140
42.2		645.6	16499.68
27.5		113.4	13119.28
1688.8		340.3	29758.96
696.4		297.6	
60.1		195.9	
821.7		195.9	
17.9		2772.3	
15.8		839.6	
15.8		927.5	
2772.3		907.4	
13927.1		619	13119.28
11141.68		100	140
		16399.1	13259.28
		13119.28	



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0095K
Vehicle Details	
Vehicle No.:	SLQ3840R
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	LF SONATA 2.0 GLS A/T S/R
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	G4NAGA532551
Chassis No.:	KMHE341CMHA271224
Maximum Power Output:	113.0 kW (151 bhp)
Open Market Value:	\$23,006.00
Original Registration Date:	07 Jul 2017
First Registration Date:	07 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$24,209.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jul 2027
PARF Rebate Amount:	\$18,156.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10

QP Paid:	\$49,802.00
COE Rebate Amount:	\$39,841.00
Total Rebate Amount:	\$57,997.00

The information contained herein is correct as at 06 Feb 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Articles



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

12/2014 Camry 2.5A Cheapest In The Market! Way Wait!



Agent Maintained Still Under
Warranty Flexible Loans
Available Very Low Mileage.
AutoPrestige Gallery

- Free VICOM eva
- Free grooming &
- In-house work
- Member of SYTA
- 100% deposit re

YONG

Browse by Category

Sort by Da

9 vehicles

hyundai sonata

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	hyundai sonata		Any	Any	Any	Any	Any
	Hyundai Sonata VIII 2.0A GLS Sunroof		\$87,888	\$10,590 /yr	20-Mar-2015	1,999 cc	-
Don't Miss! Price Can Negotiable! (100% Quality Buy)! (100% Accident Free)! 1 Careful Owner! Fully KOMOCO Servicing! 5 Y KOMOCO! Original Paintworks Since Day 1! Luxury Sporty High Spe...							
Posted: 02-Feb-2018 Tags: 2015 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai							
	Hyundai Sonata 2.0A NF		\$17,800	\$8,070 /yr	25-Feb-2009	1,998 cc	160,000
\$0 Down Payment Available! Balloon Scheme Available! We Are SGCARMART Premium Dealer 2015-2017! Buy With Confiden Mileage! 100% Accident Free! In House Loan Or Bank Loan Availab...							
88 Motor Trading							
Posted: 01-Feb-2018 Tags: 2009 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai							
	Hyundai Sonata 2.0A NF		\$20,800	\$8,610 /yr	15-Jul-2009	1,998 cc	-
No Gimmicks! Mileage Done At 19000Km Yearly, Leather Seats, Silver In Colour, Service Regularly, Tip Top Condition, Good I Renew New COE, Price Inclusive Of GST.							
Posted: 26-Jan-2018 Tags: 2009 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai							
	Hyundai Sonata VIII 2.0A GLS Sunroof		\$89,800	\$10,770 /yr	24-Apr-2015	1,999 cc	-
Low Down Payment, In House Finance Avail, Cheapest In Town. Owned By 1 Fussy Car Lover. Car In Showroom Condition. Co Warranty With Komoco. Buy With Confidence And Don't Need To Spent A S...							
Posted: 26-Jan-2018 Tags: 2015 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai							

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 15:29
Date Of Accident	21/01/2018 16:30
Exact Location Of Accident	BMENT C/PARK OF 62 CHESTNUT AVE TREE HOUSE CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3840R
Insured/Policyholder	
Name Of Registered Owner	KOMOCO CAR RENTALS PTE LTD
Co Reg No	199500095K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-38793040

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA LF-2.0 GLS A/T (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VFX/P1305555
Cover Note Number	

Driver

Name of Driver	DE SILVA CEDRIC ARTHUR
NRIC No	S1624472D
Date Of Birth	31/01/1963
Occupation	OUTDOOR
Date Of Driving Pass	31/10/2003
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97577858
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

A. SLQ3840R
B. SLZ10885

✓ SKETCH PLAN



✓ DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my car (A) SLQ3840R was parked in the car park lot facing in, On 20 Jan at 1900pm. Next day, on 22 Jan 18 at about 1630 hrs, car (B) SLZ10885 coming in and was about to turn ~~left~~, driven by MR SOEL CHAN Kim HONG, when he drove straight into the rear of my car (A). The impact of the accident caused my car to move forward and crash into the wall causing damage to the wall, front of my car (SLQ3840R) and rear part of my car. At the time of accident, I was not present. ~~That is all~~ as I had parked the car the day before the accident.

That's all.

DECLARATION

KOMODO CAR RENTALS PTE LTD
253 ALEXANDRA RD #01-02
SINGAPORE 119938

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Approve the policyholder's signature
Name
S&C

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the Gik Report Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may and are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes:
 - (i) processing, handling and/or dealing with my claims—including the settlement of the claims and any relevant investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me including about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may and are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may can be disclosed by any of the insurers and/or GIA to their third party vehicle providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NO 4/200
253 015000000 0010 001-02
SINGAPORE 150930

Policyholder's Signature
Date & Time

Driver's Signature
(if Driver is not the policyholder)
Date & Time

Reported by Addressee's Signature
Name
Spec. Title

AXA INSURANCE PTE LTD

8 Sheraton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel: 6338 7288 Fax: 6338 2522
 Website: www.axa.com.sg
 GST Registration Number: 199903512M

**Insurer's Copy**

Agent Code: **08268**
 Policy No. (if any): **P1305555 RISK 415**

Extension for RT (for Fleet)

SmartDrive Quote Ref:

MOTOR COVER NOTENo. **CN866453**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby **HELD COVERED** under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	KOMOCO CAR RENTALS PTE LTD
MAKE AND DESCRIPTION OF VEHICLE	HYUNDAI SONATA 2.0 2.0 GLS SR
VEHICLE REGISTRATION NO.	SLQ3840R
YEAR OF MANUFACTURE	2017
ENGINE NO.	G4NAGA532551
CHASSIS NO.	KMHE341CMHA271224
ENGINE CAPACITY/TONNAGE	1999
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	N/A
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 19/12/2017 TO: 18/12/2018
EXCESS (S\$)	AS PER POLICY
AXA PREMIUM WORKSHOP?	NO

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Issued by **ROSNANI MD NOOR** on **24/01/2018 3:43pm**

Authorised Signature

Note : This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged:
 - o Cover note issued and cancelled before inception.
 - o Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

REPUBLIC OF SINGAPORE
ENTITY CARD NO. S1624472D



Name

DE SILVA CEDRIC ARTHUR

Race

EURASIAN

Date of birth

31-01-1963

Sex

M

Country of birth

SINGAPORE



3463

NRIC No. S1624472D



Date of issue

04-01-2005

APT BLK 442D FAJAR ROAD #10-42
SINGAPORE 674442

NRIC No. S1624472D

Date: 24/08/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 2B Motorcycles not exceeding 200 cc

28 Sep 1995

Class 2A Motorcycles between 201 cc and 300 cc

02 Nov 1992

Class 3 Motor Cars and Motor Tractors (no weight of

21 Nov 1995

which limitations does not exceed 2500 kilograms

P 128A

Licence No: S1624472D



REPUBLIC OF SINGAPORE DRIVING



Licence Number: S 1624472D

Name:

DE SILVA CEDRIC ARTHUR

Birth Date: 31 Jan 1963

Issue Date: 21 Mar 2003





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-011958

Date of Request: 23/01/2018

Your Ref No:

Online Purchase

Komoco Motors Pte Ltd
253 Alexandra Road #01-01
Singapore 159936

Dear Sir/Madam,

Enquiry Date 23/01/2018
Enquiry By EUGENE PANG YORK LIANG
TP Vehicle No. SJL1088J
Accident Date 21/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJL1088J	MSIG Insurance (Singapore) Pte. Ltd.	01/12/2017-30/11/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



KOMOCO MOTORS PTE. LTD.

75/1 Alexandra Road #01-01 Singapore 110001
TEL: 654 6473 5585 FAX: 654 6472 1433 www.komoco.com.sg
ROR NO: 1896092935

(GST REGISTRATION NO : MR-85000364-4)

Date: 23 Jan 2018

MSIG

Attn: Motor Claims Dept /

Vehicle number : **SLQ 3840 R**
Make and model : **Hyundai Sonata V111 2.0 GLS A(S/R)**
Registration Date : **07 July 2017**
Chassis number : **KMHE341CMHA271224**
Engine number : **G4NAGA532551**

Invoice No. :
Job No. : **2018002881**
Policy Holder : **Komoco Car Rentlas P/L**
Date of Acc. : **21 Jan 2018**
Policy number : **VPX/P1305555**
Claim Type : **T.P.Claim Against MSIG**
: **SJL 1088 J**

Rear Items:

1	Rear bumper cover	86610-C1000
2	Rear bumper lower cover	86612-C1100
3	Rear bumper ctr cover(under)	86697-C1000
4	Rear bumper side cover(under)	86698-C1000
5	Rear fog lamp	92405-C1100
6	LH rear reflector	92405-C1000
7	RH rear reflector	92406-C1000
8	BWS EXT wire harness	91890-C1040
9	Rear bumper beam	86631-C1000
10	Rear beam lower ctr brkt x 4	86635-C1000
11	Smartkey antenna	95420-C1200
12	LH rear bumper stay	86641-C1000
13	RH rear bumper stay	86642-C1000
14	LH rear bumper side mtg brkt	86613-C1001
15	RH rear bumper side mtg brkt	86614-C1001
16	License plate lamp assy x 2	92501-C1000
17	LH BSD sensor	95811-C1001
18	RH BSD sensor	95821-C1001
19	Rear boot lid cover	69200-C1020
20	Back panel	69100-C1000
21	Symbol emblem	86300-C1000
22	Trunk lid inner trim	81750-C1000TRY
23	LH trunk lid hinge	81911-C1000TRY
24	RH trunk lid hinge	81921-C1000TRY
25	LH trunk lid arm cover	81911-C1000TRY
26	RH trunk lid arm cover	81921-C1000TRY
27	Trunk lid weatherstrip	87321-C1000
28	Trunk lid latch	81230-C1000
29	Trunk lid transverse trim	85770-C1000TRY
30	Ultrasonic BWS sensor x 4	95720-C1000TB7

Estimated

\$	588.00	de ✓
\$	133.20	de ✓
\$	29.70	de ✓
\$	47.90	? X nu ✓
\$	356.40	dis ✓
\$	31.90	cro ✓
\$	31.90	cro ✓
\$	324.70	? X nu ✓
\$	435.30	cro ✓
\$	42.00	ne ✓
\$	93.10	? X nu ✓
\$	142.70	ner ✓
\$	142.70	ner ✓
\$	36.70	ner ✓
\$	36.70	ner ✓
\$	51.00	dis ✓
\$	1,660.10	? ✓ dis ✓
\$	1,660.10	? X nu ✓
\$	1,241.60	bt ✓
\$	348.10	bt ✓
\$	27.50	ner ✓
\$	168.40	de ✓
\$	14.60	? ✓ bt ✓
\$	14.60	? ✓ bt ✓
\$	14.60	X ✓ X nu ✓
\$	14.60	X ✓ X nu ✓
\$	99.50	twi ✓
\$	124.00	bt ✓ ✓ 112
\$	63.70	? ✓ de ✓
\$	783.60	? ✓ X nu ✓

Tanfiah 97495749
- WP
5/2/18 @ 1630
Resurvey before paint.
sur@lkhauto.com
tanfiah@lkhauto.com.
12 days - 14 days
12/2/18
117340

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **Estimate**
Date:

Vehicle number : SLQ 3840 R
 Make and model : Hyundai Sonata V111 2.0 GLS A(S/R)
 Registration Date : 07 July 2017
 Chassis number : KMHE341CMHA271224
 Engine number : G4NAGA532551

Job No. : 2018002881
 Policy Holder : Komoco Car Rentlas P/L
 Date of Acc. : 21 Jan 2018
 Policy number : VPX/P1305555
 Claim Type : T.P.Claim Against MSIG
 : SJL 1088 J

Rear Items:

31 Rear exhaust muffler	28710-C1010
32 LH rear fender	71503-C1C01
33 LH rear inner fender	70100-C1A01
34 LH rear 1/4 glasss	87810-C1000
35 Rear floor panel	65513-C1000
36 LH rear floor member	65710-C1200
37 Back panel moulding	87370-C1050
38 Moulding clip x 20	92552-36000
39 LH rear tail lamp	92401-C1030
40 LH rear inner lamp	92403-C1030
41 LH luggage trim	85730-C1000TRY
42 RH luggage trim	85740-C1000TRY
43 Transverse trim	85770-C1000TRY
44 Luggage cover mat	85710-C1030TRY
45 Sonata emblem	86310-C1000
46 Symbol mark emblem	86300-C1000
47 Rear view camera assy	95420-C1100

Estimated

\$ 1,112.20	α m
\$ 1,855.90	bt ✓
Repair	
\$ 332.70	? ✓ bt ✓
\$ 878.30	Rx
\$ 913.50	? f n
\$ 538.70	? f n dis ✓
\$ 12.00	α x n
\$ 794.20	Cro ✓
\$ 868.00	Cro ✓
\$ 171.20	de ✓
\$ 171.20	x n
\$ 63.70	? f n
\$ 216.20	? f n
\$ 42.20	ne ✓
\$ 27.50	α x n
\$ 982.30	? dis ✓

Front items:

48 Front bonnet	66400-C1000
49 Front bumper cover	86510-C1000
50 Front bumper upper rubber strip	86362-C1000
51 Front bumper grille	86561-C1000
52 Radiator grille upper cover	86361-C1000
53 Radiator grille	86350-C1100
54 License plate moulding	86519-C1000
55 LH front fog lamp cover	86521-C1210
56 RH front fog lamp cover	86522-C1210
57 LH day running light	92207-C1000
58 RH day running light	92208-C1000
59 Front bumper absorber	86520-C1000
60 Front bumper lwr stiffner	86570-C1100
61 Front bumper rail	86530-C1000
62 BWS Ext wire harness	91890-C1510
63 BWS sensor x 2	95720-C1100TB7
64 BWS ultrasonic sensor x 2	95720-C1000TB7
65 LH side bumper brkt	86513-C1000
66 RH side bumper brkt	86514-C1000
67 LH headlamp assy	92101-C1120
68 RH headlamp assy	92102-C1120

\$ 1,688.80	de ✓ 2411.70
\$ 696.40	Cro ✓
\$ 47.80	? x n
\$ 41.70	? x n
\$ 60.10	Cro ✓
\$ 821.70	α ✓
\$ 17.90	de ✓
\$ 154.50	x x n
\$ 154.50	x x n
\$ 645.60	? ✓ out
\$ 645.60	? ✓ out
\$ 113.40	? ✓ de
\$ 119.60	x ✓ de
\$ 340.30	? ✓ bt
\$ 297.60	? ✓ out
\$ 195.90	? x n
\$ 195.90	? x n
\$ 15.80	α ✓
\$ 15.80	α ✓
\$ 2,772.30	? ✓ out
\$ 2,772.30	out ✓

Vehicle number : SLQ 3840 R	Job No. : 2018002881
Make and model : Hyundai Sonata V111 2.0 GLS A(S/R)	Policy Holder : Komoco Car Rentlas P/L
Registration Date : 07 July 2017	Date of Acc. : 21 Jan 2018
Chassis number : KMHE341CMHA271224	Policy number : VPX/P1305555
Engine number : G4NAGA532551	Claim Type : T.P.Claim Against MSIG
	: SJL 1088 J

Front items:

69 Radiator assy	25310-C1100	ht \$ 839.60 ?	
70 Aircon condenser assy	97606-C1001	ht \$ 927.50 ?	
71 Engine under cover	29110-C1000	dl \$ 211.10 x	X ny
72 Radiator support panel	64101-C1050	ht \$ 907.40 ?	
73 Radiator fan motor assy	25380-C1100	\$ 619.00 X ny	
74 Sundries		\$ 100.00 X ny	
		\$ 33,156.80	30720 90
	Less 20% Discount	\$ 6,631.36	
	Total Material	\$ 26,525.44	27416 72

Body & Paint Repair:

- | | | | |
|--|------|-------------|--------|
| 1 To carry out accident body repairs | 320 | \$ 3,840.00 | 2560 ✓ |
| 2 To complete putty and spray paint on affected area | 250. | \$ 2,500.00 | 1750 ✓ |

Labour Charge:

- | | | | |
|---|----|--------------|-----------|
| 3 Renew rear exhaust muffler (S.nett) | | \$ 150.00 | X ny |
| 4 To renew rear wirings, sensors & reset E.C.U.(Snett) | | \$ 320.00 | ✓ ✓ |
| 5 To remove & install interior trimmings, seats & carpet to fascilitates repair(S.nett) | | \$ 320.00 | ✓ ✓ |
| 6 Supply 1 pc of rear number plate(S.nett) | | \$ 40.00 | ht ✓ |
| 7 Supply 1 pc of front number plate (S.nett) | | \$ 40.00 | ht ✓ |
| 8 Remove & install rear windscreen glass(S.nett) | | \$ 180.00 | ✓ ✓ |
| 9 Supply rear windscreen sealant(S.nett) | Nw | \$ 108.00 | ✓ ✓ |
| 10 Renew cooler condenser assy, vacuum and charge refrigerant gas (S.nett) | | \$ 140.00 | photo ? ✓ |
| 11 Refocus both front headlamp(S.nett) | | \$ 40.00 | ✓ ✓ |
| | | \$ 34,203.44 | |

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carryout***

**KOMOCO MOTORS PTE. LTD.**

3753 Ayer Rajah Road #01-01 Singapore 160996

TEL: 6754 6423 5888 FAX: 6754 6422 7800 www.komoco.com.sg

P.O. Box 128800 Singapore

(GST REGISTRATION NO : MR-85000364-4)

Date: 23 Jan 2018

MSIG

Attn: Motor Claims Dept /

Vehicle number : SLQ 3840 R
 Make and model : Hyundai Sonata V111 2.0 GLS A(S/R)
 Registration Date : 07 July 2017
 Chassis number : KMHE341CMHA271224
 Engine number : G4NAGA532551

Finalising

Invoice No. :
 Job No. : 2018006555
 Policy Holder : Komoco Car Rental
 Date of Acc. : 21 Jan 2018
 Policy number : VPX/P1305555
 Claim Type : T.P.Claim Against
 : MSIG SJL 1088 J

Rear Items:

		Estimated	Revised
1	Rear bumper cover	86610-C1000 \$ 588.00	\$ 588.00
2	Rear bumper lower cover	86612-C1100 \$ 133.20	\$ 133.20
3	Rear bumper ctr cover(under)	86697-C1000 \$ 29.70	\$ 29.70
4	Rear bumper side cover(under)	86698-C1000 \$ 47.90	Refit
5	Rear fog lamp	92405-C1100 \$ 356.40	\$ 356.40
6	LH rear reflector	92405-C1000 \$ 31.90	\$ 31.90
7	RH rear reflector	92406-C1000 \$ 31.90	\$ 31.90
8	BWS EXT wire harness	91890-C1040 \$ 324.70	Refit
9	Rear bumper beam	86631-C1000 \$ 435.30	\$ 435.30
10	Rear beam lower ctr brkt x 4	86635-C1000 \$ 42.00	\$ 42.00
11	Smartkey antenna	95420-C1200 \$ 93.10	Refit
12	LH rear bumper stay	86641-C1000 \$ 142.70	\$ 142.70
13	RH rear bumper stay	86642-C1000 \$ 142.70	\$ 142.70
14	LH rear bumper side mtg brkt	86613-C1001 \$ 36.70	\$ 36.70
15	RH rear bumper side mtg brkt	86614-C1001 \$ 36.70	\$ 36.70
16	License plate lamp assy x 2	92501-C1000 \$ 51.00	\$ 51.00
17	LH BSD sensor	95811-C1001 \$ 1,660.10	\$ 1,660.10
18	RH BSD sensor	95821-C1001 \$ 1,660.10	Refit
19	Rear boot lid cover	69200-C1020 \$ 1,241.60	\$ 1,241.60
20	Back panel	69100-C1000 \$ 348.10	\$ 348.10
21	Symbol emblem	86300-C1000 \$ 27.50	\$ 27.50
22	Trunk lid inner trim	81750-C1000TRY \$ 168.40	\$ 168.40
23	LH trunk lid hinge	81911-C1000TRY \$ 14.60	\$ 14.60
24	RH trunk lid hinge	81921-C1000TRY \$ 14.60	\$ 14.60
25	Trunk lid weatherstrip	87321-C1000 \$ 99.50	\$ 99.50
26	Trunk lid latch	81230-C1010 \$ 112.00	\$ 112.00
27	Trunk lid transverse trim	85770-C1000TRY \$ 63.70	\$ 63.70
28	Ultrasonic BWS sensor x 6	95720-C1000TB7 \$ 783.60	\$ 1,175.40

Vehicle number : SLQ 3840 R Job No. : 2018006555
 Make and model : Hyundai Sonata V111 2.0 GLS A(S/R) Policy Holder : Komoco Car Rental

Registration Date : 07 July 2017
 Chassis number : KMHE341CMHA271224
 Engine number : G4NAGA532551

Date of Acc. : 21 Jan 2018
 Policy number : VPX/P1305555
 Claim Type : T.P.Claim Against
 : MSIG SJL 1088 J

Rear Items:

		Estimated	Revised
31 Rear exhaust muffler	28710-C1010	\$ 1,112.20	Refit
32 LH rear fender	71503-C1C01	\$ 1,855.90	\$ 1,855.90
33 LH rear inner fender	70100-C1A01	Repair	Repair
34 LH rear 1/4 glass	87810-C1000	\$ 332.70	\$ 332.70
35 Rear floor panel	65513-C1000	\$ 878.30	Refit
36 LH rear floor member	65710-C1200	\$ 913.50	Refit
37 Back panel moulding	87370-C1050	\$ 538.70	\$ 538.70
38 Moulding clip x 20	92552-36000	\$ 12.00	Refit
39 LH rear tail lamp	92401-C1030	\$ 794.20	\$ 794.20
40 LH rear inner lamp	92403-C1030	\$ 868.00	\$ 868.00
41 LH luggage trim	85730-C1000TRY	\$ 171.20	\$ 171.20
42 RH luggage trim	85740-C1000TRY	\$ 171.20	Refit
43 Transverse trim	85770-C1000TRY	\$ 61.70	Refit
44 Luggage cover mat	85710-C1030TRY	\$ 216.20	Refit
45 Sonata emblem	86310-C1000	\$ 42.20	\$ 42.20
46 Symbol mark emblem	86300-C1000	\$ 27.50	Refit
47 Rear view camera assy	95760-C2101	\$ 982.30	\$ 982.30

Front items:

			Revised
48 Front bonnet	66400-C1000	\$ 2,411.10	\$ 2,411.10
49 Front bumper cover	86510-C1000	\$ 696.40	\$ 696.40
50 Front bumper upper rubber strip	86362-C1000	\$ 87.80	Refit
51 Front bumper grille	86561-C1000	\$ 41.70	Refit
52 Radiator grille upper cover	86361-C1000	\$ 60.10	\$ 60.10
53 Radiator grille	86350-C1100	\$ 821.70	\$ 821.70
54 License plate moulding	86519-C1000	\$ 17.90	\$ 17.90
55 LH front fog lamp cover	86521-C1210	\$ 154.50	Refit
56 RH front fog lamp cover	86522-C1210	\$ 154.50	Refit
57 LH day running light	92207-C1000	\$ 645.60	\$ 645.60
58 RH day running light	92208-C1000	\$ 645.60	\$ 645.60
59 Front bumper absorber	86520-C1000	\$ 113.40	\$ 113.40
60 Front bumper lwr stiffner	86570-C1100	\$ 119.60	\$ 119.60
61 Front bumper rail	86530-C1000	\$ 340.30	\$ 340.30
62 BWS Ext wire harness	91890-C1510	\$ 297.60	\$ 297.60
63 BWS sensor x 2	95720-C1100TB7	\$ 158.90	Refit
64 BWS ultrasonic sensor x 2	95720-C1000TB7	\$ 158.90	Refit
65 LH side bumper brkt	86513-C1000	\$ 15.80	\$ 15.80
66 RH side bumper brkt	86514-C1000	\$ 15.80	\$ 15.80
67 LH headlamp assy	92101-C1120	\$ 2,772.30	\$ 2,772.30
68 RH headlamp assy	92102-C1120	\$ 2,772.30	\$ 2,772.30

Supplementary item

			Revised
69 CAP-FRONT HOOK	86517C1000	\$ 13.60	\$ 13.60
70 GUARD-AIR,RH	29134C1000	\$ 27.20	\$ 27.20

71 GUARD-AIR,LH	29136C1000	\$ 27.20	\$ <i>de</i> 27.20
72 GARNISH ASSY-FENDER LH	87771C1000	\$ 201.50	\$ <i>de</i> 201.50
73 MT'G CLIP-RR COMBI	924852H000	\$ 1.90	\$ <i>de</i> 1.90
74 PANEL COMPL-COMB LAMP HSG,LH	69131C1000	\$ 198.10	\$ <i>bt</i> 198.10
75 HINGE ASSY-TRUNK LID,LH	79210C1000	\$ 152.80	\$ <i>bt</i> 152.80
76 HINGE ASSY-TRUNK LID,RH	79220C1000	\$ 152.80	\$ <i>bt</i> 152.80
77 CLAMP-SPARE TIRE	628502T100	\$ 5.60	\$ <i>bt</i> 5.60
78 CLIP-SIDE SILL MOULDING MTGx10	877583L000	\$ 19.00	\$ <i>de</i> 19.00
79 MOULDING-REAR WINDOW GLASS	87130C1000	\$ 30.70	\$ <i>de</i> 30.70
80 MOULDING-REAR WINDOW,LWR	87136C1000	\$ 27.80	\$ <i>de</i> 27.80
81 HDL-TRUNK LID HOOK	812543S000	\$ 4.60	\$ <i>de</i> 4.60

86210

690-24

Vehicle number : SLQ 3840 R
 Make and model : Hyundai Sonata V111 2.0 GLS A(S/R)
 Registration Date : 07 July 2017
 Chassis number : KMHE341CMHA271224
 Engine number : G4NAGA532551

Job No. : 2018006555
 Policy Holder : Komoco Car Rental
 Date of Acc. : 21 Jan 2018
 Policy number : VPX/P1305555
 Claim Type : T.P.Claim Against
 : MSIG SJL 1088 J

Front items:

			Revised
69 Radiator assy	25310-C1100	\$ 839.60	\$ 839.60
70 Aircon condenser assy	97606-C1001	\$ 927.50	\$ 927.50
71 Engine under cover	29110-C1000	\$ 211.10	\$ 211.10
72 Radiator support panel	64101-C1050	\$ 907.40	\$ 907.40
73 Radiator fan motor assy	25380-C1100	\$ 6.00	Nil
74 Sundries		\$ 1.00	None
		\$ 3,600.00	\$ 28,062.80
Less 20% Discount		\$ 720.02	\$ 5,612.56
Total Material		\$ 2,880.00	\$ 22,450.24

Body & Paint Repair:

		Revised
1 To carry out accident body repairs	\$ 3,560.00	\$ 2,560.00
2 To complete putty and spray paint on affected area	\$ 2,500.00	\$ 1,750.00

Labour Charge:

		Revised
3 Renew rear exhaust muffler (S.nett)	\$ 1.00	Nil
4 To renew rear wirings, sensors & reset E.C.U.(S.nett)	\$ 320.00	\$ 320.00
5 To remove & install interior trimmings, seats & carpet to facilitates repair(S.nett)	\$ 320.00	\$ 320.00
6 Supply 1 pc of rear number plate(S.nett)	\$ 40.00	\$ 40.00
7 Supply 1 pc of front number plate (S.nett)	\$ 40.00	\$ 40.00
8 Remove & install rear windscreen glass(S.nett)	\$ 180.00	\$ 180.00
9 Supply rear windscreen sealant(S.nett)	\$ 108.00	\$ 108.00
10 Renew cooler condenser assy, vacuum and charge refrigerant gas (S.nett)	\$ 140.00	\$ 140.00
11 Refocus both front headlamp(S.nett)	\$ 40.00	\$ 40.00

Supplementary Labour

		Revised
1 Chassis Bench Aligner	\$ 300.00	\$ 300.00

2 To transfer rear boot wiring	\$ 200.00	\$ 200.00
3 To spray paint left frt fender	\$ 250.00	\$ 250.00
4 To spray paint left centre pillar	\$ 250.00	\$ 250.00
5 To spray paint both rear boot hinges	\$ 250.00	\$ 250.00
6 To spray paint rear inner boot	\$ 250.00	\$ 250.00
7 To apply tuff coat	\$ 350.00	\$ 350.00
8 To remove and install left rear quarter glass	\$ 90.00	\$ 90.00
9 To apply sealant 1/4 glass	\$ 45.00	\$ 45.00
	<u>\$ 37,471.56</u>	<u>\$ 29,933.24</u>
Less Excess		\$ -
Total		<u>\$ 29,933.24</u>
Add GST 7%		<u>\$ 2,095.33</u>
Grand Total		<u>\$ 32,028.57</u>

*** Estimation are base on visual inspection, should there be further damage found during process of repair, you will be inform prior before carryout***



KOMOCO MOTORS PTE. LTD.

251 Alexandra Road #01-01 Singapore 119936
TEL: 651 5473 3505 FAX: 651 6472 1804 komocomotors@comcast.sg
ACS NO: 1996097537

Vehicle number	: SLQ 3840 R	Job No.	: 2018006555
Make and model	: Hyundai Sonata V111 2.0 GLS A(S/R)	Policy Holder	: Komoco Car Rental
Registration Date	: 07 July 2017	Date of Acc.	: 21 Jan 2018
Chassis number	: KMHE341CMHA271224	Policy number	: VPX/P1305555
Engine number	: G4NAGA532551	Claim Type	: T.P.Claim Against
			: MSIG SJL 1088 J

Supplementary Labour

			Revised
1	Chassis Bench Aligner	\$ 300.00	\$ 300.00
2	To transfer rear boot wiring	\$ 200.00	\$ 200.00
3	To spray paint left frt fender	\$ 250.00	\$ 250.00
4	To spray paint left centre pillar	\$ 250.00	\$ 250.00
5	To spray paint both rear boot hinges	\$ 250.00	\$ 250.00
6	To spray paint rear inner boot	\$ 250.00	\$ 250.00
7	To apply tuff coat	\$ 350.00	\$ 350.00
8	To remove and install left rear quarter glass	\$ 90.00	\$ 90.00
9	To apply sealant 1/4 glass	\$ 45.00	\$ 45.00
			\$ 1,985.00

Supplementary item

			Revised
1	CAP-FRONT HOOK	86517C1000	\$ 13.60
2	GUARD-AIR,RH	29134C1000	\$ 27.20
3	GUARD-AIR,LH	29136C1000	\$ 27.20
4	GARNISH ASSY-FENDER LH	87771C1000	\$ 201.50
5	MT'G CLIP-RR COMBI	924852H000	\$ 1.90
6	PANEL COMPL-COMB LAMP HSG,LH	69131C1000	\$ 198.10
7	HINGE ASSY-TRUNK LID,LH	79210C1000	\$ 152.80
8	HINGE ASSY-TRUNK LID,RH	79220C1000	\$ 152.80
9	CLAMP-SPARE TIRE	628502T100	\$ 5.60
10	CLIP-SIDE SILL MOULDING MTGx10	877583L000	\$ 19.00
11	MOULDING-REAR WINDOW GLASS	87130C1000	\$ 30.70
12	MOULDING-REAR WINDOW LWR	87136C1000	\$ 27.80
13	HDL-TRUNK LID HOOK	812543S000	\$ 4.60
		\$ 862.80	\$ 862.80
	<i>Less 20% Discount</i>	\$ 172.56	\$ 172.56
	Total Material	\$ 690.24	\$ 690.24

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018		31 Jan 2018 09:56 Edit Adj Rpt	S\$29,933.24 Edit Estimates	S\$29,933.24 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	JOEL CHAN KUM HOONG, ID: S1812061E, Tel: +6596610947, Email: joe3023@gmail.com		
Main Claimant:	KOMOCO CAR RENTALS PTE LTD, Co. Reg. No.: 199500095K		
Vehicle Reg. No.:	SLQ3840R	Date of Loss:	21/01/2018 16:00 - :59 [6 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 547219	Policy/Cover Note No.:	A28634851QMY (Comprehensive) Coverage: 01/12/2017 - 30/11/2018
Vehicle Reg. No. (Insured):	SJL1088J	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Komoco Motors Pte Ltd (HQ) 253 ALEXANDRA ROAD, #01-01, 159936 Alexandra - Tel: 64735588		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/03/2018]		
Driver/Custodian (Insured):	JOEL CHAN KUM HOONG (51 / Male), NRIC: S1812061E, Tel: +6596610947		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ3840R (547219)
[SJL1088J]
TP
KOMOCO CAR RENTALS PTE LTD
Jan 21 2018 4:00PM
[JOEL CHAN KUM HOONG]
Komoco Motors Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/18 10:00	Accident Statement Addm. #1 From: OO - Reg. No: SJL1088J, Claimant: JOEL CHAN KUM HOONG	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 15:18	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/18 14:01	General View	 Load JPG	☒
2	06/08/18 14:01	General View	 Load JPG	☒
3	06/08/18 14:01	General View	 Load JPG	☒
4	06/08/18 14:01	General View	 Load JPG	☒
5	06/08/18 14:01	General View	 Load JPG	☒
6	06/08/18 14:01	General View	 Load JPG	☒
7	06/08/18 14:01	General View	 Load JPG	☒
8	06/08/18 14:01	General View	 Load JPG	☒
9	06/08/18 14:01	General View	 Load JPG	☒
10	06/08/18 14:01	General View	 Load JPG	☒
11	06/08/18 14:01	General View	 Load JPG	☒
12	06/08/18 14:01	General View	 Load JPG	☒
13	06/08/18 14:01	General View	 Load JPG	☒
14	06/08/18 14:01	General View	 Load JPG	☒
15	06/08/18 14:01	General View	 Load JPG	☒
16	06/08/18 14:01	General View	 Load JPG	☒
17	06/08/18 14:01	General View	 Load JPG	☒
18	06/08/18 14:01	General View	 Load JPG	☒
19	06/08/18 14:01	General View	 Load JPG	☒
20	06/08/18 14:01	General View	 Load JPG	☒
21	06/08/18 14:01	General View	 Load JPG	☒
22	06/08/18 14:01	General View	 Load JPG	☒
23	06/08/18 14:01	General View	 Load JPG	☒
24	06/08/18 14:01	General View	 Load JPG	☒
25	06/08/18 14:01	General View	 Load JPG	☒
26	06/08/18 14:01	General View	 Load JPG	☒
27	06/08/18 14:01	General View	 Load JPG	☒
28	06/08/18 14:01	General View	 Load JPG	☒
29	06/08/18 14:01	General View	 Load JPG	☒
30	06/08/18 14:01	General View	 Load JPG	☒
31	06/08/18 14:01	General View	 Load JPG	☒
32	06/08/18 14:01	General View	 Load JPG	☐

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	06/08/18 14:01	General View	 Load JPG	☒
34	06/08/18 14:01	General View	 Load JPG	☒
35	06/08/18 14:01	General View	 Load JPG	☒
36	06/08/18 14:01	General View	 Load JPG	☒
37	06/08/18 14:01	General View	 Load JPG	☒
38	06/08/18 14:01	General View	 Load JPG	☒
39	06/08/18 14:01	General View	 Load JPG	☒
40	06/08/18 14:01	General View	 Load JPG	☒
41	06/08/18 14:01	General View	 Load JPG	☒
42	06/08/18 14:01	General View	 Load JPG	☒
43	06/08/18 14:01	General View	 Load JPG	☒
44	06/08/18 14:01	General View	 Load JPG	☒
45	06/08/18 14:01	General View	 Load JPG	☒
46	06/08/18 14:01	General View	 Load JPG	☒
47	06/08/18 14:01	General View	 Load JPG	☒
48	06/08/18 14:01	General View	 Load JPG	☒
49	06/08/18 14:01	General View	 Load JPG	☒
50	06/08/18 14:01	General View	 Load JPG	☒
51	06/08/18 14:01	General View	 Load JPG	☒
52	06/08/18 14:01	General View	 Load JPG	☒
53	06/08/18 14:01	General View	 Load JPG	☒
54	06/08/18 14:01	General View	 Load JPG	☒
55	06/08/18 14:01	General View	 Load JPG	☒
56	06/08/18 14:01	General View	 Load JPG	☒
57	06/08/18 14:01	General View	 Load JPG	☒
58	06/08/18 14:01	General View	 Load JPG	☒
59	06/08/18 14:01	General View	 Load JPG	☒
60	06/08/18 14:01	General View	 Load JPG	☒
61	06/08/18 14:01	General View	 Load JPG	☒
62	06/08/18 14:01	General View	 Load JPG	☒
63	06/08/18 14:01	General View	 Load JPG	☒
64	06/08/18 14:01	General View	 Load JPG	☒
65	06/08/18 14:01	General View	 Load JPG	☒
66	06/08/18 14:01	General View	 Load JPG	☒
67	06/08/18 14:01	General View	 Load JPG	☒
68	06/08/18 14:01	General View	 Load JPG	☒
69	06/08/18 14:01	General View	 Load JPG	☒
70	06/08/18 14:01	General View	 Load JPG	☒
71	06/08/18 14:01	General View	 Load JPG	☒
72	06/08/18 14:01	General View	 Load JPG	☒
73	06/08/18 14:01	General View	 Load JPG	☒
74	06/08/18 14:01	General View	 Load JPG	☒
75	06/08/18 14:01	General View	 Load JPG	☒
76	06/08/18 14:01	General View	 Load JPG	☒
77	06/08/18 14:01	General View	 Load JPG	☒
78	06/08/18 14:01	General View	 Load JPG	☒
79	06/08/18 14:01	General View	 Load JPG	☒
80	06/08/18 14:01	General View	 Load JPG	☒
81	06/08/18 14:01	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	06/08/18 14:01	General View	 Load JPG	☒
83	06/08/18 14:01	General View	 Load JPG	☒
84	06/08/18 14:01	General View	 Load JPG	☒
85	06/08/18 14:01	General View	 Load JPG	☒
86	06/08/18 14:01	General View	 Load JPG	☒
87	06/08/18 14:01	General View	 Load JPG	☒
88	06/08/18 14:01	General View	 Load JPG	☒
89	06/08/18 14:01	General View	 Load JPG	☒
90	06/08/18 14:01	General View	 Load JPG	☒
91	06/08/18 14:01	General View	 Load JPG	☒
92	06/08/18 14:02	General View	 Load JPG	☒
93	06/08/18 14:02	General View	 Load JPG	☒
94	06/08/18 14:02	General View	 Load JPG	☒
95	06/08/18 14:02	General View	 Load JPG	☒
96	06/08/18 14:02	General View	 Load JPG	☒
97	06/08/18 14:02	General View	 Load JPG	☒
98	06/08/18 14:02	General View	 Load JPG	☒
99	06/08/18 14:02	General View	 Load JPG	☒
100	06/08/18 14:02	General View	 Load JPG	☒
101	06/08/18 14:02	General View	 Load JPG	☒
102	06/08/18 14:02	General View	 Load JPG	☒
103	06/08/18 14:02	General View	 Load JPG	☒
104	06/08/18 14:02	General View	 Load JPG	☒
105	06/08/18 14:02	General View	 Load JPG	☒
106	06/08/18 14:02	General View	 Load JPG	☒
107	06/08/18 14:02	General View	 Load JPG	☒
108	06/08/18 14:02	General View	 Load JPG	☒
109	06/08/18 14:02	General View	 Load JPG	☒
110	06/08/18 14:02	General View	 Load JPG	☒
111	06/08/18 14:02	General View	 Load JPG	☒
112	06/08/18 14:02	General View	 Load JPG	☒
113	06/08/18 14:02	General View	 Load JPG	☒
114	06/08/18 14:02	General View	 Load JPG	☒
115	06/08/18 14:02	General View	 Load JPG	☒
116	06/08/18 14:02	General View	 Load JPG	☒
117	06/08/18 14:02	General View	 Load JPG	☒
118	06/08/18 14:02	General View	 Load JPG	☒
119	06/08/18 14:02	General View	 Load JPG	☒
120	06/08/18 14:02	General View	 Load JPG	☒
121	06/08/18 14:02	General View	 Load JPG	☒
122	06/08/18 14:02	General View	 Load JPG	☒
123	06/08/18 14:02	General View	 Load JPG	☒
124	06/08/18 14:02	General View	 Load JPG	☒
125	06/08/18 14:02	General View	 Load JPG	☒
126	06/08/18 14:02	General View	 Load JPG	☒
127	06/08/18 14:02	General View	 Load JPG	☒
128	06/08/18 14:02	General View	 Load JPG	☒
129	06/08/18 14:02	General View	 Load JPG	☒
130	06/08/18 14:02	General View	 Load JPG	☒
131	06/08/18 14:02	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	06/08/18 14:02	General View	 Load JPG	☒
133	06/08/18 14:02	General View	 Load JPG	☒
134	06/08/18 14:02	General View	 Load JPG	☒
135	06/08/18 14:02	General View	 Load JPG	☒
136	06/08/18 14:02	General View	 Load JPG	☒
137	06/08/18 14:02	General View	 Load JPG	☒
138	06/08/18 14:02	General View	 Load JPG	☒
139	06/08/18 14:02	General View	 Load JPG	☒
140	06/08/18 14:02	General View	 Load JPG	☒
141	06/08/18 14:02	General View	 Load JPG	☒
142	06/08/18 14:02	General View	 Load JPG	☒
143	06/08/18 14:02	General View	 Load JPG	☒
144	06/08/18 14:02	General View	 Load JPG	☒
145	06/08/18 14:02	General View	 Load JPG	☒
146	06/08/18 14:02	General View	 Load JPG	☒
147	06/08/18 14:02	General View	 Load JPG	☒
148	06/08/18 14:02	General View	 Load JPG	☒
149	06/08/18 14:02	General View	 Load JPG	☒
150	06/08/18 14:02	General View	 Load JPG	☒
151	06/08/18 14:02	General View	 Load JPG	☒
152	06/08/18 14:02	General View	 Load JPG	☒
153	06/08/18 14:02	General View	 Load JPG	☒
154	06/08/18 14:02	General View	 Load JPG	☒
155	06/08/18 14:02	General View	 Load JPG	☒
156	06/08/18 14:02	General View	 Load JPG	☒
157	06/08/18 14:02	General View	 Load JPG	☒
158	06/08/18 14:02	General View	 Load JPG	☒
159	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
160	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
161	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
162	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
163	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
164	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
165	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
166	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
167	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
168	06/08/18 14:02	Reinspection Photo	 Load JPG	☒
169	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
170	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
171	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
172	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
173	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
174	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
175	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
176	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
177	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
178	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
179	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
180	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
181	06/08/18 14:03	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
182	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
183	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
184	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
185	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
186	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
187	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
188	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
189	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
190	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
191	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
192	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
193	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
194	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
195	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
196	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
197	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
198	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
199	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
200	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
201	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
202	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
203	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
204	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
205	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
206	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
207	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
208	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
209	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
210	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
211	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
212	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
213	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
214	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
215	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
216	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
217	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
218	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
219	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
220	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
221	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
222	06/08/18 14:03	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/18 09:57	TP WORKSHOP NOMINATE LKK TO BE THE SJE	 Load PDF	
2	31/01/18 09:59	ESTIMATE & TP GIA REPORT	 Load PDF	
3	31/01/18 10:00	TP SLQ3840R GIA Report From: 00 - Reg. No: SJL10881, Claimant: JOEL CHAN KUM HOONG	 Load PDF	
4	31/01/18 10:00	POLICE REPORT From: 00 - Reg. No: SJL10881, Claimant: JOEL CHAN KUM HOONG	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001928/T1TD3E2

Date: 07/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28634851QMY
 Claimant Vehicle No: SLQ3840R Insured Vehicle No: SJL1088J
 Date of Loss: 21/01/2018 Nature of Claim: TP Claim No: 547219

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ3840R**
 Make & Model: HYUNDAI SONATA LF, 2.0 GLS A/T (A) Engine No: G4NAGA532551
 Reg. Date: 07/07/2017 (Man. Year: 2017) Chassis No: KMHE341CMHA271224
 Colour: Black Odometer: 14899 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,294.96	22,638.24	5,656.72	19.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,475.00	7,295.00	2,180.00	23.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	37,769.96	29,933.24	7,836.72	20.75
+ GST 7.00/7.00% (S\$)	2,643.90	2,095.33	548.57	20.75
Nett Amount (S\$)	40,413.86	32,028.57	8,385.29	20.75

INSPECTION

Date of Assignment: 31/01/2018
 Date Inspected: 05/02/2018 Inspected At: Komoco Motors Pte Ltd (HQ)
 253 ALEXANDRA ROAD, #01-01
 Singapore 159936
 Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2018)
Parts:	143	HYUNDAI SONATA LF 2.0 GLS A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3840R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	588.00 FL	*588.00 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	133.20 FL	*133.20 FL
3	1		*REAR BUMPER CTR COVER (UNDER)	Deformed	29.70 FL	*29.70 FL
4	1		*REAR BUMPER SIDE COVER (UNDER)	Not Necessary	47.90 FL	*- FL
5	1		*REAR FOG LAMP	Distorted	356.40 FL	*356.40 FL
6	1		*LH REAR REFLECTOR	Cracked	31.90 FL	*31.90 FL
7	1		*RH REAR REFLECTOR	Cracked	31.90 FL	*31.90 FL
8	1		*BWS EXT WIRE HARNESS	Not Necessary	324.70 FL	*- FL
9	1		*REAR BUMPER BEAM	Cracked	435.30 FL	*435.30 FL
10	4		*REAR BEAM LOWER CTR BRKT	Necessary	42.00 FL	*42.00 FL
11	1		*SMARTKEY ANTENNA	Not Necessary	93.10 FL	*- FL
12	1		*LH REAR BUMPER STAY	Necessary	142.70 FL	*142.70 FL
13	1		*RH REAR BUMPER STAY	Necessary	142.70 FL	*142.70 FL
14	1		*LH REAR BUMPER SIDE MTG BRKT	Necessary	36.70 FL	*36.70 FL
15	1		*RH REAR BUMPER SIDE MTG BRKT	Necessary	36.70 FL	*36.70 FL
16	2		*LICENSE PLATE LAMP ASSY	Distorted	51.00 FL	*51.00 FL
17	1		*LH BSD SENSOR	Distorted	1,660.10 FL	*1,660.10 FL
18	1		*RH BSD SENSOR	Not Necessary	1,660.10 FL	*- FL
19	1		*REAR BOOT LID COVER	Bent	1,241.60 FL	*1,241.60 FL
20	1		*BACK PANEL	Bent	348.10 FL	*348.10 FL
21	1		*SYMBOL EMBLEM	Necessary	27.50 FL	*27.50 FL
22	1		*TRUNK LID INNER TRIM	Deformed	168.40 FL	*168.40 FL
23	1		*LH TRUNK LID HINGE	Bent	14.60 FL	*14.60 FL
24	1		*RH TRUNK LID HINGE	Bent	14.60 FL	*14.60 FL
25	1		*LH TRUNK LID ARM COVER	Not Necessary	14.60 FL	*- FL
26	1		*RH TRUNK LID ARM COVER	Not Necessary	14.60 FL	*- FL
27	1		*TRUNK LID WEATHERSTRIP	Twisted	99.50 FL	*99.50 FL
28	1		*TRUNK LID LATCH	Bent	124.00 FL	*112.00 FL
29	1		*TRUNK LID TRANSVERSE TRIM	Deformed	63.70 FL	*63.70 FL
30	4		*ULTRASONIC BWS SENSOR	Not Working	1,175.40 FL	*1,175.40 FL
31	1		*REAR EXHAUST MUFFLER	Not Necessary	1,112.20 FL	*- FL
32	1		*LH REAR FENDER	Bent	1,855.90 FL	*1,855.90 FL
33	1		*LH REAR INNER FENDER (NPA)	Repair	0.00 FL	*- FL
34	1		*LH REAR 1/4 GLASS	Bent	332.70 FL	*332.70 FL
35	1		*REAR FLOOR PANEL	Repair	878.30 FL	*- FL
36	1		*LH REAR FLOOR MEMBER	Not Necessary	913.50 FL	*- FL
37	1		*BACK PANEL MOULDING	Distorted	538.70 FL	*538.70 FL
38	20		*MOULDING CLIP	Not Necessary	12.00 FL	*- FL
39	1		*LH REAR TAIL LAMP	Cracked	794.20 FL	*794.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*LH REAR INNER LAMP	Cracked	868.00 FL	*868.00 FL
41	1		*LH LUGGAGE TRIM	Deformed	171.20 FL	*171.20 FL
42	1		*RH LUGGAGE TRIM	Not Necessary	171.20 FL	*- FL
43	1		*TRANSVERSE TRIM	Not Necessary	63.70 FL	*- FL
44	1		*LUGGAGE COVER MAT	Not Necessary	216.20 FL	*- FL
45	1		*SONATA EMBLEM	Necessary	42.20 FL	*42.20 FL
46	1		*SYMBOL MARK EMBLEM	Not Necessary	27.50 FL	*- FL
47	1		*REAR VIEW CAMERA ASSY	Distorted	982.30 FL	*982.30 FL
48	1		*FRONT BONNET	Deformed	2,411.10 FL	*2,411.10 FL
49	1		*FRONT BUMPER COVER	Cracked	696.40 FL	*696.40 FL
50	1		*FRONT BUMPER UPPER RUBBER STRIP	Not Necessary	47.80 FL	*- FL
51	1		*FRONT BUMPER GRILLE	Not Necessary	41.70 FL	*- FL
52	1		*RADIATOR GRILLE UPPER COVER	Cracked	60.10 FL	*60.10 FL
53	1		*RADIATOR GRILLE	Cracked	821.70 FL	*821.70 FL
54	1		*LICENSE PLATE MOULDING	Deformed	17.90 FL	*17.90 FL
55	1		*LH FRONT FOG LAMP COVER	Not Necessary	154.50 FL	*- FL
56	1		*RH FRONT FOG LAMP COVER	Not Necessary	154.50 FL	*- FL
57	1		*LH DAY RUNNING LIGHT	Cut	645.60 FL	*645.60 FL
58	1		*RH DAY RUNNING LIGHT	Cut	645.60 FL	*645.60 FL
59	1		*FRONT BUMPER ABSORBER	Deformed	113.40 FL	*113.40 FL
60	1		*FRONT BUMPER LWR STIFFNER	Deformed	119.60 FL	*119.60 FL
61	1		*FRONT BUMPER RAIL	Bent	340.30 FL	*340.30 FL
62	1		*BWS EXT WIRE HARNESS	Cut	297.60 FL	*297.60 FL
63	2		*BWS SENSOR	Not Necessary	195.90 FL	*- FL
64	2		*BWS ULTRASONIC SENSOR	Not Necessary	195.90 FL	*- FL
65	1		*LH SIDE BUMPER BRKT	Necessary	15.80 FL	*15.80 FL
66	1		*RH SIDE BUMPER BRKT	Necessary	15.80 FL	*15.80 FL
67	1		*LH HEADLAMP ASSY	Cut	2,772.30 FL	*2,772.30 FL
68	1		*RH HEADLAMP ASSY	Cut	2,772.30 FL	*2,772.30 FL
69	1		*RADIATOR ASSY	Bent	839.60 FL	*839.60 FL
70	1		*AIRCON CONDENSER ASSY	Bent	927.50 FL	*927.50 FL
71	1		*ENGINE UNDER COVER	Deformed	211.10 FL	*211.10 FL
72	1		*RADIATOR SUPPORT PANEL	Bent	907.40 FL	*907.40 FL
73	1		*RADIATOR FAN MOTOR ASSY	Not Necessary	619.00 FL	*- FL
74	1		*SUNDRIES	Not Necessary	100.00 FL	*- FL
75	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
76	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
77	1		*REAR WINDSCREEN SEALANT	Necessary	108.00 FS	*108.00 FS
78	1		*CAP-FRONT HOOK	Deformed	13.60 FL	*13.60 FL
79	1		*GUARD-AIR, RH	Deformed	27.20 FL	*27.20 FL
80	1		*GUARD-AIR, LH	Deformed	27.20 FL	*27.20 FL
81	1		*GARNISH ASSY-FENDER LH	Deformed	201.50 FL	*201.50 FL
82	1		*MTG CLIP-RR COMBI	Necessary	1.90 FL	*1.90 FL
83	1		*PANEL COMPL-COMB LAMP HSG, LH	Bent	198.10 FL	*198.10 FL
84	1		*HINGE ASSY-TRUNK LID, LH	Bent	152.80 FL	*152.80 FL
85	1		*HINGE ASSY-TRUNK LID, RH	Bent	152.80 FL	*152.80 FL
86	1		*CLAMP-SPARE TIRE	Bent	5.60 FL	*5.60 FL
87	10		*CLIP-SIDE SILL MOULDING MTG	Necessary	19.00 FL	*19.00 FL
88	1		*MOULDING -REAR WINDOW GLASS	Necessary	30.70 FL	*30.70 FL
89	1		*MOULDING-REAR WINDOW, LWR	Necessary	27.80 FL	*27.80 FL
90	1		*HDL-TRUNK LID HOOK	Deformed	4.60 FL	*4.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,321.70 28,250.80

- List Item Discount on L Items 20.00/20.00% (\$\$) 7,026.74 5,612.56

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					28,294.96	22,638.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIRS	New	3,840.00	2,560.00
2	TO COMPLETE PUTTY AND SPRAY PAINT ON AFFECTED AREA	New	2,500.00	1,750.00
3	RENEW REAR EXHAUST MUFFLER	New	150.00	0.00
4	TO RENEW REAR WIRING, SENSORS & RESET E.C.U.	New	320.00	320.00
5	TO REMOVE & INSTALL INTERIOR TRIMMING, SEATS & CARPET TO FACILITATE REPAIR	New	320.00	320.00
6	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	180.00	180.00
7	RENEW COOLER CONDENSER ASSY, VACUUM AND CHARGE REFRIGERANT GAS	New	140.00	140.00
8	REFOCUS BOTH FRONT HEADLAMP	New	40.00	40.00
9	CHASSIS BENCH ALIGNER	New	300.00	300.00
10	TO TRANSFER REAR BOOT WIRING	New	200.00	200.00
11	TO SPRAY PAINT LEFT FRT FENDER	New	250.00	250.00
12	TO SPRAY PAINT BOTH REAR BOOT HINGES	New	250.00	250.00
13	TO SPRAY PAINT REAR INNER BOOT	New	250.00	250.00
14	TO APPLY TUFF COAT	New	350.00	350.00
15	TO REMOVE AND INSTALL LEFT REAR QUARTER GLASS	New	90.00	90.00
16	TO APPLY SEALANT 1/4 GLASS	New	45.00	45.00
17	TO SPRAY PAINT LEFT CENTRE PILLAR	New	250.00	250.00
Gross Labour Cost (\$\$)			9,475.00	7,295.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >