

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5818P -**AAD1801-313***Not Authorized
1/18/01*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC5818P - CANDY
VF1ABL15AUC280916
RENAULT
LATITUDE
29.01.2018
CHINA TAIPING

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>R</i> 2,872.68
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1	BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
19	1	BOOT BADGE	\$	<i>na</i> 225.36
20	1	BOOT SWITCH	\$	<i>Sn</i> 168.13
21	1	BOOT LOCK	\$	<i>R</i> 202.67
22	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
23	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
24	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
25	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
26	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
27	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
28	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47
29	1	TAILLAMP RH	\$	<i>Sn</i> 552.55
30	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
31	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
32	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
33	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77
34	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-313

N0.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5818P -

35	1	EXHAUST REAR	\$	<i>R</i> 7,489.05 <i>X</i>
36	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49 <i>X</i>

TOTAL	\$	<u>29,849.67</u>
10%	\$	<u>2,984.97</u>
	\$	<u>26,864.70</u>

Specical Nett

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00 <i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i> 20.00
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i> 20.00
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00
10	1	EXHAUST MOUNTING REAR	\$	<i>nn</i> 17.82
11	1SET	BOOT FINISHER CLIP	\$	<i>nn</i> 24.20
12	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i> 30.00
13	1	BOOT STICKER "6555-3333"	\$	<i>nn</i> 30.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00
16	1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00
17	1	TAILLAMP CLIP LH	\$	<i>nn</i> 5.00
18	2	REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00
19	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i> 385.00
22	1	SPARE TYRE	\$	<i>Sn</i> 330.00

TOTAL	\$	<u>2,124.02</u>
TOTAL PARTS	\$	<u>28,988.72</u>

Putty And Spray Painting Of The Affected Portion. *2201*
\$ 3,000.00

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same *2001*
\$ 2,800.00

To Rust-Proofing Of The Affected Areas. *nn* 170.00 *X*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-313

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5818P -

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees	\$	nn 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

TOTAL	\$	7,710.00
Over All Total	\$	36,698.72

(PARTS BY PARTS)**Repair Days****10 Days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: