

REPAIR ESTIMATE

VEHICLE NO : SH 9592G

MAKE :

MODEL : TOYOTA PRIUS

China Taiping CP/P)

LKK-Kalvin

30/1/2018

TS

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	REAR BUMPER ✓			\$ 458.60
	REAR BUMPER RE-INFORCEMENT ✓			\$ 318.80
	REAR BUMPER UNDER COVER ✓			\$ 552.60
	REAR BUMPER SIDE RETAINER ?			\$ 112.70
	REAR BUMPER SPONGE X			\$ 143.40
	REAR BUMPER UNDER SIDE COVER (RH) #?			\$ 167.60
	REAR BUMPER TOWING COVER ✓			\$ 82.70
	REAR BUMPER CLIPS ✓			\$ 22.00
	ARM SUB-ASSY, REAR BUMPER, RH X			\$ 139.60
	RETAINER, REAR BUMPER, SIDE, RH X			\$ 94.80
	SEAL, REAR BUMPER SIDE, RH ✓			\$ 148.40
	TAIL LAMP ASSY (UPPER), RH ✓			\$ 557.90
	TAIL LAMP ASSY (LOWER), RH ✓			\$ 548.40
	SUB TOTAL			\$ 3,347.50
	LESS 25%			\$ 836.88
	DISCOUNTED TOTAL			\$ 2,510.63
	REAR BUMPER REVERSE SENSOR ✓			\$ 135.70
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 180 200.00
	Wiring Charge			\$ 20 50.00
	Remove/Refix Reverse Sensor			\$ 20 120.00
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 3,366.33
	Kelvin 11/11/14 N 30/1/18 1510km. 2 days. PIP Batu part photo			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.