

***TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD499D - CHINA TAIPING

AAD1801-312

Not Authorized
Reserve B4 paint 83073-59

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD499D - JHOW

VF1ABL15AUC283457

RENAULT

LATITUDE

29.01.2018

CHINA TAIPING

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1	BUMPER LOWER REAR	\$	<i>nd/wt</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>cm</i> 43.61	✓
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1	BOOT REAR	\$	<i>R</i> 2,872.68	} X
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36	
19	1	BOOT BADGE	\$	<i>nn</i> 225.36	
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
25	1	BOOT LOCK	\$	<i>R</i> 202.67	
26	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
27	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
28	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
29	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
30	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
31	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
32	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
33	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
34	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-312

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD499D - CHINA TAIPING

35	1	TAILLAMP LH	\$	Sn	552.55	} X
36	1	TAILLAMP PANEL LH	\$	N	986.70	
37	1	OUTER PANEL REAR (End Panel)	\$	N	1,471.77	
38	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
39	1	EXHAUST REAR	\$	N	7,489.05	
40	1	EXHAUST CAP REAR	\$	N	230.49	

TOTAL	\$	31,137.51
10%	\$	3,113.75
	\$	28,023.76

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nc	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nc	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	nc	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	nn	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	
13	1	BOOT STICKER "6555-3333"	\$	nn	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
16	1	TAILLAMP CLIP RH	\$	nn	5.00	
17	1	TAILLAMP CLIP LH	\$	nn	5.00	
18	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
19	1	WINDSCREEN MOULDING	\$	nn	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
22	1	SPARE TYRE	\$	Sn	330.00	

TOTAL	\$	2,124.02
TOTAL PARTS	\$	30,147.78

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 220/

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-312

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD499D - CHINA TAIPING

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	nn X
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	nn X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
Towing Fees	\$	120.00	nn X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X

TOTAL \$ 7,710.00**Over All Total \$ 37,857.78****(PARTS BY PARTS)****Repair Days****10 Days****2 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: