

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA TAIPING INSURANCE	DATE	: 30/01/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SKG562C	Asher.	
MODEL	: MERCEDES BENZ E250	WDB2110412B220918.	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 26-Jan-18
		TIME	: 18:35HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT SIDE MIRROR FRAME ASSY <i>Repld.</i>	1	\$ 2,100.00	\$ 2,100.00
2	FRONT DOOR RH <i>Disturbed</i>	1	\$ 1,980.00	\$ 1,980.00
3	FRONT DOOR HINGE <i>Best</i>	2	\$ 126.00	\$ 252.00
4	FRONT DOOR CHECKER <i>Best</i>	1	\$ 250.00	\$ 250.00
5	FRONT DOOR LOCK <i>Repld</i>	1	\$ 320.00	\$ 320.00
6	FRONT DOOR CATCH <i>New</i>	1	\$ 96.00	\$ 96.00
7	FRONT DOOR WEATHERSTRIP <i>in</i>	1	\$ 310.00	\$ 310.00
8	FRONT DOOR OUTER CHROME PROTECTOR <i>ut</i>	1	\$ 103.00	\$ 103.00
9	FRONT DOOR OUTER CHROME <i>Repld</i>	1	\$ 155.30	\$ 155.30
10	FRONT DOOR INNER BOARD <i>Repld</i>	1	\$ 1,030.00	\$ 1,030.00
11	FRONT DOOR INNER SIDE BOARD <i>Missing</i>	1	\$ 290.00	\$ 290.00
12	FRONT DOOR INNER SPEAKER <i>Repld</i>	1	\$ 188.30	\$ 188.30
13	FRONT DOOR GLASS REGULATOR <i>Repld</i>	1	\$ 530.00	\$ 530.00
14	FRONT DOOR POWER WINDOW MOTOR <i>New</i>	1	\$ 655.90	\$ 655.90
15	SIDE SKIRT RH <i>Repld</i>	1	\$ 855.00	\$ 855.00
16	FRONT FENDER <i>Disturbed</i>	1	\$ 920.00	\$ 920.00
17	FRONT FENDER OUTER PROTECTOR <i>Missing</i>	1	\$ 150.00	\$ 150.00
18	FRONT FENDER OUTER PROTECTOR CHROME	1	\$ 196.00	\$ 196.00

Missing

Manitry.

1238.

55

532.

45

19	FRONT FENDER INNER COWLING <i>Neu</i>	1	\$ 198.00	\$ 198.00	+
20	FRONT WHEEL HOUSE PANEL <i>Neu</i>	1	\$ 760.00	\$ 760.00	+
21	FRONT KNUCKLE ARM <i>Bent</i>	1	\$ 1,200.00	\$ 1,200.00	2 ✓ 1036
22	FRONT WHEEL HUP WITH BEARING <i>Ryd</i>	1	\$ 630.00	\$ 630.00	2 ✓
23	FRONT LOWER ARM(STRAIGHT) <i>Bent</i>	1	\$ 520.00	\$ 520.00	2 ✓
24	FRONT LOWER ARM(BENT) <i>Bent</i>	1	\$ 490.00	\$ 490.00	2 ✓
25	FRONT SHOCK ABSORBER <i>Neu</i>	1	\$ 820.00	\$ 820.00	+
26	REAR FENDER RH <i>Ryis</i>	1	\$ 1,900.00	\$ 1,900.00	+
27	REAR BUMPER <i>Rehnd</i>	1	\$ 1,593.00	\$ 1,593.00	1358
28	REAR BUMPER SIDE MOULDING RH <i>lt</i>	1	\$ 172.00	\$ 172.00	-
29	REAR BUMPER SIDE RETAINER RH <i>Ryd</i>	1	\$ 96.00	\$ 96.00	-
30	REAR BUMPER CENTER MOULDING <i>Neu</i>	1	\$ 196.00	\$ 196.00	+
31	TAIL LAMP <i>lt</i>	1	\$ 663.00	\$ 663.00	-

1302360

TOTAL PRICE \$ 19,619.50

LESS 10% \$ 1,961.95

1172124

SUB TOTAL PRICE \$ 17,657.55

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT FENDER INNER COWLING CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	+
2	FRONT DOOR INNER BOARD CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	-
3	SIDE SKIRT CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	-
4	REAR BUMPER CLIP(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00	-
5	WHEEL TYRE <i>Neu</i>	1	\$ 800.00	\$ 800.00	+
6	WHEEL RIM <i>lt</i>	1	\$ 2,500.00	\$ 2,500.00	800 800

860

TOTAL \$ 3,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 2,000.00	1000.	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,800.00	1000	
3	TUFF COAT	\$ 250.00	50	
4	WIRING CHECK	\$ 120.00	30	
3	TO REMOVE AND REFIX FRONT DOOR <i>Fittings</i>	\$ 250.00	80.	
4	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	220	
5	WHEEL ALIGHMENT	\$ 100.00	80	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50.	

6	RESET REVERSE SENSOR WIRE HARNESS	\$ 280.00	X	
---	-----------------------------------	-----------	---	--

TOTAL

\$5,230.00

2510

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,977.55

TOTAL LABOUR COS : \$ 5,230.00

TOTAL REPAIR COS : \$ 26,207.55

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS

:

Adrian Lj
L/S 30/01/18.
08 Days.

total: 15091.24
L/S: 12K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: