

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: -THIRD PARTY CLAIM

Insured veh.	SDJ5568X	Excess.	-
Policy No.	B 29028929 MCX	Coverage.	Comprehensive
Claiming Against.	SDJ8155J AXA		
Insured Under.	MSIG		

Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE
Engine No.	G4FC9U602536
Chassis No.	KMH DU41BR9U687724
Odometer	
Engine CC.	1591
Year Of Reg.	2009
Colour.	Silver
Parf/COE Rebate.	\$ 6,562.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion damaged.

General Information

Accident Date. 26-01-18
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
B) KINDLY LET US HAVE THE APPROVAL SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Not Affected
2450/1
4 day
2450/1
31/1/18

Qty.	Description Of Parts	Pricing
1	Rear bumper <i>DO/DE 489.60</i>	\$ 830.00
1	Rear bumper side retainer LH <i>Ref</i>	\$ 55.00
1	Rear bumper side retainer RH <i>Ref</i>	\$ 55.00
1	Rear bumper bracket LH <i>tw</i>	\$ 26.00
1	Rear bumper bracket RH <i>tw</i>	\$ 26.00
1	Rear bumper inner sponge <i>tw</i>	\$ 130.00
1	Rear bumper reinforcement <i>one 270.00</i>	\$ 414.00
1	Boot lid <i>R</i>	\$ 986.00
1	Boot lid lock <i>11</i>	\$ 96.20
1	Boot lid lock catch <i>11</i>	\$ 18.40
1	Boot lid rubber <i>tw</i>	\$ 157.20
1	Boot lid logo <i>Ref</i>	\$ 32.60
1	Boot lid "AVANTE" emblem <i>mc 35.50</i>	\$ 65.00
1	Boot lid "S" emblem <i>Ref</i>	\$ 47.08
1	Rear end panel <i>DO 537.20</i>	\$ 595.85
1	Rear end panel inner garnish <i>11</i>	\$ 177.73
1	Rear spare tyre panel <i>R</i>	\$ 635.45
		List \$ 4,347.51
		Less 20% \$ 869.50
		Total \$ 3,478.01
1	Rear bumper clips (1 set) <i>Ref</i>	\$ 45.00
1	Rear bumper reverse sensors (1 set) <i>shd</i>	\$ 260.00
1	Rear number plate <i>11</i>	\$ 45.00
1	Rear end panel inner garnish clips (1 set) <i>11</i>	\$ 35.00
S/N		\$ 385.00

1860.68
1488.54

✓ S.N
2005N

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	30 \$ 60.00
	To Disconnect & Reconnect, Check Electrical Wiring Harness Wire, Sockets, Replace Damaged Parts.	20 \$ 60.00
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	600 \$ 1,000.00
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	700 \$ 950.00
	LABOUR	\$ 2,070.00
	Sub Total.	\$ 5,933.01
	7% GST	\$ 415.31
	Grand Total	<u>\$ 6,348.32</u>

3063.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.