

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 2100384019-02
 Claims No. 820627642356
 Sum Insured: _____ Excess: \$1400
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 1751C
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 05 885 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STA 8104H Yr Regn: 2014, August
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q7 C.O. 2985
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 38944 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAU2274L5FD032820
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275/45R20
 R: 275/45R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. 25.1.2018 D.O.I. 31/01/18
 Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A16

STA 8104H - x

1/2/18 Sent preb thru manager, seek mandate
2/2/18 Authorise repair & inform repairer
6/8/18 Confirm \$11,885.04 @ 5 days
Red: \$8857.96, 43%

RECEIVED 23 AUG 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) typint

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS \$

) Photo

) Others

Report Format: 08

Lump Sum / I.B.I. (\$ 11885.04)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18001950/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-01-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJA 8104H
Policy No. 2100384019	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 25/01/2018	Inspection Date 31/01/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 01 Feb 2018

Preliminary Advice

Vehicle No	: SJA8104H	Accident Date	: 25/01/2018
Make	: AUDI Q7	Policy No.	: 2100384019-03
Assignment Date	: 31/01/2018	Excess	: S\$1,400.00
Date of Inspection	: 31/01/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,723.00
Revised Amount	:S\$	13,115.00
Check Items (Estimated)	:S\$	1,658.00
Total	:S\$	14,773.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	114,651.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,349.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3823E
Vehicle Details	
Vehicle No.:	SJA8104H
Vehicle to be Exported:	No
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	Q7 3.0 TFSI QU 272 BHP (NAVIGATION)
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CJT201928
Chassis No.:	WAUZZZ4L5ED032820
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$67,055.00
Original Registration Date:	28 Aug 2014
First Registration Date:	28 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$92,699.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2024
PARF Rebate Amount:	\$69,524.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$69,001.00
COE Rebate Amount:	\$45,127.00
Total Rebate Amount:	\$114,651.00

The information contained herein is correct as at 01 Feb 2018

OK

Print Received Message

This mail is associated with :

***SJA8104H (8206276423SG)**

OD

Jan 25 2018 4:25PM

[ALBERT TAN - LIENHART]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 01/02/2018 15:41 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13115.00) - SJA8104H - Claim Handler: Tr, Tinesh

Approved:13115.00:LH front and rear rims damage not consistent. Re-inspection to be done for damage check and supplementary items / labour.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, February 02, 2018 11:31 AM
To: 'Claims Dept'
Cc: SUR
Subject: SJA 8104H AIG OD DOA: 25.01.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJA 8104H (excess \$1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ALBERT TAN LIENHART
 Period of Insurance : 28 Aug 2017 To 27 Aug 2018
 Engine No. : CJT201928
 Chassis No. : WAUZZZ4L5ED032820

Vehicle No. : SJA8104H
 Policy No. : 2100384019-03
 Endorsement No. :
 Issued Date : 21 Aug 2017

ABOUT THE COVER

Make/Model : AUDI Q7 3.0 TFSI QU (272BHP&333BHP)
 Engine Capacity/Tonnage : 2,995.00 CC Sum Insured : Market Value
 Driver Restriction : NA Off Peak Car : No
 First Year of Registration : 2014
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

* Only for social, domestic and pleasure purposes and for the Policyholder's business.
 A Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 158) and Section 55 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and EXCESS (where applicable)

ALBERT TAN LIENHART - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

3d Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 83662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 158), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).


0504125200

PREMIUM LEASING - AP
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Signature

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

65CHRY



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 19:02
Date Of Accident	25/01/2018 16:25
Exact Location Of Accident	TRAFFIC JUNC BETWEEN DURNERN RD /BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA8104H
Insured/Policyholder	
Name Of Registered Owner	ALBERT TAN - LIENHART
NRIC No	S7303823E
Email Address	ALBERT.TANLH@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-93877670
Alternative Phone No	OFFICE-93877670

Vehicle Particulars

Manufacturer	AUDI
Model	Q7 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100384019-03
Cover Note Number	

Driver

Name of Driver	ALBERT TAN - LIENHART
NRIC No	S7303823E
Date Of Birth	26/01/1973
Occupation	INDOOR
Date Of Driving Pass	20/12/1996
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93877670
Fax Number	
Contact Number	
Email Address	ALBERT.TANLH@ICLOUD.COM


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT 4.25pm

4.25pm - At Traffic junction between Dunearn Rd & Bukit Timah Rd and intersection with Lalum Rd & Chancery Lane.

- Car A in centre lane, signaling to turn right to Dunearn Rd, Car B did not signal or check blindspot and changed lane from extreme left lane to centre lane. Car A front end was going straight in the centre lane, signaling to turn right to Dunearn Rd. Car B knocked into the left side of Car A door.

Car A passenger, 12 year old boy not injured but shocked.

Both car making speed 30-40km/h

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:
26/01/2018
1500

Driver's Signature
(If driver is not the policyholder)

Date & Time:
26/01/2018
1300

Reporting Centre Personnel's Signature


Name: WONG KATHALIN SEAG, George
NRIC/ID No: G2037143X




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0120/2018/GW
Date	:	27-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Albert Tan - Lienhart
Address	:	20 Ewe Boon Road #04-01 Singapore 259344
Telephone	:	HP +65 93877670
Type of Claim	:	Own Damage Claims
Policy No.	:	2100384019-03
Vehicle No	:	SJA 8104 H
Model Code	:	Q7 3.0 TFSI QU
Model / Year	:	Aug-14
Engine No	:	CJT 201928
Chassis No	:	WAUZZZ4L5ED032820
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Jan-18
Place of Accident	:	Traffic Junc Between Durnearn Rd/Bukit Timah Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJA 8104 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer both lhs front and rear door's multi lock system window devices and audio equipment.	S/N \$ 600.00 ✓	600
2	To remove and renew both fornt and rear door, transfer old fittings to new door. Reshape lhs front fender, renew door covers and reinstall all parts removed.	\$ 2,500.00	1200 1200
3	To respray lhs front fender, lhs front door, lhs rear door, both door covers.	\$ 3,200.00	2200 2200 $600 \times 3 = 1800$ $200 \times 2 = 400$ 2200
4	To renew lhs front and rear wheel rim and carry out alignment.	S/N \$ 600.00 ✗	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	192
TOTAL LABOUR CHARGES		: \$ 7,092.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJA 8104 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-LH <i>Painted</i>	\$ 3,850.00 ✓	3050
2	FRONT OUTER DOOR SEAL -LH <i>new</i>	\$ 218.00 ✓	174
3	FRONT COVER TRIM-LH <i>del</i> Not <i>new</i>	\$ 339.00 ?	X 271.20
4	FRONT DOOR COVER-LH <i>del</i>	\$ 330.00 ✓	263.60
5	FRONT PILLAR B BRILLIANT BLACK TRIM-LH <i>new</i> new	\$ 150.00 X ?	X
6	REAR DOOR-LH <i>Painted</i>	\$ 3,850.00 ✓	3050.00
7	STONE CHIP PROTECTION FILM <i>new</i>	\$ 67.00 -	53.44
8	DOOR ATTACHMENT PARTS <i>Not new</i>	\$ 85.00 ?	X
9	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 218.00 ✓	224.40
10	REAR PILLAR C BRILLIANT BLACK TRIM-LH ? <i>new</i>	\$ 153.00 ?	} X
11	REAR PILLAR B BRILLIANT BLACK TRIM-LH	\$ 237.00 ?	
12	REAR DOOR INSULATION STRIP-LH <i>new</i>	4 \$ 220.00 +	
13	REAR DOOR SEAL -LH new	\$ 218.00 +	
14	REAR COVER TRIM-LH new <i>new</i>	\$ 294.00 ?	234.50
15	REAR DOOR COVER-LH <i>Missing</i>	\$ 390.00 -	311.60
16	FRONT/REAR ALUMINIUM RIM-LH <i>new</i>	2 \$ 2,612.00 X	} X
17	SUNDIRES <i>new</i>	\$ 400.00 ?	
TOTAL SPARE PARTS CHARGES		\$ 13,631.00	
TOTAL LABOUR CHARGES		\$ 7,092.00	
GRAND TOTAL		\$ 20,723.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan L
Surveyed Date : 31/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, OS Rep

Liability Consultants hence notify
the Reparer of the following:

- To survey before/after spray painting
- To display damaged parts during resurvey
- Parts price are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- No third modification is allowed
- Damaged items must be resurveyed and
subject to final approval from Insurance Company

Authorised by Reparer
Signature
Date

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJA 8104 H

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer both lhs front and rear door's multi lock system window devices and audio equipment.	S/N	\$ 600.00	\$ 600.00
2	To remove and renew both front and rear door, transfer old fittings to new door. Reshape lhs front fender, renew door covers and reinstall all parts removed.		\$ 2,500.00	\$ 1,200.00
3	To respray lhs front fender, lhs front door, lhs rear door, both door covers.		\$ 3,200.00	\$ 2,200.00
4	To renew lhs front and rear wheel rim and carry out alignment.	S/N	\$ 600.00	
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,092.00</u>	<u>\$ 4,192.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJA 8104 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-LH	\$ 3,850.00	\$ 3,080.00
2	FRONT OUTER DOOR SEAL -LH	\$ 218.00	\$ 174.00
3	FRONT COVER TRIM-LH	\$ 339.00	\$ 271.20
4	FRONT DOOR COVER-LH	\$ 330.00	\$ 263.60
5	FRONT PILLAR B BRILLIANT BLACK TRIM-LH	\$ 150.00	
6	REAR DOOR-LH	\$ 3,850.00	\$ 3,080.00
7	STONE CHIP PROTECTION FILM	\$ 67.00	\$ 53.44
8	DOOR ATTACHMENT PARTS	\$ 85.00	
9	REAR OUTER DOOR SEAL-LH	\$ 218.00	\$ 224.40
10	REAR PILLAR C BRILLIANT BLACK TRIM-LH	\$ 153.00	
11	REAR PILLAR B BRILLIANT BLACK TRIM-LH	\$ 237.00	
12	REAR DOOR INSULATION STRIP-LH	4 \$ 220.00	
13	REAR DOOR SEAL -LH	\$ 218.00	
14	REAR COVER TRIM-LH	\$ 294.00	\$ 234.80
15	REAR DOOR COVER-LH	\$ 390.00	\$ 311.60
16	FRONT/REAR ALUMINIUM RIM-LH	2 \$ 2,612.00	
17	SUNDIRES	\$ 400.00	
TOTAL SPARE PARTS CHARGES		\$ 13,631.00	\$ 7,693.04
TOTAL LABOUR CHARGES		\$ 7,092.00	\$ 4,192.00
GRAND TOTAL		\$ 20,723.00	\$ 11,885.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, May 15, 2018 3:50 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: AMENDED REVISED FOR SJA8104H - OD AIG - SURVEYED 31 JAN 18
Attachments: PA01202018 - SJA 8104 H - Audi Q7 3.0 TFSI QU- LHS (AIG).xls

Hi Adrian and all,

As spoken on 3 May 18, we attached herewith the amended revised estimate for your closure.

2 pcs of door chrome were replaced as the reused parts were dropping off.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, March 21, 2018 4:27 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SJA8104H - OD AIG - SURVEYED 31 JAN 18
Attachments: PA01202018 - SJA 8104 H - Audi Q7 3.0 TFSI QU- LHS (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$11,379.04 @ 5 days of repairs.

Your early closure is appreciated.

Best regards - jlb

X

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0120/2018/GW
Date	:	27-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 21 Mar 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Albert Tan - Lienhart
Address	:	20 Ewe Boon Road #04-01 Singapore 259344
Telephone	:	HP +65 93877670
Type of Claim	:	Own Damage Claims
Policy No.	:	2100384019-03
Vehicle No	:	SJA 8104 H
Model Code	:	Q7 3.0 TFSI QU
Model / Year	:	Aug-14
Engine No	:	CJT 201928
Chassis No	:	WAUZZZ4L5ED032820
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Jan-18
Place of Accident	:	Traffic Junc Between Durnearn Rd/Bukit Timah Rd

X

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJA 8104 H

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer both lhs front and rear door's multi lock system window devices and audio equipment.	S/N	\$ 600.00	\$ 600.00
2	To remove and renew both front and rear door, transfer old fittings to new door. Reshape lhs front fender, renew door covers and reinstall all parts removed.		\$ 2,500.00	\$ 1,200.00
3	To respray lhs front fender, lhs front door, lhs rear door, both door covers.		\$ 3,200.00	\$ 2,200.00
4	To renew lhs front and rear wheel rim and carry out alignment.	S/N	\$ 600.00	
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 7,092.00</u>	<u>\$ 4,192.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJA 8104 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-LH	\$ 3,850.00	\$ 3,080.00
2	FRONT OUTER DOOR SEAL -LH	\$ 218.00	\$ 174.00
3	FRONT COVER TRIM-LH	\$ 339.00	
4	FRONT DOOR COVER-LH	\$ 330.00	\$ 263.60
5	FRONT PILLAR B BRILLIANT BLACK TRIM-LH	\$ 150.00	
6	REAR DOOR-LH	\$ 3,850.00	\$ 3,080.00
7	STONE CHIP PROTECTION FILM	\$ 67.00	\$ 53.44
8	DOOR ATTACHMENT PARTS	\$ 85.00	
9	REAR OUTER DOOR SEAL-LH	\$ 218.00	\$ 224.40
10	REAR PILLAR C BRILLIANT BLACK TRIM-LH	\$ 153.00	
11	REAR PILLAR B BRILLIANT BLACK TRIM-LH	\$ 237.00	
12	REAR DOOR INSULATION STRIP-LH	4 \$ 220.00	
13	REAR DOOR SEAL -LH	\$ 218.00	
14	REAR COVER TRIM-LH	\$ 294.00	
15	REAR DOOR COVER-LH	\$ 390.00	\$ 311.60
16	FRONT/REAR ALUMINIUM RIM-LH	2 \$ 2,612.00	
17	SUNDIRES	\$ 400.00	
TOTAL SPARE PARTS CHARGES		\$ 13,631.00	\$ 7,187.04
TOTAL LABOUR CHARGES		\$ 7,092.00	\$ 4,192.00
GRAND TOTAL		\$ 20,723.00	\$ 11,379.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

X

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJA 8104 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0120/2018/MAS

28 Aug 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SJA 8104 H, Audi Q7 3.0 TFSI QU

With reference to the above-mentioned vehicle no **SJA 8104 H**, claimant, **Mr. Albert Tan-Lienhart**, please find the related document per attached.

1. A copy of the Original invoice no. 85012835 – S\$11,218.99
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJA 8104 H

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 2100384019-03
 Period of Insurance : 28 Aug 2017 to 27 Aug 2018

Issued Date : 21 Aug 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : ALBERT TAN-LIENHART
 Address : 20 EWE BOON ROAD
 #04-01
 SINGAPORE 259344
 Occupation/Nature of Business : Manager/Director/Management

ABOUT THE VEHICLE

Registration No. : SJA8104H
 Chassis No. : WAUZZZ4L5ED032820
 Seating Capacity : 7
 Make/Model : AUDI Q7 3.0 TFSI QU (272BHP&333BHP)
 Hire Purchase Company/Employer's Loan : DBS BANK LTD
 Engine Capacity/Tonnage : 2,995.00 CC
 Engine No. : CJT201928
 Body Type : SUV
 First Year of Registration : 2014

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA
 Off Peak Car : No
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than sampling in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

* of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers - \$10,000. Dealer - AIG Authorised Workshops, PA Insured - \$100,000. Fire and Accessories
 Theft - \$50,000, Solar Film - \$1150, Loss of Use, Loyalty Home Cover

EXCESS

Section 1
 Fire - \$0, Own Damage - \$1400, Theft - \$0, Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver
 ALBERT TAN-LIENHART - \$1400 (Own Damage)

PREMIUM

Premium	: \$	1,609.42
GST (7%)	: \$	112.66

Total	: \$	1,722.08
-------	------	----------

Your Premium includes the following discount(s):

Safe Driver Discount - 5.00%, No Claim Discount - 50%



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733
Page 1 17:12

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408622
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment: 6386 2323
24 Hour Breakdown Service: 9626 1233
Email: customer.care@premiumauts.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012835 Date : 14/08/2018 Order : SJAB104H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJAB104H (V 23470) Regn Date: 28/08/2014 Mileage: 41693 WIP No.: 53882
Model: G7 3.0 TFSI DU (272 bhp) 4LB0Z Chassis: WAUZZZ4LSE032820 Engine: CJT 201928 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	1400.00	1.00	-1,400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOOR'S MULTI LOCK SYSTEM WINDOW DEVICES AND AUDIO EQUIPMENT	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND RENEW BOTH FRONT AND REAR DOOR, TRANSFER OLD FITTINGS TO NEW DOOR, RESHAPE LHS FRONT FENDER, RENEW DOOR COVERS AND REINSTALL ALL PARTS REMOVED	1200.00	1.00	1,200.00
S	BODYWORK	M: TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR AND BOTH DOOR COVER	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4L0837911	DOOR SEAL (A) Less 020%	1.00	217.50	174.00
X	A4L0831051A	DOOR (A) Less 020%	1.00	3850.00	3,850.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 2 17:12

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408622
Telephone: 6388 2223
Telefax: 6471 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6356 2323
9628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012835 Date : 14/08/2018 Order : SJAB104H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJAB104H (V 23470) Regn Date: 28/08/2014 Mileage: 41693 WIP No.: 53862
Model: 07 3.0 TFSI QU (272 bhp) 4L80Z Chassis: WAUZZZ4L5ED032820 Engine: CJT 201928 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A4L0833051	DOOR (A)	Less 020%	1.00	3850.00	3,000.00
X	A4L0853815J 2Z2	COVERSTRIP	Less 020%	1.00	293.50	234.80
X	A4L0839981A	FDIL (A)	Less 020%	1.00	66.80	53.44
X	A4L0839911	DOOR SEAL (A)	Less 020%	1.00	280.50	224.40
X	A4L0853907J 2Z2	COVERSTRIP	Less 020%	1.00	339.00	271.20
X	A4L0853959F GRU	S-LINE COVER (A)	Less 020%	1.00	329.50	263.60
X	A4L0853969F GRU	COVER (A)	Less 020%	1.00	389.50	311.60

Parts	7,693.04	Sub-Total	10,485.04
Labour	0.00	7% GST	733.95
Sublet	4,192.00	Grand Total	11,218.99
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJA 8104 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0120/2018/GW
February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q7 3.0 TFSI Qu
Vehicle Chassis No. : WAUZZZ4L5ED032820
Vehicle Regn No. : **SJA 8104 H**
Vehicle Mileage : **39212 km**
Vehicle Owner : Mr. Albert Tan-Lienhart
Certificate No : 2100384019-03
Policy Excess : \$1498.00 (inclusive 7% GST)
Accident Date : **25/01/2018**
Place : Traffic Junc Between Dunearn Rd/Bukit Timah Rd
Repair Cost : \$ 11,218.99
WIP No. : 53882
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 14/2/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2018		31 Jan 2018 17:27 Edit Adj Rpt	S\$11,885.04 Edit Estimates	S\$11,885.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ALBERT TAN - LIENHART, ID: S7303823E, Tel: +6593877670, Email: ALBERT.TANLH@ICLOUD.COM									
Vehicle Reg. No.: SJA8104H		Date of Loss: 25/01/2018 16:00 - :59 [40 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 8206276423SG		Policy/Cover Note No.: 2100384019-03 (Comprehensive)							
		Excess: S\$1,400.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/02/2018]									
Driver/Custodian: ALBERT TAN - LIENHART (44 / Male), NRIC: S7303823E, Tel: +6593877670									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (01/02/2018): Alert - Adj Mandate Approved (S\$13115.00) - SJA8104H - Claim Handler: Tr, Tinesh - AIG_SG (01/02/2018): SJA8104H / OD / 25/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJA8104H (8206276423SG)
OD
Jan 25 2018 4:25PM
[ALBERT TAN - LIENHART]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☐ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 14:08	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 14:22	General View	 Load JPG	☒
2	01/02/18 14:22	General View	 Load JPG	☒
3	01/02/18 14:22	General View	 Load JPG	☒
4	01/02/18 14:22	General View	 Load JPG	☒
5	01/02/18 14:22	General View	 Load JPG	☒
6	01/02/18 14:22	General View	 Load JPG	☒
7	01/02/18 14:22	General View	 Load JPG	☒
8	01/02/18 14:22	General View	 Load JPG	☒
9	01/02/18 14:22	General View	 Load JPG	☒
10	01/02/18 14:22	General View	 Load JPG	☒
11	01/02/18 14:22	General View	 Load JPG	☒
12	01/02/18 14:22	General View	 Load JPG	☒
13	01/02/18 14:22	General View	 Load JPG	☒
14	01/02/18 14:22	General View	 Load JPG	☒
15	01/02/18 14:22	General View	 Load JPG	☒
16	01/02/18 14:22	General View	 Load JPG	☒
17	01/02/18 14:22	General View	 Load JPG	☒
18	01/02/18 14:22	General View	 Load JPG	☒
19	01/02/18 14:22	General View	 Load JPG	☒
20	01/02/18 14:22	General View	 Load JPG	☒
21	01/02/18 14:22	General View	 Load JPG	☒
22	01/02/18 14:22	General View	 Load JPG	☒
23	01/02/18 14:22	General View	 Load JPG	☒
24	01/02/18 14:22	General View	 Load JPG	☒
25	01/02/18 14:22	General View	 Load JPG	☒
26	01/02/18 14:22	General View	 Load JPG	☒
Documentation			1 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 14:11	SJA 8104H ESTIMATE	 Load PDF	☐
2	01/02/18 14:11	Singapore Accident Statement	 Load PDF	☐
3	01/02/18 14:18	Insured Person's NRIC AND DL	 Load PDF	☐
4	01/02/18 14:18	Certificate of Insurance	 Load PDF	☐
5	06/09/18 10:29	WORKSHOP INVOICE	 Load PDF	☐
6	06/09/18 10:29	DISCHARGE VOUCHER	 Load PDF	☐

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/01/18 19:38	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/01/18 19:33	Accident Photo	Load JPG	☒
2	26/01/18 19:33	Accident Photo	Load JPG	☒
3	26/01/18 19:33	Accident Photo	Load JPG	☒
4	26/01/18 19:33	Accident Photo	Load JPG	☒
5	26/01/18 19:33	Accident Photo	Load JPG	☒
6	26/01/18 19:33	Accident Photo	Load JPG	☒
7	26/01/18 19:33	Accident Photo	Load JPG	☒
8	26/01/18 19:33	Accident Photo	Load JPG	☒
9	26/01/18 19:33	Accident Photo	Load JPG	☒
10	26/01/18 19:33	Accident Photo	Load JPG	☒
11	26/01/18 19:33	Accident Photo	Load JPG	☒
12	26/01/18 19:33	Accident Photo	Load JPG	☒
13	26/01/18 19:33	Accident Photo	Load JPG	☒
14	26/01/18 19:33	Accident Photo	Load JPG	☒
15	26/01/18 19:33	Accident Photo	Load JPG	☒
16	26/01/18 19:33	Accident Photo	Load JPG	☒
17	26/01/18 19:33	Accident Photo	Load JPG	☒
18	26/01/18 19:33	Accident Photo	Load JPG	☒
19	26/01/18 19:33	Accident Photo	Load JPG	☒
20	26/01/18 19:33	Accident Photo	Load JPG	☒
21	26/01/18 19:33	Accident Photo	Load JPG	☒
22	26/01/18 19:33	Accident Photo	Load JPG	☒
23	26/01/18 19:33	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/01/18 19:29	Sketch Plan	Load JPG	☒
2	26/01/18 19:29	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001950/ARBQ2

Date: 06/09/2018

REFERENCE

Insured/Claimant: ALBERT TAN - LIENHART Policy No: 2100384019-03
Date of Loss: 25/01/2018 Nature of Claim: OD Claim No: 8206276423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA8104H**
Make & Model: AUDI Q7, 3.0 (A) Engine No: CJT201928
Reg. Date: 28/08/2014 (Man. Year: 2014) Chassis No: WAUZZZ4L5ED032820
Colour: White Odometer: 38944 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$175,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/45 R20 Rear Tyre Size: 275/45 R20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,631.00	7,693.04	5,937.96	43.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,092.00	4,192.00	2,900.00	40.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,723.00	11,885.04	8,837.96	42.65
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	19,323.00	10,485.04	8,837.96	45.74
+ GST 7.00/7.00% (S\$)	1,352.61	733.95	618.66	45.74
Nett Amount (S\$)	20,675.61	11,218.99	9,456.62	45.74

INSPECTION

Date of Assignment: 31/01/2018
Date Inspected: 31/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Dented	3,850.00 FS	*3,080.00 FS
2	1		*FORNT OUTER DOOR SEAL -LH	Necessary	218.00 FS	*174.00 FS
3	1		*FRONT COVER TRIM -LH	Necessary	339.00 FS	*271.20 FS
4	1		*FRONT DOOR COVER-LH	Deformed	330.00 FS	*263.60 FS
5	1		*FRONT PILLAR B BRILLIANT BLACK TRIM -LH	Not Necessary	150.00 FS	*- FS
6	1		*REAR DOOR -LH	Dented	3,850.00 FS	*3,080.00 FS
7	1		*STONE CHIP PROTECTION FILM	Necessary	67.00 FS	*53.44 FS
8	1		*DOOR ATTACHMENT PARTS	Not Necessary	85.00 FS	*- FS
9	1		*REAR OUTER DOOR SEAL -LH	Necessary	218.00 FS	*224.40 FS
10	1		*REAR PILLAR C BRILLIANT BLACK TRIM -LH	Not Necessary	153.00 FS	*- FS
11	1		*REAR PILLAR B BRILLIANT BLACK TRIM -LH	Not Necessary	237.00 FS	*- FS
12	4		*REAR DOOR INSULATION STRIP -LH	Not Necessary	220.00 FS	*- FS
13	1		*REAR DOOR SEAL -LH	Not Necessary	218.00 FS	*- FS
14	1		*REAR COVER TRIM-LH	Necessary	294.00 FS	*234.80 FS
15	1		*REAR DOOR COVER-LH	Missing	390.00 FS	*311.60 FS
16	2		*FRONT /REAR ALUMINIUM RIM -LH	Not Necessary	2,612.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **13,631.00** **7,693.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOORS MULTI LOCK SYSTE WINDOW DEVICES AND AUDIO EQUIPMENT	New	600.00	600.00
2	TO REMOVE AND RENEW BOTH FRONT AND REAR DOOR ,TRANSFER OLD FITTINGS TO NEW DOOR .RESHAPE LHS FRONT FENDER,RENEW DOOR COVERS AND REINSTALL ALL PARTS REMOVED	New	2,500.00	1,200.00
3	TO RESPRAY LHS FRONT FENDER ,LHS FRONT DOOR ,LHS REAR DOOR ,BOTH DOOR COVERS	New	3,200.00	2,200.00
4	TO RENEW LHS FRONT AND REAR WHEEL RIM AND CARRY OUT ALIGNMENT	New	600.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,092.00	4,192.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >