

Investigator

Kalvin

REF:

CS / QW18001952 / KH692

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

SHA 7934J - CCG / QW18001622 / Ujb3
2/2/18 Wld P/R \$1790.40 / 2 Pys
Rd: 81317.12, 421.

DOA: 25012018

2nd Leg at Report P/R

RECEIVED 05 FEB 2018

Date/Time File Pass to?

☐

Preli. Report

☒

Final Report

Date/Time File Return to?

3)

Add Fee:

☐

Site Insp. \$

☐

Inter. \$

☐

Test \$

☐

Recovery \$

Report Format:

Independent

Lump Sum / L.B.:

1790.40

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee

Transportation

Veh No

SHA 7934J

Veh Regn

3 Sep 2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Truck / Trailer or

Make

Hyundai I40

1685

Colour

Blue

3 C

Insured / Std / NI / NA

Sp Reading

395551

Radio

Insured / Std / NI / NA

Eng No

C No

KMHL8414M64077265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD / Rim or

Tyre Size

F:

205 / 60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R Bal

2

mm

R Bal

2

mm

L Bal

2

mm

L Bal

2

mm

D.O.A

25/1/18

D.O.A

3/1/18

Survey held at

CPHE (1/2 way)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

COMFORTDELGRO ENGINEERING PTE LTD

Ref : CS/QW18001952/K1rb

59 LOYANG DRIVESINGAPORE 508969

Date : 31-01-2018



Code : QW007

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHA 7934J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/01/2018	Inspection Date	31/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Fw: Accident involving SHA7934J & your insured SKX5967X dated 25.01.18

31/01/2018 08:52 AM

Lim Tien Siong to: motor.survey
Cc: Roger How Keen Meng, kalvinang

From: Lim Tien Siong/cdge/delgronotes
To: motor.survey@axa.com.sg
Cc: Roger How Keen Meng/cdge/delgronotes@delgronotes, kalvinang@lkkauto.com

Officer in charge,

48 hours ended.

Without further delay,

Base on sequence we shall engage LKK (surveyor panel) to survey our client vehicle **SHA7934J**

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

----- Forwarded by Lim Tien Siong/cdge/delgronotes on 30/01/2018 09:00 AM -----

From: Lim Tien Siong/cdge/delgronotes
To: motor.survey@axa.com.sg (Tues)
Date: 30/01/2018 09:00 AM
Subject: Fw: Accident involving SHA7934J & your insured SKX5967X dated 25.01.18

Officer in charge,

A gentle reminder.
Thanks.

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

----- Forwarded by Lim Tien Siong/cdge/delgronotes on 29/01/2018 10:58 AM -----

From: Lim Tien Siong/cdge/delgronotes
To: motor.survey@axa.com.sg (Fri)
Date: 26/01/2018 05:10 PM
Subject: Accident involving SHA7934J & your insured SKX5967X dated 25.01.18

Officer in charge,



img-126170619-0001.pdf

Best Regards,
Lim Tien Siong
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148398 / Fax:65468156

Date/Time: 26.01.2018 16:46 Page : 1

Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: JC NO.305110902

CUSTOMER	REGN NO.: SHA7934J	MILEAGE
VMS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045	MAKE: HYUNDAI	FUEL E.....1/2.....F
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	MODEL I-40	DATE/TIME IN 26.01.2018 13:45
L (R) 65508755 (O)	YR OF MANU. 03.09.2015	TARGET DATE
(P)	CHASSIS CODE KMHLB41UMGU077265	COMPLETION DATE/TIME:
SCOUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 25.01.2018
NATURE: 3P 25.01.18/C

S/NO LABOR CODE DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Knowledge Slip	Exit Pass
Vehicle No.: SHA7934J	Vehicle No.: SHA7934J
Signature/Date	Name of Service Advisor
Date	Date
Returned to Service Reception upon collection	To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 15:06
Date Of Accident	25/01/2018 22:55
Exact Location Of Accident	STILL RD SOUTH TWDS STILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7934J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	QUEK SWEE KIEN
NRIC No	S1600992Z
Date Of Birth	30/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	09/12/1983
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	JONATHAN_QUEK@YAHOO.COM

Address	106A 07-548 PUNGGOL FIELD
Postcode	821106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX5967X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RHT REAR
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 198303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Person's Signature
Name:

26/01/18

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 25 Jan 2018 at about 22:55 hrs I was driving straight on the right lane along Still Rd South heading towards the direction of Marine Parade Rd and henceforth to Siglap

As I approached the junction I switched right hand signal lights and the same time maintaining my taxi within my lane. As my taxi was about to enter the right turning lane for vehicles to turn right towards Marine Parade Rd

At the point of entering into the right lane proper suddenly a Mercedes car SKX5967X coming from my left cut across 02 lane in a speedy manner encroached into my lane. Sensing the car is on a collision course with my taxi I instinctively hit the brakes and stopped to avoid a collision but it was too late.

In the process the right hand side front of the car hit and grazed the left hand side front of my taxi.

01 lady passenger on board my taxi. No injury at the point of the accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION, INC.
CO. REG. NO. 1993038215

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder)/Date
& Time

Witnessed by Reporting
Centre Personnel

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

(fri)

Date: 26.01.2018

Time: 17:05:51

Page: 1

AXA-CP/P

TS
Z

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305110902
 REGN NO : SHA7934J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 03.09.2015
 DATE/TIME IN : 26.01.2018 13:45
 ACCIDENT DATE : 25.01.2018

1710

48 hrs Ended
 (Refer Ena.1)

LKK - Kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2292-G	FRT BUMPER	1	1,052.20	20.00	841.76	x repair
0002	04-01-0103-0781-A	HEADLAMP LH	1	1,388.00	20.00	1,110.40	hrazel
0003	04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	24.60	20.00	19.68	xu
0004	04-01-0103-0639-G	FRT BUMPER BRKT LH	1	22.60	20.00	18.08	xu
0005	04-01-0101-0111-G	FRT BUMPER CLIPS	10	22.00	20.00	17.60	x 4

SUB-TOTAL : 2,007.52

JOB NATURE

0000	20-05	Frt Fender Adv.Sticker LH	1	100.00			
0001	L	PANEL BEATING					
0002	23-502	SPRAYPAINT ON AFFECTED AREA					
0003	17-01	CHECK ALL LIGHTING					

ncl 100.00

560.00 200

400.00 360

40.00 20

SUB-TOTAL : 1,100.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

AXA-CPIP

Date: 26.01.2018

Time: 17:05:51

Page: 2

(Fri)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305110902
REGN NO : SHA7934J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.09.2015
DATE/TIME IN : 26.01.2018 13:45
ACCIDENT DATE : 25.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,107.52

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Kalin LKK
31/1/18 1000hrs
2 Days
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price(s) are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplier (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledge Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305110902

Date : 02/02/18

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHA7934J

Date of Accident : 25-Jan-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- SKX5967X

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,110.40

(b) Labour Charges \$680.00

Total for Part-By-Part Repair Cost \$1,790.40

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 2/2/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.02.2018

Time: 18:29:55

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305110902
REGN NO : SHA7934J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.09.2015
DATE/TIME IN : 26.01.2018 13:45
ACCIDENT DATE : 25.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0781-A HEADLAMP LH 1 1,388.00 20.00 1,110.40

SUB-TOTAL : 1,110.40

JOB NATURE

0000 20-05 Frt Fender Adv.Sticker LH 100.00
0001 L PANEL BEATING 200.00
0002 23-502 SPRAYPAINT ON AFFECTED AREA 360.00
0003 17-01 CHECK ALL LIGHTING 20.00

SUB-TOTAL : 680.00

TOTAL : 1,790.40

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

(Fri)

Date: 26.01.2018

Time: 17:05:51

Page: 1

AXA-CP/P

TS
Z

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305110902
 REGN NO : SHA7934J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 03.09.2015
 DATE/TIME IN : 26.01.2018 13:45
 ACCIDENT DATE : 25.01.2018

1710

48 hrs Ended
 (refer Email)

LKK - Calvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2292-G	FRT BUMPER	1	1,052.20	20.00	841.76	X repair
0002	04-01-0103-0781-A	HEADLAMP LH	1	1,388.00	20.00	1,110.40	-
0003	04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	24.60	20.00	19.68	?
0004	04-01-0103-0639-G	FRT BUMPER BRKT LH	1	22.60	20.00	18.08	?
0005	04-01-0101-0111-G	FRT BUMPER CLIPS	10 L	22.00	20.00	17.60	X

SUB-TOTAL : 2,007.52

JOB NATURE

0000	20-05	Frt Fender Adv.Sticker LH	100.00	-
0001	L	PANEL BEATING	560.00	200
0002	23-502	SPRAYPAINT ON AFFECTED AREA	400.00	360
0003	17-01	CHECK ALL LIGHTING	40.00	20

SUB-TOTAL : 1,100.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.01.2018

Time: 17:05:51

Page: 2

(Fri)

TS

AXA-CP/P

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305110902
REGN NO : SHA7934J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.09.2015
DATE/TIME IN : 26.01.2018 13:45
ACCIDENT DATE : 25.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,107.52

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalin LKK
31/1/18 1000hrs
2 Pys
PIP
After Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey painting
- To display damage survey
- Parts are as
- Third party survey
- No other
- Supply must
- is subject to approval from

Acknowledged:
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

COMFORTDELGRO ENGINEERING PTE LTD

Ref : CS/QW18001952/K1rbs2

59 LOYANG DRIVESINGAPORE 508969

Date : 09-02-2018



Code : QW007

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHA 7934J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU077265	Colour	BLUE
Odometer	395551	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	WEST LAKE	7 mm
L/H Front Tyre	205/60R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/01/2018	Inspection Date	31/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7934J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	TO REPAIR SEE LABOUR	1,052.20	-
1	HEADLAMP LH	GRAZED	1,388.00	1,388.00
1	FRT BUMPER UPR BRKT LH	SERVICEABLE	24.60	-
1	FRT BUMPER BRKT LH	SERVICEABLE	22.60	-
10	FRT BUMPER CLIPS	NOT NECESSARY	22.00	-
	LESS 20% DISCOUNT		-501.88	-277.60
			2,007.52	1,110.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRT FENDER ADV. STICKER LH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT BUMPER.		560.00	200.00
	SPRAY PAINT ON AFFECTED AREA.		400.00	360.00
	CHECK ALL LIGHTING.		40.00	20.00
			1,000.00	580.00
	GRAND TOTAL		3,107.52	1,790.40
	RECOMMENDED COST OF REPAIRS			1,790.40

Report Ref No. CS/QW18001952/K1rbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.