

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 02 Feb 2018

Preliminary Advice

Insured Vehicle No	: YN1207U	Accident Date	: 19/01/2018
TP Vehicle No	: FT5058A	Assignment Date	: 31/01/2018
Make	: HONDA CB400ASFYJ	Est. Duration of Repair	: 5.00
Date of Inspection	: 01/02/2018		
Inspection At	: A S PHOON PTE LTD (TOH GUAN) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35 SINGAPORE 408701		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,577.00
Revised Amount	:S\$	5,327.60
Check Items (Estimated)	:S\$	4,047.20
Total	:S\$	9,374.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.