PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

31-Jan-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6059 G

1 pc	Bonnet grille		\$	386.00	
1 pc	Front bumper		\$	531.00	
1 pc	Front bumper emblem		\$	44.00	
1 pc	Front bumper reinforcement upper 🎘		\$	40.00	
1 pc	Front bumper centre grille 🗡		\$	174.00	
1 pc	Front bumper lower stiffer		\$	134.00	
1 pc	Front bumper tow hook cover X		\$	14.00	
1 pc	Front bumper lip		\$	52.00	
1 pc	Front bumper inner sponge ×		\$	110.00	
1 pc	Front bumper reinforcement ×		\$	328.00	
1 pc	Front bumper n/s side retainer X		\$	16.00	
1 pc	Front bumper n/s upper bracket 🗶	uto Consultante honco notify	3\$	16.00	
1 pc	Front bumper n/s support bracket 4 the Re	LKK Auto Consultants hence notify the Repairer of the following:		16.00	
1 pc	n/s headlamp • To res	urvey before/after spray painting play damaged part(s) during resurvey	\$	1,028.00	
1 pc	Front bumper n/s fog lamp cover Parts	 Parts prices are subject to confirmation 	\$	66.00	
1 pc	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed	gal modification(s) is allowed	\$	51.00	
	• Suppli is subj	ementary item(s) must be resurveyed and ect to final approval from Insurance Company	\$	3,006.00	
		edged by Repairer Less 10%	\$	300.60	
	Signatur		\$	2,705.40	
S/NETT	Date:				
1 pc	Front no. plate with casing ×		\$	50.00	
1 pc	Front bumper clips	n/s head lamp lower clip - Ka W (UCA)		48.00	
1 pc	Front n/s head lamp lower clip -			6.00	
1 pc	Front n/s head lamp side clip	1 3/1/18 1330 km. 3 Days. 43 Report pla	\$	3.00	
	Sundry	43 Pour 10 H	\$	50.00	20
	To check for wiring and to focus head lamps To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the support panel etc To putty and spray painting on bonnet, bonnet grille, front bumper, front n/s fender		\$	120.00	20
			\$	750.00 800.00	300
			\$	800.00	360
	To apply rustproofing on the repaired and replaced panels.		\$	120.00	7
			\$	4,652.40	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)