

Lump Sum ILB



4.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	rnationale Des Experts En Auton	nobile
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC4/LCR1800	1959/pb3
CHA	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	8-16	Date: 31-01-2018 Code: AIG	
1.		Policy Particu	lars :- THIRD PARTY CLA	IM
	Insured Veh.	SLQ 2940S	Veh. Inspected	SKH 469J
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
П	Assign From		Assign Date	31/01/2018
2.		Vehicle I	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	5)	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
<u> </u>	L/H Rear Tyre			mm
4.		Desc	ription of Damages	
5.		Ge	neral Information	
	Accident Date	29/01/2018	Inspection Date	
	Survey held at	HUI YANG MOTOR SERV	ICE	
		BLOCK 176 SIN MING DR #04-02/03 SIN MING AUTOCARE	IVE	


Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE 575721

5a.

Mon-05/02



HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721 Tel: 64515752 (2 Lines) . Fax: 64514658 Reg No. 201629438M

29/01/2018

Owner:

ALLIANCE LEASING PTE LTD

NOT Nothanke 8 6001 Purny Afthe Pring 2 days

ESTIMATE TO REPAIR MAZDA 6 2.0L - SKH469J

spray painting labour charges Total

600.00 400.00 1,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey beforefalled spray pointien
- To display damaged partial during reasonry
- . Parts prices are subject to confirmation.
- That party survey a on a Visitious Fregudice' basis
- No it's painted features; is a few and
- Supplementary lawsy) must be returneyed and is subject to first approval from Itsulance Company

Actinoplicated by Repairer Spatie



From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 7 February 2018 3:57 PM

To:

'hui_yang_motor@hotmail.com'

Cc:

Admin A

Subject:

ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref:

CC4/LCR18001959/Kpb3

Attachments:

Statement of SLQ 2940S.pdf

Your Ref: SKH 469J

Without Prejudice

Our Ref: CC4/LCR18001959/Kpb3

Dear Sirs,

ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client cut into his lane and resulted the collision. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hui Yang Motor <hui yang motor@hotmail.com>

Sent:

Wednesday, 7 February 2018 4:18 PM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

Re: ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref:

CC4/LCR18001959/Kpb3

Attachments:

vlc-record-2018-01-29-10h23m18s-07230017.AVI-.avi

Importance:

High

Hi Hsiao Tong,

Attached video fyna.

Is it possible to forward us your insured's video footage?

Thank you & Regards, Sandra

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Wednesday, February 7, 2018 3:57 PM

To: hui_yang_motor@hotmail.com

Cc: Admin A

Subject: ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref: CC4/LCR18001959/Kpb3

Your Ref: SKH 469J

Without Prejudice

Our Ref: CC4/LCR18001959/Kpb3

Dear Sirs,

ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client cut into his lane and resulted the collision. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of video footage as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 28 March 2018 7:57 AM

To:

Tee, Chee-Wah (Chee-Wah.Tee@aig.com)

Subject:

<SEEK INSTRUCTION> Your Ref: 4091478354SG *Our Ref: CC4/LCR18001959/Kpb3

[ACCIDENT INVOLVING SLQ 2940S(OI) & SKH 469J(TP) ON 29/01/2018]

Attachments:

SKH 469J vs SLQ 2940S - OI VIDEO.mp4

Your Ref: 4091478354SG

Our Ref: CC4/LCR18001959/Kpb3

Dear Sirs/Madam.

ACCIDENT INVOLVING SLQ 2940S(OI) & SKH 469J(TP) ON 29/01/2018

We refer to the above matter.

Third party reported that he was stationary to wait for traffic light to turn green. After a while, he felt an impact from behind. Third party driver alighted from his car and saw OID was trying to squeeze in from his right.

OID reported that he was on the 1th lane queuing to proceed right turn from AMK Ave 5 towards AMK Ave 10. Suddenly third party filtered into his lane and collided onto his front left portion.

Based on OI's video footage, third party cut into the right lane where OID was travelling with right of way.

In view of this, we are intending to reject third party claim based on BOLA scenario 15.

For your approval/comments/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Tee, Chee-Wah < Chee-Wah. Tee@aig.com>

Sent:

Wednesday, 28 March 2018 10:49 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: <SEEK INSTRUCTION> Your Ref: 4091478354SG *Our Ref:

CC4/LCR18001959/Kpb3 [ACCIDENT INVOLVING SLQ 2940S(OI) & SKH 469J(TP)

ON 29/01/2018]

Dear Hsiao Tong,

Thanks for your email.

Please proceed to reject TP claim as OI has the right of way.

Regards.

Tee Chee Wah AIG Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120 Tel +64191089 | Fax +68357416

Chee-Wah Tee@aig.com | www.aig.com.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or dissemisate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printends thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, if is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Wednesday, March 28, 2018 7:57 AM

To: Tee, Chee-Wah

Subject: <SEEK INSTRUCTION> Your Ref: 4091478354SG *Our Ref: CC4/LCR18001959/Kpb3 [ACCIDENT

INVOLVING SLQ 2940S(OI) & SKH 469J(TP) ON 29/01/2018]

Your Ref: 4091478354SG

Our Ref: CC4/LCR18001959/Kpb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLQ 2940S(OI) & SKH 469J(TP) ON 29/01/2018

We refer to the above matter.

Third party reported that he was stationary to wait for traffic light to turn green. After a while, he felt an impact from behind. Third party driver alighted from his car and saw OID was trying to squeeze in from his right.

OID reported that he was on the 1" lane queuing to proceed right turn from AMK Ave 5 towards AMK Ave 10. Suddenly third party filtered into his lane and collided onto his front left portion.

Based on OI's video footage, third party cut into the right lane where OID was travelling with right of way.

In view of this, we are intending to reject third party claim based on BOLA scenario 15.

For your approval/comments/instruction.

Best Regards, Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From:

Hsiao Tong (LKKAuto)

Sent:

Thursday, 29 March 2018 9:08 AM

To:

'Hui Yang Motor'

Cc:

Admin A

Subject:

RE: ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref:

CC4/LCR18001959/Kpb3

Attachments:

SKH 469J vs SLQ 2940S - OI VIDEO.MP4

Without Prejudice

Dear Sirs/Madam,

We refer to the above matter.

Attached here is a copy of our insured video footage for your easy reference.

We have reviewed the matter and we are of the opinion that our insured driver should not be blamed for the accident. Based on our insured's video footage, your client cut into the right lane where our insured driver was travelling with right of way.

In view of this, we regret to inform your that we have our principal instruction to deny liability and unable to look into your client claim.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: Wednesday, 7 February 2018 4:18 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref: CC4/LCR18001959/Kpb3

Importance: High

Hi Hsiao Tong,

Attached video fyna.

Is it possible to forward us your insured's video footage?

Thank you & Regards.

Sandra

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Wednesday, February 7, 2018 3:57 PM

To: hui yang motor@hotmail.com

Cc: Admin A

Subject: ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018 *Our Ref: CC4/LCR18001959/Kpb3

Your Ref: SKH 469J Without Prejudice

Our Ref: CC4/LCR18001959/Kpb3

Dear Sirs.

ACCIDENT INVOLVING SLQ 2940S(AIG) & SKH 469J ON 29/01/2018

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client cut into his lane and resulted the collision. Attached here with a copy of our insured driver accident report for your easy reference.

We would like to request a copy of <u>video footage</u> as stated in your client accident report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) LKK Auto Consultants Pte Ltd Attn: Thin Thin / Jas Blk 51 Paya Ubi Industrial Park, Ubi Ave 1 #02-25 Singapore 408933

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721 Tel: 64515752 (2 Lines) . Fax: 64514658 Reg No. 201629438M

Date: 10/02/2018

AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department 78 Shenton Way #08-16 AIG Building Singapore 079120

RE: ACCIDENT INVOLVING SKH469J & SLQ2940S ON 29-01-2018 ALONG RD 1 ANG MO KIO AVE 5

SETTLEMENT OF OUR CLAIM FOR SKH469J

repair cost as recommended by surveyor (TP0298) 2 days Loss of Use @ \$100.00 per day

\$ 642.00

\$ 200.00

Total

\$ 842.00

*The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.

Please let us have your reply soonest possible, thank you.

Best Regards, Marco Neo HUI YANG MOTOR PTE LTD

DID: 64515752 Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

address of Hui Yang Motor Pte Ltd, that	hereby declare and agree to use the is at Blk 176 Sin Ming Drive, #04-02 Sin Ming
Autocare Singapore 575721 in all my/our c	orrespondences with any party in connection with
my/our claim arising from an accident invo	olving my/our motor vehicle registration number
and other vehicles	registration number SUQ 39405 along
1500), And MO KUD HURNUE 5	on 39/6/1018
representatives to open all my/our letters and	
I/We wish to inform you that you could issue	the cheque payment in favour of my/our repairer
Messrs Hui Yang Motor Pte Ltd.	t a y and as a state of my our repairer

ALLIANCE LEASING PTE LTD 201706503M

Signature of registered owner

HUI YANG MOTOR PTE LTD

Bill To:

AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department

78 Shenton Way

#08-16 AIG Building

Singapore 079120

TAX INVOICE

TP Claim Invoice No:

TP0298

Bill Date: 10/02/2018

 Description	Am	ount
Date of Accident: 29/01/2018 Owner: ALLIANCE LEASING PTE LTD Vehicle No: SKH469J Make & Model: MAZDA 6 2.0L		
repair cost as recommended by surveyor	S	600.00
Sub-Total :	S	600.00
Add 7% GST:	\$	42.00
Total Amount SGD :	S	642.00

GST No:201629438M

HUI YANG MOTOR PTE LTD

Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax: 64514658

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

LAIM SUBF	OLDER TRA	CKING							
Case	Notified:	Est Submitted	Adj Assigned	Adj Rpt	Adj S	ubmitted	Ins Auth'ed	Status	
Main	31 Jan 2018 Edit Reg		31 Jan 2018 00:00 Edit Ad) Rpt	S\$600.00 Edit Estimates	S\$60 View	0.00 v Rpt		Pending for Report Cancel Car	1413.1032.74V
,	tain	∏ R	eference	Claim D	etails		Documents		Show All
CLAIM SUE	FOLDER DI	TAILS				[Created	by adjuster]		
Insured:	LCRF PTE	LTD, Co. Reg. !	Vo.: -						
Main Claimant:	ALLIANC	E LEASING PTE L	.TD, Co. Reg. No.:	201706503M					
Vehicle Reg. No.:	SKH469)		Date			8 07:00 - :59 hs and 5 Days Fro	m LTA Reg Date	e (Man Yr)]
Claim Type:	Bolies/County								
Vehicle Reg. No. (Insured):	SLQ2940	s		Policy (Clain	1.1	5086870343-01			
				Exces	62				
Repairer:	Hui Yang	Motor Pte Ltd (4Q) 176 Sin Ming Dr	ive #04-02, Sin M	ling Auto(Care, 5757	21 Sin Ming - Tel:	64515752	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	is) - Tel: 65-6419	-3000	[Handled b	y Tee, Chee-Wal	h] Chee-Wah.Te	e@aig.com
Claimant's Insurer:	100000000000000000000000000000000000000		Co-operative Ltd (10.20 A.722					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Hand	ed by KE	NNETH KO	ONG] [Final I	Rpt due 09/0	2/2018]
ASSOCIAT	ED MAIL RE	CEIVED					Vit	w All Comp	se Case Mai
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	iks⊟			VI	ew All s	Search Tasks C	reate New Task	Complete
Due Date	Priority	Type Task	Group Subjec	t Handler	Assigne	-	Completed On	Created C	-

Claim Documents

*SKH469J (4091478354SG)

[SLQ2940S]

TP

ALLIANCE LEASING PTE LTD

Jan 29 2018 7:00AM

[LCRF PTE LTD]

Hui Yang Motor Pte Ltd

		pload Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	ser v
Vid	eo		1 per p	page 🔻	V
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/03/18 08:32	Video - Accident	0	Load MP4	
Ass	sessment Reports		1 per s	age 🔻	7
No:	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	01/02/18 09:57	Accident Statement From:SC - Reg. No. SLQ29405, Claimant: LCRF PTE LTD	0	Load HTM	
Pho	otos/Images		3 per i	sage V	V
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	_
1	29/03/18:09:03	General View	0	Load JPG	V
2	29/03/18 09:03	General View	0	Load JPG	V
3	29/03/18 09:03	General View	0	Load JPG	V
4	29/03/18 09:03	General View	0	Load JPG	V
5	29/03/18 09:03	General View	0	Load JPG	V
6	29/03/18 09:03	General View	0	Load JPG	2
7	29/03/18 09:03	General View	0	Load JPG	V
8	29/03/18 09:03	Odometer Reading	0	Load JPG	~
9	29/03/18 09:03	Chassis Number	0	Load JPG	V
10	29/03/18 09:03	Reinspection Photo	0	Load JPG	V
11	29/03/18 09:03	Reinspection Photo	0	Load JPG	V
Do	cumentation		1 per p	age 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1.	31/01/18 18:03	EMAIL FROM AIG DD 31012018	0	Load PDF	
2	31/01/18 18:03	TP EST & GIA REPORT	0	Load PDF	
3	06/02/18 19:14	TP ESTIMATE- MARKED	0	Load PDF	
4	29/03/18 09:02	Email from AIG dd 280318	0	Load PDF	
5	29/03/18 09:10	Email to TP wksp_Reject dd 290318.	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			¥
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199507 1988)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/LCR18001959/KPB3Q2

Date:

16/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999995070

Claimant Vehicle No:

SKH469J

Insured Vehicle No :

SLQ2940S

Date of Loss:

29/01/2018

Nature of Claim:

TP

Claim No: 4091478354SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKH469J

Make & Model:

MAZDA 6, 2.0 SDN V (A)

Engine No:

LF20226445

248256 km

Reg. Date:

24/07/2008 (Man. Year: 2008)

Chassis No: Odometer:

JM6GH10F180110033

Colour: Engine Capacity: Metallic Black

1999 cc

Market Value/New Car Price: N/A

Sum insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

225/45 R18

Rear Tyre Size:

225/45 R18

Front Tyre Size: Front Left Side:

Toyo 7 mm

Rear Left Side:

Toyo 7 mm

Front Right Side:

Toyo 7 mm

Rear Right Side:

Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	600.00	400.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,000.00	600.00	400.00	40.00

0.00 Global Sum Settlement (S\$)

INSPECTION

Date of Assignment:

31/01/2018

Date Inspected:

05/02/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair:

2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINTING	New	600.00	400.00
2	LABOUR CHARGES	New	400.00	200,00
		Gross Labour Cost (S\$)	1,000.00	600.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >