

ASS. REC. BY:

REF: TH1 /CC3 / TM18001972 / Kgbnz

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured: SLA 9235HPolicy No. MV007561Claims No. M180656

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1/2File pass to Catherine461 Ry 85950 (Red 839m.73, 86%)SHC 5203M - XSLA 9235H - X01/2/18 @ 2.53pm Email GIA report & estimate to Shirley.

Veh No:

Site 5203M

Yr Regn:

01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1985

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

226203

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL 15AUC 276736

Gen. Cond:

Good Fair / Poor / Burnt

Steering:

In order Jammed / Leaked / Burnt or

Brake:

In order Jammed / Leaked / Burnt or

Modl:

Nil S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal:

4 mm

R/Bal:

8 mm

L/Bal:

4 mm

L/Bal:

8 mm

D.O.A.

30/1/18

D.O.I.

31/1/18

Survey held at

Des. of Damages:

Nil Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

11/2/18 TH1☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

250

S + RS \$

10

Photos

Others

TOTAL:

260

Report Format:

Lump Sum / I.B.I. (\$

5950



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CC3/TMI18001972/Kqb

20 MCCALLUM STREET #09-01

TOKIO MARINE CENTRESINGAPORE 069046

Date : 01-02-2018

Code : TMI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 9235H	Veh. Inspected	SHC 5203M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	30/01/2018	Inspection Date	31/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Reference No.: CC3/Am/18001972/Kg5
Policy Type: OD / TP / TP RES / TL / EVA

SHC 5203m

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

<u>Y-Date</u>	<u>N-Date</u>	<u>Y-Date</u>	<u>N-Date</u>
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		
✓	✓		

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

C	Vehicle No
C	Regn Month/Year
N	Vehicle Type
N	Make & Model
C	Engine Capacity, (C.C)
N	Colour
C	Odometer, (Sp.Reading)
C	Chassis No
N	General Condition
N	Steering
N	Brake
N	Modification (Modi)
C	Tyre Size
N	Tyre Make
C	Tyre Balance
C	Date of Inspection
N	Survey held
N	Des.of Damages

The image shows a handwriting practice sheet. On the left, there is a vertical column of ten boxes, each containing a cursive lowercase letter 'u' for tracing. To the right of this column is a large grid of 10 rows and 2 columns, intended for independent practice of the cursive 'u'.

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	

C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date _____

*C: Critical *N: Non-Critical

21/05/2014

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 1 February 2018 2:53 PM
To: Too Joon Hwa
Cc: Priscilla Tan; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 30/01/2018, SHC 5203M (TP VEHICLE), SLA 9235H (OI VEHICLE)
Attachments: SHC5203 EST.pdf, SHC5203 GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHC 5203M M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 31/01/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5203M
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C001023
Chassis No.:	VF1ABL15AUC276736
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Jan 2014
First Registration Date:	24 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	23 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$30,280.00
Total Rebate Amount:	\$39,653.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 09:34
Date Of Accident	30/01/2018 07:50
Exact Location Of Accident	JURONG WEST ST81 BLOCK 833-843 CARPARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5203M
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	ONG CHIN HUAT
NRIC No	S1395306F
Date Of Birth	01/05/1959
Occupation	OUTDOOR
Date Of Driving Pass	07/03/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81937333
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 531 JELAPANG ROAD #15-11
Postcode	670531
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On the 30.01.2018 at about 0750hours, i was heading towards Jurong West Street 81 Block 833-843 Carpark exit with the intention of making a right turn. With the red traffic light ahead of my lane, i slowly inched out after vehicles on my left side stopped before the yellow box. When suddenly Vehicle B(SLA9235H) squeeze through one of the vehicle which is in front of it and came at a fast speed on my left side. Hence, Vehicle B front portion had hit onto my taxi's front left side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA9235H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	XU JUN WEI
NRIC/Passport Number	S8328157Z
Contact Number	98172630
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

SKETCH PLAN

A - 246 5203M
B - 8LA 922SH

Jurong West
Street 81
B1K 833-843
Corporate Exit

A - 246 5203M
B - 8LA 922SH

Jurong West
Street 81
B1K 833-843
Corporate Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to GIA report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SketchPlanForm_V3

3

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5203M -

AAD1801-320

Not Notified
1/8/8 5950

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5203M - JHOW
 VF1ABL15AUC276736
 RENAULT
 LATITUDE
 30.01.2018
TOKIO

PART			LIST		
1	1	BUMPER COVER FRT	\$	<i>Bul</i> 1,259.42	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	X
3	1	BUMPER BEAM FRT	\$	<i>n</i> 914.08	X
4	1	BUMPER SPOILER FRT	\$	<i>D11</i> 181.75	✓
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	X
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>D11</i> 207.22	✓
7	1	BUMPER RETAINER FRT LH	\$	<i>cm</i> 151.41	✓
8	1	BUMPER BRACKET FRT LH	\$	<i>n</i> 181.75	X
9	1	HEADLAMP LH	\$	<i>m/c m</i> 1,184.43	✓
10	1	HEADLAMP PANEL FRT LH	\$	<i>n</i> 152.15	X
11	1	FENDER PANEL FRT LH	\$	<i>Bu</i> 783.83	✓
12	1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84	X
13	1	FENDER BRACKET FRT LH	\$	<i>n</i> 34.14	X
14	1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84	X
15	1	RADAIOR GRILLE	\$	<i>m/c m</i> 1,707.78	✓
16	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>n</i> 173.36	✓
17	1	RADAIOR GRILLE FRAME	\$	<i>cm</i> 1,353.75	✓
18	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90	} X
19	1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79	
20	1	BONNET	\$	<i>n</i> 1,941.63	
21	1	LOWER ARM LH	\$	<i>Sn</i> 685.76	
22	1	KUNCKLE ARM LH	\$	<i>Sn</i> 846.98	
23	1	ABSORBER FRT LH	\$	<i>Sn</i> 360.54	
24	1	WHEEL HOUSING PANEL FRT LH	\$	<i>n</i> 4,682.09	
25	1	AIR CLEANER LOWER	\$	<i>Sn</i> 271.26	
26	1	AIR CLEANER HOSE	\$	<i>Sn</i> 76.14	
27	1	AUTO COMPUTER	\$	<i>Sn</i> 5,032.17	
28	1	STEERING PUMP ELECTRIC	\$	<i>Sn</i> 2,306.90	
29	1	DOOR PANEL FRT LH	\$	<i>n</i> 2,844.66	
30	1	DOOR HINGE UPPER LH	\$	<i>n</i> 274.50	
31	1	DOOR HINGE LOWER	\$	<i>n</i> 300.55	
32	1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77	
33	1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23	
34	1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 258.12	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-320

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5203M -

35	1	DOOR HANDLE CAP FRT LH	\$	Sn	26.44	}	X
36	1	DOOR HANDLE SEAL FRT LH	\$	nn	7.89		
37	1	DOOR HANDLE COVER FRT LH	\$	Sn	13.22		
38	1	DOOR HANDLE MODULE FRT LH	\$	Sn	133.60		
39	1	DOOR FINISHER FRT LH	\$	Sn	515.06		
40	1	DOOR MOULDING FRT LH	\$	Sn	176.82		
41	1	DOOR GRAB HANDLE FRT LH	\$	Sn	210.96		
42	1	DOOR MIRROR LH	\$	Sn	1,483.40		
43	1	DOOR MIRROR GLASS LH	\$	Sn	148.20		
44	1	DOOR MIRROR BACK COVER LH	\$	Sn	218.46		
45	1	DOOR WHETHERSTRIP FRT LH	\$	Sn	474.21		
46	1	DOOR SEAL FRT LH	\$	Sn	68.67		
47	1	ROCKER PANEL OUTER LH	\$	n	987.49		

TOTAL	\$	34,733.66	4
10%	\$	3,473.37	
	\$	31,260.30	

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	nn	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	nn	66.00	
3	1	RIM LH FRT	\$	Sn	nn	385.00 X
4	1	TYRE LH FRT	\$	Sn	nn	330.00 X
5	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
6	1	DOOR STICKER "Classic"	\$	nn	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	nn	80.00	X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	32,297.30

To Check Electrical Lighting Concerned. \$ 170.00 201

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 4,200.00 5001

Putty and spray painting of the affected portion. \$ 4,500.00 4401

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$ nn 170.00 X

To transfer of tire, rim and on wheel balancing. \$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHC5203M -

AAD1801-320

To check steering geometry and computer wheel alignment	\$	220.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 X
Towing fees	\$	120.00 501
To rust-proofing of the affected areas.	\$	170.00 301
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X

TOTAL	\$	10,880.00
Over All Total	\$	43,177.30

28

(PARTS BY PARTS) Repair Days

15 Days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18001972/KQBN2

Date: 05/02/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV002561
Claimant Vehicle No :	SHC5203M	Insured Vehicle No :	SLA9235H
Date of Loss:	30/01/2018	Nature of Claim:	TP
		Claim No:	M1800656

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5203M	Engine No:	M9R8839C001023
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC276736
Reg. Date:	24/01/2014 (Man. Year: 2013)	Odometer:	226203 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	32,297.28	6,368.65	25,928.63	80.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,880.00	1,040.00	9,840.00	90.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,177.28	7,408.65	35,768.63	82.84
Approved Total (Overridden) (\$\$)		5,950.00		
(S\$)	43,177.28	5,950.00	37,227.28	86.22
+ GST 7.00/7.00% (S\$)	3,022.41	416.50	2,605.91	86.22
Nett Amount (S\$)	46,199.69	6,366.50	39,833.19	86.22

INSPECTION

Date of Assignment: 01/02/2018

Date Inspected: 31/01/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2018)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5203M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
4	1		*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
5	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
6	1		*BUMPER FOG LAMP GRILLE LH	Distorted	207.22 FL	*207.22 FL
7	1		*BUMPER RETAINER FRT LH	Cracked	151.41 FL	*151.41 FL
8	1		*BUMPER BRACKET FRT LH	Repair	181.75 FL	*- FL
9	1		*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
10	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
11	1		*FENDER PANEL FRT LH	Buckled	783.83 FL	*783.83 FL
12	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
13	1		*FENDER BRACKET FRT LH	Repair	34.14 FL	*- FL
14	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
15	1		*RADIATOR GRILLE	Mtg Cracked	1,707.78 FL	*1,707.78 FL
16	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	173.36 FL	*173.36 FL
17	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
18	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
19	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
20	1		*BONNET	Repair	1,941.63 FL	*- FL
21	1		*LOWER ARM LH	Serviceable	685.76 FL	*- FL
22	1		*KNUCKLE ARM LH	Serviceable	846.98 FL	*- FL
23	1		*ABSORBER FRT LH	Serviceable	360.54 FL	*- FL
24	1		*WHEEL HOUSING PANEL FRT LH	Repair	4,682.09 FL	*- FL
25	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
26	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
27	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
28	1		*STEERING PUMP ELECTRIC	Serviceable	2,306.90 FL	*- FL
29	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
30	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
31	1		*DOOR HINGE LOWER	Repair	300.55 FL	*- FL
32	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
33	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
34	1		*DOOR HANDLE OUTER FRT LH	Serviceable	258.12 FL	*- FL
35	1		*DOOR HANDLE CAP FRT LH	Serviceable	26.44 FL	*- FL
36	1		*DOOR HANDLE SEAL FRT LH	Not Necessary	7.89 FL	*- FL
37	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
38	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
39	1		*DOOR FINISHER FRT LH	Serviceable	515.06 FL	*- FL
40	1		*DOOR MOULDING FRT LH	Serviceable	176.82 FL	*- FL
41	1		*DOOR GRAB HANDLE FRT LH	Serviceable	210.96 FL	*- FL
42	1		*DOOR MIRROR LH	Serviceable	1,483.40 FL	*- FL
43	1		*DOOR MIRROR GLASS LH	Serviceable	148.20 FL	*- FL
44	1		*DOOR MIRROR BACK COVER LH	Serviceable	218.46 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*DOOR WEATHERSTRIP FRT LH	Serviceable	474.21 FL	*- FL
46	1		*DOOR SEAL FRT LH	Serviceable	68.67 FL	*- FL
47	1		*ROCKER PANEL OUTER LH	Repair	987.49 FL	*- FL
48	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	66.00 FS	*- FS
49	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*RIM LH FRT	Serviceable	385.00 FS	*- FS
51	1		*TYRE LH FRT	Serviceable	330.00 FS	*- FS
52	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
53	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*- FS
54	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	35,770.64	7,068.95
- List Item Discount on L Items 10.00/10.00% (S\$)	3,473.36	700.30
Total Parts (S\$)	32,297.28	6,368.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	500.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	440.00
4	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
5	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
7	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	-
8	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TOWING FEES	New	120.00	50.00
10	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	-
12	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	-
Gross Labour Cost (S\$)			10,880.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >