



Attention : FWD SINGAPORE PTE LTD
 Vehicle No : SKD 7655 M
 Make / Model : TOYOTA VIOS - 1.5A
 Year : 2005

Date: 31/1/2018

S/N	Qty	Description	Unit Price	Amount
Material				
1	1 pc	FRONT BUMPER <i>no form</i>	\$680.00	<i>✓</i>
2	1 pc	FRONT NUMBER PLATE WITH HOLDER <i>del</i>	\$85.00	<i>405.00</i>
3	1 pc	FRONT BONNET <i>no issue</i>	\$750.00	<i>✓</i>
4	1 pc	FRONT GRILLE <i>320</i>	\$280.00	<i>✓</i>
5	1 pc	FRONT BONNET LOCK <i>4w1</i>	\$195.00	<i>✓</i>
6	1 pc	FRONT HEADLAMP LH <i>Sen</i>	\$650.00	<i>✓</i>
7	1 pc	FRONT CONDENSOR	\$480.00	<i>?</i>

Total Material: \$3,120.00**Other Cost**

1 TO CHECK WIRING AND SYSTEM FUNCTION

\$200.00 *30*Total Cost: \$200.00**Labour**

1 TO REMOVE AND REPLACE THE ABOVE DAMAGE PARTS,
 REALIGN PANELS, REPAIR AND REPOSITION

\$1,200.00 *550*Total Labour: \$1,200.00**SPRAY PAINT**

1 TO SPRAY FRONT BONNET
 2 TO SPRAY FRONT BUMPER

\$500.00 *180*\$350.00 *180*Total Spray Paint: \$850.00Total Cost Of Repair: \$ 5,370.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized Signature
 Kenneth How
 Signature
 HP: 9763 0075
 Date:

*NOT Authorized
 LKK Auto Consultants
 Express?*

*Take photo before painting -
 4 day for repair
 1/2/18
 Tel. 62533561*