


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6439M  
Ref. No : TAX/01/18/2185  
Reg. Date : 01/11/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : HOONG ENG  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 31/01/2018 10:00:00 AM  
Accident Reported Date / Time : 31/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024094395  
Special Instruction to ARC, if any : *after*  
GY5056S *1EQ / Resin by paint*  
Prepared Date : 31/01/2018 02:26:42 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU603573398

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 1,155.74	1,155.74
Other Charges	: 280.00	0.00
<b>TOTAL</b>	<b>: 2,331.74</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	0.00 <i>2 days - p/p</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 31/01/2018 03:56:22 PM	01/01/1900 12:00:00 AM

  
*31/01/18 @ 1600*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 31/01/2018 03:56:22 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/31/2018 3:57:22 PM

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section D - Details of Repair Estimates****Part-1 - Labour Works**

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION		338.00	0.00 150
<b>Total Labour</b>		<b>338.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER		378.00	0.00 200
TO RESPRAY BUMPER BEAM		180.00	0.00 100?
<b>Total Spray Painting &amp; Panel Beating</b>		<b>558.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope		Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM		120.00	0.00 X
TO REPLACE SUNDRY PARTS		100.00	0.00 20
TO WASH AND VACUUM		60.00	0.00 40
<b>Total Other Costs</b>		<b>280.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>Repair</i>	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>DE</i>	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace <i>?</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>X</i>	No
<b>TOTAL MATERIALS</b>							<b>1,155.75</b>	<b>1,155.74</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>1,155.74</b>	<b>1,155.74</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									