

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/EGI18001981/Wd3e2 ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER Date: 19-04-2018 **FIVE SINGAPORE 038985** Code: EGI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. PA 8528Y Veh. Inspected **SGH 3356D** Policy No. Coverage (\$) 0.00 DSMOB1800231 Excess (\$) 0.00 Claim No. **Assign From** YEE PEI LI 01/02/2018 **Assign Date** 2. **Vehicle Particulars & Condition** Make & Model TOYOTA HARRIER 1986 c.c **Engine No. HIDDEN** Year of Reg. 2016 ZSU600076271 Chassis No. Colour **SILVER** Odometer **IN ORDER** Steering **IN ORDER** Brakes **Modification** SPORTS RIM GOOD General 3. **Conditions of Tyres** Size Make **Balance** YOKOHAMA 3 mm R/H Front Tyre 225/65 R17 YOKOHAMA L/H Front Tyre 225/65 R17 3 mm R/H Rear Tyre 225/65 R17 YOKOHAMA 3 mm 225/65 R17 YOKOHAMA 3 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. **General Information** 5. Inspect Date / Time 01/02/2018 (11:49 AM) **Accident Date** 29/01/2018 HANIP AUTOMOBILES ENGINEERING Survey held at NO 1 KAKI BUKIT AVE 6 #01-73 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500

Report Ref No. CS3/EGI18001981/Wd3e2

Estimate Days of Repair

Inspected By

5b.

WILSON TEO CHENG MING

Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.