

Surveyor: Nilson

ASSIGNMENT (Office)

From (Person): Yee Pui Li

of EGI

Date/Time: 1/2/18 @ 8:46am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 3356D

Insured:

PA8528Y

at Workshop m/s:

Hanip Automobile

Tel:

67470513

of No.1, Kaki Bkt Ave 6 # 01-73

Policy No:

Claim No:

BSMO B18 00231

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 9:12am @ 1/2/18

Person Contacted:

Hanip

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SGH3356D-X

PA8528Y-NS/INC12023206/R/vy

D.O.A. 28/11/2012

Dismantled Part - 02/02/18

AAU Repair - 07/02/18

PRS

EGI

ASSIGNMENT

From: Date: 01/02/2018

Estimated Cost

OD / TP / WS / TP RES / CD RES / EVA / INV / MY

To inspect Vehicle No: SGH 3356D

at Workshop No: Hanip Automobile

at No. 1, Kaki Bkt Ave 6 #01-73

Insured

Policy No

Claims No

Sum Insured

Excess

Driver's Record: Hanip @ 6747 0513

Make of VEH

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball on Market Value

IDAC Accident Report: Consistent? Yes or No

GIA / PP Seen: Consistent? Yes or No

Est. Repairs: 5 days Rep: Yes or No

Lum. Sub: 3 Val: Yes or No

CA / REV / REP / 24 HRS 'wp'

Date: Person Contacted

Vehicle IN / OUT

Vehicle: SGH 3356 D Date: 7/6/2016

Type: M/Cycle Bus/Van/Long Taxi/Prime Mover

Truck Trailer

Make: Toyota/Honda Year: 1986

Colour: Silver Insured: Std / Nil / NA

3rd Party: "Radio Insured: Std / Nil / NA

Eng No

Chassis No: ZSu 60-0076271

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt

Brake: In order / Jammed / Leaked / Burnt

Mod: N/A / STD Air / Std

Tyre Size: F 225/65 R17

R 225/65 R17

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO: GEOLANDER (R) Yokohama (F)

Front

R.Bal: 3 R.Bal: 3

L.Bal: 3 L.Bal: 3

DOA: 29/1/2018 DO: 1/2/2018

Survey held at: Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop

Left Frnt

The U/C / Chassis frame Body Structure affected due to collision

Date / Time / Action / Instruction

Range \$4500 - \$5500

5 days repair

RECEIVED 16 APR 2018

Date/Time File Received: ☐ Prelim. Report

☐ Final Report

Date/Time File Returned

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee

Add Fee:

☐ Stamped

☐ Stamp

☐ Stamp

☐ Stamp

Report Format: PRQ

Left/Right/Top/Bottom

50
50450
150

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 1 February 2018 8:46 AM
To: 'admin-d@lkkauto.com'
Subject: OI : PA8528Y / TP : SGH3356D/LKK / DOA : 29/01/2018
Attachments: SGH3356D - SAS.pdf; PRI : ERGO Insured PA8528Y [EAL.2018.5442.MK.ya - SGH3356D] (14.7 KB)

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey **EAST ASIA LAW CORPORATION**,

ADDRESS : HANIP AUTOMOBILE ENGINEERING
NO 1 KAKI BUKIT AVENUE 6
#01-73
SINGAPORE 417883

PERSON TO CONTACT : MR HANIP / MS ROHAINI @ 6747 0513

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 12:15
Date Of Accident	29/01/2018 14:00
Exact Location Of Accident	ALONG KANDAHAR STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH3356D
Insured/Policyholder	
Name Of Registered Owner	RIYATH BIN SALLEH ABDAT
NRIC No	S1640554Z
Email Address	JULIE.BAKES@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93874600
Alternative Phone No	OTHERS-93874600

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 ELEGANCE (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080577532-01 DRIVO CLASSIC
Cover Note Number	07/06/2017 TO 06/06/2018

Driver

Name of Driver	RIYATH BIN SALLEH ABDAT
NRIC No	S1640554Z
Date Of Birth	22/08/1964
Occupation	OUTDOOR
Date Of Driving Pass	10/09/1982
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93874600
Fax Number	
Contact Number	OTHERS-93874600
EMail Address	JULIE.BAKES@HOTMAIL.COM

No. Of Passenger (Including Driver)



**SINGAPORE
POLICE FORCE**



T/20180130/2004

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3
Report No. T/20180130/2004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	RIYATH BIN SALLEH ABDAT	ID No.	S1640554Z
Related Vehicle	SGH3356D (Car)	Contact No.	93874600
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 29/1/18 at about 1400hrs, I parked my vehicle SGH3356D along Kandahar Street on a proper parking lot. At about 1700hrs, I retrieved my car and went home.
At about 2000hrs, I retrieved my vehicle at my multistory carpark and saw that there were damages on my vehicle.

The front left-side of my vehicle suffered damages such as a dents, scratches on the bumper and rims and the front left bumper gave way.

I looked through my in-car camera footage and caught a bus PA8528Y had side-swiped my vehicle prior to making a left turn. It then left without leaving a contact number.


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18001981/Wd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 19-04-2018		
FIVE SINGAPORE 038985		Code: EGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PA 8528Y	Veh. Inspected	SGH 3356D	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMOB1800231	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	01/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600076271	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	YOKOHAMA	3 mm	
L/H Front Tyre	225/65 R17	YOKOHAMA	3 mm	
R/H Rear Tyre	225/65 R17	YOKOHAMA	3 mm	
L/H Rear Tyre	225/65 R17	YOKOHAMA	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5. General Information				
Accident Date	29/01/2018	Inspect Date / Time	01/02/2018 (11:49 AM)	
Survey held at	HANIP AUTOMOBILES ENGINEERING NO 1 KAKI BUKIT AVE 6 #01-73 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/EGI18001981/Wd3e2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.