

ESTIMATE TO REPAIR

VEHICLE NO. : SKZ 6189 H
 MAKE : TOYOTA
 MODEL : HARRIER PREMIUM 2.0 CVT
 YEAR : 2015
 CHASSIS NO : ZSU600068347

SURVEYOR NAME : 01 FEB 2010
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 31-Jan-18
 DATE OF ACCIDENT : 29-Jan-18
 THIRD PARTY REF : GW 5596 K / EQ INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			form	\$ 1,897.80
1 pc	Rear Bumper Sponge			form	\$ 165.80
2 pcs	Rear Bumper Sensor		\$ 398.80	short	\$ 797.60
2 pcs	Rear Bumper Retainer		\$ 78.87	dis	\$ 157.74
1 pc	Rear End Panel			bat	\$ 887.80
1 pc	Rear End Panel Garnish			dis	\$ 687.80
1 pc	Tailgate			off	\$ 2,580.80
1 pc	Tailgate Top Lock			bat	\$ 789.80
1 pc	Tailgate Bottom Lock			R	\$ 66.90
1 pc	Tailgate Rubber				\$ 587.80
1 pc	Tailgate Top Outer Garnish GLW Lamp			dis	\$ 1,870.77
1 pc	Tailgate Emblem			new	\$ 89.80
1 pc	Rear Windscreen Sealant moulding			cost	\$ 125.70
	Tail Gate Lamp				\$ 10,706.11
	Less 25%				\$ 2,676.53
	Bumper lower garnish				\$ 8,029.58
1 tube	Rear Windscreen Sealant	S.Nett		new	\$ 40.00
1 pc	Rear Number Plate	S.Nett		bat	\$ 40.00
	To putty & spray painting.		NA	700	\$ 950.00
	To remove and refix rear windscreen glass.		Authent	100	\$ 120.00
	To transfer tailgate fittings.		P/P Repair	60	\$ 120.00
	To anti-rust.		Before Paint	40	\$ 80.00
	Signature Protection Treatment at accident affected panel.		Photo	X	\$ 450.00
	Labour Charges.		Work Auto	700	\$ 800.00
					\$ 10,629.58

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd

76 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64589127 Fax: 65-64589127

Website : www.LTM.sg

Co-Reg No.199307277D

GST Reg No.M2-0019086-0

This document is subject to final approval from Insurance Company and is not to be disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd



SUPPLEMENTARY TO REPAIR

VEHICLE NO. : SKZ 6189 H
 MAKE : TOYOTA
 MODEL : HARRIER PREMIUM 2.0 CVT
 YEAR : 2015
 CHASSIS NO : ZSU600068347

SURVEYOR NAME	: Mr Ma Chin Fook
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 1-Feb-18
 DATE OF ACCIDENT : 29-Jan-18
 THIRD PARTY REF : GW 5596 K / EQ INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Tailgate Lamp			<i>cut</i> \$	488.53
1 pc	Bumper Lower Granish			<i>cut</i> \$	369.10
				\$	857.63
	Less 25%			\$	214.41
				\$	643.22
TG-RA/-					\$ 643.22

Lim Tan Motor Pte Ltd

Blk 175 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel 65-64520893 Fax:65-64589127

Website : www.LTM.sg

Co Reg No 199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd